

This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

- + *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.
- + Refrain from automated querying Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.
- + *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.
- + *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at http://books.google.com/














MODERN MILLING MACHINES



MODERN MILLING MACHINES

THEIR DESIGN CONSTRUCTION, AND WORKING

A HANDBOOK >

for Practical Men and Engineering Students

BY

JOSEPH G. HORNER, A.M.I.MECH.E.

AUTHOR OF "PATTERN MAKING," "HOISTING MACHINERY," "TOOLS FOR ENGINEERS AND WOODWORKERS," "ENGINEERS' TURNING," ETC. ETC.

WITH 269 ILLUSTRATIONS



LONDON
CROSBY LOCKWOOD AND SON
7 STATIONERS' HALL COURT, E.C.

1906

372291

MOY WIM OLISIA YAASSII

Printed at THE DARIEN PRESS. Edinburch

PREFACE.


THE present period is one of growing specialisation in Technical Literature, as in Manufacturing. The books which give a general treatment of a particular subject appeal less to practical men than to students and amateurs. No apology, therefore, is necessary for issuing a work which treats of a single department of machine-shop practice, and one of great and growing importance. Its scope is very broad, as a perusal of the contents of this work will show. Milling machines have become highly specialised, and the work of milling is now subdivided between different groups of hands just as that of turning is, ranging from very plain to very difficult work.

The Author has treated lightly those sections of the subject which offer no special difficulties, and has given considerable space to the manufacture of cutters and the work of the machines that call for the exercise of special skill. A number of typical methods of holding work, as well as some fixtures and jigs, are shown, but more as a general guide to the machineattendant, than with any thought of their covering a field that is immense in its extent and variety. Some of the latest improved machines are illustrated with fully detailed drawings reduced from workshop prints, and special attention has been given to the vexed question of obtaining speeds and feeds.

The thanks of the Author are due to the firms who have kindly supplied drawings and photographs of machines and operations.

JOSEPH G. HORNER.

BATH, November 1905.



CONTENTS.

CHAPTER I.

THE LEADING ELEMENTS OF MILLING MACHINE DESIGN AND CONSTRUCTION.

The Development of the Milling Cutter—The Utilities of the Milling Machine—The First Machine—Early Improvements—The Influence of the Emery Grinder in its Development—Existing Machines Classified—The Lincoln Miller—The Characteristics of this Type—Modified Forms—The Work of the Lincoln Miller

CHAPTER II.

PLAIN AND UNIVERSAL MACHINES.

Pillar and Knee Machines, with Horizontal Spindles—The Characteristics of this Type—Typical Machines Described—Difference between the Plain and Universal—Variable Details—Headstocks—Tables and Knees—Feeds—Whence Derived—Countershaft on Spindle—Numerous Examples—Microincter Movements to Feed Spindles—Vernier Fitting to Tables—Differences between Plain Machines and Universals—Index Centres and Spiral Heads—Various Examples—Footstocks

CHAPTER III.

ATTACHMENTS AND BRACINGS.

Vertical and Angular Spindle Attachments to Horizontal Machines— Examples—Heads that Swivel Bodily—Examples—Slotting Attachments—Examples—The Overhanging Arm—Bracings— Examples—The Work of the Pillar and Knee Machine 16

PAGE

CHAPTER IV.

ν	ERTIC	1 T.	SP	מע	7. F.	MA	CHI	NES
ł.	ran i itaz	4//	17 / 1		I , F2	ма	U/HI	18 E217.

Vertical versus Horizontal Spindle Machines—Vertical Spindle Machines—The Profiling Machines—Various Examples—Designs of Vertical Spindle Machines—Built after the Model of Drilling and of Slotting Machines—Examples—Spindles coming from Below—The					
Work of the Vertical Spindle Machine-The Work of the Pro-					
filing Machines	94				

CHAPTER V.

PLANO-MILLERS OR SLABBING MACHINES.

Plano-Millers or	Slabbin	Slabbing Machines Their Characteristics - Details o							υf	
Spindles –	- Horizo:	ntal	Vertical	l — Rot	tary P	laners	\mathbf{or}	Endin	ıg	
Machines	-		-			-		•	-	136

CHAPTER VI.

SPECIAL MACHINES.


Special Machines for Gear Cutting, &c.—For Spur and Bevel Gears—For Worm-thread Milling For Hobbing Worm Threads—For Fluting Twist Drills - Three spindle Machines - Cam-cutting Attachments — Profiling Mechanism — Milling Attachment for Planer-Machine for Effiptical Holes 139

Differences in the Teeth of Milling Cutters and Single-edged Tools.—Size of Cutters and Spacing of Teeth for Roughing and Finishing Cuts Rake and Clearance—Spiral Form—"Handing" of Spiral—Compensation for Wear—Attachment to Spindles—Inserted Tooth Cutters—Various Examples—Manufacture of Cutters—Steel—Hardening—Cutting the Teeth—Examples—Grinding and Sharpening—Examples—Clearances—Form Grinding

162

CHAPTER VIII.

MILLING OPERATIONS.	
The Operations of Roughing, Finishing, and Profiling—Milling Compared with Planing, Shaping, and Slotting—Examples—Holding Work in Jigs—General Considerations—Examples	PAGR 199
CHAPTER IX.	
INDEXING, SPIRAL WORK, AND WORM, SPUR. AND BEVEL GEARS, ETC.	
The Universal the Machine of Applied Geometry—The Spiral Dividing Head—The Basis of Calculation—Worm and Worm Wheat—Indev Plate—Sector—Differential Indexing—Angles of Spirals—Poles and Examples—Graphic Method—Muling Screw Gears—Relations between Spiral, Helical, and Worm Gears—Elements of the Spiral Gear—Velocity Ratio—Pitches—Graphic Methods—Examples—Trigonometrical Rules—Worm Gears—Methods of Cutting	243
CHAPTER X.	
SPUR AND BEVEL GEARS.	
Spur and Bevel Gears—Diametral Pitch -Blanks—Cutters—Projection of Bevel Wheels—Multiple Cutters Multiple Centres—Milling Squares—Tapered Work	278
CHAPTER XI.	
FEEDS AND SPEEDS.	
Governing Conditions Feeds of more Importance than Speeds Hardness and Softness of Metal Pickling—Its Limitations Lequency of Grinding—Examples of Feeds and Speeds	291



MILLING MACHINES AND THEIR WORK.

CHAPTER I.

THE LEADING ELEMENTS OF MILLING MACHINE DESIGN AND CONSTRUCTION.

The Development of the Milling Cutter—The Utilities of the Milling Machine—The First Machine—Early Improvements—The Influence of the Emery Grinder in its Development—Existing Machines Classified—The Lincoln Miller—The Characteristics of this Type—Modified Forms—The Work of the Lincoln Miller.

The Development of the Milling Cutter.—The rapid development of milling processes during the lifetime of the present generation is one of the most remarkable and interesting facts in the history of workshop practice. At one time these processes were regarded by engineers of the old school with disfavour, and the belief was very general that they could have but a limited application in the formation of only small surfaces of comparatively simple outlines. Neither would much improvement have been possible but for the fact that the development of emery-grinding machines has kept pace with the elaboration of the milling cutters. Milling, therefore, affords an illustration of ideas long latent, good in themselves, failing of translation into general practice in consequence of necessary conditions not having developed sufficiently.

There is an early, possibly one of the earliest milling cutters in existence in America, made by Vaucanson, a famous French mechanic, born 1709, died 1782. It is pierced with a hexagonal hole, and its profile is approximately that of the cutters for gearwheel teeth. The pitching of the teeth is very fine, more like that of a saw than a modern milling cutter, and they are irregular.

Mr Bodmer, of Manchester, it is stated, had made a milling machine so early as 1824. But the general use of milling cutters in England dates only from about twenty-five years past—since emery wheels were introduced for grinding the faces of the teeth.

The late Mr Dixon stated that, as the result of careful inquiries, he found that the use of the emery wheel for sharpening milling cutters was due to a Mr George Hannay, of Ulverstone, a brother of Mr Hannay of the firm of Schneider & Hannay, the original founders of the Barrow Steel Works.

The difficulties of cutter formation having been got over, there remained another equally great, relating to the construction of the machines. The depth of cut which can be taken by a tool, conditions remaining the same, diminishes with increased breadth of cutting edge. Deep and broad cuts do not coexist. Roughing tools are narrow, the finishing tools are broad. This fact holds good in relation both to single-edged tools, and to milling cutters. One result is that the latter cannot take the deep cuts that the former are capable of doing. More than that, when the width of such cutters increases beyond an inch or two, the stresses are so severe, even with shallow cuts, that vibrations are set up which strain the machines, and detract much from the accuracy of the work. This is the key to the difficulties which have been experienced by the builders and users of milling machines.

The Utilities of the Milling Machine.—The study of the operations of milling machines involves the consideration of a type of rotating tools differing in all respects from those used in drilling and boring. The boring head with cutters has some resemblance to a mill. In fact, some mills with inserted teeth are constructed very similarly to the boring head. But there the resemblance ceases. Mills have a larger number of cutters, and their functions are quite different. Some will bore circular work. But that is not the chief function of milling cutters. Their function is that of universal tools, capable of operating on surfaces plane, curved, regular or irregular, straight or spiral. In short, I can think of no tooling in the machine shop, save that of drilling, which is not also done by means of circular milling cutters. The circular form is, of course, merely a convenient method of arranging a large number of single cutters at equal distances around the axis, the

mill being in effect a multiplication of single-cutting tool edges or points, each of which operates in quick succession without any return stroke. The number of teeth and the resulting diameter of a mill are therefore not of a hard-and-fast character, these being details which are settled by practical considerations and convenience. Thus, it would not matter in the case of most jobs whether a mill were 3 or 5 inches diameter, the results in the shape imparted to the work would be the same. Considerations of cost, stability, and class of machine used will determine the choice of one size in preference to that of another.

No milling machine has yet been constructed suitable for all classes of work. There are universal machines, capable of performing all varieties of operations; but they lack the stability necessary for the heaviest work, and the range requisite for many operations. Compromises in milling machines have not been very successful: hence it follows that for nearly every special class of work a special machine is obtainable, and the nature of the jobs to be done should always determine the selection of a machine.

Very much milling is of such a character that the cutters become subsidiary to measurement; either a single cutter may be made to definite dimensions, or two or more cutters may be arranged in series or gangs, with or without provision for adjustment for wear. The value of arrangements of this kind over single-cutting tools is apparent. With the latter there is a lot of preliminary experimental setting and adjustment required, much of which work, so far as dimension adjustments are concerned, is saved by the use of milling cutters. The question of higher cost of cutters in the first place has to be considered, but as the practice of milling increases, the relative cost of these diminishes.

Milling machines are of less value in general engineering shops than in those which deal with specialities. As these machines received their first development in the manufacture of pistols, rifles, sewing machines, and articles of kindred character, so these shops and those of analogous character still afford the best illustrations of the practice of milling. In some manufactories of this kind there will be scores of milling machines performing every conceivable kind of operation on iron, steel, and brass. The wide extent, precision, and economy of the operations performed must, however, be studied in several shops in order to be fully appre-

ciated. In these firms, and others of which these are types, milling is reduced to a system in which interchangeability of parts is secured at a ridiculously low cost per piece. And in proportion as shop systems approach more nearly to these does the value of milling increase. Growing specialisation and the increase in number of small fittings are the conditions most favourable to this class of work. Such, however, is the tendency of modern engineering practice, and therefore that practice is favourable to the increasing use and development of the milling machine. Planing, shaping, slotting, all labour under the disadvantages of having a non-cutting return stroke, besides being unsuitable for cutting surfaces which have very irregular contours. And when these last are cut, they cannot be done at once, but must be produced in detail with traverse feeding. In the milling machine, on the contrary, broad surfaces of irregular contours can be cut with mills having those contours, without any traverse feed.

Yet, though it is true that milling lends itself more readily to special work than to that of a general character, the assumption has been too often hastily made that it has little chance in the general shop. It certainly would be most injudicious to make a radical change in the methods of a general shop already equipped with single-cutting tool machines. But it is wise to introduce milling gradually, beginning with those classes of work for which the long experience of other firms has proved them suitable. In any general shop there are a lot of articles which without doubt can be treated more economically by milling than by any singletool machine. An enumeration of such articles is hardly worth attempting, but in the work of nearly any firm it would be easy to select scores of pieces to which milling would be eminently superior to any operation done on planer, shaper, or slotter. remark is applicable not only to plane surfaces, but to those in which profile cutters can complete at one traverse many jobs which must otherwise be done by more than one cutter, and more than one series of traverses, and often by setting on more than one machine. Illustrations of these kinds will appear in later chapters; for the present it is sufficient to note the fact. There are also machines which are capable of dealing with heavy work—using long fluted cutters, or gangs of cutters, or face cutters with inserted mills; and there are many bulky castings which can be tooled

more rapidly thus than with the single tools of the planer and slotter. Machines of this class are not of recent origin, but they are being developed and brought more under the notice of engineers, their value becoming better recognised than they were a few years since. These facts afford an indication that the milling machine is destined yet to occupy as important a place in the general shop as the single-cutting tool machines have done.

Milling has not nearly reached its possible developments with us yet. The planer, shaper, and slotter still hold their own, with little rivalry in some shops, and surfaces are slowly tooled which could be done more expeditiously and often with equal accuracy under a good system of milling. Many machinists would be astonished at the large areas and the intricate sections which are milled in some shop practice, where milling is the rule, and planing and shaping are of secondary importance. The real era of the milling machine will not arrive with us perhaps until the pressure of closer competition develops its yet latent possibilities. It is from milling and grinding that the greatest developments of machinists' work are to be anticipated in the future.

The selection of milling machines to perform general, or special functions is a question for individual choice, and must depend mainly on the requirements of any given shop. One of the favourite types to-day—the Brown & Sharpe—also one of the oldest, has either a wide range of functions or is absolutely universal. A machine equal to it in value for general work is the vertical one, with slotting machine type of framing, and compound tables. Strictly specialised machines are confined mostly to shops which do a special class of work. In the future, these, like other classes of machines, may be expected to become more common.

There is no machine in the shop which requires more skilled attendance. Even the gear cutters do not need such constant attention as the universal milling machines, because the work of the former is more repetitive than that of the latter. The care of the various milling cutters themselves, the methods of lubrication, the setting of the work, the best arrangements of tooling in order to produce in all cases the most accurate results, in the most economical ways or by the means at disposal, the relations of depth of cut and feed, the most suitable treatment for the quality of material being cut, the best form of cutters to use for any given job—these

points have all to be settled by an intelligent apprehension of the carron bances of each each, ad not by the perfunctory attention of the more machine minder. There is an immensely greater variety of pile on the universal machine than on others, the lathe excepted. and the mind must be always on the alert if the capacities of the machine are to be attribled to the atmost. It is in truth a beautiful piece of mechanism, the mest and application of which are ever being extended in the machine shop; and the greater the intelligence brought to operate it the greater is its value. It is therefore unwee for employers to give such machines in sole charge of tals or unskilled labourers, who will bring the machine and its work into discepute. They should be attended to by intelligent mechanics or by men who have had a good deal of experience in then charge Unskilled men or boys can attend to machines done plan or repeat work, but then they should simply be attendants working under the supervision of another who is repon this for the scheming of methods setting of work, regulation on access and so torch. Machines doing a variety of work like about of the analog it experient only be operated economically, and Para all approximate continuously highly skilled intendim of

Object results of the day of the service seed response of the first winder that the control transfer are always in fermion of the control transfer and the control transfer are always are always and the control transfer are always are always and the control transfer are always are always and the control transfer are a

That depends on the way in which they are treated. Always regard must be had to the power of a machine. attempt to drive it quicker, and to feed harder than its capacity will justify, can only result in chatter and untrue work, which must afterwards be corrected by the fitter. It is not the mere revolution marks left by the cutters, which occur in all work, but the departure from truth due to the springing of the arbor and cutter, which will make surfaces convex, or otherwise distorted from the profile that the cutters should impart. Unduly heavy feeding, therefore, is incompatible with true work. Further, the care of the cutters themselves influences results. Even when properly formed and fluted, the maintenance of the cutting edges by grinding is a vital matter, since dull edges will not cut so truly as keen ones, due to the spring of the arbor.

Another point in connection with milling is this—that the hard scale on forgings and castings, which does so little injury to the single-edge cutting tools, for the simple reason that they are able to penetrate beneath it at once, is ruinous to the delicate edges of the milling cutters. Hence in every shop where milling is adopted as a system it becomes a matter of economy to remove the hard skin by pickling the iron and steel work in dilute sulphuric acid, and the brass work in nitric acid.

The capacities of the milling machine are more limited in one sense than those of the average machines in the shop. The reason is that an arbor of great length is objectionable because of the vibration set up in it by heavy, or even moderate, cutting. The size of arbors is limited by the diameter of the holes in the smallest mills. To increase the diameter of arbor would preclude the employment of small cutters, and restrict very much the utility of the machine. It becomes therefore impossible to put work of very large dimensions on ordinary milling machines. Exceptions occur in the heavy slabbing tools which do not fulfil universal functions, and the ending or rotary machines, which are used only for facing large work laid on a table alongside the machine.

Milling has conduced to general machining of a higher degree of excellence, both in respect of accuracy and of finish, than was formerly economically possible. Very much work that is done well and cheaply by milling was formerly done laboriously and imperfectly by the single-tool machines, or by hand, or by grinding.

The single-tool machines are accurate, but there is no one of them which is capable of performing so great a variety of processes as the milling machine. Neither is it possible, without taking two or three cuts, the last one with a broad tool, to produce so smooth a finish as a milling cutter will produce with one cut. Hand labour is too costly to hold a place against modern conditions, neither is it adapted for repetitive work. The excellent results which are producible by milling have rendered inferior work, by whatever method done, unjustifiable and inadmissible, so that a shop well provided with milling machines is able to turn out work not only better, but often cheaper, than a rival shop working by the older methods. In another way milling has acted on machine-shop practice. It has favoured the cheap production of repetitive work of small dimensions, so that uniformity of dimensions and form, and interchangeability, unknown and impracticable not so many years ago, are now becoming the rule.

The First Milling Machine.—The late Mr E. G. Parkhurst, known best by wire-feed reputation, but great in all that concerns the manufacture of small arms, has given an account of what is probably the first milling machine ever constructed. He saw the machine, and gathered the facts relating to it in 1851 from a Mr Robert Johnson, who gave the year 1818 as that in which it was first set to work. This was at a gun factory in Middletown, Conn., on a site known then, as now, as Mill Hollow.

At that period the file was the principal tool used by the gun makers, and the new milling machine was used as a roughing tool to lessen the labour of rough filing, leaving the finishing to be done by hand. Its application was confined to plane faces, and did not include either curves or profiled forms. It was a hand-operated machine for several years before a self-acting feed was added.

The machine, shown in Fig. 1, comprises the following parts:— A bed plate A, a rough casting measuring about 24 in. by 18 in. by 2 in. thick. A headstock B, removed from an engine lathe, was bolted to the bed, and carried a spindle with a square-tapered socket to receive the cutter spindle. The cutter was a plain one, with filed teeth. It measured about 1½ inches in diameter, by 1 inch face. The cone pulleys were of wood, of about 2½-inch

face, the largest being about 8 inches in diameter. The drawing shows the grooved pulley at the rear for feed, a later addition to the first design.

The work was traversed under the cutter by the hand crank c, turning a pinion a, engaging with a cack screwed on the under side of the table it. The edges of the table were veeled to fit the vec notches cut in the plugs b, b, carried in drilled holes in four uprights E. E. bolted to the bed, and secured by and rendered adjustable for wear by set screws v. c. The work was gripped in the piece r, fitted with pinching screws, having pointed ends. If a piece of work required a second cut, it was packed up in r with paper or sheet metal.

This machine, in existence three years after Waterboe, though crude in the extreme, is a venerable relic worthy of Illustration in a book that deals mainly with present-day construction. Spite




Fig. 1. - The First Milling Machine.

of its simplicity, the working none said not to have taken kindly to it at first, considering it an innex tion on filing!

Early Improvements.—The first great improvement which was effected in the milling machine by in the substitution of provision for vertical adjustments of the spindle bearings, for the fixed hearings of the first machines.—This is said to have originated at the works of Mr Eli Whitney, of New Haven, Cerm.

Lattle fraction progress was made until the early fitties, at which period there were a great many millers in existence, but mostly manuact is by firms to their ewn use. About this period they began to take rank as precision tools for duplicating pieces previously to which they had retained their first function—that of roughing-down muchines to the filers. Gang mills began to figure about this time, and an masuccessful attempt was made

to build a slabbing machine, somewhat on the lines of the planer. Soon after, 1850, the Howe machine was brought out, and then the Ames Manufacturing Co. of Chicopee, Mass., made numerous machines, one being a modified Howe, designed by Mr C. M'Farland. These machines much resembled in outline the Lincoln miller, designed by Mr F. A. Pratt in 1854, a type on which probably more machines have been made than of any other. Its distinguishing feature was the substitution of a screw feed in place of the pinion and rack feed hitherto applied. The quick return was effected by hand. In 1848 came the Root machine by Mr E. K. Root, superintendent of Col. Colt's armoury at Hartford. This was in the main built on the Lincoln and other earlier models, but the table was driven by a worm gearing into a spiral rack underneath the table. It embodied also a yielding clutch, with a hand lever for operating it, for the purpose of disengaging the driving cone pulley, so that the spindle could be stopped from the countershaft. There was also an automatic knock-off, which stopped the machine instantly, leaving the table standing at any desired part of its traverse. Some of these machines have remained in service for fifty years. Between 1861 and 1866, during a portion of which the American Civil War was raging, the hundreds of thousands of small arms turned out in government and private factories gave the opportunity for the improved milling machines, and they became firmly established as precision tools. At that period, too, sewing machines were booming, and so after 1863 nearly all the armoury-milling machines, which were being abandoned in consequence of the closing of the war. were purchased by the sewing-machine manufacturers.

Up to this period, therefore, forty-five years after the invention of the milling machine, there was but one type in use, the modern representative of which is the Lincoln miller. All these machines had horizontal spindles, and housings adjustable vertically. Most had tailstocks also, but the Root introduced an overhanging arm with movable centre, in place of the tailstocks. Back gears were fitted and compound tables. The legs in every case were of the A form, in lathe fashion. The pillar and knee machine had not appeared, nor the vertical spindle machines, nor any successful slabbing miller, nor rotary face mills with inserted teeth, nor any cutters of large dimensions.

The Influence of the Emery Grinder.—The milling machine would never have attained its present development but for the growth of the emery grinder. Its era dates from this period, notwithstanding that the milling cutter itself is more than a century old, and the milling machine was born about eighty years ago. In the older methods the temper of the cutters had to be drawn for sharpening, and rehardened, and this was inconsistent with accuracy, and with economy. It is to the emery wheel also that we owe the displacement of cast gears by cut ones. The old cutters were not accurate enough for such work, nor would they retain their shape unimpaired by grinding but for the form type of cutter.

Existing Machines Classified.—The types of machines, ranging from plain to universal, are as varied as the classes of work which are done by milling. These types also merge into one another, so that strict classification is not possible. The following will, I think, be a comprehensive and serviceable one:—

- 1. Lincoln millers.
- 2. Pillar and knee machines with horizontal spindles.
- 3. Vertical spindle machines and profiling machines.
- 4. Plano-millers or slabbing machines.
- 5. Special machines for gear cutting, &c.

The Lincoln Miller, Figs. 2 and 3.—This is one of the most common types of milling machine, dividing favour about equally with the pillar and knee types. As it was the first to be invented, it has retained a permanent place in favour notwithstanding the advent of new forms. Its great value lies in its stability and rigidity, the arbor being supported from the bed below, and the table being backed up by a solid bed resting on the ground, instead of by an overhanging knee. Its slight disadvantage is that the table and its work are partly behind the foot block or end support of the arbor, so that the workman cannot get round the job so readily as when an overhanging arm is used. But this does not interfere with the ordinary work put upon the miller, largely consisting of that which would otherwise go to the small planer, or to the shaper.

As the table has no provision for elevation in the Lincoln

machines, all movements of this kind are imparted to the spindle. The spindle bearings in the smaller machines slide in housings within the head and foot stocks, Fig. 2. In the larger ones they slide on the front upright faces of these heads, Fig. 3, each in-




Fig. 2.-Lincoln Miller. (Pratt & Whitney Co.)

volving different operating mechanisms. Independent hand wheels and vertical screws are used, in some mitre gears operate the screws, as in the elevating mechanisms of planers. Frequently the bearings of the head and tail stocks are moved in unison by a single set of gear on the head, by the simple device of connecting the two spindle bearings with a stiff round bar, Fig. 3. This bar is made rigid enough to ensure the alignment of the spindle at all vertical positions. In some machines exact heights can be obtained by micrometric divisions of thousandths, or sixty-fourths of an inch. In one type of machine the dial boss revolves with the




Fig. 3.-Lincoln Miller. (J. E. Reinecker.)

screw by a spring friction, but is adjustable by hand, the index finger remaining stationary. The mass of the spindle and bearings is counterbalanced in all but the smallest machines by weights suspended from chains passing over pulleys.

Generally the headstock is a fixture, sometimes cast with the bed, and the tailblock is adjustable to and from the head to a small amount, in order to permit of inserting cutters of different widths. The carriage of the table also has a lateral adjustment of three or four inches to accommodate the work slightly to the cutter after the latter has been fixed. In a few machines the headstock is also capable of some adjustment along the bed.

The forms of the beds vary. In the small machines the bed much resembles that of a lathe, Fig. 2, and is surrounded in modern machines with a deep waste-oil tray, and carried upon legs.




Fig. 4.-Modified Lincoln Miller. (Tangyo Tool & Electric Co., Ltd.)

In larger machines the cabinet form of bed, Figs. 3 and 4, reaching to the ground is adopted.

The spindle drive is from stepped cones and through gears, provision being embedded to permit the spindle gears to engage at all heights. The feeds are derived from smaller stepped cones, the first of which is on the main come shaft, the second on a shaft running alongside the bed, having a worm which drives a werm wheel, and thence through other goars the table feed screw. The feed is tripped, and the worm dropped automatically out of engagement at the end of a out.

There are numerous modifications of this general type of machine. The principal differences are those due to increasing size. The machine begins to resemble the planer. Fig. 4, the head and foot stocks developing into two large housings bolted against the sides of a bed, which carries a table of greater proportional length than that of the ordinary Lincoln machine. These in strictness are not Lincoln machines, but they form an obvious link between these and the plano-millers. Allied to these are the double-headed milling machines, carrying horizontal spindles for face milling, and the machines with one head removable, so converting them into open-side machines.

With scarcely an exception the Lincoln machines are of plain type. There is an example of a universal machine, rendered so by the fitting of a swivel table, and a dividing head.

The Work of the Lincoln Miller.—The work put on this machine is generally of small dimensions, because the tables and their traverses are short in the standard machines. But within these limits there is a large volume which the machine will take. It has scored most in the work of the gunsmiths and sewing-machine makers, and then in engineers' work of a similar character. The greater volume done is horizontal milling, either plain or profile, the conditions being very favourable to the latter by reason of the good support given to the spindle and the table. Cuts as heavy as the teeth of the cutters will stand can be taken in consequence. Face milling is also done. In many cases the footstock is readily removable to permit of the insertion of wide pieces of work to be tooled thus. Small pieces of work are frequently arranged in series, up to the capacity of the machine.

CHAPTER II.

PLAIN AND UNIVERSAL MACHINES.

Pillar and Knee Machines with Horizontal Spindles—The Characteristics of this Type—Typical Machines Described—Difference between the Plain and Universal—Variable Details—Headstocks—Tables and Knees—Feeds—Whence Derived—Countershaft or Spindle—Numerous Examples—Micrometer Movements to Feed Spindles—Vernier Fitting to Tables—Differences between Plain Machines and Universals—Index Centres and Spiral Heads—Various Examples—Footstocks.

Pillar and Knee Machines with Horizontal Spindles.— The reason why so many, probably the majority of milling machines, are of the pillar and knee kind is traceable to the fact that the early milling was of a light character, for which machines of this type are eminently adapted. As this was among the earliest, so it is in its elements the simplest form of machine. Fig. 5 shows the earliest machine of this kind, and interesting comparisons may be made between that and machines in subsequent pages.

Among the simplest types of pillar machines are those which comprise in the main a lathe type of headstock, cast with or bolted to the pillar, and having a compound table on the knee to carry the work. There are three movements to the table—that in the vertical direction with the knee, one towards and away from the spindle, one transversely to the spindle. A few machines of this class have hand feeds only for all movements for the slides, through screws and handles, and through hand wheel and screw for the knee. Such machines have but a limited range, though with a dividing apparatus fitted to the table they are useful to brass-finishers and others for cutting hexagonal and other faces, and macking screw heads, while boys can attend to them. Machines of this kind, too, generally have a screwed nose to receive chucks, the idea being that cutters can be turned up in place by means of tools.

held and operated on the table. There is no support to the outer end of the cutter arbor, and therefore neither long cutters can be used nor heavy tooling done. Those most generally employed are



Fig. 5.—First Universal Milling Machine built. (Exhibited by Brown & Sharpe, Paris, 1867.)

fly cutters, or of the face or end type, and as these lie close up to the headstock, they are stiff enough for the work which they have to do. Generally such machines are single-geared only. For die sinking, special pillar and knee machines are fitted with vertical spindles, driven by belt through guide pulleys at the back. In such types the movements of the table are generally by hand, or the longitudinal traverse may be self-acting. A circular table is also senactimes fitted with a rotary motion through worm goar.

These machines are not standardised forms, but are generally of a somewhat special character. The simplest standard machines of pillar and knee type are those in which the spindles are horizontal, but in which the outer end of the arbor is steadied by an arm. These are generally termed "plain" machines, to distinguish them from the universals, which are built upon the plain types by the addition of an angular movement to the table, and of dividing heads and change wheels. On the plain machines rectangular relations only are obtainable. The methods of actuating the differents movements will vary in considerable degrees, rendering these movements of a more or less automatic character, but the tange of the operations is still limited rigidly to rectangular planes

A pillar milling machine, to be thoroughly complete and efficient must fulfil many conditions—conditions which are combined in one by the best manufacturers. Good useful machines at moderate prices are, however, made by many firms, and the low-priced ones will often be as well adapted for some classes of work as the more complete but higher-priced tools. In this as in other matters every tool user must consider his own special needs and requirements and pecket.

The leading dimensions of pillar machines are:—Distance from centre of spindle to the overhanging arm, which limits the diameter of the mills that can be used; the distance from the end of the spindle to the centre in the overhanging arm, which governs the length of mills that can be used. The height from the centre of the spindle to the top of the table, when the latter is in its lowest position, which limits the height of the work that can be tooled. The size of the table, and the length of longitudinal and transverse feeds, that regulate the dimensions of work that can be operated on. The terms "longitudinal" and "transverse" movements are used somewhat loosely by tool makers, the same terms sometimes indicating movements of opposite character. It will be better to

state precisely the direction in any case. Properly, longitudinal traverse denotes the movement of the table at right angles with the spindlet and the transverse no venient that to or from the pillar.

The range of work which can be done on a plain milling machine, though usually restricted to rectangular movements only, is yet wide enough for nearly all the requirements of some firms. those, for example, who have no heavy willing, or near cutting, in spiral-cutter making, or form milling. The work of the plain machine is done mostly by cutters threaded on an arbor. The diameter of arbor will range between about I inchested 11 inches in the smaller and larger machines respectively, and the length of arbor from about 10 inches to 24 inches respectively. The fonetions of the plain pillar machine lie chiefly in axial and edge work done in strictly longitudinal planes. End mills can be used by supporting the arbor at the heidstock end simply. It is convenient sometimes to be able to use an end mill, but such work is not as a rule so readily detection as it would be on a vertical spindle machine. Petallel grooves of the or of plain section was is cut thus, and a series also of parallel grooves, by utilished the vertical movements of the knee. The principal utility of the machine consists, however, in the realities which it air a is for hear and edge milling using single outlets or gains of outlets, of claim and of motile outlines.

The principal points which are essential to the still two objects which is placed in the influence and the still the substituted frequency well-specified at the base to come of the theory wishness of the strategy and the one-side latitudes of the three and tables. There well-titled spinile with previous to take up wear, and begins to be of both which the other all value corps to the other end of the about a control to stee all value corps is being bose—or important titling to specifing the let also which opinions in i proctice wary. Another essential condition is the perfect digmost of the factor in the respective to the spinile in any position whether closer in or father out from the isolate of the arms. The amounts is sentited and really that it has be easily moved yet mindy claraced in any position or swong out of the

way or removed altogether. It is essential, too, that the knee or table and the slides have large bearing surfaces, be fitted in the best manner, and in very accurate rectangular relations to each other and to the spindle, and with provision for taking-up wear. These points are all essential in the plainer, cheaper machines, as in those more elaborately fitted. They are details which are not apparent at a glance, and hence must be made matters for test, or,




Fig. 6. -- Vertical Section through Pillar and Knee Machine.

which is generally sufficient, taken on the guarantee of a high-class firm

That which may be fitted, or not, to a plain machine, according to individual requirements, is provision for movements of a more or less automatic character. It is seldom that the longitudinal traverse motion is effected by hand only, since the addition of cones, a telescopic shaft, and gears is a simple matter. But in a

: 4

number of machines the automatic movement is restricted to this alone. Another detail relates to the reversal of the table, which may be by hand only, or made automatic, with quick return. The use of adjustable stops in connection with this reversal, and, in fact, with all movements of the slides, is inseparable from perfectly equipped machines. Related to this closely is the need for micrometer readings. These are fitted to the bosses of the operating handles, so that exact depths of cutting can be done. A wide range of feeds also is necessary for the longitudinal traverse of the table.




Fig. 7.—Plan, and Part Section of Pillar and Knee Machine.

Fig. 6 is a vertical section taken through a machine of the pillar and knee type, such as may, in its general features, be seen in large numbers of shops; and Fig. 7, a plan view, with knee and other details omitted. It is a type which is being subjected to much modification, particularly in the matter of feeds (see page 32), while the details of construction adopted by different makers vary in most parts of the design. The broad characteristics which distinguish all these are the horizontal spindle, the height of which is fixed, and the knee, which is capable of vertical adjustment on the pillar, or column. It is therefore a type of an exactly opposite kind to that of the Lincoln machine, with spindle vertically adjustable, and a table at a fixed height. The elements of the machine are as follows:—

The pillar A, of hollow or boxed section, and cast usually, as shown, in one with the headstock B, and having slide faces to receive the knee c. In a poorly designed machine, and in all in some degree, the head and the knee are the weak elements, the arbor being insufficiently supported, and the knee being liable to spring under heavy or wide cutting. Hence the reason for the fitting of the overhanging arm when edge milling is being done, and the fitting of bracings rigidly connecting arm and knee (see also page 86).

In the figure the upper part of the headstock is made continuous, forming a long boss a, Figs. 6 and 7, instead of having separate bearings, which is the case in many machines, particularly in the older designs. In the boss, the overlanging arm D is clamped by screws passing through split lugs. This arm is an important element, and is varied in design. It cannot be used for face milling, and is thrown up out of the way when this is being done. It receives a bushing to support one end of the arbor, in the example shown. Often a bracket is employed instead, sliding along a plain parallel bar, and the arbor is supported Either arm or bracket is adjustable through the boss a, of the headstock, to receive arbors of different lengths. The advantage of the straight arm is that it need not be turned up, or removed when some adjuncts of the machine are put on the table.

The main spindle is generally back geared, as indicated in both Figs. The knee c carries the cross slide E, and the table F, the first having a transverse cross movement, or one to and from the pillar; the second a longitudinal, or traverse one, that is tangentially to the pillar. The mechanisms by which they are operated are varied greatly. Hand feeds are employed, and power. Power feeds are derived from the three-stepped cones G and II, driving in this example from the main spindle to the telescopic shaft b, which is jointed thus in order to permit of its The objections to following the vertical movements of the table. this method of feeding are stated on page 31, and substitutes for it are illustrated and described in some detail. c is the screw for cross traverse, or transverse movement, d that for vertical feed when effected by hand, which actuates the screw r, through bevel wheels, also used for power feeding. The screw f forms an adjustable stop for the height of movement of the knee. The table \mathbf{r} is traversed by a screw, indicated at g, in universals, but often by a rack in plain machines. The advantages of a screw are finer precision in operating, and that the table remains at a standstill immediately the feed is disengaged. A rack permits




Fig. 8.—Vertical Section through Spindle and Back Gears, No. 5 Plain Milling Machine. (Brown & Sharpe Manufacturing Co.)

of making more rapid adjustments by hand when setting, and removing work. A universal also has a swivel table above F, which introduces other details. A universal head (see page 63) can be used on plain machines as well as on universals. But its utilities are limited on the first-named, spiral gears for example,

requiring a swivelling table. Plain machines are also generally built stiffer than the others, and are sometimes termed manufacturing machines, to denote their greater power.

Other points to note in Fig. 6 are the waste-oil trough cast round the base of the pillar, and the shelves j, j within it for receiving tools, also the hole k cast in the base to permit the screw




Fig. 9 .- Rear View of Fig. 8.




Fig. 10.--Sectional Detail of Eccentric Movements and Locking Pin in Figs. 8 and 9.

to pass down through the floor as the table is lowered. This is not a good device, and an example is given of a telescopic screw (page 53) to obviate this objection.

Headstocks.—Figs. 8-10 show the headstock details of the Brown & Sharpe largest size of plain milling machine.

Fig. 8 shows the headstock in vertical section, with the back

gears placed below, where they are covered in and protected. the arrangement shown, the drive takes place from the cone pinion A to B, on an intermediate spindle, then through C, D, E, F, and G to H on the main spindle. The ratio thus obtained is 13:3 to 1. Both the back-gear shafts K and L have eccentric movements. On the gear quill on the shaft L there is a disc M, which, in the position shown, prevents the clutch N from being thrown into engagement. But when the gears D and E are thrown back and out, by the eccentric spindle L, that movement throws down the disc also, so permitting the clutch x to be engaged. When this is in, the drive takes place from the pinion A, through the gears B and G to H, with a ratio of 3:677 to 1. The upper gears can be thrown out also by the eccentric movement of K, giving a simple belt drive. By means of a two-speed countershaft, and the three-stepped pulley, and double-back gears, eighteen different speeds are available, ranging from 10 to 403 turns per minute, in geometrical progression as follows:-

SPINDLE SPEEDS IN REVOLUTIONS PER MINUTE.

Without Back Gears.

403	32 5	262	211	170	137
C. S. Speed Fast.			Slow.		

With First Back Gears.

110 88.5	71.3 , 57.5	46.3	37.3	
C. S. Speed F	ast.	Slow.		

With Second Back Gears.

	30:4	24.4	19.7	15.9	12.8	10.3
	C. S. Speed Fast.			Slow.		
١				'		:

The illustration, Fig. 11, shows the new headstock by the Cincinnati Milling Machine Co., designed mainly with a view to the employment of cutters of high-speed steel. The features present are, that a high belt speed can be used in conjunction with the power of back gears, and that the latter are double, providing a large range of spindle speeds, eighteen in number, as follows:—11, 13, 16, 20, 25, 30, 36, 44, 54, 66, 81, 99, 119, 146, 178, 218, 267, and 326. The countershaft speeds are also high, having 145 and 260 revolutions per minute. The smaller cone steps are larger




Fig. 11.—Headstock of Cincinnati Milling Machine.

than usual, for greater power. The steps measure $9\frac{3}{4}$, $10\frac{7}{8}$, and 12 inches diameter respectively.

The action of the back gears, seen in Fig. 11, is as follows:—
The gears A and B slide in unison with a quill, which slides on
the back-gear eccentric quill. A gears with C, producing slow
driving from E to F. When B is slid into engagement with
D, E drives F quickly. To bring either set into gear, the eccentric shaft must be thrown out, and the gears thrown in. The
rim seen on B prevents it from engaging D when A and C are

driving. When the machine is in operation, the back gears are encased.




Fig. 12.—Headstock Spindle of Cincinnati Milling Machine.

Fig. 12 illustrates the headstock spindle of the latest Cincinnati machines, having the double back gear shown in Fig. 11. The

spindle is hollow, of forged crucible steel, running in adjustable bearings. The hinder, parallel bearing has two lock nuts for adjusting diametrical wear. front coned neck has but one. End play is taken up on this by turning the lock nut A on the spindle to the right, or in the direcwhich tion in the spindle turns, so drawing the latter into a





Fig. 13.—Garvin Front Spindle Bearing.

close bearing. The clamping plate B for the spindle gear ϵ is made separately from the cone pulley, and is fitted into the latter

at front and back. The gear C is connected to the cones by the spring plunger D. Other details, as the keying of the back gears



on the cone boss to the rear, provision for lubrication, the protecting cap to the front bearing, &c., will be noticed.

Fig. 13 illustrates the Garvin form of front spindle bearing. The neck is tapered to an angle of 5 degrees, and end play is prevented by the washers which come against the collar A.

Two of these washers a, a are hardened and ground, the third b is a soft one, which can be taken out and its thickness reduced in the lathe by the amount to which end play might have developed. The washers and spindle are held in contact by the cap b, screwed in front. Lubrication is provided for by the groove and channels seen. The hinder bearing is parallel, with a bushing tapered externally.

Other details of spindles and bearings will be found on pages




Fig. 15.—Transverse Section through Knee and Table, No. 5 Miller.

34, 36, and 39, in connection with illustrations of feeds. In the meantime we consider the details of knees and tables.

Table and Knee Feeds.—Figs. 14-19 show the table and knee details of the Brown & Sharpe plain miller. In Fig. 14 the fitting of the table A to the cross slide B, on the knee, is shown in section, with the take-up strip. The table is rack driven, as is usual with plain millers, the vertical rack being indicated at a, compare with Fig. 15, and the pinion at b, on the short vertical shaft c. This is actuated by hand from the front of the machine by the shaft D, through the bevels seen, and by

power from the pinion E, driven from worm gearing, the worm wheel F being on the opposite end of the shaft c that carries E.

The feed is automatically tripped by the lever G, Fig. 16, without dropping the worm H, which is a frequent device, and the objection to which is that it leaves the table unlocked. If the worm is allowed to remain in gear the table remains fixed in its place whenever stopped. But it is necessary to disengage the worm when the table movement has to be effected rapidly by hand, and this is done by moving an eccentric J, Fig. 16, that throws down the hinged bearing in which the spindle d, of the




Fig. 16.—Vertical Section through Worm Gear, &c., driven by Telescopic Feed Shaft, No. 5 Miller.

worm H, is carried. A crank handle in front of the knee, at к, operates the quick feed through the bevel wheels on shafts D and c. There is also a fine hand feed to the table, with graduations reading to $\frac{1}{1000}$ th of an inch, operating the worm gear through an intermediate pinion L, Fig. 15.

When the automatic feed is tripped, it is done through the lever G moving an eccentric sleeve M bodily

along, and so disengaging the clutch N, Fig. 16. This clutch is constantly running, being in the train of connections between the sprocket chain drive from the spindle to the box of feed gears, and thence through the universal joint to the table feeds just described:

The eccentric sleeve M, which is connected with or disconnected from the clutch, is employed to reverse the table feed, engaging either directly from pinion o to pinion P, or through the intermediate L, for reversal, being operated by a lever.

The cross and vertical feeds can be operated by power, or be disconnected. The worm H furnishes the drive in both cases.

For the cross-feed screw Q, the drive takes place from pinion P, through f, g, h, and j,—j being driven from the splined clutch on Q.

The tripping arrangements of the table are shown in the detailed drawings, Figs. 18 and 19. The method of elevation of

the knee by hand, or power, is clearly shown in Fig. 14, R being the horizontal spindle driving the vertical feed screw s through bevels, the mass of the knee, &c. being carried on a ball race.

A good deal of discussion has taken place on the question of the best method of imparting




Fig. 17.—Horizontal Section through Worm, &c., driven by Telescopic Feed Shaft, B. & S. Miller.

milling machine feeds. The old plan was, and it is still the one chiefly adopted, to drive the feeds directly from cones on the end of the main spindle (see Fig. 6, page 20). The result is that only a medium range of workable feeds is available when using the




Fig. 18.--Trip Movement, B. & S. No. 5 Machine.

medium - spindle speeds, while at the extremes of small cutters it is impossible to get feeds at all suited to the speeds at which those cutters should be run economically. Using a large cutter, requiring a slow-spindle speed, the feed will be much too slow. Using a small cutter requiring a high-spindle speed, the feed will be much too fast. The case has been

put by Mr P. V. Vernon thus:-

"Assume spindle speeds varying from, say, 10 up to 300 turns per minute, giving a 30 to 1 ratio of highest to lowest speeds.

"Assume, as a suitable range of feeds for slowest spindle speed, 1 inch up to 8 inches per minute, giving a 16 to 1 ratio of highest

to lowest feeds. (The above ranges both of speeds and feeds are well within the usual limits.)

"At the highest spindle speed (300) the above feeds would become 15 up to 240 inches per minute, as they would increase with the speed of the spindle, and would of course be quite useless on the higher speeds.

"Conversely, if the range $\frac{1}{2}$ inch up to 8 inches per minute could be obtained on the highest spindle speeds, these feeds would be only $\frac{1}{30}$ of that amount on the slowest spindle speeds, and would also be of very little use, the highest feed for the slowest spindle speed being only about $\frac{1}{4}$ inch per minute.




Fig. 19.—Trip Movement, B. & S. No. 5 Machine.

"In order to obtain the proper range ($\frac{1}{2}$ up to 8 inches) at all spindle speeds it would be necessary to have a total range of feed variation provided by means of the change mechanism giving a total ratio of (30 × 16) to 1 = 480 to 1, which is obviously impracticable."

The case is thus very strongly put for the driving of feeds from the countershaft,

or if from the spindle, in such a way that they shall not respond to the variations in spindle speeds, but be driven from a speed independently capable of variation to suit the sizes of the whole range of cutters being used.

Numerous designs have been fitted which provide independent feeds by means of gears—hence termed positive feeds. An objection to these is that they will not slip in case of slip of the main belt occurring, and the feed going on, is likely to cause fracture of something. A slipping clutch, or breaking piece, is therefore sometimes fitted in the feed-gear trains.

But the question of belt versus geared feeds is still in a state

33

of transition. Many prefer the belt because it would slip rather than cause a jam. There need not be much virtue in gears over belts in point of power, though the belief is usually tacitly accepted. That is strictly true only when comparison is made with the narrow belted feeds hitherto used. A belt feed can be made powerful, and a sufficient number of variable feeds obtained therefrom, provided it is not driven from the spindle speeds, but from the countershaft. Though it is not possible to get a powerful

feed from a slowly rotating main spindle, it can be obtained from

the countershaft.

Whichever method is adopted, the separate feed gear not only provides an independent range of feeds, but it simplifies calculations in two ways. It is easier to understand feeds irrespectively of varying spindle speeds, than in connection with them. Also it takes account of the diameter of the cutter, or number of teeth, instead of feeds per revolution, which does not consider cutter diameter, or number of teeth.

It may also be pointed out that economy in power is studied by separating the feed drive from the spindle drive. When the latter drives the former, power is taken directly from the spindle, which would be better utilised for heavier cutting, unless there is excess of belt power.

One advantage of the geared feeds in the heavier machines is that they are better able to feed heavy knees, carrying heavy work vertically, than the ordinary belt feeds are.

The objection to an independent feed for milling machines, that is, one obtained by arrangements entirely disconnected from the main machine spindle, is that the spindle belt may slip under heavy duty while the feed continues in operation, with disastrous results. But the independent feed is nevertheless desirable, and it has been embodied in many machines of late years. Feed is given in inches per minute, or parts of inches per revolution, and this cannot be estimated directly, but only by reference to the spindle speed.

The desirability of having a table feed independent of the spindle speed induced Messrs Brown & Sharpe to design a machine with constant and uniform belt speed, and variable spindle speed, and variable table feed, derived from the constant-motion spindle. It has been in operation for some years, and given satisfaction.

The single-driving speed renders the machine adaptable to an

ordinary belt drive, or motor drive with sprocket chain. The spindle speeds range from 15 to 376 revolutions per minute, arranged in geometrical progression. They provide, with a surface speed of cutter of 20 feet per minute, for a range of cutters from $\frac{1}{16}$ inch to 5 inches in diameter; with a surface speed of 30 feet per minute, for cutters from $\frac{1}{16}$ inch to $7\frac{1}{2}$ inches; and with a surface speed of 40 feet, for cutters from $\frac{3}{6}$ inch to 10 inches. The speed mechanism is as follows:—




Fig. 20. Vertical Section through Main Spindle, No. 2 Universal Machine, (Brown & Sharpe Manufacturing Co.)

The main driving pulley is seen at A, Fig. 20. This drives the long pinion B, which, through an idler C, Fig. 21, may actuate either a,b,c, or d. The lever B slides the idler C along to engage with either wheel in the series, and the lever E then lifts it into gear. The drive as shown is taking place from a to c, but a lever provides means for sliding c out of gear, and bringing the larger wheel c into engagement with the smallest wheel d. A fast or slow motion is thus obtained for any one of the combinations obtained between B and the cone of gears a,b,c,d.

Besides this, there is a back-gear set, derived from r and f, which wheels slide upon a quill G. This is shown in the next Fig. 22, where H is the back-gear spindle. This has a cam g, which actuates a forked lever, and this in turn a collar J, connected to locking pins i. The handle K engages the back gear, the first action of which is to withdraw the pins i, and the final action is to throw the collar J to the left. This causes compression of the springs behind the pins, which, on the first turn of the

machine, throws the pins into place with a sharp snap.

The guard which encloses the back gear is cut away as shown, Fig. 22, to permit the quill, encircling the eccentric spindle II, to be turned by the hand, in order to bring the gears into a position to engage, and the outside of the quill is knurled with that object.

A small gear is shown at k, which can be made to engage with the main back gear M by pulling out the knob l, but at other times it is kept clear of the wheel by the encircling spring shown. The reason for this is to permit the




Fig. 21.—End View of Headstock, B. & S. Machine,

spindle to be turned by hand when the drive is by motor, as in that case the sprocket chain with its wheels is enclosed by a shield.

The table feed is rendered independent of the spindle drive as follows (Fig. 23):—

The sprocket A, driven by a pitch chain, drives the long pinion B. An idle wheel, not indicated, but which is similar to c in Fig. 21, and carried by the frame D, engages with either a, b, c, d, c, or f by the lever E, after its position has been located by a

lever similar to D, in Fig. 21. In the figure, b engages with g on the telescopic feed shaft F; but by reversing the lever G, g is slid out, and h put into engagement with f, so giving choice of fast or slow feeds for either one of the combinations of the cone of gears, as in the speed drive just noted in Fig. 20.

Gear plates are provided for speeds and feeds, and are placed directly above the speed and feed-changing levers. The speeds given for each position of the stop pin of a lever are marked immediately above the stop-pin hole for that position.




Fig. 22.—Horizontal Section through Back Gears, B. & S. Machine.

Some other feed arrangements applied to the Brown & Sharpe machines are shown in Fig. 24. The feeds are derived from the spindle, driving down to the sprocket wheel A, in the first place. The shaft B is thus rotated. B carries two wheels, C and D. C runs on B, and has a long boss which forms a journal for wheel D. These wheels are engaged by the clutches a and b, operated by a vlever outside the gear box, the range of movement being controlled by a knob. C operates a slow series of feeds, D a series of fast ones. These first movements are transmitted through the wheels on the intermediate shaft E to the wheels on the feed shaft F,

whence the table is operated through a telescopic shaft. The details are as follows:—

The two nests of gears G, H are keyed upon their shaft E. The gears J, K are loose on their shaft E. The latter wheels have long sleeve bosses, and either one in the nest is engaged with its fellow on the shaft E by means of a series of six locking pins, two of which are shown at e and d, and which enter recesses in the




Fig. 23.—Section through Feed Gears, B. & S. Machine.

bosses of the gears. Their positions are controlled by an index disc e, that turns on the disc f, and carries a cam for actuating levers which are fastened to the ends of small pinions that engage with rack teeth (not shown), cut in the locking pins. The pinion levers drop into a recess in the index disc, and as there is but one recess, only one feed can be engaged at a time.

The feeds of the recently designed motor-driven pillar and

knee machines of the Cincinnati Milling Machine Co. are shown in section in Fig. 25. The machine is driven by a variable-speed motor, having field control. The entire range of speeds is obtained by the motor, supplemented by two sets of back gears. The total range gives a surface speed of 20 feet per minute to cutters of from $\frac{5}{16}$ inch to 6 inches diameter, or of 40 feet per minute to cutters of from $\frac{5}{8}$ inch to 12 inches diameter. Power is taken from the motor to a friction clutch in the first place, and thence to a sleeve on the main spindle. The friction clutch is introduced into the




Fig. 24. Another B. & S. Geared Feed.

drive in order to permit of instant starting and stapping of the machine without waiting for the motor either to stop, or to attain full speed, which must be done when the drive is effected directly from the motor. The spindle can also be turned by hand on disconnection of the clutch. The field rheestat is not disturbed when starting or stopping the machine, whether done by the trictler clutch or the main switch. It is set once for all to the required speed, and is not altered unless a change of speed is wanted.

In Fig. 25 the motor drives through a sprocket chala the

wheel A, which drives the sprocket B through the clutch C, operated by the lever D, coming within reach of the attendant. The second chain comes from B to the wheel E, which is mounted on a sleeve F. This wheel and sleeve either drive the spindle G directly through the usual pin a, or through the back gears H and J, or K and L. These are thrown




Fig. 25.—Section through Feed and Spindle Gears of Cincinnati Machine.

into or out of engagement by the usual eccentric spindle and lever, the boss of which is seen at b. The endlong movement is effected by sliding the sleeve of J and L along the main sleeve c. A flange or shroud d on the wheel J prevents risk of endlong movement taking place when either pairs of gears are engaged. The gears M transmit the feed motion. The small pulley N is for driving the oil pump.

The transmission of the feeds of the recent Cincinnati machines is obtained through the gears M directly from the rear end of the spindle. One box of gears is placed there, the other at the rear of the column, and the two are connected by a vertically inclined shaft. The first box is shown in section in Fig. 26. It provides by the sliding sleeve A, with its two pinions engaging with the pinions a and b, on the spindle end, two speeds for each cone speed. The sleeve is operated by a lever c, outside the encased box. Thence the mitre wheels B transmit motion to the feed gears in the box below on the column. In the latter are nests of




Fig. 26. Sliding Goars at Rear of Spindle of Cincinnati Machine.

gams driven in the first place by two wheels, the common spindle of which is actuated by mitre gears from the telescopic shaft. Each of these two wheels is in permanent engagement with a wheel on one of two nests of spur gears below, arranged in cones in the manner now so common in feed gears. These cones of gears we mounted loosely on their shaft, and are independent of each other. The larger of the two upper wheels is in engagement with a smallest wheel or one set of cones, and the smaller wheel with the largest on the other set of cones, so that the two sets of cones included wheely different rates. Variable rates are transmitted

thence to the machine slides by an intermediate sliding gear on a separate spindle, which can be slid along and engaged with any wheel on either series of cone gears. There are two levers used in this box, one of which is set opposite to figures on a quadrant, that indicate the rate of feed in thousandths of an inch per revolution of the spindle. The upper lever next brings the intermediate wheel into engagement.

Fig. 27 illustrates a feed gear fitted to the Garvin machines for





Fig. 27.—Feed Gears of Garvin Machines.

feeding the knee and its slides, with provision for a series of eighteen changes by the movement of handles.

The gears are enclosed in a box within the column or pillar of the machine. A portion of the gears projects at the back, being covered with a removable cap, and the operating levers are at the side adjacent within reach of the left hand of the attendant.

The power for feeding is transmitted from the main spindle to the sprocket wheel A, on the outside of the box. This engages by a sliding clutch with the spur wheel B to the left, which is in engagement with the wheel C above, on a short shaft, on which frame N, and drives the pinion O; P and Q are clutches, keyed, and pinned to the shaft H. A sleeve R has a helical groove which is operated by a lever S, to the right, to engage either P or Q. The






Fig. 29. Feed Box Details. (A. Herbert Limited.) Section in Plane b.b.

end of the telescopic shaft is seen to the left. A plate attached to the gear box indicates the position of the levers for any feed.

Figs. 29/32 illustrate a geared dial feed fitted by Messrs Alfred Herbert Ltd. to recent machines, Fig. 33. The views

comprise plans and sections of the gear box attached to the main framing. The feature to be noted is that the simple turning of an index wheel A gives at once the rate of feed to which the pointer is set.

The nests of gears, entirely enclosed, are carried on three vertical spindles which revolve and carry the various gears. Tracing the feed movements from the shaft B, in the first place, belt driven, compare with Fig. 33; this drives mitres c, the second of the pair having a spur D on its spindle, which engages with a wheel on the shaft E. There are four such wheels on a sleeve running loose on shaft E, and each is engaged with the gears F on shaft G Either one of the latter gears is made to drive the shaft G, by means of the sliding spring key H, retained and pivoted in the




Fig. 30 -Food Box D tans. Section on Driving Shaft.

collar 3, and actuated by the lever K. The method of moving this lever is the most interesting feature of the device, being effected by the movement of the index wheel A, which revolves a cam block L, having grooves cut around its body, which grooves correspins in the lever K, as seen in Figs. 29 and 32, and so rock the levers upwards or downwards according to the direction of rotation of the index wheel. The shaft G is thus rotated at either one of four different speeds, and imparts motion to four gears M, keyed on it through the medium of a sleeve forming part of the smallest gear. Then these four gears drive others N, on a shaft O, fitted up with a sliding key P, and collar Q, actuated also by a cam groove in the block L. Sixteen different speeds are thus obtained through the

movement of the hand wheel A. Finally, the gears R, s, T convey the movement to the splined vertical feed shaft U, Fig. 29, which drives the horizontal feed shaft to the table through spiral gears.

Fig. 31. Feed Box Details. Front Elevation.

The machine to which the feed box just described is fitted is shown by the photo in Fig. 33. It combines several features of well-recognised value with some novel ones.

The principal novelty lies in the dial feed box just described, by means of which any required feed can be obtained by the simple movement of the hand wheel seen over the box in Fig. 33, the feeds being marked consecutively round the edge of a disc on this hand wheel, the dial being rotated until the number corresponding to the feed required comes opposite the pointer. other movement whatever is required.


Another feature is that the feed can be driven either from the countershaft, or from the spindle as desired. the combination giving the most complete feeding arrangements. In another machine by this firm, the vertical spindle

one, illustrated on page 108, the feed is driven from the counter-shaft only. Another detail which is also illustrated in that machine, as well as in Fig. 33, is that the usual telescopic feed

shaft is abandoned in favour of gear drives through shafts at right angles.

Other valuable points in this machine are the following:-The knee is of boxed form, being completely closed underneath. Its bearing on the column extends above the plane surface of the knee, so conducing to steadiness of movement. Telescopic cover plates are fitted to prevent dust and cuttings from falling on the mechanism within the knee. The table is thick and massive, and is oiled from the side, so that fixtures and vices need not be disturbed for the purpose of lubrication. This is a point of much importance when a machine is kept a long time in service with the same fixture upon it, doing repetitive work. The screw by which the table is operated does not rotate, is always in tension, and is not splined. A covered channel in the table extends from end to end to enable the water used in lubricating the cutters to pass away freely.

The good practice of fitting hand wheels to move the slides in preference to using levers is embodied. The rim of a hand wheel is readily felt, while a crank handle has to be searched for round the



SECTION a-a




Fig. 32.—Feed Box Details.
Side Elevation.

circle. Also when the knee is lowered, the attendant has not to stoop to a hand wheel, while he would often have to do so for a




Fig. 33.-Milling Machine with Dial Feed,

handle. Another feature is that the feed shafts are separated sufficiently far to permit of having an independent hand wheel for each motion, so avoiding the trouble of changing wheels when making adjustments. These are apparently minor matters, but they tell up in the economies of the work of the machine. The elevating screw is of the telescopic type, so doing away with the necessity of cutting a hole in the floor. All motions of the slides have clamping handles. The feed has automatic trips, and dead stops. All motions have adjustable graduated index discs. The head fittings embody the best practice. The head, with its sleeve, is cast solid with the pillar. The sleeve is tubular, embracing the overhanging arm, and pinching it with clamping handles. The arm is of solid steel bar. The spindle, of crucible steel, is bored right through. Its nose is threaded, and protected with a cap




Fig. 34.—Feed Gear Box. Plan View.

when not in use. Provision is made for adjusting diameter and end thrust independently. The broad base of the machine will be noticed. The interior is fitted up as a cupboard. All gears are encased. A pump is fitted.

A design of variable feed gear by Messrs A. Herbert Ltd., to be driven either from spindle or countershaft, is shown in Figs. 34-36. If from the first, there are sixteen changes, if from the second, thirty-two, independently of the speed of the spindle. The dial feed just described has been designed to supersede this.

The upper feed cone, which drives to the cones A, on the feed box is geared to the spindle, and runs at twice the spindle speed, doubling the power by comparison with a cone mounted directly on the end of the spindle. As the cones have four steps, and are interchangeable, this accounts for eight changes. By interchangeable is meant that the driving and driven cones can be made to change places, so reversing the speed relations, a smaller driving to a larger, and *vice versa*; a method which is commonly adopted in all or nearly all machines in which cones for feeds are retained. Looking at Fig. 36 it is seen that the cone fits on the sleeve which it drives by a short key over which it is slid, and it is secured end-




Fig. 35.—Feed Gear Box. End View.

wise by the knurled nut B, so that the changing of the cones is only a work of two or three minutes. All the various speeds obtainable on each step, for the two changes of the cones, are given in the plates usually attached to machines.

These changes are doubled in the feed box shown by the movement of the lever c, the effect of which is shown clearly in Fig. 36. Two gears in the lower part of the box, fast on the cone sleeve, engage with two gears in the upper part of the box loose on their sleeve. Either one is caused to be driven from its lower gear by the sliding of

the lever c, moving a pin and its key along into the boss of either gear. The spring pin a, in Fig. 35, automatically locks the lever in a position to drive one wheel or the other, or in a middle position of no drive. The great advantage of this device is that a change from a roughing to a finishing cut, and vice versa, can be made without shifting the belt, or stopping the machine.

The feeds transmitted from telescopic or horizontal shafts are made to actuate the two movements of the table and that of the knee in the most complete machines. In addition to these, hand

movements are also fitted. Many modifications are effected in the details of these by different firms, the practice of which also changes from time to time. Reference may be made to Figs. 14-19, pages 28-32, for a present-day design.

The Knee.—The knee and its method of fitting on the latest types of pillar machines possesses several characteristic features which are worth noting. In the first place it often has a solid




Fig. 36.—Feed Gear Box. Front Elevation. (Dotted Pulley for larger Machine.)

top, which is better calculated to resist stresses of certain kinds than one which is open on the top. The latter type is likened to a box without a bottom, which is not so well able to resist stresses as one with a solid bottom. The weakness of an open knee is generally recognised, and is to some extent lessened in many cases by the practice of casting internal ribs and fillets, so narrowing the area of the opening. Another objection to the open top is the tumbling down of chips on the screws and gears that lie within the knee. This however can be avoided by the

use of telescopic slides. But the solid top at once stiffens, and affords protection. Its advantages from the point of view of stiffness are not so very pronounced when work lies within its area. But they are most evident when heavy cutting is being done with the table run out a good way over one side, with the result of producing a considerable amount of leverage, the fulcrum of which is on one edge of the knee, while the effect is to lift or attempt to lift the slide on the other edge. To prevent a wedging action against the vee'd edges under such conditions is the object of imparting square edges to the slides, but these are not considered necessary with solid knees.




Fig. 37.- Garvin Knee, with Solid Top.

The Garvin knee shown in Fig. 37 has a solid top, and also has its sliding face extended above the top slide, a feature which is conducive to stability. In these machines the screw for the cross traverse movement is placed alongside the knee, outside to the right, lying in a recess. The nut is bolted to the slide, being also fitted thereto with a tongue. The method of taking up slackness due to wear consists in splitting the screwed boss into two portions, one of which is rigid, the other slightly elastic. The latter can be tightened against the traverse screw by an adjusting screw, effected similarly to the taking-up of the wear endwise on a worm made in two parts, by which means it is not necessary to take the precaution of allowing for backlash when making exact settings

of the slides. The vertical feed screw (which is of telescopic type) is operated by a worm and worm wheel, Fig. 37, and the hand wheel for this, A; and B for transverse feed stand squarely at the front. Micrometers are fitted to both (see page 56).

Fig. 38 illustrates a great improvement on the method of fitting the elevating screw to the knee, which involved cutting a hole in the floor. The screw is encircled with a vertically adjustable nut through which it passes, being turned either by hand or power.

Fig. 39 illustrates the Garvin stationary screw, which




Fig. 39.—Stationary Screw.




Fig. 38.—Elevating Screw passing through a movable Nut. (Cincinnati Co.)

not only does not come through the floor, but which is fixed in the base with a Woodruff key. The rotating nut. B is of good length on the screw A, and a boss extension of it comes up through the knee. The weight of the latter is taken on a

ball race a.




Table Feeds.—The method by which the table feed is transmitted from the telescopic shaft in the Garvin machines is shown in Fig. 40.

A is the universal joint on the end of the telescopic shaft, whence the first driving shaft B is actuated. The shaft carries a gear C, that actuates tumbler gears D or E; the pins for these are carried in a swinging casting F, the bottom of which




Fig. 41.—Cross Section through Table and Swivel Carriage. Le Blond Universal Machine.

forms an oil box. The reversal can be effected by hand when the machine is running by pulling out the knob G, and throwing the rocker casting F over to the other position. The feed is transmitted and tripped as follows:—The tumbler gears actuate the wheel H, on the shaft to which the worm J is fastened.




Fig. 42. - Longitudinal Section through Table Screw. Le Blond Machine.

J drives the worm K, mounted on the feed screw. The bearings of the worm shaft are in a solid casting, and include the oil bath for the worm. The casting is pivoted at b, and retained during feeding by the latch c. The feed is tripped by the button d, on the table, pressing down the spring plug c. The effect of this is

to thrust the trip rod L, that supports the latch pin c, outwards, so letting the worm bearings drop, and disengaging the worm from gear with κ . The feed can be disengaged by hand by pulling at the knob of L. It is thrown in by pressing down the handle κ , which is attached to the drop bearings.

Figs. 41 and 42 show the table sections of the R. K. Le Blond Universal machine, illustrating the two methods of driving; that of a rack (not shown) from the pinion A, and that of a screw B. The feed is necessarily driven through the centre of the saddle. The screw B, adequately supported in long bearings, is




Fig. 43.—Micrometer Fittings to Feed Spindles.

encircled by a mitre wheel c, driven by one on the stem of which A is keyed. C runs freely on the screw, but is made to rotate it by the clutched sleeve D, splined to the screw and slid along by the double-forked lever E. The latter is operated by the handle F, or by the dogs, one of which is seen at G. These thrust down a plunger H, a rack on which gears with the pinion J, cut in the spindle which actuates the lever E. The gib K is a tapered one.

Fig. 43 shows the micrometer fitting applied to the various feed spindles of the Garvin machines, the upper view being an external

one, the lower the same in section. On the spindle there is a steel collar A, bevelled, and graduated to indicate thousandths of an inch, and knurled to permit of turning it to start at zero. It is slackened, and again tightened when set, by the small knurled screw B at the end, which presses up a pin with a bevelled end suited to the bevelled end of the screw.

The best table stops are of precision type, set by a micrometer screw, which is bound by a clamp screw. Their value lies in the means which are afforded of feeding up to a given point, and up to shoulders.

Fig. 44 illustrates a vernier, applied to the tables of the B. & S. milling machines for the purpose of effecting fine adjustments of the table, reading to thousandths of an inch. The scale A is 24

inches long, the finer divisions being omitted in the engraving, and is attached by screws, and tee-headed nuts entering the slot which receives the trip dogs. The vernier B is attached to the front of the saddle of the machine by the bolt shown, a is the clamping screw for the vernier, and b the fine screw by which it is adjusted to zero.




Fig. 44.—Vernier applied to Table of B. & S. Machines.

The vernier, whether applied to machine or to caliper, is a means by which fine readings can be taken by inspection from comparatively coarse dimensions. It comprises two parts, the "vernier" proper and the "beam." Different units of division are adopted by different makers, but the most useful is one which is embodied in the Brown & Sharpe vernier calipers for English divisions of a thousandth of an inch.

Figs. 45-47 show one of these much enlarged for the sake of clearness. Each inch in length of the "beam" A is divided into ten equal parts, and each of these again into four, making forty parts to the inch; so that χ^1_{00} , or 0.025 inch is the value of each part. The vernier B is divided into twenty-five parts on a total length which equals twenty-four parts of the beam. These divisions are not so fine but they can be readily seen, and yet they register χ^1_{000} inch easily, thus:—

As twenty-five parts on the vernier correspond in extreme length with twenty-four parts on the beam, = twenty-four fortieths of an inch, then $\frac{1}{25}$ of $\frac{1}{40} = 1,000$ th of an inch.

When the vernier is set at zero, Fig. 45, there is then a difference in the next two lines of division, of $\tau_0^{\dagger}\sigma_0$ of an inch, and so on,— $\tau_0^{\dagger}\sigma_0$ for each successive division, until they correspond again at the 25 division on the vernier.




Fig. 45.—Vernier set to Zero.

If the zero marks are set together, as in a caliper, no fractional parts exist, but whole numbers, corresponding with the inches, as 1, 2, 3, &c. But when the zero on the vernier comes elsewhere, then, first, the number of inches, tenths, and parts of

tenths are read, by which the zero point on the vernier has moved from the zero point on the beam. Thus in Fig. 46 it has moved from zero a distance of one tenth, and also past two of the four divisions of the second tenth on the beam. That is one tenth added to twice 0.025 inch, equalling 0.10 + 0.05 = 0.15 inch.

In Fig. 47 the vernier is shown moved past the second subdivision of the second tenth. To read this the eye must be run




Fig. 46. -Vernier set to an Exact Division.

Fig. 47.—Vernier set to Fractional Division.

along to find where coincidence occurs between vernier and beam. This occurs at the twelfth division, and represents the number of thousandths to be added to the distance read off on the bar, giving 0.012 + 15 inch = 0.162.

If the readings are taken decimally, calculation is facilitated. The tenths on the beam are then 100, or one hundred thousandths, and the fortieths, or fourths of tenths on the vernier

are 0.025, or twenty-five thousandths. Thus in Fig. 46 the jaw is open one tenth, and two twenty-five thousandths = 0.150 thousandths. In Fig. 47 it is open one tenth, two twenty-five thousandths, and twelve thousandths = 0.162.

Differences between Plain Machines and Universals.— Sometimes the plain milling machines are made with rack feeds, and sometimes with screws to the table; the universals have screws. The latter are more exact, and better suited to micrometric dimensions; the former permit of more rapid adjustments by There are not so many joints for the table as in the universals, there being no swivelling arrangement; it is stiffer, therefore, which is more favourable to slogging. The universal milling machine was patented by J. R. Brown in 1865. Fig. 5, page 17. It was exhibited at the Paris Exhibition of 1867. A modern machine by the firm is shown in Fig. 48. In this type of machine the table is capable of three movements: one, that of the table transversely along with its saddle; the other, that of the table alone, longitudinally, by means of a feed screw; the third, by the knee. The saddle swivels in a horizontal plane on a bed having vee'd edges, which bed slides along the top of the knee bracket, that moves vertically on ways on the front of the standard. The table carries the dividing head, with its gear, and the loose headstock or "footstock."

The universal machine will fulfil the functions of the plain machine of the same type. The essential difference between a plain machine and a universal is, that the latter has, in addition to the fittings of the former, a spiral head, index plate, sector, and change gears, with a swivel table. The index plate furnishes circles of divisions, change gears give variable rates of spiral movements, while the table is being traversed a certain distance by the feed screw. By these additions any angle up to 45° can be given to the table, which can also be fed automatically at any angle, and a definite rotary movement can be given to the work. There is nothing therefore in the range of small gear cutting, cutter or tool making, or the tooling of small parts within the dimensions covered by the machine, which cannot be accomplished on the universal type. It owes its chief value therefore to the fact that there is no job of milling of moderate dimensions which

. ...

cannot be done upon it. Every shop should have at least one of these, but it is a mistake to suppose that it is economically adapted for all kinds of jobs, even though these may be of medium dimen-



Fig. 48.—Universal Milling Machine. (Brown & Sharpe Manufacturing Co.).

sions. Many such can frequently be tooled to better advantage in large quantities on the larger and more specialised machines of various kinds. It is not judicious to attempt heavy tooling on a

universal, for which almost any other types are better suited, It is a somewhat delicately-constructed piece of mechanism by comparison with some others. The table is not quite so rigid under stress; and as it is driven by screw instead of by rack, the truth of the screw should be retained as long as possible. It is a little top-heavy. The universal head is a piece of delicate construction, there is a deal of gear introduced for the automatic movements, all if which details are incompatible with heavy tooling. Only work should therefore be put on the universal which cannot be done at all, or at least so conveniently elsewhere, and specially that which requires the assistance of the head and the swivelling arrange. nexts of the table. A skilful man is required to attend to a mayersal machine, because the work done upon it is of an intricate character, and also because calculations have to be sizele for the cutting of teeth of spiral form; and when gears are out, edculations also for the numbers of feeth. A good attendant will turn out a large volume of excellent and carried with from a universal machine and he will prove the best me ostnest.

The table is fed internationally from the cone pulleys through a telescopic toleral worm year in the older machine, but through evel zeros and a screw in others can in the automatic movement of estapients, reversed. The automatic movement of the table is the table of each offentive at a time to the table. The table is expected by her totage to the table of the table of each of the table of table of

The handle for the vertical movement of the table by hand is often placed at an angle, instead of just below the cross-feed handle, so that they do not interfere with one another, neither has either of the handles to be removed, but remain permanently on their spindles. It is easy therefore to operate two handles at one time.

Ball bearings are commonly applied to the feed screw of the table, as well as to the vertical feed screw. Quick return can be employed to the table. Its base is of large diameter, and graduated on the outside into degrees for milling spirals, or work of similar character.

In conformity with an agreement adopted by the manufacturers of milling machines in the United States the movements on plain milling machines are as follows:—

	No. of Machine.									
	0	1	113	2	3	4	5			
Transverse movement	Inches.	Inches.	Inches.	Inches.	Inches.	Inches.	Inches.			
Vertical movement -	15	19	19	19	20	20	21			
Automatic table feeds	18	24	24	28	34	42	50			

The movements on universal milling machines are as follows:-

			No. of Machine.						
			1	11/2	2	3			
Transverse movement			Inches.	Inches.	Inches.	Inches.			
Vertical movement -		-	18	18	18	19			
Automatic table feeds	-	-	20	20	25	30			

Index Centres and Spiral Heads.—The index centres used on milling machines range from those which are quite plain to

those which are universal in character. A plain type, of which there are several varieties, consists of centres without any provision for setting to a vertical angle, and without any means of sub-division in the head except that afforded by holes drilled in a dial. A tapered pin inserted in the holes locks the spindle while teeth are being cut or edges milled equidistantly.

In a more elaborate kind, the centres, as before, have no means




Fig. 49.—Universal freezing Head.

of angular allostment is to nearly some erast range of indexing can be obtained by the employment of index plates with circles of holes and a worm and worm wheel the latter owing on the head-stock splindle.

In the most perfect type the inner head will angle from a few degrees beneath the normalization few degrees over the perpendividar, giving a total range of the or two of any expent in a certical plane. Index plates in communation with worm gears give In these machines the cutting of 68 different spirals is provided for. Three index plates are sent with the machines, having 15, 16, 17, 18, 19, 20; 21, 23, 27, 29, 31, 33; and 37, 39, 41, 43, 47, 49 holes respectively. The plate g, for rapid indexing on the nose of the spindle, has 24 holes.

Fig. 53 shows the spiral head used on the No. 1 B. & S. universal machines. It is simpler than that just illustrated.




Fig. 54. Plain Indexing Centres.

Let thus, as in the former one, the worm wheel has forty teeth, so that one turn of the index crank A, and worm shaft B, moves the spindle of through one tortieth of a revolution. By means of the index clate E, the fortieth of a revolution can be further solving ded, and the sector F is set to divide the holes without country. The crank A is admistable radially, so that the pin can be used in any civile of holes.

Bushings of steel encircle the spindle B and form a durable pivot for the box F. The spindle and box can be swivelled, and set to any angle from 5° below the horizontal to the perpendicular. One side of the head is graduated. Change gears transmit motion from the feed screw to two mitre gears, one of which is seen in the Fig.

Plain indexing centres by the Cincinnati Milling Machine Company embody some special features. The headstock has no power of angular adjustment: but instead, the centre of the




Fig. 55 - Le Blond Dividing Head. Longitudinal Section.

tallstock is made movable in a vertical direction. The principal dements of these centres are shown in Viz. 54, in sectional clevation, plan and front-end elevation.

The spindle A is carried in bearings b and c, the latter of which split to clamp the spindle, this being rendered necessary by the fact that it has a power of endlong movement imparted to it secure there is no such motion in the spindle of the tailstock. It move the spindle endwise, grooves are formed for the grip of the boal on the body of a sleeve b, which encircles the spindle A about the centre, the spindle and sleeve being mutually threaded.

The sleeve on being turned by hand, while coerced by the uprights B and C, moves the spindle A endwise. In order that the sleeve shall not move accidentally, and that it shall turn when the index plate is moved, it has frictional connection with the spindle by means of a small screw a pressed on the spindle. By means of the split bearing c the spindle is clamped after adjustment.

The spindle has a tapered socket at the front end to receive the centre E, while a thoroughfare hole permits of the insertion of a bar for shooting the centre out.

The indexing is done by the plate F at the rear of the spindle, two or more of which are supplied. The pin G is adjusted up and





Fig. 56. "Transverse Section through Le Blond Dividing Head.

down, and clamped in a slotted standard cast in the top of the rear bearing. The position is adjusted by means of a finger, which moves with the bearing of the pin over a scale on the standard, and which indicates the row of circles in which it will engage in any given position.

Figs. 55 and 56 illustrate the Le Blond dividing head, the leading features of which are the following:—The body is circular in form, and a solid easting, capable of swivelling through an arc of 200°, or 10° below the horizontal on each side. A dovetail is turned on each side, Fig. 56, by which it is clamped to the base with two bolts, the heads of which are turned to the radius of the dovetail. The drive from the table screw, through simple or compound

gear, takes place through a bracket bolted to the side of the base (not shown), and which carries the quadrant for the change gears.



At the opposite end to the quadrant, a bevel wheel engages with a bevel (not shown), running on a stud a, Fig. 56, in the centre of the

swivel head, and a spur gear connected to this bevel drives a spur b on the sleeve of the index plate. The positions of the gears are thus maintained at all angles of the swivel head. The head a is bored taper to receive the spindle a. A worm wheel a centicles the spindle, rotated by the worm a, solid with the spindle that carries the division plate a; a; a is the index pin. The spindle is clamped by the locking plug a. The worm and its shaft are carried in an eccentric sleeve provided with a slot, and stop, so that it can be thrown into and out of gear rapidly. The worm gear can thus be quickly disconnected when quick indexing is required by a




Fig. 58.—Longitudinal Section of Dividing Head.

dividing plate alone, as in fluting taps, reamers, and cutting some small gears, sprockets, &c.

Figs. 57-59 illustrate a spiral headstock by the Cincinnati Milling Machine Co. Fig. 57 shows the head in elevation. Fig. 58 is a longitudinal section through the head, and Fig. 59 a transverse one.

Heads are mostly confined to angular movements, ranging from 10° below the horizontal, to 10° beyond the vertical. In this example the spindle A is carried in a swivelling block B, which is capable of a complete revolution in a vertical axis, and the edge of which is graduated into degrees. An advantage of this complete

swivel is that it permits of the cutting of right and left hand work without changing the cutter, and the cutting of the same piece on each side of the vertical. Another is that the swivelling block is always in any position contained wholly within its bearings, and therefore adequately supported.

No strain is thrown on the spindle in clamping, which is done on two clamping rings c, c, Fig. 59, embracing trunnions on the block. The rings are pinched by the cap screws D, Fig. 57. As the circumference of these is so large, no strain or distortion can affect the spindle, or the worm gear.




Fig. 59.—Transverse Section of Dividing Head.

The spindle A is provided with a clamping ring at E, which secures it endwise. Wear is taken up between the coned neck at the front of the bearing, and the coned bushing at the back.

The dividing mechanism includes the worm and wheel, index plate, and sector, and another index plate F, added for low numbers, or those under forty, the ordinary sector plate being reserved for those over forty.

Plate F, used for direct indexing, is provided with three circles of holes on the back, namely, 24, 30, and 36, into which the index pm a is inserted. The holes for divisions 4 and 6, which are

so often wanted for fluting and nut milling, are indicated by corresponding figures on the edge to save the trouble of counting round.

The regular index plate is seen at H with its index pin. It is drilled from both sides to increase the divisions by simple reversal of the plate. Divisions are obtained by this in conjunction with the worm K and its wheel L. The worm—right handed—is single threaded, with $2\frac{1}{2}$ threads per inch. The wheel has forty teeth, so that forty turns of the index handle M turn it through one revolution. The handle M turns the worm and wheel through equal gears, P, Q, for dividing, or indexing only. For spiral work, R is the gear through which changes in pitch are effected through trains of wheels.

The worm K can be thrown out of gear by dropping it, with




Fig 60. -- Footstock.

its bearings, bodily, by the eccentric pin N, the case being hinged about the pin α as a centre. As the easing 0 is confined in the lateral direction, the eccentric end of the pin is inserted in a bushing, which has an endlong movement in the worm case. The latter is fastened to the block containing the bushing with screws, which afford means for adjusting the worm to the wheel. The worm runs in a bath of oil, and this can be cleaned out

on removal of the cap $\it c$.

The change goars are seen in Fig. 57, s being the lead screw, with ball thrusts, T the swing plate, and U one of the two studs for compound goars. Motion is transmitted through the bevel wheels V actuating the spur wheels in Fig. 57.

At w a ratchet and pin are shown which permit of making fine adjustments of the index plate for the purpose of re-setting work.

Footstocks.—The footstock of the Cincinnati Company is shown in Fig. 57. The housing A carries the longitudinal slide E, fitting with a dovetail. It is traversed by the knob C, and clamped by the bolt D. The centre E is double ended, one end being the ordinary centre for heavy work, the other being reduced on the

top face to permit cutters to clear it when depthing flutes. The centre is therefore reversible. It is adjusted vertically with a rack and pinion, actuated by a knob F, and is clamped by the bolt G. The centre can be tilted forwards, or swivelled about the centre D, exact angles being given by graduations at the rear of the housing.

The Brown & Sharpe footstock is shown in Fig. 60. Its




Fig. 61. - Footstock.

centre is adjustable for milling tapered work. Being adjustable, it is set in a horizontal position by taper pins. It is elevated and depressed by means of a small rack and pinion through a nut. The nuts a,b,c clamp the centre in position.

Fig. 61 illustrates another tailstock in two horizontal sections, in vertical longitudinal section, and in plan. The bar centre A, it will be seen, moves vertically in the body in a dovetailed

groove. It has rack teeth on the back, which are actuated by a long pinion a, turned by a milled head B. The bar A has two centres: one for stiff work of large diameter, the other for that of small diameter, the face being cut away close down to the centre. The pinion spindle is prevented from endlong movement by a set screw b entering into a turned groove. The centre A is clamped by means of a bolt, the head of which is chamfered to bed against the bevelled edge of the sliding centre.

CHAPTER III.

ATTACHMENTS AND BRACINGS.

Vertical and Angular Spindle Attachments to Horizontal Machines—Examples—Heads that Swivel Bodily—Examples—Slotting Attachments—Examples—The Overhanging Arm—Bracings—Examples—The Work of the Pillar and Knee Machine.

Vertical and Angular Attachments to Horizontal Machines.

—Several firms make an attachment for their universal milling machines by means of which the direction of cutting can be changed either to the vertical or to any angle. It comprises a tool-holder which is clamped to the overhanging arm vertically or at an angle. Its main spindle is driven by the horizontal spindle of the machine, and drives through spiral gear or through bevel gears the cutter spindle. It renders the machine available for revolving cutters for key seating, for tee slots, for sawing off work to definite lengths, &c. The spindle can be set at any angle in a vertical plane through a graduated index.

The convenience of being able to do vertical, horizontal, or angular milling on one machine is largely a concession to the small shops. None of the early machines had this convenience. They were either horizontal or vertical. Now there are many machines of horizontal design that are rendered capable of vertical milling, and many vertical spindle machines with provision for horizontal milling. Angular work is usually included. These are often effected by separate attachments, rather than by the swivelling of the main spindle bearings; but there are many instances of the latter, especially in Continental practice, where it is very common, examples of which are given on pages 78-82.

Fig. 62 illustrates a vertical spindle head by the Cincinnati Company attached to a horizontal machine. It is fixed to the piece A bolted to the headstock, by a large circular flange B, 85 inches in diameter, and four 5-inch bolts in an annular tee groove c, by which a

movement of 360° is available. A subsidiary advantage of this swivel is that the head can be swung to an angle for the purpose of changing cutters conveniently, which is done more easily thus




Fig. 62.—Vertical Spindle Attachment.

than with a rigidly fixed vertical spindle. Further support is afforded to the swivelling body ${\bf p}$ by a bracket ${\bf E}$, clamped to the overhanging arm ${\bf F}$.

The spindle G is tapered at the lower end for take-up of wear

by the lock-nut a, and runs in a bearing of babbitt. The upper bearing is of bronze, tapered externally for taking up its wear, the taper being drawn along in the bore of the head by the nut b. The lower end of the spindle is clutched to match clutches on the




Fig. 63.—Attachment for Spiral Milling.

shanks of the cutters, which affords a positive, or non-slipping drive. The taper is the same as that of the horizontal spindle, so that arbors are interchangeable on both. The ends of the shanks are tapped to fit the 5-inch bolt shown at II, by which

they are secured. The shoulder seen next the tail of the bolt serves for backing a shank out of its hole, as well as for drawing it in. The nose of the spindle is threaded externally, like the end of the horizontal spindle of the machine, so that chucks or disc cutters are interchangeable on both.

The illustration, Fig. 63, is that of an attachment made to the Cincinnati milling machines, to permit of doing spiral milling when the angles exceed 45°. It will mill these when either right or left handed, and also plain spur gears and racks.

The casing A of the attachment is bolted to the front of




Fig. 64. Swivelling Spindle Bearing.

the headstock, and further steadied by the overhanging The cutter arbor a is slewed to any horizontal angle, and set by the bolt bby the graduated horizontal edge of the head A. drive takes place from the spindle through arbor B, which fits the spindle. It is feather-keyed into the driving bevel wheel, which rotates the vertical spindle c through another bevel wheel. From c the cutter spindle a is driven through spiral gears, having a ratio of 2 to 1. The advantage of this is, that as the speed of the cutter arbor is

only half that of the main spindle, the belt is run at twice its usual speed, and power is gained for heavy milling. Gears of 3 diametrical pitch are thus milled at a single cut. The thrusts of the vertical and cutter spindles are taken with ball bearings. A gauge is provided for setting the cutter centrally with the blank. It can be adjusted laterally to bring the vec central with the tooth of the cutter, and then reversed to bring the centre of the tailstock central with the vec.

Swivelling Heads.—A large group of machines have heads

that swivel bodily, in preference to making loose swivelling attachments to ordinary machines. Arrangements are very diverse. A selection, therefore, is given here.

The firm of Prétot, of Paris, make machines in which the spindle bearing is pivoted near the cutter end, being moved over a quadrant B at the other, Fig. 64, in which it can be clamped at any angle from vertical to horizontal. Adjustment is made by hand in the smaller machines, but in the large ones by a hand wheel, which actuates mitre wheels that turn a screw in a nut, which is connected




Fig. 65. - Swivelling Head.

to the bearing through the slot of the quadrant. The screw is pivoted to give freedom of movement at varying angles. The driving and the guide pulleys are carried in a cast-iron frame of **U** shape, which is attached to the upper end of the spindle bearing. The spar gears, seen within the belt pulley, are used in conjunction with two others, hidden by the pulley, as back gears, giving a slow drive, more powerful than the belt alone will carry.

Vautier & Co. obtain vertical and horizontal movements by using two separate spindles, Fig 65. The vertical one has to be

swivelled to one side to permit of the horizontal one being used. To permit of this, the vertical head a swivels on top of the pillar B to any horizontal angle, a provision which permits of doing angular milling without swivelling the table. The horizontal cutter arbor is carried between the horizontal spindle and an overhanging bracket C having a centre, which arrangement is indicated by dotted lines. The spindles are both belt-driven, the vertical one direct over guide pulleys, the horizontal one from the cone pulley through a pair of equal spur gears.

Fig. 66 illustrates the arrangement in the (French) Bariquand & Marre machines. The head A can be set to any vertical angle




Fig. 66.—Swivelling Head.

on the face B of the pillar. The vertical spindle is driven from the horizontal one, through spur and mitre gears. When the horizontal is in use, the head is turned round 180° on the vertical face B, to bring the overhanging centre c for the outer arbor support into line with the horizontal spindle.

A head by Sculfort & Fockedey has the spindles arranged as in Fig. 67. The horizontal spindle is driven directly by the stepped cones, or through back gear. That of the vertical is derived from the horizontal, through the long pinion A, sliding on its shaft, and pushed into engagement with the gear c by the knob B. A is always in gear with a pinion enclosed in the hood D, on a




Fig. 67.—Swivelling Spindle Head.




Fig. 68.—Swivel Head Machine.

horizontal shaft, which drives the vertical spindle through mitre wheels. The bracket ϵ can be set to any vertical angle on the face of the graduated arm.

Figs. 68 and 69 illustrate a machine by E. Dubosc, of Turin.

The head A is adjustable for vertical angle on the face B of the pillar, to bring either one of the two spindles into operation.




Fig. 69.—Head of Dubose Machine swivelled for Horizontal Work.

The horizontal spindle is driven directly through the stepped cones c, with or without back gears. The vertical spindle is driven from the spur wheel next the large cone step through a spur wheel D. The swivelling head has a socket to receive a steady bar E, which

carries a centre to support the overhanging end of the horizontal arbor.




Fig. 70.—Slotting Attachment for Pillar Machines.

Slotting Attachments.—Fig. 70 illustrates a slotting attachment fitted to the Brown & Sharpe pillar machines. The overhanging arm A receives the main casting B, clamped thereon by the boss and split lug above. B is provided with a curved

slot below, which permits it to be radiated about the arm A, within the limits of 10° on each side of the perpendicular, so that tapered edges can be tooled as well as those which stand square, which provision renders it suitable for the cutting of smiths' stamping dies. To increase its rigidity, the main casting is bolted through the curved slot to a piece c, which is attached to the slide on the front of the column of the machine.

The ram is driven in the first place from a tapered shank,




Fig. 71.—Slotting Attachment.

shown broken at D, that fits into the spindle nose, and which has a disc E, at its outer end, slotted on the face to receive a crank pin, adjustable for radius, to give different lengths of stroke to the ram F, connection being made through the rod G. The ram slides between guides, one of which has a take-up strip.

The tool, of circular section, fits the hole a, a key in the tool shank fitting the groove seen in a, to fix it in its correct position. After being set, the lug b, slewing on the pin c, is brought round and over the tool to receive the thrust of the latter; b is locked

by the spring plunger entering by its pointed end a countersink in the pin c.

A slotting attachment by R. M. Clough, of Tolland, Conn., is shown in Fig. 71. A is the main milling and drilling spindle of the machine, which carries a four-threaded worm B, driving the wheel c, which reciprocates the connecting rod D, and thence the ram E. The object in having a four-threaded worm is to reduce the speed of the ram for slotting. As the wheel has forty-four teeth, it is rotated but once to eleven revolutions of the spindle. The tool holder r is pivoted on a pin at a, which lessens the dragging of the tool on the return stroke, a spring above pulling it up to its bearing in the ram ready for the next cut.

In the machine the milling spindle A is carried by a sliding head moving on the face of the machine, similarly to many drilling-machine spindles. It is racked vertically by the handle G, operating an enclosed pinion and rack on the sliding sleeve. The bearing is split to take up the wear of the sliding sleeve. The handle H throws the worm wheel out of action when slotting is not being done.

The Overhanging Arm.—The type of overhanging arm in the pillar machines considered in this chapter, which is very generally adopted, follows in this respect the early Brown & Sharpe model. It is fitted into and pinched in a socket above the cones. The advantage is that it can be reversed end for end, turned aside, or taken right away. These are conveniences, but some rigidity is sacrificed thereby, and some trouble in readjustment for centres. It is, when properly fitted and pinched, a very satisfactory fitting, but only when so made. It is so seldom that it is necessary to remove the arm itself that a good many firms think it better to make it a rigid portion of the machine framing. In these types the overhanging arm, cast with the headstock, is a rectangular bar, grooved to receive an adjustable stay, with movable centre. The adjustment of the stay is strictly lineal, and it is therefore not liable to get out of line with the main spindle. It is clamped to the arm in any position required. In another type the headstock cap is prolonged to form a straight overhanging, turned arm, and a socket, sliding along this, carries the adjustable centre for the arbor. In this the socket can be

turned out of the way, but the arm remains fixed. This method is adopted in the No. 4 B. & S. machine, the heaviest of their universals, and on some of the heavier plain machines. Still the arched arm is in greatest favour, because it is less in the way when swung aside than a rigid arm cast with the head, and it can be removed entirely. When a cross bracket is bolted up in addition, connecting the arm to the knee, the arbor is absolutely rigid under the heaviest cutting.

In the universal machines, not being designed for the production of the heaviest kind of work, but more specially for light milling, gear cutting, fluting, and grooving, the overhanging arm is often left unsupported. For the heavier classes of work, however, for which the plain milling machines are better adapted, sup-




Fig. 72.—Arbor supported in Bushing in Arm.


port is commonly afforded to the outer end of the overhanging arm by means of two crossing slotted ribs, pivoted against the knee below, and bolted to bosses in the end of the arm above. These have a very slight appearance, but their triangular disposition affords ample stiffness under heavy cutting. Examples of other supports, more or less substantial, are given in succeeding pages.


One reason, perhaps the principal one, why overhanging arms are nearly always now made of circular in preference to rectangular section, is that the former is the better design for resisting all the stresses which come upon it from all directions.

Fig. 72 illustrates an alternative to point centres for affording support to the outer end of the arbor or mandrel. This is

a parallel end A, encircled by a split bush of phosphor bronze E, fitting with a parallel body, and short tapered neck into the hole in the arm. It is drawn in by the screw c entering into its end. In this example three key-ways are milled in the bush, so that it can be turned one-third round to equalise wear.

Bracings.--The pillar and knee type of milling machine is seldom made without some form of bracing to tie the knee and the overhanging arm together. However rigidly the knee may








Fig. 74.—Bracing formed of Pivoted and Slotted Rods.

be built, it is nevertheless unsupported on one side, and there is under heavy cutting operations some tremor perceptible, which leaves its result in more or less chatter. For this reason some tirms prefer to abandon the overhanging design and provide a solid base under the table, as in the Richards' design, making the cutter spindle adjustable vertically.

But the greater number of firms retain the convenient form of the open side table and vertically adjustable table and knee, using bracings in some form or another, which are more common on the plain machines, than on the universals, the reason being that they have, as a rule, heavier duty to perform. For a large number of operations on the latter the bracing may be dispensed with.

A simple form of bracing is shown in Fig. 73. Two screwed rods are brought down from lugs in the outer arm support through similar lugs provided in the front of the knee. After adjustment is made for height, the double nuts will securely tie the knee to the overhanging arm above.




Fig. 75. -Bracing, with Rods in Clamping Bosses.

The earlier and a still common type of bracing comprises two slotted bars crossing each other. In one design they are attached by bossed ends to the cross-slide face as far apart as the width of the slide will allow. They are then crossed against a boss on the overhanging arm, to which they are bolted, the three bosses forming a triangle.

In another form, Fig. 74, two bosses are provided on the overhanging arm, so that each brace has its separate bolt, and the braces cross higher up. In each case adjustment for height is obtained through long slots in the braces, which slide over the bolts.

An objection to braces of this kind is that they encroach slightly on the cross traverse of the table, and in some cases they prevent the putting on of wide pieces of work overhanging the table, which it would often be desirable to do, but which the presence of such bracing prevents.

In several Continental machines the bracings provided are different from any of those made in England or America. Two round rods, Fig. 75, with bossed ends, are in some cases used, these fitting and pivoting over a large pin in the overhanging




Fig. 76.—Double Cast Bracing with Slot-hole Attachments.

arm. The free ends of the rods go through split lugs at the ends of other rods, which lie horizontally along on each side of the knee, passing through split lugs on the sides of the same. Both sets of lugs have clamping bolts, so that, at whatever angle and height the braces are set, they are readily secured. A wide range of horizontal adjustment of the rods and braces is obtainable in this design to permit of the insertion of broad work.

Bracings of wrought iron or steel rods are not, however, so rigid in themselves as it is sometimes desirable that they should be. The methods by which they are attached make rigid connections, but the bars themselves are subject to some vibration when heavy cutting is being attempted. Theory indicates, and

experience is in favour of cast-iron braces, the substance of which is more rigid and solid, and in which there is a better chance of massing and proportioning the metal.

One of the stiffest bracings of this type is illustrated in Fig. 76. The vee'd edges of the knee are embraced by a vertical standard, the two slotted uprights of which are connected at the bottom with a deep cross bar, but having a space above which




Fig. 77. Bracing screwed to Knee with Bolts, with Adjustment Slots.




Fig. 78.—Deep Bracing, on Arm, Knee, and Base, with Slot Adjustments.

clears the overhanging arm when the knee is raised to its higher positions. The end of the overhanging arm is embraced by the boss of another bracket clamped on the arm, and having horns with slot holes coincident with those in the lower bracket. The two are bolted together at any vertical position of the knee, with four bolts. The horns of the upper bracket are tied together with a cross bar, and a boss serves as an outboard support for arbors. Such a bracing as this is perfectly rigid, making of the knee and

overhanging arm practically a solid mass. The objection is that the machine is no longer open-sided.

In another form of bracing, Fig. 77, a bracket with horns is gripped on the end of the overhanging arm. Two bolts are tapped into the front edge of the saddle that fits upon the knee. The slots in the horns slide over these bolts when the knee is being adjusted for height, and are gripped when set. The horns are often connected with a cross bar.





Fig. 79.—Bracing Bracket, fitted on Arm and Knee.


In another the device is reversed. The bracket fits on the vees of the knee, and the horns extend upwards. Bolts in bosses on the overhanging arm, which is of the turned-down type, pass into these slots, and are tightened at any height required. The horns are tied with two cross bars.

Again in some instances, Fig. 78, there is a long bracing provided, one end fitting to the arm above, one to bosses, on the base of the frame, and intermediate slots receiving bolts to the knee.

A more simple form consists of a bracket which fits to the vees of the knee, and has a single slot above, Fig. 79, in which a single bolt in the overhanging arm is tightened. In others the bracket is bolted to the top face of the knee, as in Fig. 80.

In some machines the bracing takes the form of a vertical bracket fitting to the knee, and having a sliding face parallel with the spindle. Over the face slides a bracket which receives an extension of the overhanging arm, and to which it is bolted.








Fig. 81.—Bracing which ties Arm, Knee, and Base together.

In another allied form, Fig. 81, the knee, overhanging arm, and base plate are all braced together by a stiff casting that is bolted to each. This removes the chance of vibration due to the overhang of the knee. It requires structural alterations in the end of the same, and in the positions of the operating handles, converting the machine into one of rather special design. The vertical movement of the knee is provided for by a slot and tee bolt in the upright bracing.

These devices are interesting as showing how the same object

is attained in many different designs, according to the ideas of different firms.

The Work of the Pillar and Knee Machine.—It would be more easy to say what this type of machine cannot do, than what it is able to do. Its only limitations are those of dimensions, for within its capacity, it is, in its highest developments, of universal range. For the type includes both the plain and universal designs, while in most of the later machines some provision or other is made not only for horizontal, but also for vertical and angular cutting (see page 75). Besides this, the type is made larger and stiffer than formerly, and better braced, so that, subject to its limitations in capacity, it is the most generally useful machine in the shop.

In this machine the height of the spindle being unalterable, the feeds are imparted to the knee, and all that it carries in the form of table slides, gears, &c. This taxes the elevating mechanism, and requires good fitting if unsteadiness is to be avoided.

The alignment of the outer support of the spindle bearing is embodied in the machine. The task of the workman therefore is confined to setting the work truly in all directions, and attending to the feeds. Methods of holding are illustrated in later chapters. Plain edge and profile milling are the special work of the machine. but a good deal of face milling is also done. The universal machine will do all that the plain miller will do, but the utilities of the latter are limited by comparison with the former. The plain machine being, however, built more heavily of the two, is preferably to be selected for heavy duty, and the universal for lighter, and for that specially requiring the swivel table and spiral Work requiring the dividing head alone, without the spiral movement, is better done on the plain machine if heavy cutting is The functions of the two, therefore, notwithstanding their general resemblances, are kept distinct in shops where economical considerations are allowed to prevail.

On the universals there is no operation of the machine shop which cannot be performed, not merely as a makeshift, but as a perfectly fair and legitimate function. This, of course, excludes the work of the turning lathes. It is also true to say that any operation of the machine shop can be performed on the lathe if

fitted with suitable appliances and adjuncts. But much of this is not legitimate work for the lathe; in fact, many jobs when so done are not done economically, but from necessity or through force of circumstances and conditions. On the milling machine it is all regular work, for which the machine has been specially designed. The exception noted to the work of turning is not absolute either, since wheels with very light rims are often milled more rapidly and more accurately than they could be turned in a The universal machine, therefore, fitted with suitable adjuncts, is capable of milling in rectangular relations, or at an angle, of milling circular outlines, or spiral flutes in a wide range of pitches, of cutting spur, bevel, worm, and rack gears, and cams, and all with a degree of precision for which little or no provision is embodied in other classes of machines, some of the most modern lathes and gear cutters alone being exceptions. The universal machine, as made by a few firms, is about the most beautifully designed and fitted article in the machine shop.

CHAPTER IV.

VERTICAL SPINDLE MACHINES.

Vertical recess Horizontal Spindle Machines—Vertical Spindle Machines—The Prefiling Machines—Various Examples—Designs of Vertical Spindle Machines—Built after the Model of Drilling and of Slotting Machines—Examples—Spindles coming from Below—The Work of the Vertical Spindle Machines—The Work of the Profiling Machines.

Vertical versus Horizontal Spindle Machines.—A question that often arises is the relative utilities of vertical and horizontal spindle machines, and also the relative values of face and edge cutters.

The principal advantage of having the face of the work lying horizontally is that it is under observation, and that heavy masses can be handled and set better, as a rule, in that position. Fastening flatwise directly to a table is usually more convenient than bolting to the vertical faces of an angle plate. With a vertical spindle, both faces and edges can be milled with face and edge catters respectively, without re-setting the work. This is not so conveniently done with horizontal spindles. Hence we find that, plano-millers excepted, the vertical spindle machines are more trequently employed than the horizontals for general engineers' work. The Lincoln miller is used more largely, in some of the lighter industries, but not so in engineers' shops. Besides which it was the first in the field, and has therefore had more time to become established.

Face and edge milling are often employed indifferently on vertical and horizontal faces. An advantage of working on vertical faces is that the chips fall away at once. On horizontal faces they should be swept off with a hand brush. Sometimes a suction pipe or a blast pipe with compressed air is used for the purpose.

Whether the spindle of a milling machine shall be horizontal or vertical depends mainly on the class of work for which it is selected. On the universal machine the horizontal position is preferable, because it is more convenient for gear cutting and fluting, and for work done by form cutters with linear traverse. The lubricant, too, lies on the work more efficiently under horizontal cutters. Generally, for broad-edge cutters also, the horizontal position of the spindle is best.

Vertical spindles are generally preferable when end mills are used. Profile milling must generally be done with vertical spindles.

On the other hand, the heaviest work is performed with horizontal spindles on machines of the planer and slabbing type. Better support can be afforded thus to the arbor, and therefore longer arbors can be used on the horizontal than on the vertical spindles. The latter are frequently supported at the lower end for heavy work, but not so efficiently as the former can be on their sliding heads on stiff uprights. Heavier cutting can be done on the planer type than on the vertical type.

Vertical Spindle Machines.—The pillar and knee type of machine has to be greatly modified when a vertical spindle is employed, and dimensions increase. The knee, always a weak element, is then frequently abandoned, the base of the pillar being extended—in slotting-machine fashion—to carry compound tables having no vertical feed. Then the vertical feed is imparted to the spindle and spindle head, and these are counterbalanced. The machine thus much resembles in outline a powerful drilling machine. Frequently also geared drives are abandoned in favour of the belt drive over guide pulleys.

These machines include examples of the heavier and the lighter types, constituting a large group, the members of which are employed more extensively than others the Lincoln, and pillar and knee excepted. They have both their advantages and disadvantages. They take the place of the slotter in tooling circular pieces, and perform the work more correctly, because the slotting tools produce minute facets, leaving finish to be imparted in other ways. The vertical miller tools internal and external portions on a piece without re-setting, or on segmental pieces arranged in circular order. Both faces and edges can be tooled without re-setting—faces with face mills, and edges with edge mills.

It is also the lest type of machine on which to fit profiling attachments.

The disadvantage of the type is that due to milling on horizontal faces, which does not permit the cuttings to fall away as they do from vertical faces tooled from horizontal spindles. And when vertical faces are being tooled on it with edge mills, limitations of depth come in, due to the spring of the arbor. This is controlled in the heavier machines by a bottom supporting bracket, which fulfils the same function as the outer arbor support on the horizontal spindle machines. This support is variously fitted, being sometimes brought down from the lower spindle bearing, sometimes hinged at the side of the upright. But the essential is that it shall have provision for being swung aside, to permit of doing work for which the support is not required.

Within the very comprehensive generalisation of the vertical machines there is included a large number of designs, varying in the methods of the drives, through gears or belts, with vertical adjustments imparted to tables or to spindles, and with heads having one range of movement only, or combining horizontal or angular settings.

The Profiling Machines may be common vertical spindle machines first, to which profiling movements are added, or the profiling may be the principal function, plain milling being a secondary thing. The first division generally embraces the larger machines, the second the smaller ones.

In profiling machines the table is not adjustable vertically, but that movement is effected in the spindle. The machines in some cases have rigid knees, on which the main table slides, in others a bed of greater or less length carries the table, which then resembles the general type of planing machine, and the spindle slide is carried on a cross rail adjustable on the faces of housings attached to the bed.

Methods of profiling are described later. The essential of a profiling cutter slide is that it shall be coerced, not by screws, but by the pull exercised by a weight suspended from a chain. The triction of the slide is lessened as much as possible by fitting reflers to the lower or the upper bearing edges, and steadiness is secured by giving a long contact between the slid-

ing parts. The former pin may or may not have a range of adjustment. The spindle is driven directly by belt in the smaller machines, through cones and back gears in the heavier. The mass of the spindle and its bearings is counterbalanced. Though most profiling machines have vertical spindles, an exception occurs in some made by Messrs Webster & Bennett, of Coventry, which have horizontal spindle heads resembling those of lathes, on a lathe form of bed.

Small machines for general milling and profiling have vertical spindles of from 3 inch to 11 inches diameter. A horizontal crosshead is east with two uprights, and the latter are bolted to a box base which carries guides for a table, upon which the work is traversed under the mill. A carriage slides transversely along the crosshead, adjustable by handle lever, and the spindle slide moves vertically on the carriage, its movement being adjustable by means of vertical stops. In these the spindle is revolved by means of a belt and drum only. The traverse of the carriage, and also that of the table, is effected by hand. Light double-spindle profiling machines are also made nearly similar, so far as the methods of operation of the slides by hand are concerned. The traverse movement of the slide is effected through spur gear and a rack on the bottom edge of the slide. The driving of each spindle is from a long drum at the rear, driving half-crossed belts on to the spindle pulleys, the drum being fitted with fast and loose pulleys. The spindles are balanced with springs above.

A vertical spindle machine of simple design, by Messrs Webster & Bennett, is shown in Fig. 82. The style of frame provides for carrying the table slides without vertical adjustment, this being imparted to the spindle slide only.

The method of driving the spindle A is by the belt pulley B, which runs upon a sleeve, in order to relieve the side pull; to B the belt is carried over idler pulleys c, from the driving one D. A four-stepped cone on the same spindle as D provides for variations in speed. Some types of this machine are without gear, but others have a back gear contained within the pulley B.

The spindle is moved up or down by the slide E, which is travelled by the balanced handle F. On the same shaft as the latter is a worm, which drives a wheel working upon a vertical screw, so imparting a fine feed to the slide E. As the lower end

of the spindle A is confined in E with collars, it partakes of the movements up or down, the upper splined end passing through the pulley B, in which keys drive on to the spindle, while still permitting the latter to slide endwise. A stop screw G, in a boss on E, abuts against a lug standing out from the fixed frame, seen




Fig. 82.—Vertical Spindle Machine.

in the figure, and so provides for a definite depth of feed, which may be repeated as often as desired on repetition pieces.

The table movements are effected by the handles seen, or the longitudinal feed by power through the four-stepped cone H. driven from a pulley forming an extension of P. H imparts motion to another cone J, revolving a shaft K. The latter drives a worm

beneath the apron L, engaging with a wheel which is splined on, and rotates the feed screw, on the end of which the balanced handle is seen.

An automatic knock-out is provided, which drops the worm




Fig. 83.—Vertical Spindle Machine.

out of engagement with its wheel at a predetermined position of the table travel. This is effected by dogs bolted on the under ledge of the table at M. When one of the dogs strikes against the end of the lever N, the latter, which normally holds the worm in a hinged box up to engagement, allows it to drop, so letting the teeth out of mesh, and stopping the feed. The cases where this feed are used comprise those in which a long cut is taken, and the stop is set to trip the feed at its termination. For short work the hand feed is employed.

Fig. 83 is a vertical spindle machine by J. Parkinson & Son, which embodies vertical movement to the table instead of to the spindle. The latter is driven by a plain pulley A, through idlers B, B off a pulley C, the latter being given four speeds through the cone D on the same shaft.

The tables are operated through the handles seen, or the longitudinal and cross movements are actuated by power. The feed is derived first from the three-stepped cone E, on the same shaft as c and D. E drives up to another cone F. On the same shaft is a two-speed pulley G, driving down to a similar one H. It will be seen that, by means of the two sets of cones, five rates of feed can be obtained for each rate at which the spindle may be driven.

From the shaft of H a pair of mitre gears J drives a short horizontal shaft K, upon which a worm and worm wheel convey the motion to a vertical shaft L, mitre gears M at the top of which drive a horizontal shaft within the knee. The shaft L is splined to slide through the worm wheel, to accommodate itself to the vertical table movements. The shaft N, driven by the mitres M, first rotates the feeding screw above it (on which is the handle o) through a pair of gears, and also the screw in the longitudinal table P through mitres, seen dotted in the views. A trip device is fitted to the table P, seen in the front elevation, the block q striking a lever R, which disengages the feed within the table. The vertical travel of the knee, and table is effected by the handles, working bevel gears which rotate the vertical feed screw F, turning in the threaded foot at the base.

A profiling attachment is made for use on this machine, which embodies the principle of the former or templet, controlling the movements of a roller. Three views of this device are seen in Fig. 84, in plan, and front, and side elevations. A circular revolving table A is driven by worm gear through spur wheels, actuated by another worm gear, which derives motion from a telescopic shaft, the latter being employed because of the irregular movements of the table under the guidance of the former. The work

is carried upon a small table B, the edge of which is shaped to the required outline to be milled; a roller c presses against the edge, being held in a bracket D. The holder of the roller c is capable of adjustment with a screw E, to permit of milling sizes larger or smaller, and giving the depth of cut. The sliding table A, and small table B, are pulled against the roller c by weights F.




Fig. 84.—Profiling Device for Parkinson's Machine.

It will be seen therefore that on revolving the table A, it will partake of the motion given by the profile of B (which is that of an ellipse in the illustrations), and so bring the work likewise against the cutter.

A circular table, also fitted to the machine, is shown in Fig. 85. It is bolted down to the tee slots of the main table, and is pro-

vided with a worm and hand wheel, which rotate it. Graduations are made around the edge. The worm can be thrown out of engagement, to enable the table to be rapidly turned for purposes of adjustment. It can also be locked when straight portions have to be milled, the circular table being then carried along bodily by the machine tables.

A vertical profile milling machine by Messrs Webster & Bennett of Coventry is shown in Fig. 86.

The drive to the spindle is by belt from a drum at the rear, which is necessarily made long to permit the belt to follow the cross traverse of the carriage C along the cross rail D, in the act of profiling. The carriage runs on rollers on the top of the cross rail, in order to reduce the friction as much as possible.




Fig. 85.—Circular Table for Parkinson's Machine.

The spindle slide E has a vertical adjustment on C. The former pin is seen at a. This is held closely against the form or pattern by the pull of the weight seen at the side, which draws the slide C by the chains indicated, passing over pulleys. The saddle C can be clamped on the cross slide D when ordinary milling has to be done.

The table F has a longitudinal feed, that is, perpendicularly to the faces of the slides, derived from the stepped cone G, through the train of spurs, and worm gear shown, to the rack beneath the table. The stops b b, on striking the lever c, reverse the motion through the claw clutches d, on the worm shaft II. A handle put on H affords a hand feed to the table.

The table also has a circular feed through worm and spur gears, which can be disconnected instantly by throwing out the clutch ϵ . A pump j is belted from the main driving shaft. The body of the machine forms a sud tank.

With increase in the diameter of spindles, the profiling machines approach more nearly in the length of table and bed, and in general appearance to the planing machine framing. A circular




table is also often included, being detachable from the rectangular table when not required. This is provided with a central arbor, and with worm gear for rotating the work. A cutter stay is also

attached, being made so that it can support the lower end of the mandrel or arbor in any position. It is attached to and swivelled upon the spindle slide, and locked in any position. In some machines the slides are indexed with steel rules, and the circular tables are also indexed. Machines of this kind are made with spindles up to 6 inches diameter.

As the capacities of these machines increase, nearly every detail becomes much modified. The hand lever, by which the cross traverse of the spindle slide is adjusted in the light machines, gives place to a weight, the chain of which passes over pulleys at the head of the framing. Tables are extended, so that, instead of getting a table traverse of from 12 to 18 inches, we have traverses equal to those of the average planing machines, so that objects can be profiled up to 4 ft., 5ft., and 15 ft. in length. The tables are, in fact, like those of planing machines, made with numerous tee slots, and running on flat beds with vee'd edges. They are driven by screw, have self-acting feeds, reversals, and quick traverses by power. Troughs around the edges are provided to catch the oil. The feeds of the traverse carriage, though still capable of being operated by hand, are also rendered self-acting, and variable, and reversible. Again, though machines of very considerable dimensions, up to those with 2-inch spindles, are driven by belt, the spindles of those of large sizes are driven through stepped cones and bevel gears. In some machines, again, the cross slide is not confined horizontally by the uprights, but slides vertically upon them, exactly as in a planing machine, being adjustable by hand or by power. To all machines of this kind a centrifugal pump is fitted for the lubrication of the cutters.

These types of machines are equally suitable for the work of general milling, the profiling attachment being a convenient adjunct superadded, and one which extends the usefulness of the machine, without detracting from its value as a plano-miller.

The principal vertical spindle machines may be broadly classed as those having tables fixed in regard to height, and those in which the tables have vertical adjustments and feeds.

The first-named great group have framings much resembling those of the slotting machine, or the similar outline of drilling machine framings. There is a broad base, usually cast in one piece

with the uprights, with slides to carry the table slides, and an overhanging head, either cast with the upright, or bolted to it. The spindle bearings are movable vertically, and the lower bearing, or the entire bearing arrangements have vertical adjustments, not only to suit the height of the work, but also to afford support to the cutter close to the latter. The spindle ranges from 3 in to 5 in diameter. The spindle slides are counterbalanced in various fashions, and are adjustable by hand, and also by power in the heavier machines, the latter being a slow motion by a belt-operated The spindle drive takes place through worm and a wheel. stepped cones, with back gears included, and through bevel gears for changing the direction of motion in all the older, heavier machines, and in the majority of the recent ones. But a considerable number of the latter are now fitted with high-speed belt drives, even in heavy machines. The belts then come over guide pulleys, driving immediately to the spindle, which can be operated directly, or through back gears. Bevel wheels are eliminated in this design. The pull of the belt does not take place directly on the spindle, which would produce unequal wear in the bearings, but on a sleeve which encloses the spindle (see page 109).

Feeds are taken from belt cones, and all the table motions are self-acting, and controllable by the attendant at the side or front of the machine. A circular table is almost invariably included, also made self-acting through worm gears. The tables are compound: if the additional table is not circular, but square, it has the circular motion. The feeds, which are towards or away from the vertical frame, transversely thereto, and circular, are each selfacting and reversible through gears and screws, and worm and wheel, similar to those employed in slotting machines. reversals are effected by hand, either through three bevel gears and a sliding clutch in many machines, or by means of a friction disc and roller. Each feed motion also is capable of disconnection by means of friction elutches, and of quick hand traverse. circular table is in the way of fixing work for plain milling, and is therefore removable. But in some designs this is rendered unnecessary by the simple device of flanking the circular table with wing tables, which partake of the rectilinear movement of the slides below. The faces of these stand a trifle higher than the face of the circular table, so that work bolted to them clears

the circular one, and can be thus tooled without removing the latter. On vertical spindle machines, fitted with compound slides and circular table, all rectilineal work can be done with face or edge mills; and all curves, alone or in combination, with straight edges.

It is an exceedingly useful type, better suited, perhaps, than any other to the requirements of the general shop. It covers a large volume of work, and will take heavier and larger pieces than the pillar machines previously noted. It is made in a wide range of dimensions. Some of the machines of this class which have been constructed in recent years are exceptionally massive and stiff, capable of doing plenty of heavy cutting. The details are worked out in many ways by different makers, so that beyond the main design there is not much in common between them.

An unsatisfactory feature of the ordinary slotting-frame type of milling machine is the projecting unsupported spindle, resembling in this respect the ordinary drilling and slotting machines. It is not possible in some jobs to use the bottom supporting bracket provided in many machines of this class. There are two methods in use, therefore, for supporting the spindle and increasing its stiffness as far as possible, one of which in its essential features is embedded in most American drilling machines, and on a very limited number of slotters.

It a vertical milling machine by Hulse & Co. Ltd., steadiness of the stress of the cutting at a sensured by enclosing it in a long, hollow square slide, which is ensured by enclosing it in a long, hollow square slide, which is in run in conical bearings therein. The slide is made apable of vertical movement, and can be set and clamped by a looking screw at any height required. Vertical movement of the spindle is provided for by means of a pinion that embraces it, and which is driven by a pinion long enough to cover the whole range of travel of the spindle. The weight of the spindle and slide is slightly overbalanced by means of a balance weight. Several tirms, both in England and America, construct vertical milling machines of the slotter type in which the spindle head can be adjusted vertically by a hand wheel and gear to suit work of different depths.

In the second great group of machines the knee is adjustable,

the arrangements then resembling those of the pillar and knee machines. The objections to this design increase with mass, and therefore it is not adopted much for the heaviest types, though some good massive examples occur. The vertical adjustments of the knee are not always employed for feeding as in the ordinary pillar and knee machines. Frequently it is a movement of adjustment only, the cutting feeds being imparted to the spindle, as being more convenient. These generally have a micrometric device, and in good machines an adjustable dead stop which regulates the depth of cutting for any number of similar pieces.

The three views, Figs. 87-89, give general and side elevations of a vertical milling machine by Messrs Alfred Herbert Ltd., of Coventry, which combines the best points of present-day practice. It is a massive tool, weighing about 6,000 lbs. The leading dimensions are:—Longitudinal feed of table, 36 inches; transverse feed, 12 inches; vertical adjustment of table, 12 inches. The spindle The circular table is 16 inches diameter. is 25 inches diameter. The maximum distance from the surface of the table to the spindle is 19 inches. Feeds are automatic, are reversible, and have automatic trips in both directions, and dead stops to table feed. Gears are all enclosed, and lubrication is amply provided for. machine is of the type in which the knee is adjustable vertically, and the spindle has similar adjustment, the fine adjustments being given with the latter. The spindle is belt-driven, direct or through spur gears, no bevels being used anywhere in the driving mechanism. These are the leading elements, whence we now proceed to work through the details, enlarged views of which are given in subsequent Figs. 90-97.

In Fig. 88 the countershaft is driven by two sets of pulleys, A and B, at 375 and 150 revolutions per minute respectively. The single-shipper lever shown actuates each set of striking gear by being pulled into contact with either one of the two sets of blocks a, a on the shipper bars. The three-stepped cone pulley c drives to: spindle, the two-stepped cone D to the feed cones, and the pull to the pump.

driven by c. As these have three steps, and there are two counter speeds, this gives six spindle speeds for either belt or back gear, so making twelve in all. They range from 20 to 500 revolutions




Fig. 87.—Vertical Spindle Machine, (A. Herbert Limited.)

per minute, the quicker speeds being reserved for fine finishing with the smaller cutters. The drive takes place from the pulley of on the cone shaft below, over the two guide pulleys it to the

spindle pulley J. The latter, it is to be observed, is not keyed directly on the spindle, but its pull is taken by an intermediate bush or sleeve κ encircling the spindle, relieving the spindle of




Fig. 88.--Side Elevation of Herbert Vertical Spindle Machine.

side pull, which would cause unequal wear. The driving of the spindle is transmitted as follows (compare with the details which are shown enlarged in Fig. 89):—

The boss of the pulley J is keyed on a boss encircling the sleeve

K, and this boss forms an extension of the first gear b. b drives c, with which gear d is solid, and d drives c. c is secured to a driver plate f. L is an equalising driver, whence motion is transmitted to the spindle by two keys g, g, to receive which the spindle is splined on opposite sides down a good portion of its length to allow of its sliding motion taking place. In this way the spindle




Fig. 89.—Details of Spindle Drive.

drive is given through the back gears b, c, d, and e. All these are enclosed by the light cast-iron casing shown in Figs. 87-89.

The back gears c and d are mounted on an eccentric spindle, which is thrown in or out by worm gear, indicated in the figure, and actuated by the hand wheel h to the left of the machine. Direct driving then takes place on locking the wheels e and b with a spring pin j, seen in the detail to the right of Fig. 89, the spindle being rotated by the driver L and keys g, g as before. The

handle k in the figure is used to revolve the driver until the pin j comes over its hole, the casing preventing this operation being done by pulling on the wheel itself. The tension of the belt on the pulley J is maintained in an alternative design of the machine by means of the sliding bracket N, Fig. 88, and of its set screw in opposition to the abutment piece on the main framing.

A slide which carries the lower bearing of the spindle is capable of vertical adjustment to move the latter and afford continual support close to the cutter. Exact feeding is attained with the hand wheel o at the front, operating through a worm and wheel enclosed in the casing seen. On the same spindle as the




Fig. 90.—Side Elevation of Reversing Gear Box.

worm wheel is a pinion, which gears into a rack on the machine frame, and so racks the bearing up or down. A dial l, mounted on the hand-wheel spindle, is graduated into thousandths, and is adjustable to zero in any position, in which it may be then locked. The motion of the spindle bearing can be arrested at any height by the setting of the vertical stop m, which has fine screw adjustment and a lock-nut. A handle n locks the slide when face cutting is being done, and both this handle and the stop handle "lock" when in the horizontal position. The slide is balanced by weights p within the framing, the chain for which passes over guide pulleys, the anchorage being at o.

The conical spindle bearing is of hard phosphor bronze, with provision for taking up wear. The end thrust is taken by washers of hard tool steel and phosphor bronze. The spindle is of crueible steel, bored throughout. Its nose has a No. 10 taper, with a clutch drive for the arbors. The latter are retained in place with a draw bolt. The nose is threaded to receive large cutters, and when these are not in use the thread is protected by a cap.

Tracing next the table feeds from the countershaft pulleys D to the pulleys Q on the machine, these drive four-stepped cones R and S, giving eight feeds, doubled by the pulleys A and B on the counter. They range from 500 to 12.75 inches per minute. The




Fig. 91.—End Elevation of Reversing Gear Box.

feed motion for the circular table is transmitted through the reversing gear box T to the vertical shaft U, thence through spiral gears to the horizontal shaft V. A comparison of the views of this box in Figs. 90 and 91 will render much description unnecessary. The reversal is effected by the handle p, which slides a splined clutch into engagement with either one of a pair of loose bevels, so driving the wheel in the nest of three gears in one direction or the other in a manner well understood. The extreme positions of the handle are fixed by the stude outside the box.

The table feeds, derived from the shafts U and V, may now be studied in Fig. 92, compared with the general views, Figs. 87 and

88. The two views of the machines are not wholly alike, because the general views include a circular table which is not illustrated in the details; but that does not affect the main table drive, which we are now to consider.

Taking up the connection at the vertical shaft v, and horizontal shaft v, the function of these is to drive the circular table in the manner indicated in the side view, Fig. 88, but not shown in detail there. The drive of the oblong table takes place from a vertical shaft w within the framing, which is actuated from bevel gears direct from the gears in the reversing box (compare Figs. 91 and




Fig. 92.—Detail of Knee, and Table Drives.

92 with Figs. 88 and 93). At the upper part of w a sliding spiral gear q is seen, which is the first element in the table feed. q, with a nest of gears is carried in a bracket which is bolted to the back of the knee, and therefore moves vertically with it, the corresponding sliding of the gear q being provided for in the splining of the vertical shaft w. q drives a spiral of equal size at right angles on the end of a shaft which carries four spur gears driving four smaller gears on a shaft s. On the latter, and mounted between the spurs, are two worms driving worm gears s' s' on the shaft and screw t, t, the worms being double-threaded. The shaft

and screw t, t come out through the knee nearly to the front, Figs. 92 and 94, where, by means of a train of three spur gears each, the middle one being an idler, they are connected to the hand wheels x, x at the front of the knee. The hand wheels are thus separated sufficiently far to permit of both being retained on their shafts at one time, while the idler wheels allow the rotation of the hand wheels to take place in the same direction as the shaft and screw. As the worms can be dropped out of mesh with the worm gears, the shaft and screw can be worked either by power from the one end, or by hand from the other.






Fig. 93.—Detail of Driving Gears in Column.


The connection between one of the shafts t and the screw Y that imparts the longitudinal feed to the table is easily seen, being traceable through the mitre gears in Figs. 92 and 95. The transverse feed to the knee saddle is through the medium of the nut u seen in Fig. 95. The vertical adjustment to the knee is clearly seen in Figs. 92 and 94. The three screws for these motions are of the Acme form. The weight of the knee is taken on a ball race, and the crown bevel wheel is of large diameter. From these




three movements we now pass to notice the locking and other arrangements.



It will be observed that every slide has its locking handle or handles. These include the table, knee, and saddle. The various locking handles are all distinguished by the letter v in the views (see also Fig. 96). All the feed screws have micrometer adjustments, the dials for these being indicated by the letter w, and one is shown enlarged in Fig. 97. The handles z, z, Figs. 92 and 95, are for dropping the worms on the shafts into and out of engagement with their wheels. These handles drop the box w which carries the worm shaft w. The box pivots around the axis of the shaft w, and thus the movement of w and the rod w throws it down or up, breaking or effecting gear between the worms and their wheels w, w. This is a spring plunger to cause the box to drop with certainty (see Fig. 92). The movement of the rod w








Fig. 97.-Micrometer Dial.

automatically, constituting an automatic trip, as shown in Figs. 92 and 95. The adjustable stop z elamped to the tee slot on the edge of the table, coming into contact with the top of the spring plunger, seen adjacent to it, thrusts down the lever aa, and with it a lever within the knee which bears on the upper ends of rods bb, Fig. 92. These press on the rods y, and so throw out the gear box x at any predetermined point. The spring plungers in the knee under the rods y serve to just hold up the latter from dropping when in gear and locked. In addition to these automatic trips, dead stops are fitted—blocks clamped in the tee slots of the table edges, and abutting solidly against the automatic plunger casing instead of passing over the rounded top of the plunger. All these stop blocks are tightened up with handles instead of providing hexagon nuts, so that no separate spanners are required.




Fig. 98.—Side Elevation of Vertical Spindle Machine.
(B. & S. Manufacturing Co.)

Very complete arrangements are made for lubrication. There are the pump, tank, and feed pipes seen in the general views, Figs. 87 and 88, and the numerous waste-oil trays and lubricators shown





Fig. 99.—Front Elevation of Machine.






Fig. 100.—Plan of Head, and Sectional Elevation of Head.

in the details. Especially should those in Fig. 92 be observed, to be supplied through the doorway marked "Oil Gears," Fig. 93. Also




Fig. 101.---Details of Spindle Feed.

the taps for drawing off the lubricant from the trough around the table in Fig. 95. When the full system of piping is fitted, unions

go in these holes, and allow the liquid to run down through the flexible pipes, shown in the general views, into the tank to be again pumped up.

The drawings of this beautiful machine will repay a more extended study than we have afforded it, many minor details being passed over without comment. A high-class machine tool such as this possesses an interest and fascination which increases with closer knowledge.

Figs. 98-103 illustrate the latest Brown & Sharpe vertical Its principal interest centres in the feeds, which are derived from a shaft running at constant speed, instead of from stepped cones. The general outlines of the machine are shown It is of the elevating knee type, the in Figs. 98 and 99. vertical movement being 15 inches. The spindle has a range of vertical feed of 4 inches up or down. The latter makes from 17 to 354 revolutions per minute, and has fine hand feed, and quick return by separate hand wheels. The table travels 34 inches, and has a transverse movement of 131 inches. The arrangements for feeding are to the right of Fig. 98, driving to the telescopic shaft.


Fig. 100 shows the head in plan view and in sectional elevation. The spindle, of crucible steel, runs in bronze bushings, the lower one of which has provision for adjustment. The spindle is hollow to receive a draw-through bolt for cutters, and the end is coned, threaded, and clutched. Its mass and that of its sliding bearing is counterbalanced, as shown in Fig. 100.

The mechanism of the spindle feed is shown in Fig. 101. The fine hand feed and quick return are effected by different hand wheels. The first is through worm gear, the second by a pinion gearing into the rack direct. The worm shaft is automatically driven from a sprocket.

The spindle is driven by a Renold chain A, Fig. 100, from a vertical shaft at the rear, which is connected by bevel gears with the driving mechanism at the rear of the pillar. The spindle is back geared in the ratio of 4.97 to 1. All these gears are enclosed (see Figs. 98, 99, and 100).

The drive from the countershaft (or motor) takes place to the pulley B, 14 inches diameter, Fig. 98, whence the mechanism of the gear box c is actuated. This is shown in detail in Fig. 102.

The shaft of B makes about 310 revolutions per minute. Between this and the shaft which is geared to the vertical shaft through the bevel wheels, there is an intermediate shaft D that carries






Fig. 102.—Details of Variable Feed Mechanism for driving Spindle.

four gears. Through the medium of an idler indicated at E, either one of these is engaged with a long pinion on the driving spindle. On another shaft are two gears constantly engaged with two of those in the cone of gears, and either of which may be

engaged by the splined clutch seen to the right. The knobs F and lever G control the idler. F slides, and G unlocks and locks by downward and upward movements respectively. The position of the index slide for a given speed is set by bringing the knob F opposite the column of spindle speeds on the outside of the box.





Fig. 103.--Details of Feed Box.

The crank handle II controls the two clutch gears above, giving two series of speeds. In this way 16 speeds are obtained through gear box, and back gears, ranging from 17 to 354 revolutions. The gear ratios range from 1 to 1, to 18 to 1.

The feed box is seen at J, Fig. 98, and its details in Fig. 103. The general design is similar to that for the spindle drive, though

ن .

not quite identical. It is driven at a constant speed through a chain to the pulley κ , thus rendering the table feeds independent



of the spindle speeds. A cone of six gears is driven through an idler and thence to the telescopic shaft. A sliding knob and

lever, seen in the box below, gives the feeds in inches per minute, ranging from $1\frac{1}{2}$ to 17.

The table has, in addition to its automatic movements, a hand feed by the wheel seen below the table in Figs. 98 and 99. It has a quick return through a screw of coarse pitch, to effect which the feed worm is disengaged and a crank handle used.

There is a valuable class of machines, at present the speciality of one firm, that of Curd Nube, of Offenbach-on-Main, the leading feature of which is that the principal spindle comes up from below through the table. This feature alone is embodied in some of the machines by this firm, and there is consequently no overhanging arm, and nothing above the table. But in another group, an upper vertical spindle is also included, and in another, a third In addition the head swivels for angle. spindle horizontally. Fig. 104 illustrates a machine of this complete type in vertical section. The spindles can be operated in unison or independently, and the upper spindle is capable of receiving vertical adjustments. The machine is capable of doing milling, drilling, and die cutting. The tables have compound movements. In machines which have no upper spindle, the table has provision for vertical adjustment.

The essential mechanism of the complete three-spindle machine in Fig. 104 may now be traced out. All three spindles are driven from the cones A, back geared, each spindle B, C, D, through its own set of mitre gears. The top bearing of B is protected with a cap a. The spindle fittings, and the method of taking up wear are similar in each, the lock nuts pulling against the coned bearing necks. The method of attaching the arbors is only indicated in the horizontal spindle, comprising a screw in addition to the taper of the shank.

The compound table is carried on the knee R, capable of vertical adjustment on slide faces at the front of the main framing. It is elevated and lowered by the worm gears E, actuating a vertical screw, threaded into the boss F, which is let into the machine framing. The knee also encircles a boss G, fitting by a turned check into a bored hole in the framing. It is clamped on G by the set screw b. On the knee the traverse slide H is moved to and from the pillar by the screw c and its hand wheel. The transverse slide J is moved at right angles to the direction of that of H by its screw and hand wheel, and the circular table

K is rotated on J by worm gear, the wheel being cut solidly around the edge of the table. K carries stepped chucking strips d, d, which have setting-up and clamping screws (not indicated), and by means of which dies or other pieces with parallel or with tapered edges are gripped. It is thus seen that though the bottom spindle B has no vertical movement, the table can be adjusted for height with great precision, and within a large range, and clamped securely, so being adaptable for work of different depths, and for coarse and fine feeding. Also that cuttings fall away

down into a hollow space in the knee, and together with waste lubricant are received in the tray L. Any other chips and lubricant are received by the channel that is formed all round the foot of the main framing.

The vertical spindle c is carried by the swivel plate M, which pivots around the axis of the driving shaft c. M has an index or zero mark on its flanges by which the spindle is set perpendicularly, or to an angle, to right and left, with graduations on the corresponding flanges of the main framing, and is clamped by bolts, one of which is seen at f. The spindle c can slide in the sleeve N, thus accommodating itself to the vertical adjustments of the sliding bearing o. The latter moves on flat slides on the swivel head M, when




Fig. 105.—A Pratt & Whitney Spindle,

operated by the mitre wheels P, and serew, the wheels being turned by a hand wheel standing out to the front (not shown), o receives an overhanging arm Q, with a centre for the arbors held in the horizontal spindle P.—s is a pulley which supplies self-acting feeds to the table when required.

This is a brief description of one of a great group of machines which possess a very wide range of utility.

One method of elevating the table in one of the types of machines by this firm is this: the support to the tables has a long cylindrical boss, encircling a long boss that forms a prolongaThe Garvin spring-balanced size is in the Fig. 128 in which the spiralle driven in the try with a easily in the in adjustable learners in a casting which carries has the number of the balancing spring is a number of the balancing spring is a number of the carries as privated with an adjusting size.

The Work of the Vertical Spindle Machines—Employed work involving the employment of the spind heal and some table, these machines include everything place and the comes within the range of their limited apparaty influences and edge milling. They are equally a spindle of roots introduced methods of catting. But the machines are a mently some roots a large. Combinations of our es with stream parts are less a readily come by combining the movements of the linear subsecution by the bore through the arbors which are intended to the service of the table, as in slotting machines. Process of inflerent replace can be done with face mills which is convenient in cutting recesses such as those is smithal dies for straighnys.

The Work of the Profiling Machines.—In: general mechanism of these machines has been been leseriles, page 2000 104. The work done consists in moding an i attaching a cuitable trace to the table of the machine, and a questing the work to the malar cutter and both in relation to the fermer pin. In come case provision is made to adjusting to latter, but generally there, a lare, excepting sometimes the choice of two belost medical of which the pin may be clamped. The pin is tapered, where permits by its vertical adjustment, of deepening the successive const.

CHAPTER V.

PLANO-MILLERS OR SLABBING MACHINES.

Flane-Millers or Slabbing Machines—Their Characteristics—Details of Spindles— Horizontal—Vertical—Rotary Planers or Ending Machines.

Plano-Millers or Slabbing Machines.—This is a name that seems most appropriate to designate that large and growing group of machines which is built on the model of the common planing machine, with bed, table, housings, and cross rail carrying These are the most obvious rivals to the planing spindle heals. They differ from planers in the slower table feeds, machines. and in the character of the vertical feeds imparted to the milling cutters. But the plane-millers have gone beyond this design, for many machines include both horizontal and vertical spindles, and some with angular movements, others also have profiling attachments, and many include circular tables on the reciprocating ones. Bosides this, some machines have two tables moving side by side and these again may be run independently, or coupled for simultaneous movement, to carry wide work. Then there are the transmachines convertible into the open side type, and social forms of these.

The principal points which should characterise a good milling tachine of the planer type, Fig. 107, are, besides massiveness in natiowerk and in spindles, and ample bearing proportions; provision to taking up wear, balanced slides or heads (when these are of constitution weight), easy, accurate, and smooth movement to the table; a wide range of table speeds and entter feeds, provision for rapid theorem, on the table in each direction for setting work, quick movement of the heads for setting spindles, fine vertical adjustments for the cross rail, fine adjustments for the table and heads, self-acting feeds to the table, with automatic knock-out; provision for lubrication by pump, an oil trough round the table, ample belt and gearing power, and convenient location of handles

for the various movements. In proportion as a given machine embodies these general characteristics may its value be estimated. All machines do not include the whole of these: some are deficient in most of them; some are very well designed in regard to certain details, while deficient in others.

In selecting a slabbing machine regard also should be had to the class of work which has to be mainly done. If both faces and edges on the same piece of work have to be tooled, then, having a horizontal arbor only, the work will have to be re-set for each separate face. But if, in addition, there is a vertical arbor, then two faces can be tooled at one setting. If there are three or four arbors—which is the case in some machines—the range of duty is correspondingly increased.

The number of firms who make small milling machines of excellent design and workmanship is greater than that of those who construct heavy ones. One reason lies in the fact that fewer shops are equipped for the building of heavy machine tools than of light ones. But the principal reason is that the practice of heavy milling is of much more recent development than light milling. The economy of heavy milling rersus planing is as yet a matter open to question in the minds of some engineers. The planer type of machine is, however, becoming more and more adapted to the work of heavy milling, and cutters are made more capable of taking heavy feeds.

As remarked in a previous page, the early uses of milling were all confined to the tooling of small articles, and not at all to service in general machine shops, nor for heavy work. Of late years that has been changing, and a good deal of heavy milling is now done on the slabbing machines, both with edge mills and with face mills having inserted teeth. During this development lessons have been learned, the results of which have been utilised in later designs, so removing the objections and prejudices to heavy milling, which have been due to want of knowledge of proper conditions and necessary limitations. The stresses due to the use of wide cutters with continuous edges being much greater than those due to the use of single-edged tools are the cause of the greatest difficulties in milling considerable widths. Though these are diminished by the spiral grooving of cutters and by staggered teeth, true work, when of considerable width,



can only be done by the use of stiff machines, stiff arbors (by supporting both ends of the arbor in long bearings), or by both devices in conjunction, and by taking shallow cuts and slow feeds. Without these precautions, milling which is at once broad and accurate is impracticable. And so we find that the best machines to-day are designed and constructed of very massive proportions. Yet the best are none too stiff now for much of the duty imposed upon them.

Of the planer types of milling machines there are various modifications. The first variation occurs in machines in which one upright is made either extensible or removable, to receive work wider than the normal capacity will take. Another occurs in the entire removal of one upright, making a permanent form of open-sided machine. Each of these general designs is constructed with variations in detail.

The four-spindle machines are specially designed to operate on two faces, vertical and horizontal respectively, of two pieces of work at one time. There are two sliding on the cross rail, and




Fig. 108.—Ingersoll Spindle (Horizontal).

two on the uprights. All are driven from one cone shaft, and all have independent adjustment.

The spindles of the Ingersoll machines are constructed in the way shown in Fig. 108, being for the 36-inch size. In these figures A is a fixed bearing on the cross rail, B the wheel which drives the spindle, C is the movable bearing on the cross rail, and D the parallel portion of the spindle, which slides in the boss of A, as C is adjusted endwise. The arbor support E also can be slid endwise on the cross rail and over the arbor F. It will be seen that the spindle is fitted with double reverse cones. The front cone G is kept pulled back to its bearing by the adjustment of the hinder cone H, tightened by the lock nut I. The cone, which encircles the spindle, is of cast iron. Its bearing is of phosphor bronze. The wheel B drives the spindle, while permitting its parallel end D to slide endwise through it in the sleeve extension J.

This sleeve runs in the bearing of A, and is prevented from moving endwise in either direction, the spindle D moving along with C. A couple of keys are fitted in the bush. These slide in the key grooves in D, and rotate D in any position covered by the range of the key groove. The inner end of the arbor fits the tapered hole of the spindle. The outer end F runs in a parallel bearing in the bracket E, and wear is taken up by the lock nuts and cone.




Fig. 109. Ingersoll Spindle (Vertical).

The vertical spindles of the Ingersoll plano-millers are so designed that the speeds of the same spindle can be changed by clutches from fast to slow and vice versa, the device employed being that of spiral gears and worm gears driving to the same spindle. The details of the arrangement are shown in Fig. 109, which represents two vertical sections taken in planes at right angles with each other.

In these figures the hollow spindle A has its bearings in a sleeve B that slides vertically in a boss cast solidly with the saddle plate C,

which traverses on the cross rail. The sleeve is adjusted by the pinion and rack shown, operated by the cross handles a, and is clamped by the screws b, b.

The rotary movements of the spindle A are derived in the first

place from the horizontal feed rod D, splined to drive the spur wheel E and the worm F. F engages with its worm G, and E drives the spiral gears through H; H being on the end of the spindle that carries the small spiral wheel J engaging with the large wheel Wheels G, H, and K all loose on their are spindles, K and G fitting with sleeves, and are therefore put into engagement by the sliding clutches L, M, and N respectively. L and N are slid along by the locking levers o, p. The worm and spiral gears are enclosed by the casings Q and R.

Fig. 110 gives a vertical section of the spindle details of a massive double-headed machine of the planer type by Messrs John Hetherington & Sons Ltd.

The cross slide is seen at a enclosing the two feed




Fig. 110.—Hetherington Spindle (Vertical).

screws B. B, one for each head. C, C show operating dogs, adjustable along the feed rod, by which, through clutches and levers, the screws B, B are tripped. The rollers by which the friction of the carriage is lessened when profiling, run on the lower flange of the cross

slide, one being shown at D. The take-up strip E, of gun-metal, is on the top flange. The milling spindle on each head derives its motion from the horizontal shaft r. A nest of bevel wheels with spurs connect shaft and spindle, and a clutch, moved to right or left by the lever G between the bevels on the shaft F, effects The driving spur pinion is on the crown bevel. driven spur II drives the spindle J through an intermediate sleeve R, which runs in the bearing L. The object of this device is to relieve the spindle of strain due to the pull of the belt. If the wheel H overhanging its bearing had no such aid, the pressure of driving would cause the spindle to wear the bearing to one side. M is the vertical feed screw operated by bevel wheels above, driven from a horizontal shaft. The screw runs in a gun-metal bush in the bottom spindle bearing N. Wear is taken up by lock nuts r and similar nuts below. The arbor of fits with a taper of 1 in It is secured with the tang and screwed cottar seen. jaws engage the spindle end to give a positive drive. A support or stay to the lower end of the arbor is included, seen at R. This carries a gun-metal bush for the arbor end, tapered 1 in 6, and the bush has adjustment for wear.

The three or four-spindle milling machines of the planer type are admirable tools for a large class of work hitherto done on the planer. They ensure the correct tooling of three faces at right angles without re-setting the work, and using face cutters with inserted teeth, they remove material rapidly. If sufficient care is taken they will also effect fine finishing cuts accurate enough for all the ordinary run of engineers' work, such as faces against which attachments are to be bolted, the feet of brackets, the ends of distance pieces, and specially that class of work in which ends and edges or surfaces and edges have to stand at tight angles. They are also admirably adapted for tooling two independent sets of work simultaneously when there are two vertical spindle heads and two horizontal ones. The utilities of these machines, though recognised more than they were three or four years ago, are not appreciated as they might be.

The space available for work set on the plano-milling machine is not so large as that on the beds of the rotary planers, Fig. 111, with traversing heads. The space is limited in the first by the capacity between heads. In the latter the work may cover the area of the



Fig. 111.—Rotary Planer.

table, and extend much beyond it if necessary. The difference is analogous to that which exists between the limitations of the ordinary planing machine and the large dimensions which can be

got upon the beds of the vertical planers and of the edge planers. The classes of work, therefore, for which the two machines are specially serviceable are different. Each can be used for fine tooling. But the ending machines are frequently employed for jobs which would otherwise be done on the plate-edge planer, or with a cold saw, or in the lathe, or with a vertical planer—such work as squaring the ends of beams and girders, facing column ends, ends of standards, and engine and machine framing of various kinds, besides tooling pieces arranged in series on the bed.

CHAPTER VI.

SPECIAL MACHINES.

Special Machines for Gear Cutting, &c.—For Spur and Bevel Gears—For Worm-thread Milling—For Hobbing Worm Threads—For Fluting Twist Drills—Three-Spindle Machines--Cam-cutting Attachments--Profiling Mechanism - Milling Attachment for Planer—Machine for Elliptical Holes.

Special Machines for Gear Cutting, &c. — Figs. 112-119 illustrate a machine by Brown & Sharpe for cutting both spur and bevel gears. In the main the machine is built on the pattern of the spur gear cutters by this firm, with the difference that the cutter slide is made to angle. This example is selected as representing a modern high-class fully automatic machine, which embodies the following valuable features:—

Stiffness of build, a large number of changes of speed and feed, to be noticed presently. Protection of the working parts. Support afforded to the cutter spindle. A high speed of positive indexing, which, with the return of the cutter slide is independent of the speed and feed of the cutter. The elevation and lowering of the work spindle slide by power in the largest machines. The drawings, with the following brief remarks, will be readily understood.

Fig. 113 is a rear elevation of the machine, Fig. 114 a right-hand end elevation, Fig. 115 a plan view. A, the base, is fitted as a cabinet, and B, the pillar, is fitted with shelves for gears or tools. A carries the cutter slide C, D; D being adjustable on C to any angle to 90°, by means of a quadrant rack, so that it is suitable either for cutting spurs or bevels. The slide C has longitudinal adjustment by hand through pinion and rack, and power feeds and quick return operated by gears enclosed. The motion is communicated at any angle of the slide D, through the splined shaft E, by means of bevel gears at both ends, enclosed. The pulley F, driven from the countershaft, drives the cutter spindle, and the pulley G, the cutter slide,

through gears and a quick pitched screw, so making the movements of slide and spindle independent of each other.

The cutter spindle has ten changes of speed, ranging from 30




Fig. 112.—Automatic Spur and Bevel Gear Cutter. (B. & S. Manufacturing Co.)

to 163 revolutions per minute obtained through change gears. Fig. 116 gives a section through the spindle and its bearings, with the details of the method of adjusting it.

The cutter has sixteen changes of feed, ranging from 0 012 to

0.235 inches per revolution of spindle, in geometrical progression. These are obtained through change gears enclosed in the box H. When cutting bevel gears there is a cross slide which can be moved to bring the cutter to either side of the centre. The mechanism for this movement is seen at J, Fig. 115, while the vernier is seen in Fig. 118.




Fig. 113.—Rear Elevation of Gear Cutting Machine.

The work spindle head K is adjusted by the hand wheel, Fig. 115. The thrust of the elevating screw is taken by ball bearings. A graduated dial reads to thousandths of an inch. The spindle is hollow, with a 1½-inch hole, and tapered at the front to No. 12 taper. It is threaded to receive a face plate or other fixture. An overhanging arm M affords support to the outer end of the arbor. Large gears are supported by a rest behind the rim opposite the

outter. The worm wheel, enclosed in the casing N, is driven by a vertical worm, and the indexing change gears provide for cutting all numbers of teeth from 12 to 50, and all numbers from 50 to 400, excepting prime numbers and their multiples. The indexing mechanism is shown in Fig. 117. Fig. 119 is an indicator for setting the cutter.




Fig. 114. -Right-hand End Elevation of Machine.

Worm-thread Milling.

- A worm - thread milling machine, by J. E. Reinecker, is shown by the accompanying Figs. 120 and 121. There is no doubt that the milling of worm threads, though a comparatively recent innovation, will in time displace the single-cutting lathe tool for that class of work. cutter, of rack section, gives no trouble with regard to clearing itself. The present demand for multiple-threaded worms is the opportunity for the development of machines of this class, which are now made in Great Britain, the United States, and Germany.

As the cutter in the Reinecker machine is fed longitudinally in relation to the worm blank, while the

worm is rotated, this involves two distinct sets of mechanism, each with its change gears. Figs. 120 and 121 show the arrangements of the machine as a whole.

The arbor, indicated at a is carried in the headstock A and tailstock B. The spindle is made hollow, in order to take the axles of worms, when in one piece with their worms, so that they can be gripped and supported close to the threads. The cutter is held on the arbor b, the bearings of which are carried on the

plate C, adjustable for angle on the face of the head D. The blank is rotated from the cones E, through the two sets of worm gears F,




Fig. 115.-Plan View of Machine.




Fig. 116. -Section through Cutter Spindle, showing Method of Adjustment.

and a. The shaft a, that carries the worm that drives a, on the headstock spindle, also actuates the set of change gears a, whence the correct longitudinal feed is imparted to the head a, which

carries the cutter arbor. The due proportion or ratio between the diameter and the pitch of any worm being milled is thus obtained by changes in the gears H, the worm drive being constant from the




Fig. 117. -- Indexing Mechanism.

stepped cones E. Changing the belt on the steps of E does not, of course, affect the relations of the worm gears and change wheels.

The rotation of the milling cutter is effected by an independent




Fig. 118.—Vernier and Screws for adjusting Cutter Spindle.

set of mechanism, derived from the cones J. course of the motion can be traced from J, through bevels and spurs to the last spurs, K and L. K, it will be noticed, has the axis of its shaft central with the swivel plate c, and L runs in a bearing in a boss projecting inwards from the plate c, so remaining in gear with K at all angular positions of the cutter arbor b; L drives a spiral gear d through the

plate, which engaging with another c, on the arbor b, rotates the latter at four variable speeds obtained from the cones.

There is an indexing device shown at M, over the headstock

spindle, for obtaining settings for multiple-threaded worms. This has been abandoned on later machines in favour of direct indexing with holes and index

peg.

Hobbing Worm Gears.—A remarkable machine, Figs. 122 and 123, by the same firm, for hobbing worm gears by the method just described, also cuts both spur and spiral gears either with a hob, or with an ordinary cutter. Its movements are auto-




Fig. 119.-Indicator.




Fig. 120.-Worm-thread Milling Machine.

matic, and the results theoretically as well as practically perfect. The worm wheel blank to be hobbed is put on the arbor A, and

the hob (which is fed in endwise) goes on the arbor B. The mechanism is designed to effect the relative movements required. The distance from the centre of the hob to the centre of the blank remains unchanged from start to finish of the operations. The rotation of the hob and that of the blank are so proportioned as to be exactly the same as those of the wheel and its worm. The longitudinal feed may be varied, and does not affect the pitch, or the diameter, and number of teeth in the worm and worm wheel. The driving mechanism is actuated from the




Fig. 121. - Worm-thread Milling Machine.

cone c, belted from one of the countershafts. From it, through the change speed gears D, the vertical splined shaft is actuated, and from this the rotation of the hob is effected by the pinion F, and wheel G, while the rotation of the master wheel H, and from it the blank, is imparted by a set of change gears (not indicated, but situated behind wheels F and G). The mechanism of this rotational movement is carried through the centre of the carriage to change gears K, at the opposite end of the table. The feed, or longitudinal travel of the table J, is derived from

the feed cones L, driven from a separate countershaft. From L the vertical feed rod M is driven through the worm and mitre gears seen in the figure, at variable rates, and thence the horizontal feed shaft N. The latter operates two sets of





Fig. 122.--Universal Gear Cutter.

worm gears 0, 0, one for longitudinal traverse of the table J, the other for the cross traverse of the carriage P. Both sets of worm gears are clutched for throwing out and in. These movements are capable of reversal through the dogs a, a on

the level actuated above the worm shaft N, which through the level setting actuates the clutch of the bevel gears Q. The object of the change gears K, is to add the proper rate of rotation to the bank on the arison A, to compensate for the forward motion of the



1. , 173 Universal Gear Cutter.

some star a ked peculiarity of this machine, necessive some series for at a tangent to the blank, and being two are which drives the master wheel it, must be fed at a law of which drives the bearings are carried on the slide stars of the movements are the same as those existing

between the hob and the wheel which it cuts, and the master wheel and its worm. The rates of rotation of the hob and worm are similarly proportioned.

For cutting spiral gears, the slide J is mounted on a swivel table, a special milling attachment being added. The dividing is done by hand by means of a dividing plate and change wheels. For cutting spurs, the carriage P is traversed towards and from the column.




Fig. 124.-Flute Milling Machine.

Fluting Twist Drills.—Though the flutes of twist drills can be cut on a universal machine, only one flute can be done at a time. A special Reinecker machine, designed for cutting both flutes simultaneously, is shown by the illustrations. In it the drill is fed forward and rotated between cutters, the centres of which move apart to give the increase of thickness from point to shank that is necessary to strength. Relieving as well as fluting is done. The machine shown is the larger size of two made, its maximum capacity being a 4-inch drill, 40 inches long. The following is a description of the principal elements of the mechanism:—

Fig. 124 illustrates the machine in side view parallel with the drill. Fig. 125 is a front-end view looking towards the drill. The bed is made in two portions, standing at right angles and bolted together, one part carrying the drill and feeding arrangements, the other the spindle head.

The drill blank A is carried in a chuck B, which may have either a Morse taper, as shown, or a straight shank, and it is fed forward and rotated by a long screw c, splined to permit of its




Fig. 125.—Flute Milling Machine.

endlong movement through its operating gears. The worm gear D feeds, and E rotates, and the rates of both are controlled by the change gears, indicated by the dotted circles, which establish the desired relation between the pitch of the feed screw c and the lead of the spiral of the twist drill. Rough adjustments of the forward and the rotary motions can be effected by the handles seen. A stop a can be set to gauge the termination of the cut.

The fluting cutters are seen at F, F. They are carried on arbors

which fit by taper shanks in the spindles G, carried in long sleeves in the head H. The tail supports b, b are fitted in slide ways to permit of their movement and setting for removal and insertion of cutters. The swivel heads are adjusted for angle on the headstocks J, J, on which they are set with tee-headed bolts.

The angle, of course, varies with drills of different diameters.

The spindles G have a small amount of vertical adjustment on a feather seen in the section, and they are driven on the sleeve, the spur wheel being keved thereon to avoid direct pull and wear on the spindle. The drive to K is readily seen in Fig. 125, coming from a spur wheel on the same spindle as the stepped cones, thence through bevels to the spur that gears with K. The adjustments of the heads J, J towards or from the drill blank are effected by the hand-operated screws L, L, working through nuts in the base, the rectilinear movements being controlled by vee'd edges. Divisions on plates on the base of each head permit of making fine adjustments, and micro-




Fig. 126.—Three-Spindle Machine.

metric divisions are effected by the discs and pointer seen at d, d. After the cut starts, the heads are gradually separated by mechanism that is only partly indicated on the drawings, but which is derived from the rod m lying beneath and parallel with the screw c. This actuates a pinion ϵ engaging with a

Three-Spindle Machines.—The Kempsmith Manufacturing Company have a fitting to their pillar and knee machines which permits of the simultaneous operation of three vertical milling spindles. The particular application of this device is the milling of the tee slots in machine tables.

The drive is effected by an extra or auxiliary slide carried between the headstock and the vertical brace in front of the knee. This fitting carries a horizontal spindle in line with the main spindle. Three angle wheels, capable of adjustment along it, drive three similar angle wheels on vertical spindles, which have their




Fig. 128.—Development of Surface of Valve, cut on Three-Spindle Machine.

bearings in slides adjustable along the face of the auxiliary slide. The lower ends of the spindles carry the milling cutters, which, after being adjusted for centres, are driven simultaneously through the angle wheels. The work is bolted to the table and so traversed under the cutter.

Figs. 126 and 127 illustrate a vertical three-spindle machine by the Beaman & Smith Company for duplicating small pieces, and Fig. 128 illustrates the development of the surface of a valve so cut. The periphery of the valve was divided into degrees, and the location of each cutting was fixed by a graduation of the hand wheel A; shown on the fixture in the machine. There is a driving spindle B,




Fig. 129 - Plan View of Cam-cutting Attachment.




Fig. 130.—Front Elevation of Cam-cutting Attachment.

at the left of the machine which carries a point that runs over the master valve, and on three blanks placed under the operating spindles the cutting is performed simultaneously. This fixture can be removed from the table and any other substituted. The mechanism of the three-spindle machine itself is sufficiently clear from the drawing.

Cam-cutting Attachments.—A cam-cutting attachment by the Brown & Sharpe Manufacturing Company is shown in Figs.

129 - 131. Ιt is mounted on a base A. which is bolted to the table of the machine. A carries a sliding table B, which is capable of longitudinal travel, and upon which the head and footstock shown are bolted. The spindle in the headstock is driven by the worm and worm wheel c. seen at the right-hand end, the worm wheel being driven by the hand wheel p. The handle a of this wheel can




Fig. 131.--End View of Cam-cutting Attachment.

be drawn out to give sufficient leverage for turning heavy work round. The outer face of the worm wheel has two tee slots b, b, at right angles with each other, against which the former is bolted. This is of flat steel, or cast iron, and has its edge shaped to suit the cam to be cut. At the end of the slide B is a vertical guide F, in which slides a rack, having a hardened steel roll at its upper end that comes in contact with the edges of the former. The rack engages with a pinion H, turning on a stud in the slide B, which pinion is also in gear with a horizontal rack, attached to the base A. Hence when the vertical rack is forced down-

ward, the slide B is moved to the right, and when pressure is removed from the rack, the slide B is pulled to the left by the weight J, and the vertical rack is run up. The roller is therefore always held in contact with the former. And also when the work is rotated by the hand wheel D, the former in turning with the hand wheel produces the longitudinal movement in the slide.

When a cam is being cut on a cylinder, the arrangement is that shown in the figures. But when a face cam is being done, the headstock is set round with its spindle parallel with that of the machine. The vertical rack and guide F being carried round with




Fig. 132.—Cam-cutting Attachment.

the head, the rack then engages with the pinion κ , Fig. 129. This pinion is fast on a shaft L, which carries on its inner end a pinion M, that engages with the horizontal rack in the base A, operating the slide B, as already described, when the headstock is at right angles with the machine spindle.

An attachment for cutting cams on the machine table is shown in Fig. 132, an example by the Cincinnati Milling Machine Company. It is shown at work on a face cam. The arrangement comprises a mandrel to carry the work, and the master or former-cam behind. This mandrel is revolved at a suitable speed, and, by means of the weight seen to the right, the entire slide is pulled constantly sideways, so that the master-cam presses against the roller.

Profiling Mechanism.—The profiling mechanism of a machine by Messrs Webster & Bennett is illustrated in Fig. 133, the piece being a cycle fork crown A. The first Figs., 1 and 2, show it attached to the cam plate B, and just commencing




Fig. 133.—Profiling Mechanism.

its revolution in the direction of the arrow. The cam plate B is held against the roller in the ordinary way, until the position shown in the next 3, is reached, at which point the cam is assisted by a roller at the rear of the automatic head, in the manner illustrated in 4. An inclined bracket C is bolted

į

to the bed, against which the roller pushes. The result is that as the bracket will not move, the whole head is pushed over bodily in the direction of the arrow. This has the effect of




Fig. 134.—Adams' Planer Attachment.

drawing the cam out of the awkward position of the previous figure, and allow it to proceed on its revolution, the large wheel being mounted on a friction cone to permit it to slip slightly in the operation, the lost motion being taken up in a division plate,

the small holes in which are indicated in the last diagram 4.

Milling Attachment to Planer. — The illustrations, Figs. 134 and 135, are those of an application of the milling head to the planer, by the Adams Company, the drawings showing the sectional details of the spindle drive.

When in use, the ordinary Fig. 135.—Bracket for Tail End of Arbor, tool box of the planer is run

to the end of the cross slide, out of the way, and the milling head takes its place, being adjustable on the cross rail. The spindle-head A swivels by an annular tee groove on the slide B, so that either vertical, horizontal, or angular milling can be done. There

1

is also a bracket to afford support to the tail end of the arbor in horizontal milling, Fig. 135.

In Fig. 134, c is the driving pulley, which is operated from a separate countershaft, distinct from that of the planer. As the axis of the pulley stands at right angles with that of the cutter spindle, the direction of drive is not affected by the angling of the The length of the belt is, but the slack is taken up by a weighted pulley. The drive to the spindle is through worm gear D, the worm being of hardened steel, and having ball-bearing thrust collars, and the worm wheel of bronze, enclosed in an oil The spindle is tapered at both ends, so that cutters can be used at either end. Or, when two heads are used, the cutters can be placed to right and left. The inner bearing sleeves are of bronze. One has a flange at its inner end, and the other a square thread to receive a steel ring at that end, by which end play is taken up. The sleeves have a longitudinal slot, which is fitted with a compressible metal at the outer end, but retains the oil elsewhere. The outer sleeves, of cast iron, are split, and are threaded at the outer ends to receive the ring nuts seen. The outer sleeves fit the bore of the casting, and are fitted to the inner by a double taper. Wear is taken up by turning the ring nuts on the outer end of the larger sleeves. countershaft has two belts for different speeds. As the table of the planer must be driven at a much slower speed for milling than when planing, the planer countershaft is driven for milling through worm gear, the worm wheel being on this shaft. The worm can be thrown out by a lever, and when out, the table can be returned at the quick planer speed. made variable through a friction disc, the roller being on the worm shaft. Feeds up to five inches per minute are thus obtainable.

Machine for Elliptical Holes.—Fig. 136 illustrates a milling machine for cutting elliptical or round holes in boiler plates, made by Curd Nube, of Offenbach-on-Main, Germany.

Cutting the manholes in boilers and boiler plates, and round holes in boilers, is still in many cases effected by hand, with hammer and chisel, or with apparatus in which an analogous process is employed. The machine permits of cutting such holes automatically, by means of a rotary cutter with teeth of sufficient length to enable it when working on plates, or the periphery of cylindrical boilers, to reach through the whole thickness of the material to be cut. The method of operation of the machine is as follows:—

A spindle b, carrying a rotary cutter c, is driven from an overhead countershaft, through suitable gearing a, o. The bearings of the cutter spindle b, and the intermediate shafting d d, are so arranged that the cutter c can be moved both vertically and horizontally in any direction. The cutter spindle is carried in an




Fig. 136. -- Milling Machine for Cutting Elliptical or Round Holes in Boiler Plates.

arrangement i in a circular guide, which, with the guide, can be shifted and fixed in position on a plate f. This device permits the cutting of circles or manholes of varied sizes. The motion of the cutter c is obtained by means of an eccentric g,g with adjustable throw; moved by a spindle h, while a ring i to which the plate f carrying the bearing c of the cutter spindle h is fixed, revolves round this eccentric, in the opposite direction. This rotation in opposite directions of the spindle h of the eccentric g,g on the one hand, and the ring i with the plate f fixed to it, and the cutter c on the other hand, is obtained by worm wheels k.

and worms, and gears l, l. This arrangement, and hence that of the cutter c, is driven from a double-throw eccentric which receives its motion from the driving shaft of the machine, so that when the latter is thrown out of gear this movement is also stopped. The double-throw eccentric m, m for circular or elliptic motion is itself variable as to stroke, so that small holes can be cut in a shorter time, larger ones in proportion with the longer travel in a longer time.

The machine is arranged for 100 mm. (31% inches) difference of diameters, but it may also be adjusted for other differences. Ovals can be cut up to 450×350 mm, and circular openings up to 400 mm, diameter. The time within which a normal manhole, 12 in. × 16 in., can be cut in an 18-20 mm, boiler plate is about 13 to 2 hours; a 10-inch circular hole can be cut in 3 to 1 hour. To do this by hand would take from 6 to 7 and from 4 to 5 hours respectively. All that is required before cutting is to trace a cross representing the major and "minor" axes of the ellipse on the piece of work, and to drill a hole at the end of one of these axes, to give the cutter a starting point. The machine as shown in the figure is fixed to the wall, and the pieces of work go on the ground. The weight of the machine is 1,000 kilogrammes.

CHAPTER VII.

CUTTERS.

Differences in the Teeth of Milling Cutters and Single-edged Tools—Size of Cutters and Spacing of Teeth for Roughing and Finishing Cuts—Rake and Clearance - Spiral Form—"Handing" of Spiral -Compensation for Wear—Attachment to Spindles—Inserted Tooth Cutters—Various Examples—Manufacture of Cutters—Steel—Hardening—Cutting the Teeth—Examples—Grinding and Sharpening—Examples—Clearances—Form Grinding.

Differences in the Teeth of Milling Cutters and Single-edged Tools.—It is not necessary in this chapter to give drawings of all the numerous forms of milling cutters made, even if the scope of this book permitted it. Illustrations of the principal kinds occur in this chapter dealing principally with the tooth forms, and the care of the cutters generally.

In several respects the forms of the teeth differ from those of single-edged tools. They are generally much weaker, approaching in most cases to the form of saw teeth, namely, triangular. seldom have any front rake, nor ever more than a very slight amount, while most single-edged tools have several degrees of front or top rake. The amount of clearance is generally the minimum of that present in single-edged tools. The spiral or twisted tooth adopted on all edge mills, excepting those of about an inch in width and under, has its analogue in the diagonal or shearing devices embodied in other cutting tools. The mills with staggered teeth, whether solid or inserted, are in effect assemblages of single-edged tools. All milling cutters except the last-named differ from singleedged tools in their fine cutting. They are not in any sense roughing tools, though the term "roughing cuts" is used to distinguish the relative difference between a first and a finishing cut. they do not and cannot penetrate deeply, there results one of the chief difficulties incidental to these cutters, namely, the inefficiency of a mill which is not ground accurately and supported on a stiff arbor carried in a stiff machine. If the depth of cut is divided between the number of teeth, it is clear that the minute fraction apportioned to each tooth may well exceed the degree of radial inaccuracy resulting from indifferent grinding. How fine this inaccuracy may be is evidenced by the revolution mark visible in all milled work.

The revolution mark is due to the impossibility of grinding teeth exactly alike, because the grinding wheel itself becomes smaller as the work proceeds. Though the difference is extremely minute, it is enough to account for the effects seen.

Size of Cutters and Spacing of Teeth.—The size of milling cutters and the spacing of teeth are two questions that arise first for settlement. With regard to the first, the smaller cutters should generally have preference over the larger, because their traverse is less for a given length of surface cut. The smaller cutter has to move a smaller distance than the larger, and therefore occupies less time in reaching to, and receding from the work.

Messrs Brown & Sharpe state that a difference of half an inch only in diameter has been found to make 10 per cent, in the cost of the work in their practice. In some cases a small cutter is objectionable, as sharpening the edges of milling cutters with a small wheel produces concave edges, but that may be got over by angling the wheel.

The number of teeth in a cutter is now nearly fixed in practice by pitching them at from 4 inch to 3 inch apart. Early cutters were pitched too finely, with the result that crowding and choking occurred. It is well open to question now if coarser pitching than is usual would not be advantageous in roughing cutters and in these for brass, though the practice is to use the same cutters for all metals and alloys, and for roughing and finishing.

Mr Addy's rule for the pitch of cutters from 4 inches to 15 inches diameter is—

Pitch in inches = $\sqrt{\text{diameter in inches}} \times 8 \times 0.0625$.

In another method, from a German source, the thickness of tooth is first obtained, and thence the number of teeth and pitch, thus:—The diameter, D, of the cutter is first obtained. This

depends upon the work to be done, and should be as small as possible. The thickness of teeth, t, should then be determined from the following formula that has been derived from practical experience:—

 $t = \frac{D}{10} + c.$

For cutters up to - 2 inches diameter $c = \frac{3}{16}$ inch.

In order to determine the number of teeth, the nearest whole number to the quotient of $\frac{3\cdot1416 \text{ D}}{t}$ should be taken. Thus for a cutter of 4 inches diameter we should have 24 teeth, and this would cause a modification of the calculated thickness of the tooth from 0·55625 inch to 0·5027 inch.

Spacing of Teeth for Roughing and Finishing Cuts.—In the spacing of the teeth of milling cutters sufficient allowance is not made for the difference between roughing and finishing cuts. It has been demonstrated that coarsely pitched cutters absorb less power than those of fine pitch. Tests were made in a Cincinnati motor-driven machine on two cutters of the same diameter, but one having twice the number of teeth of the other. The results are given in the table below:—

		Finely Pitched Cutter.	Coarsely Pitched Cutter
Diameter of cutter		4 inches.	4 inches.
Number of teeth in cutter -	•	30	: 15
Width of cutter		is inch.	1
		ig men.	i3₁ inch.
Depth of cut	•	، ن	, ,,,
Number of teeth in contact with	metal -	· a	1
Volts		110	110
Amperes		13.2	10:5
Feed of table		0.134 inch.	: 0·134 inch.
Revolutions of cutter per minute		40	40
Thickness of chip per tooth	٠	0.0044 inch.	0.0088 inch.

The conditions, it will be noted, were precisely alike in respect of size, speeds, feeds, &c., only that while one cutter had 30 feeth, the other had 15. But the 15-toothed cutter took a chip 8,000ths of an inch in thickness, while the 30-toothed one took a chip of only half that thickness. But the latter required 13% amperes, while the former took but 10% amperes, a difference of about 22 per cent, in favour of the coarse-toothed cutter. As the 30-toothed cutter had 5 teeth always in contact with the work, while the other had only 3 teeth in contact, the differences above-named were due evidently to the better clearance afforded to the chips.

The case is therefore analogous to the coarse pitching of the inserted tooth cutters and those with staggered teeth.

Wide spacing is favourable to heavy feeding, because the chips escape freely, so that the advantage both of deep cutting and of free cutting is secured. Finishing cuts demand fine-toothed cutters to leave a smooth surface. Hence, though it is not usually done, a difference should be made in cutters for roughing and finishing when the amount to be removed in the first cut or cats is considerable. For much work, where the total amount to be removed is small, the distinction is of no importance. But when milling comes into rivalry with the planer and shaper for heavy work, the difference ought to be made if the best results are to be so ured.




Fig. 137. - Coursely Pitched Cutter for Gun-metal Fittings.

Fig. 137 shows a cutter designed by Mr James Vose, and used in the shops of Messrs Meldrum Brothers Ltd. for milling gun-metal tatings. It will be recognised as simply a series of brass scraping tools, very coarsely pitched, to leave room for the cuttings to clear. Mr Vose says that more than seven feeth only seems to produce ascless rubbing on the finished surface.

Rake and Clearance.—Angle of front rake is not generally imparted to the teeth of cutters. It is found that for ordinary duty radial teeth cut as well as those with rake. Undercut teeth

The state of the s

ntil the machine stopped. The feeds carried to in 14 meb per unhete to 0.16 meh per inhate and there was no perceptible slip till heef light.

The results of the test were somewhat complicated, but they tailor to show any double bady artigor one to the everanother. The general inclusions seemed to be that the advantage cest of with the Saders of teeth, with a big feed, and dietachal teeth gave better results with a the feed.

A very slight rake is however, given the some ordinary cutters, ranging from the U. the latter for wavegit from U. so were a stouch, as a lead open in some uniters, were believe to be given a finite table.

The angle of leader of palaether that are maly greating the teachines of the attens) ranges from 3 to 3, the latter securious used habitually at these. This has satting in the grinding reachine by the

to the second of the problem of the second o

Plants of cells generally go on arbors. Fig. 138 is from a shop

drawing giving a section of a cutter of this kind, with Mr Brayshaw's remarks thereon below.

"According to this drawing, it has been determined that if the error in the thickness of a ½-inch cutter does not exceed one-thousandth (0·001) of an inch, it is good enough. This is clearly shown, and the grinder must adhere to the limits given, but must not waste time in making every ½-inch cutter to within one half-thousandth (0·0005) of the nominal size.

"Again, it has been found that about one-hundredth (0.01) is a reasonable allowance for cleaning out the turning marks on the sides after hardening. It is, however, quicker to grind off a few extra thousandths than to turn them off, and the turner must keep within the limits—ten to fifteen thousandths above $\frac{1}{2}$ inch $\binom{0.515}{0.510}$. He has no excuse for leaving too much or too little for grinding, nor yet for wasting time by taking a cut of two-thousandths (0.002) off the side.

"It is shown that the actual diameter is not important, and the turner has a limit of one-hundredth (0.01) of an inch, which he must keep within. No grinding size is given here, which means that the grinder must just clean out the turning marks.

"The drawing shows that the side recesses may vary in diameter by one-tenth (0:1) of an inch. The clearance each side is stated as ½, and it is essential that this shall run out to the extreme tips of the teeth."

Messrs Brown & Sharpe give about five one-hundredths in one inch for clearance for mills that have to cut grooves. That is, a grooving mill should be about one-hundredth of an inch thinner at one inch from its circumference than it is at the edge. The firm gives a limit of two-thousandths in thickness to their grooving mills. Mr Brayshaw's ½ on each side causes the cutter to become two-thousandths (0002) thinner when ¼ inch has been ground off its diameter. More clearance would cause it to lose its proper thickness too soon. Extra clearance might be given to cutters when the width of grooves is not particular, or when they are used only for roughing.

Spiral Form.—The spiral form given to all but the narrowest axial mills varies from about 15° to 40°. Its object is to reduce

the stress on a tooth by causing it to cut in detail, in a shearing fashion. Its value is more pronounced in the fibrous metals, as wrought iron and mild steel, than in cast. In ordinary axial mills it may be low or high in amount, and right or left handed in direction. But in end mills, and those which cut profiles, conditions come in which fix these things arbitrarily.




Fig. 139. Fig. 140. Fig. 141. Examples of End Mills.

If cutters operate by their sides only, the inclination may be large, ranging up to 30° or 40°, which in wrought iron gives a marked advantage. But in end mills this should not exceed 20°, because the teeth would be too keen, and become broken, due to the large angle of front rake imparted to the end teeth.

"Handing" of Spiral.—The question of which hand the flutes in a milling cutter should run may seem of little moment. In the case of end mills going deeply into the work it seems best that the flutes of the sides should be right handed, like those of twist drills. These then tend to draw the chips out of the groove, while left-

hand spirals would tend to force them down towards the cut.

The handing of the twist is important in certain cases. Fig. 139 is a right-hand spiral with right-hand teeth, Fig. 140 is a left-hand spiral with right-hand





Fig. 142.—Mandrel Set for Turning Diagonal Joints of Cutters.

teeth. The differences in the two in working are these:—Fig. 140 is only suitable for edge milling, since the end teeth have negative rake, and the direction of twist tends to push the cutter into its socket, and the work down to the table, and to thrust the cuttings downwards. But for use as an end mill, the form in Fig. 139 is correct, because the teeth have front rake, and the tendency is to

draw the cuttings upwards. For general end milling, the cutter in Fig. 141 is more often used, giving no trouble of any kind.

Compensation for Wear.--When it is desired to make compensation for wear in side mills, they are jointed diagonally, or the








Fig. 144.--Shell Cutter Arbor, with Nut for Forcing off the Cutter.

teeth are interlocked, or sometimes every alternate tooth on the meeting faces is cut away to make room for the teeth on the other mill. Either of these permits of the insertion of thickness slips of





Fig. 145. -Cutter held on Arbor with Nut, Arbor forced out of its Hole with a Nut.

paper or other material. Diagonal jointing of smooth faces is not open to the objection of leaving a mark on the work, which parallel flat cutters would do, if jointed. The diagonal jointing is done by turning the faces on a mandrel, Fig. 142, having two sets of centres,

one for turning the parallel faces of the cutters, the other situated at about $\frac{3}{16}$ inch out of centre, used for turning the diagonal faces.








Fig. 147.—French Method of Gripping Cutter with Parallel Shauk.

When the faces are tooled, the two portions are put together and united with a pin, the key groove is cut, and the teeth milled, hardened, and ground.

Attachments to Spindles. — Mills fit into taper sockets in their spindles, or they fit over arbors. Small mills are used in both ways, but large ones, and also the greater

number of any size employed, fit over arbors only.

Figs. 143-148 illustrate taper sockets for mills, which are nearly self - explanatory. Solid shank mills are seen in Figs. 139-141. Fig. 143 shows the common method of holding shell cutters on an arbor, using a round key to drive, and a screw, the head of which lies in a recess in the mill to secure it. In the next example, Fig. 144, a nut is fitted above instead of a plain collar. The object of this is to push off the cutter by the simple pressure of turning the nut, a feature ap-




Fig. 148.—Large Face Cutter locked with Clutch and Ring Nut.

preciated if cutters stick. In Fig. 145 a nut and washer are shown, with a forcing-off nut. Fig. 146 is Muir's coupling.

The arbor is retained in place with a screw collar, the cutter is threaded to receive the arbor, and a lock nut above holds it according to the little and the little are t

it securely. A method of holding a parallel shank cutter in a split tapered grip with an encircling nut is seen in Fig. 147. The arbor is retained by a screw on its end. In Fig. 148 a cutter of large diameter is driven from the spindle end by means of an interlocking clutch, and held with a ring nut turned with a tommy.

Very thin mills are ground straight through to fit the arbors, and wider ones are recessed as in Figs. 138 and 145. The key groove should be of half-round section, to lessen risk of cracking in hardening. Some, however, have square grooves with radii. The thinnest cutters are




Fig. 149. - Diagrams for Proportions of Key Ways.

not keyed, but pinched between shoulders. The diagrams, Fig. 149, and tables below give standard sizes of both shapes of key ways.

SQUARE	KEY	WAY.
. 4		

Size hole, 2	١	ξ to p	å to ?	[} to]}	$\left[1_{16}^{n} \text{ to } 1\right]$	1_{15} to 17	11% to 2	2½ w 2]	2,% to :
Width, B		.32	1	5 52	i ² 6	}	15	3	7 1 %
Depth, C						ļ			
Radius, R		454)	030	.035	-040	050	1060	.060	4)660

HALF-ROUND KEY WAY.

	Size hole, A	₹ to §	11 to 13	$\xi \text{ to } L_{\mathcal{V}}$	14 to 17a	13 to 2	2^{1}_{16} to 2^{7}_{16}	2½ to 3	
•	Width, B	. !	1 %	4	16		រ ⁷ ឧ	, i	
1	Depth, C		34	1	ډ د.	1 ⁸ 6	:75		
ì						' -		! !	

Inserted Tooth Cutters.—The growing employment of the inserted toothed cutters for face mills has done as much for the extension of the practice of milling as perhaps any other single improvement or innovation. The terms face milling and rotary

planing are both applied to this practice. The latter is the more suitable term, because it distinguishes between the single cutters inserted in a disc, and the end milling as done with teeth on the ends of solid cutters.

The ordinary solid mill with finely pitched teeth is never a roughing tool in the sense of removing material in quantity, its depth of cut is far too limited. It roughs, of course, but always in a depth measured in hundredths of an inch. But the coarsely pitched inserted cutters are narrow planer tools with penetrative capacity, and they therefore rough deeply when backed




Fig. 150, -- Inserted Tooth Mill.

up by machines of sufficient power. They are made and used in all dimensions from a few inches up to several feet, and on vertical and horizontal spindles. There would appear to be no limitations in reason to the size of a face mill. It fills a most valuable place in the work of roughing down, and in that rough finish which is commercially good enough, in perhaps half the volume of engineers' work done. Its

utilities lie in the facing of flanges and feet, and of the areas to which they are to be attached. It is of especial value in plates and constructional work, in facing the ends of beams and stanchions, of columns, and pipes, and the edges of plates superimposed, involving numbers of similar pieces. The front rake which is imparted to the cutters in most of these heads makes them true cutting tools, and their coarse pitching permits the chips to get away freely, which is further facilitated by the horizontal setting of the majority of the spindles which earry the rotary planers.

Fig. 150 shows a common and good form of inserted tooth cutter. The body is split, and the cutters are fixed by taper

pins driven into every alternate spacing. In various modifications this device of tapered tightening pins is adopted.

A widely used method of holding the blades is shown in Fig. 151. The blade A is ground on the sides, on a magnetic

chuck. The bush to is turned parallel, and has a flat milled on it at an angle with the centre line. This bush, which fits in a recess, as shown, is simply a wedge, and is knocked in. There is a screw of to prevent it becoming




Fig. 151. - Inserted Tooth Mill.

loose. A second screw b the patent of Mr W. S. Baskerville, is shown for adjusting the blades sideways.

Fig. 152 shows the construction of a large inserted tooth catter, nine inches diameter, by twelve inches long. The cutters are




Fig. 152. -Inscreed Tooth Cutter.

inserted in diagonal grooves, and secured with set screws pressing a wedge piece against their faces. The cutting faces are radial, and of helical shape. This was produced after the fixing of the cutters in the diagonal milled grooves, the machine being geared to cut the spiral faces.

The tooth gaps are cut to alternate, and not in a spiral

fushion. Each alternate cutter was put in place, and the gaps cut at intervals. Afterwards these cutters were removed, the other alternate set inserted, and the grooves cut to come behind the teeth in the first set. The objection to cutting them spirally, as though screw-cut, is that one side of each gap would be prevented from clearing.

Fig. 153 illustrates a novel form of inserted tooth cutter made




Fig. 153.—Inserted Tooth Cutter.

by the Garrard Manufacturing Company Ltd., of Birmingham. Its main feature is the adjustability of the cutters in the head, to permit of backing off by simple The teeth A turning. have their inner ends convex to fit down in concavities in the head. The latter consists of three pieces, the body or stock B, and the caps C, C, and the latter are clamped against the teeth by the nuts on the mandrel that secure the head. Conical

lugs a, a are provided on the sides of the teeth which enter into annular recesses in c, c, tapered on the outer edges to tighten

the teeth by the screwing up of the clamping nuts. When the caps c, c are slackened, the cutters can be turned through a small arc in either direction, to the extent of the difference in their thickness, and the width of their grooves. The cutters are pushed over to one side, and clamped to be turned. They are then removed, and hardened. When replaced they are moved over to the opposite side, which gives the angle required for cutting, when they are again clamped.




Fig. 154.—Inserted Tooth Cutter.

Fig. 154 is an inserted tooth cutter of French design, in which set screws are used to hold the tool points.

Fig. 155 illustrates a German type of large cutter by the Maschinen Fabrik Lorenz. Provision is made for adjustment of the cutters by means of tapered operating screws (one of which is shown in section adjacent), and clamping is by the outer screwed ring.

Fig. 156 shows an inserted tooth cutter having front rake, used in one of the A. Herbert machines, with swivel head attachment. The fastening of the cutter is by means of splits, similar to Fig. 150.

Fig. 157 shows details of the fitting of a large cutter by the Tangye Tool & Electric Company Limited. The diameter over the




Fig. 155. Inserted Tooth Cutter.

cutter is 2 ft. 6 in. The block carries thirty-four roughing tools, 1 inch square in section, and two finishing tools, 1½ inch by ¾ inch section. The tools are inserted at an angle of 5° right hand, and are adjusted by means of ¾-inch screws, turned with a podger, inserted in a square hole, and locked with a nut. Two set screws hold each cutter firmly. A pinion rotates the cutter block through an internal ring of teeth. It is used on the style of machine shown on page 137.

The cutter of the Goliath milling machine at the Fairfield Works measures 16 feet from point to point of tool. It has fifty-

imitating the practice of burning-on. The act of casting anneals the steel, so that the teeth can be trued up after the shank of the head has been turned. Or they can be roughly ground, after which they are finished in the tool grinder in the ordinary way. They are then hardened. In some of these cutters made by Professor Sweet, 10° of face angle or rake is given in setting the cutters in the mould. It is necessary to prevent rust forming in the steel before casting. They are therefore ground bright on the emery wheel, and put directly into the mould; or preferably coated with boiled oil, or else are tinned, either of which methods effectually prevents the formation of rust. The presence of rust, even in traces, causes a blow, and prevents union of the metal.

Manufacture of Cutters.—The question of making versus buying milling cutters is often a vexing one. Cutters are not cheap, neither are the lathes, milling machines, and grinding machines by which their teeth are formed. Cutters purchased from an experienced firm are reliable. Those made by the shop tool smith and in the tool room are not always so, either as regards truth or temper. The case is much akin to that of twist drills and reamers: few small firms make their own, but prefer to buy them. Still, the making of milling cutters is work that a firm can get into gradually. Having a universal milling machine in the shop, the teeth can be cut spirally or straight; hardening and tempering should be managed in the tool room, and grinding machines are semi-automatic. Many large firms make their own cutters. The more unusual the forms required, the greater the reason why they should be made on the premises. This is the case in all formed cutters, the outlines of which are almost infinite, and large numbers of which are used in some shops. In such cases it is better to be independent of outside help, which often means delay and misunderstanding of precise requirements.

Steel.—The production of a suitable class of steel for milling cutters is of cardinal importance. It is useless to spend a lot of time on mills, and then fail through buying cheap steel unfit to stand the work demanded of it. The following tables illustrate the chemical composition of high-class steels suitable for mills:—

CRUCIBLE CAST STEEL.

]	Per cent.		
Carbon	-	-	-	-	-	1.2		
Silicon	-	-	-	-	-	0.112		
Phosphore	us	-	-	-	-	0.018		
Manganes	e	-	-	-	-	0.36		
Sulphur	-	-	-	-	-	0.02		
Iron, by d	lifferenc	e	- .	-	-	98.29		
Iron	-	-	-	-	about	98		
Carbon	-	-	-	-	from	1.0	to	1.2
Manganes	se.	-	-	-	٠,	0.10	,,	0.40
Silicon		-	-	-	:,	0.10	,,	0.25
Sulphur		-	-	-	**	0.003	٠,	0.004
Phosphor	us	-	-	-	,,	0.01	,,	0.02

Actually when steel is wanted for mills, the manufacturer must be informed of the specific purpose for which it is required, and a good price paid.

The quality of the steel cannot be judged by inspection, nor can cutters made of good or bad steel be distinguished one from the other after manufacture. The temptation to use cheap steel is due, not only to the lessened first cost, but to the lower expense of machining it. The economy of using such steel is considerable on large cutters, sometimes effecting a saving of one-third or one-half; but it should not be allowed to weigh in small ones, particularly those which have profiled edges or which are to be built up and thus involve extra work in the jointing. This is one of the advantages of the inserted types—the ability to use cutters of the best material in the commoner matrix.

After cutters have been shaped by turning, grinding, and milling they should be allowed to rest for a few days previous to hardening. If they are to be annealed, Mr Brayshaw recommends keeping an excess of charcoal near them in the furnace to maintain a reducing atmosphere and prevent risk of their becoming decarbonised.

Hardening.—With regard to the methods of heating and hardening much has been said and written, with much difference

in expression of opinion. Two or three essentials are clear—that heating must be gradual and uniform, that overheating must be avoided, that every different brand of steel needs a different temperature, that there is a best and an exact temperature for quenching a steel, that cutters of different shapes require differences in the ways of heating and quenching, and that the virtues of particular quenching liquids are of a somewhat indeterminable character. Some of these matters call for extended remarks.

A gradual heating up is one of the virtues in the process. By it risk of cracking is greatly lessened. Even though heating may be uniform throughout, yet it is better if brought slowly to that condition than rapidly. The importance of these facts is so great that it is desirable to have some precise and mechanical means of regulation instead of the old method of the forge. As the dimensions of cutters have increased, the necessity for the substitution of the mechanical for the rule of thumb has become more apparent. Hence the efforts made to utilise a liquid for heating instead of a furnace heated by air, and employing a pyrometer for registering the exact heat of the liquid or of the heating furnace. Though molten lead has been employed, there are several objections to its use. Whatever means of heating be adopted, the pyrometer is becoming a most valuable instrument for ensuring uniformity of temperature.

Overheating may be present without cracking resulting if the heat be very uniform. It is an axiom that the lowest heat which will give sufficient hardness is the best to adopt. Cracks may be detected by sand-blasting a cutter after hardening, when they will be revealed.

The question of frequency of grinding a mill is one of economical importance. The time lost is that due to changing mills in the machine with stoppage of the latter, the time occupied in grinding, and the more rapid wear and shorter life of a soft mill over that of a suitably hardened one. This is one way to look at the subject of hardening suitably done or improperly.

This, however, may be less serious than the question of hardening cutters with the least risk of cracking. It is less risky to make cutters medium hard than to make them sufficiently hard to be durable, combined with sufficient toughness to avoid risk of cracking.

Cracks are the great evils to which cutters are liable, and the larger a cutter and the more abrupt the forms of its teeth the greater is this risk. Slight distortion does not matter, because that is corrected in grinding; but cracks are fatal, and these sometimes do not develop until the first grinding is done and the skin being removed.

Risk of cracking is lessened by avoiding keen angles in the roots of the cutters. Hence, though the teeth sections may be angular, the roots should have radii. But the important work lies in the methods of heating and cooling adopted. The chief points to be observed after a suitable temperature are equal heating and the avoidance of draughts.

The temperature must be graded to suit a given brand of It may be estimated by the eye or by the pyrometer, but it should not be allowed to fluctuate. Hence the open fire is not suitable for mills as it is for single-edged tools. If employed at all, the cutters must be thrust into a tube: but a gas furnace, such as those used for case hardening, or one of the special furnaces made, is the proper thing. The work is placed in a muttle or in iron boxes, either open or enclosed in hardening mixtures. Some hardeners prefer mixtures for the larger mills, such as charred leather and charcoal pounded to the size of a pea. within which the mill is completely enclosed and kept for three or four hours at a low red heat. The mill is then quenched in a bath of raw finseed oil, being moved about rapidly to bring tresh oil into contact with the teeth, and there kept till cold. Mills with large teeth treated thus need not have the temper drawn subsequently. Smaller ones may be drawn to a light straw or at a temperature of about 430° Fahr. In this packing method, which Mr Markham adopts in preference to open heating and water quenching, a great deal depends on the quality of the leather used. The scrap shoe sole leather from factories is recommended. This should be prepared by packing in one of the hardening boxes, luted with fireelay, and put in the furnace just long enough to allow it to become charred sufficiently to be pounded up well.

Another important point in the work of hardening is to remove internal strains by slightly warming the cutter immediately after quenching. Mr Markham attaches great importance to this in all mills of over ½ inch diameter. The suitable tempera-

reposed to a which the hand cannot be held on the entropied of some of sets how are to open ecloses. The explanation is a transfer of the policy of the explanation is a transfer of the policy of the open of the allowance of the unfolder which is constructed to the catalogue of figure in the research the set of the entropy. This research is considered to the decrease of the entropy of the catalogue of the ensemble of the entropy of the en

The control of the definite, when he could be to share or introol of the control of the effect of this associately. The a beginned the really continues to sbrink with a thirteen home esset a discontants which way from some of them and be the control of the single test occasion. And suitable method of the ding therelone bessels this disk, whether done before or subsequently of the control. To the same reason all cold drag atsociating of a discontrol of the same reason all cold drag atsociating of the discontrol of the same reason all cold drag atsociating of the discontrol of the same reason and to be readed in the week of the control of the

The left and participate generally small in [44] is of the reservoir of the continuous be plunged vortically and that the continuous temperature of the conject temperature of the reservoir of t

When he are some control report all the some analogy for a first transfer of the control of the

Ones, so to done the does not contain patelly as water. We set to be a Shortel by a derivers the testic of a loss.

Within curves with lines and but stared in a stand notice of the field with veoden pins. These are frequently drops had in our emposite sides, either enclosed in employees to delocate run. Object cussings along which the man in that go care will. Cutting the Teeth.—There is often much similarity between the methods of cutting the teeth of mills and of grinding them. That is, the sectional shapes of the cutters and the grinding wheels are often identical. This only holds good, however, when a tooth space is ground entirely, and not when the tips or the faces alone are done. The following are illustrations of both kinds.

Fig. 158 is an example of a cutter with straight teeth, having its teeth formed with a cutter of the general shape seen in Fig.




Fig. 158.—Cutting Teeth of Milling Cutter having Straight Teeth.




Fig. 159.—Usual Type of Cutter for Producing Teeth.



Fig. 160. Deepening Teeth, or Cutting New Teeth with Emery Wheel.




Fig. 161. Cutter for Spiral Mills,

159. Such a cutter would be sharpened afterwards on its edges, but as it becomes worn its teeth would require to be deepened occasionally with a grinding wheel like Fig. 160, or the teeth might be cut in the first place with an emery wheel, though that is an unusual and unsatisfactory method. These are ordinary cutters, which, if profiled in section, lose their shape by regrinding. Fig. 161 shows the cutter suitable for a spiral mill with the same form of tooth.

The most valuable improvement introduced into milling-cutter practice, ranking only second to that of the development of special cutter-grinding machines, was that of making "formed" cutters. This term was given by the firm whence they emanated—the Brown & Sharpe Manufacturing Company. The advantage is that the cutters never lose their original sections by regrinding. The grinding is done only on the cutting faces. The profile forms are




Fig. 162.—Cutting Backed Off Mill having Straight Teeth.



Fig. 163.—Cutting Backed Off Mill having Spiral Teeth.




Fig. 164.- - Twist Drill Fluting.




Fig. 165.—Cutting Reamer Flutes.

maintained correctly until the tooth thickness is ground away, by the simple device of striking them from a different centre than the centre of the cutter diameter. This is now adopted, not only in the cutters for wheel teeth, but in those also for milling most profiles of irregular kind. The value of the device in prolonging the life of cutters and ensuring the interchangeability of parts is incalculable.

Figs. 162 and 163 show formed mills being cut, the first with

straight, the second with spiral teeth. Afterwards the teeth are backed off in a relieving lathe or in a rig-up on an ordinary lathe. Grinding is always subsequently done on the radial cutting face, never on the backed-off portion, and thus the sectional shape remains unchanged until the teeth are too weak to perform service.

Some special cutters are shown in succeeding figures operating on cutting tools. Fig. 164 shows the milling of a flute of a twist drill, Fig. 165 cutting a concave-toothed reamer, Fig. 166 a convextoothed reamer or boring tool, and Fig. 167 cutting tap flutes.

Grinding and Sharpening.—To go into the construction of



Fig. 166 —Cutting Fove hpped Boring To 4.




Fig. 167. -Milling Tap Flutes.

the cutter-grinding anachines would lead us too far afield. They are numerous, ingenious in design, and the results are arrived at in various ways. We are content to deal with the results achieved. Fig. 168 must suffice for illustration.

This machine provides for universal movements to perform all classes of grinding. The table is carried on a knee, which may be swivelled around the circular column and clamped at any location thereon. The table also swivels, and a head is fitted to the latter maying capacity for horizontal and vertical angling, so that the work may be presented to the wheels at any angle. All these angles can be read off on dials, so that their precise amount is known. The table travels to and from the column by means of a




Fig. 168.—Cincinnati Cutter Grinder,

graduated screw, allowing of movements of one-thousandth inch being read off. Adjustable stops limit the travel.

The head carries two wheels—a cup and a disc—which are employed according to their respective suitability for the work in hand. Two speeds are available. The table attachments, besides the angling head mentioned, include a tailstock with a spring plunger allowing for endlong expansion of work, a vice mounted on a swivel face to allow of angular movement being given to the work gripped in the vice jaws, an internal grinding attachment having a small spindle running in long sleeve-bearings and carrying a little wheel at the end. This is driven by a pulley on the spindle actuated from the overhead countershaft. A gear-cutter grinding attachment is fastened to the table, having a vertical stud to carry the cutter by its bore and a pawl to lock each tooth in




Fig. 169.—Cutter Grinding with Edge Wheel.

correct radial position. Another special device for grinding the tooth faces of form cutters takes the form of cranked centres, which overhang from the table so as to bring the work underneath the wheel, enabling the latter to pass along the radial faces. For grinding on dead centres, a loose-running pulley is fitted to the table-head, driving the work as it lies between the centres. The height of cutters in relation to the wheels is regulated by the table elevating mechanism provided with a micrometer.

The capacity of the machine is 16 inches between centres by 8 inches diameter. Face mills up to 12 inches and saws up to 24 inches can be treated.

Almost invariably cutters are ground and sharpened in one of two ways—either by passing the grinding wheel over the edges of the teeth as in common mills, or along the faces as in formed mills.

The practice of sharpening over the entire tooth space (in saw-sharpening fashion) is unusual because wasteful of time and productive of heating.

Taking the edge grinding first, this may be effected by different wheel shapes. The principal results desired after the equal length




Fig. 170.—Grinding with Edge Wheel on a Cincinnati Machine.

of teeth are a correct and uniform clearance angle, and a flat face rather than one concave.

Figs. 169 and 170 illustrate the most common method of grinding axial cutters. The only objection to this is the concavity formed by the wheel. To diminish this, the wheel is selected as large as is convenient, and so long as it does not foul the tooth above, it may be any diameter in reason. In different machines the wheel is presented differently, either in the manner shown, or vertically above. Many prefer to use a cup wheel, Fig. 171, which leaves a flat face to the edge of the tooth.

The tooth rest is an essential fitting, not only for pitching the teeth and supporting the wheel, but also for fixing the angle of clearance. After the rest, in Fig. 169, has been set to suit any one cutter, its position is not changed until the cutter is completed, but each tooth in turn comes round on it. The socket which carries the rest is provided with a wide range of movements to suit plain, cylindrical, spiral, and angular cutters. The blade is often formed of an elastic strip of steel, sometimes solid, sometimes divided as in Fig. 172. The object of dividing it is




Fig. 171. -- Catter Grinding with Cup Wheel.

Fig. 172.—Tooth Rest.

that the narrower portion can be sprung out and in from tooth to tooth, without running the rest quite clear, so saving time, and avoiding risk of missing a tooth.

The amounts of clearances on milling cutters are important. They should vary only from about 5 to 7', the first being suitable for finishing, the second for roughing. The Cincinnati Milling Machine Company gives tables by which these clearances can be obtained by the setting of the tooth rest below the centring gauge. The tables are for cup wheels, and for disc wheels, and are given overleaf.

CUP WHEEL CLEARANCE TABLE.

For setting tooth rest to obtain 5° or 7° clearance when grinding peripheral teeth of milling cutters with cup-shaped wheel.

Diameter of Cutter.	For 5' Clearance.	For 7° Clearance.
Inches.	Inches.	Inches.
1	011 = 1.64 -	015 = 1.64
8 1	.015 = 1.64	022 = 1-64 +
1 2	022 = 1-64 +	030 = 1-32
5	.028 = 1.32 -	037 = 1.32 +
3 4	033 = 1-32	045 = 3-64
į	0.037 = 1.32 +	.052 = 3.64 +
1	0.044 = 3.64	0.060 = 1.16
11	.050 = 3.64 +	.067 = 1-16 +
1	.055 = 1-16 -	0.075 = 5.64
1	.066 = 1-16	090 = 3-32
13	077 = 5-64	105 = 7-64
2 [*] i	.088 = 3.32 -	120 = 1-8
$\frac{1}{2!}$	099 = 3-32 +	1 $\cdot 135 = 9-64$
$\frac{1}{2}$	110 = 7.64	150 = 5-32
24	121 = 1-8	165 = 11-64
$\overline{3}$	132 = 1-8+	180 = 3-16
31	143 = 9-64	195 = 13-64
31	.154 = -5.32	210 = 7-32 -
33	.165 = 5.32 +	-225 = 7-32 +
1	176 = 11-64	240 = 15-64
41	187 = 3-16	255 = 1-4
11	198 = 13-64 -	270 = 17-64
13	209 = 13-64 +	285 = 9-32
71	220 = 7-32	300 = 19-64
	231 = 15-64	315 = 5-16
: 1 : 1	242 = 1.4 -	330 = 21-64
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	253 = 1-4	345 = 11-32
6	264 = 17-64	360 = 23-64
•	286 = 9-32	390 = 25-64
$\frac{2}{6}$	308 = 5-16	420 = 27-64
-1	330 = 21-64	420 = 27 - 64
$\frac{7\frac{1}{2}}{8}$	350 = 21-04 352 = 23-64	480 = 31-64
0 1	002 = 20-0 4	100 - 01-04

CUTTERS.

DISC WHEEL CLEARANCE TABLE.

Giving distance for setting centres below centre of spindle to obtain 5° or 7° clearance with wheels of different diameters when grinding with periphery of disc wheel.

Diameter of Emery Wheel.	For 5° Clearance.	For 7° Clearance.	Diameter of Emery Wheel.	For 5° Clearance.	For 7° Clearance.
Inches.	Inches.	Inches.	Inches.	Inches.	Inches.
2	3-32	1-8	41	3 - 16	17-64
21	3 - 32 +	9-64	4 أ	13-64	9-32
2Ĭ .	7 - 64	5-32	$4\bar{3}$	13-64 +	19-64
23	1-8	11-64	$\begin{vmatrix} 4\frac{3}{4} \\ 5 \end{vmatrix}$	7 - 32	5-16
3	1-8+	3-16	54	15-64	21-64
31	9-64	13-64	51	15-64+	11-32
$3\overline{1}$	5-32	7 - 32	55	1-4	23-64
$3\overline{3}$	5 - 32 +	15-64	6	17-64	3-8
4	11-64	1-4	ļ.		i

Note.—If emery wheel selected is too large, that is, if it scores the next tooth, a smaller wheel should be chosen and the centres readjusted so as to be right for this wheel.

It makes no difference if the mill is spiral. In the latter during its traverse, the teeth bed upon the rest, Fig. 173, and the




Fig. 173.—Tooth Rest set for Spiral Cutter. Grinding Tapered Cutter.

portion of the length of the spiral which is being ground at any instant is passing the cutter at a constant height, which is fixed

by the setting of the rest. The rest is also used for staggered mills and hobs. The teeth of angular cutters also receive support



Fig. 175. Grinding Side Teeth.

from tooth rests. Taper mills are treated similarly, the axis of the cutter is set to half the taper; and edge or cup wheels are used, Fig. 174.

The side teeth of cutters are ground with disc cutters, Fig. 175, with a wheel as large as possible without fouling the tooth above. Or frequently the wheel is set vertically over the cutter, with the axis of the latter vertical instead




Fig. 176.—Grinding Side Teeth with Cup Wheel.

of in a horizontal plane. Or cup wheels are used alternatively, as shown in Figs. 176 and 177, the cutters being set for angle

of clearance in each case, but the wheels being differently presented.



Fig. 177.—Grinding Side Teeth with Cup Wheel.

The teeth of end mills are ground with cup wheels, Fig. 178, the wheel axis, or that of the cutter, is set out of parallel by

the amount required to give clearance to the teeth. Fig. 179 shows the hole of a cutter being ground with the internal attachment.

Profile mills if ground on their edges are done by the aid of a former. An example is given in Fig. 180. In this class of work the relieved cutters are generally to be preferred, because being ground on their faces, they can be done in any machine without rigging-up a profile arrangement.




Fig. 178.-Grinding End Mill.






Fig. 179.-Grinding the Bore of a Cutter.




Fig. 181.—Elevation of Form Cutter Grinder.




Fig. 182.—Plan of Form Cutter Grinder.





Fig. 183.—End View of Form Cutter Grinder.

Figs. 181-183 illustrate a form cutter grinder by the Actien Gesellschaft für Schmirgel ünd Machinen Fabrikation, of Bockenheim. A is the base, bolted to a bench or a pillar. On it the sliding table B is capable of adjustment by the handle c, operating



a screw. The emery wheel carriage is pivoted at D, and is lifted, lowered, and controlled by the handle E. The form or profile piece is bolted to the bracket F, made in three pieces, giving adjustments in the vertical direction,

Fig. 184.--Grinding Formed Cutter.

and horizontally, on a sliding face on the table B. The tooth rest G, on the opposite side, has vertical adjustments, and two horizontal ones at right angles with each other. The work spindle H is held in a head J, having endlong adjustments on the base K, which swivels on the table B, upon which it




Fig. 185.—Grinding Formed Cutter.

can be clamped. The wheel has two speeds by coned pulleys, the tension being adjusted by a screw and nut in the wheel arm.

The second method of grinding adopted, that of faces for form mills, is simple. The shapes of the wheels used and their presentations are illustrated in Figs. 184 and 185. The resemblance to that of grinding a tap is shown in Fig. 186.

The economy of regrinding is too valuable to be neglected. It is not only that better work is produced by keeping cutters sharp, but that the operation of grinding is also more readily done. Heavy grinding produces heating, and distortion, and draws the temper, as indicated by blueing. If a cutter has been treated badly by being allowed to become very dull, it is better to regrind it while revolving on a mandrel, before taking it tooth by tooth. Dry grinding is usually adopted. In some firms the cutters are sharpened more finely by rubbing




Fig. 186. Sharpening Tap.

each tooth with an oil stone, or with an emery rubbing stone, or a carborundum stick. Firms who adopt the practice speak highly of the results.

CHAPTER VIII.

MILLING OPERATIONS.

The Operations of Roughing, Finishing, and Profiling—Milling Compared with Planing, Shaping, and Slotting—Examples—Holding Work in Jigs—General Considerations—Examples.

The Operations of Roughing, Finishing, and Profiling.—
The time has now come when the true position of the milling machine in the engineers' shop may be considered as practically determined, at least for a long term of years. We have seen that its utilisation in engineers' work did not follow until half a century subsequent to its invention, its applications during that period lying in the small-arms and sewing-machine industries. Then, for many years, engineers used it for light operations only, and chiefly in those which had been hitherto performed at the vice. Milling did not come into much rivalry with the general operations of the machine shop until within about the last ten years. An exception must be made in the case of slabbing face-milling cutters, with inserted teeth, which have been used for twenty years or more, in some shops for rough facing.

About ten years ago the milling machine began to boom in general engineers' work, and it made its appearance in many shops where it had hitherto not been seen at all. Then something like a reaction occurred, and many thought that the multiple cutter was going to displace the single cutter on planer, shaper, and slotter. Practical mechanics did not, as a rule, share that delusion. What has happened is, that though some displacement has occurred, the milling machine has taken charge of a comparatively new field of work, the nature of which we propose now to consider briefly.

From this point of view we may regard milling in three broad pects—that of roughing, finishing, and profiling.

The estimated and the second are second as the end of the staggered and a second are second as the end of the staggered and a second are second as the end of the staggered and a second are second as the end of the end of the staggered and a second are second as the end of th

But roughing is a term of relative meaning, denoting generally the first, or often the second cuts on a job, as preparatory to the final or finishing cut. A cut may be a roughing one without being deep, but a finishing one is always fine. Both are generally done with the same mill, fed deeper, or shallower. But no cut taken with continuous edged mills can ever be as deep as that which is taken with a single-edged tool, or with staggered mills. The difference is that between scraping and cutting, between broken shavings and coarse chips. It is because this distinction has been often neglected that too much has been expected from milling cutters.

Limits are set to the action of single-edged tools in latter, planer, shaper, and slotter by the spring of rests, of cross rails, and rains. The stresses on a broad-cutting linishing tool prevent any but very shallow cuts being taken. Yet milling cutters exceed in width many times those wed for broad finishing, and therefore so much less depth of cut can be expected of them. This increased breadth of action the breaking up of the chips by the scraping process, and another fact, the small spacing of the teeth, tending to cause choking and dragging, are the disadvantages under which the milling cutter does its work.

What has partly disguised these facts is the abundant lubricacion amparted to these cutters in the best practice, which contrasts strongly with that of the single-edged tools, the wider spacing of the tecth given for some kinds of work, the more efficient support attorded to cutters and work than of old, and the spiral arrangement of teeth, which effects a shearing cut. Features which may conduce to a better solution of the difficulty are the adoption of a more rational method of feeding, and a further stiffening up of the machine elements.

The roughing operations of the milling cutter may simply mean the first, or the second cuts of the common mill, preparatory to the finishing cut of the same tool. Or it may mean roughing performed preparatory to planing, either by a common mill, or gang of cutters, or by means of an inserted toothed mill, or of a staggered toothed solid mill. Or it may mean rough tooling only, as in that large class of face cutters which are used for ending rolled beams, or facing the feet of standards or brackets, or other eastings in which the object is to remove the rough exterior, and leave a roughly faced surface, suitable for attachment to other parts. Each of these is largely represented in the practice of the shops. finishing operations of the miller include the greater portion of the work done on these machines, and these can never be any but very shallow cuts, consistently with accurate results, and the wider the surface, the less must be the depth tooled. So that practically we may say that broad and accurate finishing is not where the miller scores best, though it is possible under the conditions just named. Its best work is done on narrow pieces, or on those of medium width only.

Milling Compared with Planing, Shaping, and Slotting.—
Milling over a broad surface or on a number of narrow pieces arranged side by side having their aggregate area covered with a single broad cutter is a rival operation to the single tool, or couple of tools held in the tool box of a planing machine. When the question is one of roughing down, the milling machine scores; when it is that of very accurate finishing, the planing machine is found superior in accuracy, though not perhaps in smoothness of surface. The question, therefore, is not an absolute one, but relative. And the reason is fairly clear to a practical hand, being due to the difference between the spring of a broad cutter operating over a width, say, of 12 to 20 inches, and the rigidity of a shanked tool taking a narrow cut. It is practically impossible to avoid spring on any cutting that is both heavy and broad in character. Spindles are being constantly stiffened up, more attention is given to their

bearings: cutters are serrated and staggered for breaking up the chips, and provided with teeth having a high angle of spiral for finishing, yet they spring and chatter. And even though the amount is not much, it is sufficient to destroy the very fine accuracy that is required in machine tool slides, and in other intimately fitting parts. The conditions are not comparable with those of a narrow milling cutter on a stiff arbor. Lathe men will understand this when they remember that heavy cutting and very accurate results are incompatible; that fine precision of results requires light cuts, and that it is better to rough coarsely and finish finely than to reverse the process.

The mills with spiral teeth are better for finishing, since they take extremely shallow cuts. But what they lose in depth they may gain in area, and thus show considerable economies over planing: hence their special value for preliminary operations.

In fine finishing, no less than in roughing down, a stiffly built machine, whether planer, miller, grinder, or lathe, is essential. It may sometimes seem incongruous to see a massive machine weighing several tons revolving a tiny milling cutter or emery wheel, nibbling at a bit of work, removing perhaps a hundredth or a thousandth of an inch of metal. Apart from experience, this disproportion would appear absurd. This has not been arrived at by calculation, but it is a case of evolution in the workshop. the effects of vibration, or slackness of spindle and slides, or even of the spring of parts that are too slender to hold the work or the cutter stiffly, are found to occur in the smallest work, it is not difficult to see what may happen in the case of a very large cutter. The faintest trace of vibration, of yielding of frames and spindles, produces unevenness in the surface of the work, which is fatal to the finer degrees of accuracy required in the production of highclass machinery; hence machines are constantly being built of more massive design than their predecessors.

Plain surface tooling—using mills which cut by their edges—constitutes the largest class of work done. For this the mills should be longer than the width of the surface which has to be operated on. They are either vertical or horizontal. The work may be a single piece, or a number of pieces arranged in series. Mills of this general type are used on every class of machine, and on an infinity of duties. Mills about an inch in width

have the teeth arranged spirally to give a shearing cut, which separates the metal in detail, and puts less strain on the arbor. The amount given varies widely by different firms, but in recent years the angle of spiral is greater than was formerly adopted.

When employing broad cutters, a great deal of work is either ground or planed after being milled, being so treated in order to impart a higher degree of accuracy than is found practicable under ordinary conditions when using broad cutters in the milling machines. When work leaves a planing or shaping machine it is finished, except when scraping for high-class work only is required. The practice just instanced seems a proof that broad, heavy milling, with axial mills at least, is not yet so accurate as planing. are exceptions, but they serve to accentuate the rule that the milling of heavy work with deep cuts and rapid feeds is chiefly valuable in removing the bulk of the material and producing a fairly accurate surface, which then has to be finished by light grinding or planing. Much of this is probably due to the employment of light machines on work for which they are not adapted, and to the practice of performing too heavy cutting on large areas, with arbors also too light for the work.

Wide faces and inner edges can be tooled with broad face and side mills, many examples of which occur in the slides of machine tools. Smaller flanking mills may cut edges simultaneously. The angular mill affords good facilities for tooling the angles of slides accurately.

Face-milling cutters are preferable for some purposes to cylindrical cutters, since they are useful for depthing, as well as for surface work.

Another advantage which the large face mills with inserted teeth possess over single-edged planer tools is, that these will reach down or across to surfaces that cannot be reached with a planer tool, properly supported. There is a great difference between the overhang of the shank of such a tool from the tool box, and the mass of a cutter head.

A limitation of the milling machine is that a mill cutting axially must always leave a radius in corners of recessed portions of work. If this is objectionable, it will often happen that a face mill can be substituted. But in many cases a radius is to be

preterred. The following are some of the principal jobs done by milling, several examples of which are shown on subsequent pages:—

The flanges of steam chests can be tooled by a face mill on a horizontal spindle, and the truth of the work will be ensured by bolting one end flange, already faced when boring, on the machine table. At the same setting the ports can be milled.

Three sides of parallel bars can be tooled simultaneously with rotary mills on a machine of the planer type, fitted with one vertical and two horizontal heads. Or two edges can be milled simultaneously with a machine having two vertical spindles only.

The shoulders between brasses are shaped parallel, with mills having teeth on ends and edges. All kinds of brass fittings have their angular faces tooled in special or plain machines. Bearing caps have their edges milled with edge mills on vertical spindies. The faces of eccentric straps are tooled with edge and with end mills. So are keys and cottars, slide valves, and eccentric rod links. The edges of eyele cranks are tooled with profile cutters. Taps, reamers, and twist drills are grooved, as already shown, between centres with cutters having the profiles of the grooves. Tee grooves and vee grooves are milled with cutters of corresponding sections carried in vertical or horizontal spindles. Vec ways for slides of moderate width can be tooled at once with a one solid mill. The teeth of tacks are milled, several at a time, by a gang of cutters. The rims of gear wheel blanks are milled to section on periphery and edges, the blank being fed circularly on a horizontal spindle. The square ends of spindles can be cut with end mills. Vice jaws can be milled, and oil channels in small tables. Slits for tightening purposes are cut with slitting saws on a milling machine instead of casting them. Then there is besides the work of cutting all kinds of gear wheels, which subject will be treated in another chapter.

Key ways and that class of grooves can be tooled with mills cetting at bottom only, or at bottom and edges at once, the shaft or other piece of work being clamped to the table or in the vice. The tool is a disc with teeth on the periphery only in the narrower sizes, but with teeth also on the sides in the wider ones. In the narrow ones the teeth are square across, in the wider a spiral twist is given to them.

Faces and outer edges can be tooled simultaneously by what are termed straddle mills, and a constant width maintained easily in a large number of pieces. By turning the side mills round, the outer edges can be used after the inner ones have become dulled. Also, edges can be tooled thus without touching the face by inserting a plain distance piece between side mills. Or a single edge can be tooled with a side mill of sufficient size to cover the area required.

A convex edge is a very simple detail. These edges occur with great frequency in engineers' work. The old method was to plane or shape them, adjusting the tool slides by hand, or to file them. The modern method is to mill them with concave cutters if half-circles, or with cornering or radius cutters if quarter-circles. These can be used equally well on vertical or horizontal arbors. Concave forms can be milled.

Half-bearings or keeps can be milled singly or in series, instead of boring.

More elaborate sectional forms can be cut by mills operating by edges and ends: and these may run in one plane or irregularly, as in profile work. They may be formed in one piece or built up in gangs. There is no limit to such combinations, save the strength of arbors and the capacity of machines.

Large profile cutters are multiplied in gangs on an arbor to tool several sections at once. The ways of small lathe and machine beds are thus shaped. These gangs are made up more cheaply than by forming solid mills for intricate work, besides which the separate mills can be used for plain work. They may lie closely together, with or without overlapping of teeth, or plain distance collars may be used to separate them, if the cutting is not continuous. Edge mills may also fulfil the function of distance Mills are locked together in gangs by projections on one pieces. entering recesses in the one adjacent. Several similar mills may be arranged side by side for duplicating work. In cases where an exact dimension across faces has to be worked by, two mills may cut on each face at once, whether the faces are internal or external. Where the alteration in size of a single mill is objectionable because the later pieces tooled would not be of the same dimensions as those first done, then, for inner faces, interlecking mills are used, and for outer ones mills separated by a collar, either device of which permits of micrometric readjustment.

The utilities of the miller are very great on form, and on profiled work. The distinction made is that between the work of the gang mill operating on a plain surface longitudinally, and that of any edge mill, gang or otherwise, operating on a surface which is irregular in the plane of the axis of the mill. There is no other tool in the machine shop which will produce such surfaces. Before the mill came they were done by hand at the vice, or in a rough fashion by a succession of settings of tools and cuts on the planer, shaper, and slotter. On the milling machine they can not only be done cheaply, but with nearly absolute uniformity, which was not possible under the old system. This, therefore, is a new sphere which the miller has almost wholly created for itself.

There is another aspect of the methods which either came in with the milling machine, or the development of which it has greatly helped. Since cutting, to be accurate, must be shallow, and since slight allowances are only consistent with very close approximation to dimensions, the practice of milling has reacted on the work of the die forger, and of machine moulding. As these methods are only economically available when considerable numbers of similar pieces are required, they have favoured the development of interchangeable methods, and the practice of The latter has reacted on the work of the smith jig making. and moulder, in demanding the closest adherence to dimensions, and the smoothest surfaces possible, because it is difficult to design jigs for pieces of work that vary in size and form, and it is wasteful of time to have to set such pieces in jigs. as allowances diminish, the presence of scale becomes more objectionable than when a good roughing cut can be taken with a single-edged tool, penetrating below it at once. Pickling therefore is resorted to, both for castings and forgings, in shops where consideration is given to the permanence of the edges of cutters.

The relative degree of accuracy of surfaces which is desirable or essential must frequently control the decision of the alternative methods of planing or milling. There is, for example, no comparison practicable between milling a number of girder ends, or stretcher ends, or pipe flanges, and milling a long lathe bed, or planing machine bed, or slides. The two classes of work, and the large group of which each is broadly representative, stand in an

entirely different category. Lathe and machine beds are not considered true enough unless they are within about $\frac{1}{1000}$ of an inch in a length of 6 feet. Now an extremely slight amount of deflection under cutting will produce this minute degree of inaccuracy. But for a large proportion of faced work, $\frac{1}{100}$ of an inch would be sufficiently accurate.

Then further, the question of whether roughing or finishing is being done is on a par with that of relative degree of accuracy. If a piece of work has to be finished by grinding, then fine accuracy in the roughing is not important, but the roughing may correspond with the degree of accuracy, say $\frac{1}{100}$ of an inch, which might be the finish limit in a different grade of work.

The springing of work under cutting is a matter of which account must be taken when comparing alternative methods of tooling, and deep or shallow cutting, coarse or fine feeds. It may be accepted as beyond doubt that all planing or milling causes some deflection and springing, though the amount would be very variable under different conditions. But its presence and amount would in numerous instances be the principal factor in deciding the choice between planing and milling, or between roughing by one method and finishing by the other, or between taking heavy and light cuts, or between using inserted tooth rotary face mills or solid edge mills.

The question of milling versus planing lathe beds has been and is to an extent an open one. In some cases it is solved by employing milling as a roughing operation, and planing as a finishing one. But planing involves the employment of a gauge or gauges as the work proceeds, and several settings of the tools. Hence the idea of a single gang of mills tooling the shears at one operation has its fascinations. But such work is only practicable under certain conditions.

The great difficulty encountered is that of spring, both that of the gang of cutters, and that of the beds, and these forbid the employment of any but very shallow cuts for broad finishing. A single-edged tool, though heavily fed, can be trusted not to cause spring in a bed, but the case is on an entirely different footing in a gang of cutters operating over a width of several inches.

This elasticity may be minimised, but not eliminated entirely. Stiff arbors are essential, and careful levelling and packing up of

the beds with wedges, or with special appliances, as stools and charps in a fixture attached to the machine bed. Clamps must also always be pinched right over the points of support that are employed. After a rough cut has been taken, the clamps should be slackened to note it the bed has sprung in consequence of the removal of the skin, which is liable to happen in the lighter class of castings. Also light cuts taken over the rough skin of a casting rain milling cutters, so that between these and the heavy ones, which are impracticable, there is little if anything to be gained by milling, especially when extra expense may be entailed for final coraping.

The work however may be divided with advantage either by roughing down with single-edged planing tools on the pinner, and finishing with very light cuts by a gang of cutters operating over the whole width. This involves setting at two machines, unless a combined planer and plano-miller is available. Or the roughing down may be done by mills, roughing sections of the work only, with coarse feeds, to be finished as before with a broad gang mill. Given machines specially rigid in beds, tables, arbors, and cross slides, there is no reason why milling should not be both broad and accurate in character. Thus, at Messrs L. Loewe & Co.'s, lather beds are roughed out on the milling machine, and finished on the planer, the latter being employed to ensure greater accuracy. The precaution is taken of allowing the work to stand for several weeks, after rough milling, before it is finished by planing, to give time for the slight change of shape that occurs to take place.

Serew machine beds are regularly milled in the Warner & Swascy shops with gang mills on a planer type of machine. The gang mill goes over the surfaces of the vees, the bed edges, and the tack bed. Supplementary spindles in special heads, with a slight vertical range of adjustment, mill the bottom faces for the gibs, using shank mills. Roughing and finishing cuts are taken thus. The beds are finally corrected by scraping.

The problem of milling versus planing is not only governed by the spring of the work, and the relative quantities of metal removed, but by the relative facilities existing for tooling faces at different angles and in different planes. The planes is the more accommodating of the two in this respect, because tools can be cranked and set to operate on undercut faces, often in situations that neither vertical nor horizontal cutter spindles are able to reach. In consequence of this, numerous jobs can be tooled at a single setting on the planer that would require two on the milling machine. And some could not be finished at all on the latter, or if so, an expensive special tool would have to be made, and special tools are not to be considered in the work of the general shops.

Face, and edge milling afford two alternatives which often have to be discussed and considered in relation to special jobs. The question of rotary planing is also often included when face milling is concerned. In a good many cases there is no alternative, as when faces on the same job lie, some horizontally, some vertically; or as when a job can only be fixed one way on the machine. But when choice can be made, the face mill has the advantage that the chips fall away from the work at once. In edge milling the action




Fig. 187.—End Mill working on Thin Piece held with Side Strips wedged against Round Pins put in Holes in Table.

of the cutter is impeded by the presence of the chips, which do not get away freely from between the teeth, and this acts as a limitation on the depth of cut and feed. And when castings are not pickled, the sand and scab lying in the path of the teeth aggravate results, so that the

horizontal face mill scores more heavily still than when working on clean surfaces. For the roughest class of milling, therefore, the face mill on a horizontal spindle is the best rival to the planing machine.

Some examples of milling work which would alternatively go on the planer are shown in subsequent figures. Taking thin pieces, there are two or three ways of holding, as follows:—A few parallel pieces, Fig. 187, A, of various widths and lengths, chamfered off to a narrow edge down one side and planed parallel, are kept handy to suit different jobs. The thin edges go against the sides of the work, and, being shallow, do not interfere with the milling of the top face. The shorter pieces are used for short bars, the longer ones for long bars. They may be held in place by means of wedges simply, and used in pairs, as in Fig. 187. The holes in the Fig. or the tee slots in a machine table run pretty close

together, and, by selecting parallel pieces of different widths to suit varying sizes of bar being tooled, any width can be held on the table. In Fig. 187 plain pins B, inserted in one set of holes, take the thrust of one parallel piece, while the other piece is forced against the bar by means of wedges C, C driven against pins B in other holes.

Another way is to hold one of the parallel pieces A down with a bolt, which may be long or short, Fig. 188, and the other B




Fig. 188.—Edge Mill working on Thin Piece held with Side Strips wedged against Blocks Bolted in the Slots.

wedged c against a pivoted block p. Or pinching is done by means of adjustable points or fingers and screws. The fingers are bits of round rod, flattened at the ends which bear against the work, and they are hollowed at the other end to receive the push of the tightening screws. The screws are tapped into stops, which, fitting into the table groove, take the reaction due to the tightening up of the screws. Or a bracket of larger size, with feet, can be used, and tightened down with bolts




Fig. 189.—End Mill working on Piece held with Clamping Plates and End Stop.

fitting in the table slots. Long parallel guides are further useful in imparting steadiness to narrow, weak bars by affording them some measure of support. Being also parallel, they serve to set the work true with the tee slots or holes.

Bars of rectangular section often have to be milled on all four faces, as, for example, the wrought-iron guide bars used for hydraulic rams, and also those for some engines. In such cases no clips can be used for holding down the bars

on the table. There are no side danges either to afford a bearing for plates. Such work is held by end or by side pressure alone. Then one of the methods shown in Figs. 189 and 190 is adopted.

Fig. 189 shows a long guide bar for a hydraulic ram. The actual clips by which the bar is held are shown at A. These, it will be observed, are pressed against the sides by leverage. They stand at an angle, and are jammed between the sides of the bar and the tee-




Fig. 190.—Broad End Stop which steadies and keeps a Piece square.

head bolts. The tightening of the bolts c presses down the plates B upon A, the plates B being supported at the outer face upon the packing pieces D. As the plates A are longer than the parallel distance between the sides of the bolts c and of the bar, it is obvious that the tightening of the bolts c must wedge them against the bar, and the more tightly c c are turned the more securely will A A be pinched against the sides of the bar, so that it is held perfectly rigid, and the top face is left clear for milling.




Fig. 191.—End Mill operating on Claw Clutch clamped by its Collar.

The number of bolts and plates will depend on the length of the bar being tooled. There may be four, six, or even eight sets, their distances apart ranging from about 2 feet to 2 feet 6 inches. A stop block is often placed at the end, as seen.

In some light work even, in which it would be practicable to effect a hold with clips upon the top face, it is better to adopt the method illustrated in Fig. 189, because the flank pressure obtained thus is not nearly so liable to pull the work out of truth as the

pressure exercised by the direct pinching down of a clip on a light bar, or forging, or easting.

Another way of arranging clips of this kind is to place them at the ends, or a broad steady piece like Fig. 190 may be used. It is suitable for work of no very great length, say, not exceeding




Fig. 192.—Edge Mill operating on Two Thin Strips clamped between Angle Brackets.

3 feet. Fig. 191 illustrates another way of gripping with clips, taking a bearing on a recessed portion—a claw clutch, in this case, but equally adaptable to straight pieces having recessed portions.

Bars may be held on edge by the rig-up shown in Fig. 192, by means of brackets held with tee-head bolts, one set of brackets carrying pinching screws.




Fig. 193, "Motion Bar, tooled on Face and Edges with Straddle Mill, while bolted against Angle Plate, and supported on Packing Blocks.

Fig. 193 shows how east-iron guide bars may be held for milling. No clips can be pinched on the top faces of the guide bars because they have to be machined all over, and neither are there holes of any kind which can be utilised as means of holding down. The rib affords the only convenient means of attachment.

Fig. 194 shows the fixing of the curved side plates for tanks, going at the bottom and side of the tank, illustrating the setting of the plate A for milling the longitudinal edges. It is laid




Fig. 194.--Corner Tank Plate, having Joint Faces tooled with End Mills while Clamped, and adjusted between Angle Plates.

directly upon the table of the machine, or on shallow packings a, a, and set and bolted to angle plates B, B, which are bolted to the table. These plates always form quadrants of circles. The caulking strips down the longitudinal edges are therefore at right




Fig. 195.—End Joints of Corner Tank Plates being tooled with End Mills while held down with Clamping Bolts and Plates.

angles with each other, and the lines of the right angle, when prolonged, meet at the centre from which the radius of the curve of the plate is struck. To set the plates, therefore, they are first lightly bolted to the angle plates when brought nearly into position, and

then adjusted exactly with the square and rule. The square is held against one strip or "fillet," and measurement is taken with the rule to the outside of the curve. When this distance—usually either 6 inches or 9 inches—equals the radius of the curve, plus the allowance for tooling on the lower strip, then the plate is square, and the bolts can be tightened ready for milling the strips. Both top and bottom strips are tooled at one setting.

To mill the ends, several plates are laid in line across the table




Fig. 196. -End Mill facing a Boss Bearing pinched between Special Clamps, with Stop Blocks.

of the machine, Fig. 195, and bolted down with clips near the ends, the clips clamping adjacent plates as shown. The longitudinal edges already tooled must be set square across the table. Both sets of ends will be milled at the same time. The lengths of these plates must be the same as the lengths of the square plates, and will be measured with a gap gauge of sheet steel.

Fig. 196 shows a boss bearing which cannot be gripped on top nor on edge without special angle brackets. One of these, A, is

fixed by tee-head bolts in the table slots; the other, B, is permitted a limited amount of adjustment before it is tightened by the reaction of the screws c, c against the stop blocks D, D bolted in the grooves.

Fig. 197 shows how eccentric straps are machined preparatory to being bored. A number of half-straps are bolted to an angle plate

by means of a clip, the joint faces being levelled properly. After the joints are milled, the bolt holes are marked and drilled at the same setting on the angle plate.

There are very many types of that kind of work which are comprehended under the term " brackets." They constitute a large class. Many bearings are so denominated, rather loosely; but such is the usage. The method of fixing brackets for machining will depend partly on their shape and proportions, partly on the number of similar castings. Small brackets, of which there are but one or two castings, will generally be either bolted to the angle plate or held in the vice. If numerous, they will be arranged in series on the milling machine, and a continuous cut taken over the lot. Shallow brackets will be tooled with the foot uppermost. Deep




Fig. 197. - End Mill tooling Joints of Eccentric Straps clamped against Face of Angle Plate.

brackets are tooled while laid upon their sides, the feet standing perpendicularly, and then they may either be milled superimposed, or end to end, or in some cases an alternative will be to mill deep brackets with their feet uppermost, lying horizontally while bolted to an angle plate attached to the table of the machine. The reason why the mode of fixing shown in Figs. 198 and 199 is not suited for deep brackets is that it would not be firm enough to ensure steady cutting.

Fig. 198 illustrates two brackets held down for milling the feet. In this case the brackets have been already bored, which, when practicable, is generally done before tooling the feet. It cannot always be done, but in very many cases—in most instances




Fig. 198.—Edge Mill tooling Feet of Brackets carried on a Mandrel in Vee Blocks, Mandrel clamped down.

probably—it is as easy to bore first as afterwards. Then, supposing the setting is done accurately, the foot is bound to be parallel with the bore.

Through the bored holes in the brackets a turned shaft A is




Fig. 199.—Angular Mill facing Bracket supported in Vee Blocks.

thrust. The ends of this are laid on vee blocks E, E, B, A and plates C, C rest upon the bosses and upon packing pieces D, D, A and are held down with bolts E, E in the tee slots. In a space left in the middle between the two brackets a clip, laid directly upon the shaft, is pulled down with two bolts.

These suffice to hold the shaft A down, and with it the brackets. But the latter would turn or cant upon the shafts under the stress of cutting, and so it is necessary to pack them at each side under the feet. Pieces of bar might be used, but they must either be of the precise length required, or else the length must be made up with thin iron or steel wedges inserted under


their ends, or bolts F may be used, the precise adjustment for length being made by turning the nuts.

Two brackets only are shown in Fig. 198. More than two can be arranged in line, taking care to have a sufficient number of strips for elamping. Also, two similar rows can be clamped side by side, and two cutters be brought into operation at once.

Cases arise in which it is not practicable to insert a shaft through holes, because the latter cannot be bored until the brackets have been tried in place, in which case the holes will be either rough cored or left solid. Then the brackets can be held with side clips, still being sustained from canting sideways by means of bars or bolts.

Fig. 199 illustrates a regular jig for bracket work. Capped vee blocks are bolted to the table, and the proper adjusting screws take the place of the bolts r in the previous figure.

Fig. 200 is an example of two double bearings set back to back, and






Fig. 200.—Two Brackets, set Back to Back, being faced with a Rotary End Cutter.

bolted and clamped down thus together to the table of the machine. Such bearings could be set end to end simply, and milled in line. This method would be more economical of time than that shown in Fig. 198, because the cutter would only have to travel about half the distance. But the method shown in Fig. 200 has this counterbalancing advantage—the

brackets being set back to back, are in the precise position which they will occupy during boring, and also when bolted in their places to receive their shafts. The alignment of the brackets is therefore assured by doing as shown, while adopting




Fig. 201.—Bellied Connecting Rod being milled on Centres.

the end to end method there is just a risk that after the feet have been milled the holes might be bored out of line: or, if set truly for boring, they might not bore out clean, or "hold




Fig. 202.—Planer Tool cutting Tee Grooves.




Fig. 203.—Milling Tee Grooves

up" to dimensions everywhere. Hence the reason for the adoption of this method.

Or again, the brackets might be bolted to an angle plate. But being in line, the same objection would exist.

The joints of fly-wheels, cast in halves, are often milled in similar fashion to Fig. 200.

Fig. 201 illustrates the use of centres in milling the faces of a connecting rod. Vee blocks might be used, if the rod were not bellied. It is centred by the centres left from the lathe, is packed on blocks at each end, and clamped down, blocks being inserted immediately under the bolts.




Fig. 204.—Milling Dovetailed Grooves.




Fig. 205.—Nut Milling with Straddle Mill.

Fig. 202 illustrates the familiar method of planing out tee grooves in machine tables, Fig. 203 shows how they are milled. Fig. 204 is a slot of another kind being similarly treated. In each




Fig. 206.- Gang of Six Cutters, with Adjusting Screws, operating on Six Faces of a Bed.

case the milling cutter has the advantage of sizing as well as shaping.

Fig. 205 shows a straddle mill cutting nut faces, thus sizing as well as shaping. No lining out is wanted, but a division plate sets the exact angles. Fig. 206 is an example of a built-up

straddle mill tooling six faces, and edges of a bed. Adjustment for side wear is by the nuts at the centre of the arbor.

Small work is generally held for tooling in the vice, rather than by bolting by the tee grooves. There are two main classes of vices—those which swivel, and those which do not. The first are employed on the majority of jobs, but the second are often handy. The ordinary milling machine vice is a squarely constructed appliance, the hinder jaw sliding over broad surfaces. There are many special forms. In one of the latter, made by the Garvin Machine Company, the fixed jaw is adjustable on the base by means of tee grooves, to facilitate rapid adjustment. In another the vice is made to swivel, but the swivelling can be




Fig. 207 .-- Walker Magnetic Chuck.

either in a horizontal or vertical plane, by the simple plan of having two bases at right angles with each other, which brings the plane of the swiveiling face into the vertical or horizontal.

In the Brown & Sharpe Company's universal vice the upper part consists of two portions: the lower, which swivels in a horizontal plane; the upper, hinged to the lower to swivel in a vertical plane anywhere between the horizontal and 90°. The clamping of this portion of the vice is done by tightening the hinge bolt, and also by a bolt which connects a double-bracing lever, by which the freely moving part of the vice is connected to the lower portion.

In another type of universal vice, the base, which swivels in a horizontal plane, has two uprights cast upon it, between which the upper portion pivots on a pin running right through. Two quadrant slots in the uprights receive a through bolt, by which the upper part is allowed to swing through 100°, and permits of clamping in any position.

Figs. 207 show end views of the No. 5 standard type magnetic chuck by O. S. Walker & Co. The underlying principle of these chucks is clear from the figures. The first one shows the chuck set up for surfacing the flat side of the parallel piece A, which lies against the back strip B, and the vertically adjustable back rest c, the edges of which are exactly square with the chuck top.

In the next figure is shown the method of holding the piece A, for finishing one of the edges-note that its bottom edge is slightly bevelled. When placed on the chuck, with the acute angle outward, this piece is magnetically held, not only downward against the chuck top, but also against the back strip B, and back rest c, which latter has been elevated to come near the top of the piece. In this manner the top edge of the piece can be tooled square with the side. The magnetic action on the piece when adjusted in this position is illustrated in the next figure. The dotted circles and arrows serve to indicate the course of the magnetic lines of force. The broken lines a, b represent the positive and negative magnetic poles, the magnetic force seeking an easy path across the gap between these poles. The lines of force therefore preferring a metallic circuit to an air gap, travel through the piece of work A, and then dividing and passing down through c and B to the other pole of the magnet. Owing to the peculiar construction of the magnet face, a strong side pull is obtained as well as a direct down pull of the work. In milling, this piece would require additional staying at the side to hold it in place, and across the end of the chuck there is fastened a vertically adjustable strip that forms an end stop, this not being shown in the drawing.

The next figure illustrates the chuck with the back rest ℓ removed, and the chuck holding the strip D, for finishing one of the flat sides. A portion of the end of the chuck is broken off to show the coil chamber. E represents an ordinary kinfe-edge switch, which is protected by a guard on the edge of the chuck as shown.

The next figure shows the method employed for holding a number of parallel pieces at one setting. In this case additional holding power is got by laying a strip of non-magnetic metal P between the pieces to prevent the magnetic lines from flowing horizontally through the pieces toward the back strip B, thus diverting the power from the face of the chuck. This view also shows one of the slotted fingers for staying the work and preventing the side slewing. The last figure illustrates how the piece G, with a right-angular projection, can be held.




Fig. 208.—Brass held with Angle Plate, for milling Joint Face.

In case the chuck is to be used with water, the coil is given a waterproof treatment and the terminals are capped over entirely, leading the wires through a rubber hose to some convenient position outside of the area of the water where the switch may be attached.

A duplex switch is used with these large chucks. This is very desirable, especially for large work which is difficult to remove from the chuck. It consists merely of a double throw with cross connected wires, so that, when the handle is thrown completely over, the current is led through the coil in the opposite direction. The contact must be timed exactly right to prevent recharging the chuck face with the polarity reversed.

Fig. 208 illustrates the milling

of the joint faces of brasses instead of putting them on the shaper. The half brass is clamped against an angle plate, and additional steadiness secured by a piece of wood packing at the front end. In Fig. 209 a cap is clamped through the medium of a clip, and the joint face and edges and cap faces are milled.

So much clutch work is done that the old style of using the teeth as they are cast, without tooling, is not considered good enough for any but the roughest class of work. Even though the

teeth are cast, as in the larger clutches, they are tooled subsequently, the case of spiral teeth excepted. At one time all such work was done at the shaper, and is so done still in some firms: the clutch being held in the vice, and turned about to present successive faces to the tool. In the absence of dividing apparatus




Fig. 209.—Cap held with Clip for milling Faces and Edges.

the jaw edges were lined out, and a templet kept to check them by. Such work is now often properly appropriated by the milling machine, using an indexing head for effecting the divisions correctly, without lining out or templating.

Fig. 210 illustrates one method of milling the teeth, which applies alike to clutches having the teeth cast, and to forged or cast






Fig. 210.- Claw Clutch to be Milled.

axis being set at right angles with that of the clutch. width must be a trifle less than the space between adjacent teeth at the inner part, next the hole, where the space is narrowest. It is then set to mill one side of a tooth, and fed across down to the full depth of tooth, or nearly so, depending on whether a fine finishing cut will be taken all over the bottom subse-The table is then quently. run back, and the index set for face in that direction are done. ones having the teeth milled from the solid. The work is clamped as in Fig. 191, page 211.

A cutter is selected having teeth on the edge and sides, its



Milling Claw Clutch.






Fig. 211.—Milling a Slot.

the next tooth, and so on until the sides of all the teeth which face in that direction are done. The other side of the cutter is

next set to do all the opposite sides of the teeth in the same manner. Finally the bottoms are finished with the same cutter.

Fig. 211 is an example of slot milling versus slot drilling.

The formation of circular bossed ends is often done on the slotting machine and on the shaper. It is usually more convenient to set small levers on the shaper for bossing, and large ones




Fig. 212.—Illustrates Value of Circular Table for Boss Milling.

on the slotter. There is rather more difficulty in setting them on the latter than on the cone mandrel of the shaper, which is self-centring. On the slotting table, measurement alone is frequently the only means of setting. Many tables with a central hole are, however, fitted with a central arbor or mandrel, standing up vertically, upon which the bored holes of bossed ends are

centresl. Such arbors are turned parallel to different diameter can be suit different jobs, or one of a constant small diameter can




Fig. 213.—Cone Mandrel to bolt on Circular Table.

used, and bushes slid over it holes of larger diameter.

Fig. 212 shows a common which is preferably done by mill that leaves a smoother surface t slotting. When such a piece slotted, the boss is turned down far as the web. This is not nesary in milling, for by altering height of the cutter the boss car milled all round. Figs. 213illustrate useful attachments milling circular work, borro from the shaper arbor. Fig. 21 a fixture for bolting directly on centre of the circular table. lever shown is held by the con centres, and clamped, and this 1 takes of the circular movement

the table. Fig. 214 is a fixture derived from the previous but it is bolted to an angle plate, and holds a double-ended le





Fig. 214.—Angle Plate with Cone Mandrels for Clamping Levers by for Mil

while the web is being milled. A washer is inserted between forks to prevent them from being closed inwards by the b Fig. 215 is an auxiliary table or plate bolted to the machine table for holding objects having holes, so as to mill both bosses and webs.

The milling machine has invaded the province of the lathe to a slight extent. Some jobs that are not infrequently done are the rims of very light spur-wheel blanks that are rather delicate and springy to operate on in the lathe. Bevel-wheel blanks are also tooled as in Fig. 216. Belt pulleys are sometimes so treated, Fig. 217, and rope pulleys, Fig. 218. In each of these cases the cutters are built up, and the entire rim is tooled at one operation.






Fig. 215 .-- Auxiliary Table with Cone Mandrels for Objects having Holes.

Milling is largely taking the place of other machine tool operations in die cutting. Fig. 219 shows a group of cutters used in this work. They comprise tools for tapered edge, and for parallel work, for producing concave portions, for roughing and finishing. They fit directly into the spindle, or into an intermediate fitting shown in the figure.

Fig. 220 shows a job of profiling being done in which the tapered form of tracer or former pin is seen bearing against the form carried on a bracket bolted to the table and controlling the

operation of the cutter on a pile of six pieces of work. The tracer pin is adjustable in a slot by the screw indicated. For remarks on profiling machines, see pages 96 and 100 to 104.




Fig. 216. Milling a Bevel-Wheel Blank.

Holding Work in Jigs.—There are several ways to look at this subject, and many things to be considered in so apparently simple a thing as gripping pieces of work to be milled. Other matters besides holding merely have to be borne in mind. The following are the chief considerations:—

Security of course is necessary; but avoidance of risk of distortion is essential. So is rapidity of gripping. Also a method of holding that will not interfere with the freedom of movement of the cutter or cutters; frequently, too, facility for changing the position of the work to expose fresh surfaces to be milled. The question of adjustment of rough or of

tooled surfaces in relation to other surfaces of the work, or of holes, often affects the question. So does that of fixing one or of several pieces for simultaneous milling. Frequently the table of the machine receives the piece or pieces of work, as in the examples previously given. But in many instances this would not afford sufficient conveniences for holding, as in cases where numerous important and necessary relations of parts have to be taken account of, and then the special jig has to be devised for one particular kind of article made in quantity or sometimes for articles that are not very dissimilar in shape or size.




Fig. 217.—Milling the Rim of a Belt Pulley.

Going a step further, the same jig is often designed to include another operation besides milling—that of drilling of holes, effected at the same or another setting in the

jig, which is done in order to ensure the correct relations of such parts without resorting to measurement or check.

Then further, in another stage, a gauge piece is sometimes included, by which to adjust the relations of the mill and the work, and so to ensure correct height or thickness for tooling, without resorting to direct measurement.

The first and most obvious method of holding work directly on the tables of milling machines, with only the aid afforded by the tee grooves, has been already illustrated. The clamping plates or pieces used are held with tee-headed bolts in these grooves, and

the

clamps




Fig. 219.—Group of Mills for Die Cutting.




Fig. 218. - Milling the Rim of a Rope Pulley.

may bear on top, or against the edges of the work, either by the sides or the ends. Or the work may be held against the face of an angle bracket or plate clamped to the table. Pieces to be milled circularly are held by an arbor in the centre of a rotary table. Holes are frequently drilled first to receive plain or conical arbors inserted in the circular table, or attached to angle plates. If jigs are used, these are provided with a tongue in the bottom to fit the table grooves, to which they are bolted down. These summarise the general methods of holding work for milling.

It is more difficult, as a rule, to make suitable jigs for castings than for rolled metals, as shafts and plates, or for drop forgings. This is due to the fact that variations occur in nearly every dimension of the separate castings, though made off the same pattern. From experience I should say that no two castings, when hand made, are ever exactly alike when brought to the test of the jig maker. With good machine moulding they are generally uniform, though not always. Variations increase with increase in dimensions. This difference in hand and machine work is that due to rapping in delivery, and mending up in the first case, and the coercion exercised by the machine lift in the second, and the fact that mending up is rarely attempted. The reason why slight differences




Fig. 220. - Milling with a Former.

do sometimes occur in machine-made castings is that differences in metal involve variable shrinkage amounts, and changes occur in the mould in the act of pouring, such as scabbing, swelling, producing rough surfaces; and lumps, straining of boxes increase the dimensions. Increase in dimensions of castings gives larger masses on which these causes operate.

The jig maker has to be on his guard, therefore, when making provision for holding eastings, and his appliances must embody some elasticity in design to permit of the embracing of eastings that vary in dimensions, even if only by slight differences.

The methods generally adopted include vee'd spaces for bosses, and adjustment screws. Bosses generally when present are taken as the parts from which to commence the settings, in order to locate their holes centrally. It looks bad to see holes out of centre, whereas a trifle of difference in the thickness of a foot or facing is of little moment.




Fig. 221,-Jig for Locking-Plate Castings.

In some jobs that are nominally left rough cast on a lower face it is often advisable to take a light cut over that surface, simply for convenience of clamping the face down to the table, to avoid packing up. The same may often be done with advantage when the face has to be finish-tooled subsequently. This applies more particularly to light flimsy castings, or forgings which are most liable to spring. Such precautions are more necessary in the case of milled work than in that of work to be tooled on planer or shaper, because of the greater pressure of the cut in milling, with increased risk of distortion. If only the high parts are removed, bedding can take place there, and the clamps be brought opposite them. In some cases this will be quicker, and almost always safer than attempting to pack up with wedges, or thickness strips. For a



Fig. 222.—Turrét Fixture.

similar reason it is often found necessary to touch off the high spots or lumps on castings and forgings before they can be inserted in their jigs, even though those localities have to be subsequently tooled all over to dimensions.

Fig. 221 illustrates a very interesting piece of work being done on one of the Herbert horizontal spindle machines, consistThe methods generally adopted include vee'd spaces for bosses, and adjustment screws. Bosses generally when present are taken as the parts from which to commence the settings, in order to locate their holes centrally. It looks bad to see holes out of centre, whereas a trifle of difference in the thickness of a foot or facing is of little moment.



Fig. 221,-Jig for Locking-Plate Castings.

In some jobs that are nominally left rough cast on a lower face it is often advisable to take a light cut over that surface, simply for convenience of clamping the face down to the table, to avoid packing up. The same may often be done with advantage when the face has to be finish-tooled subsequently. This applies more particularly to light flimsy eastings, or forgings which are most liable to spring. Such precautions are more necessary in the case be noticed, which provides for adjustment to keep the width of grooves constant, to compensate for resharpenings. The stiffness of the outer bracings may be noted, as important elements in the work of heavy cutting.

Figs. 222 and 223 show an advanced piece of milling practice as done in the shops of A. Herbert Ltd. It comprises a turret




Fig. 224.—Fixture for Toggle Levers.

fitting to the table of a horizontal machine, rigged up specially for milling the heads of bolts. The two illustrations show the fitting from two points of view.

There are six custers—two outside, and two pairs in intermediate positions. The bolts are fastened in the turret, and the latter rotated into six equidistant angular positions, in each of which three bolts have two opposite faces milled simultaneously, the equivalent of a single bolt finished at each position of the turret.

The cover for the cutters includes an arrangement for lubricat-

ingthem. The finished bolts are removed, and fresh ones inverted while the machine is in operation. One man operates two machines in the Herbert works, but this could be exceeded in a screw factory, or on some classes of work.

Fig. 224 illustrates the milling of malleable-iron toggle levers that form a portion of




Fig. 225.—Jig for Milling Arbor Tangs.

the automatic chuck on the Herbert hexagon turret lathe. Three grooves are milled at once, to fine limit gauges, the work being .




Fig. 226. Setting Gauge.

interchangeable. The cutters are of the inserted tooth kind, alternate teeth cut on opposite ends, thus permitting adjustments to be made to compensate for wear—effected by driving the teeth farther through the body of the cutter in both directions. The clamping of the pieces in the fixture is interesting. The levers to be milled drop into recesses in the jig, and as clamping by the top edges would interfere with the cutter arbor, they are clamped on rods coming out at the sides. The rods are inserted in holes previously bored in the pieces.

A neat rig-up for milling the tangs on the ends of taper shank drills, arbors,

reamers, and which is adaptable alike to the square necks of hand taps and hand reamers, is illustrated in Fig. 225. It consists of a bracket, fitting on the table, with a tongue for

cutter—is determined by the notch in the fixed jaw A, and when the machine is set by these two positions, the work can be commenced; and continued without any experimental cuts being required. The hole in the sliding jaw takes bushings that fit the arbors on which the cutters are placed to be milled.

A good many devices have been schemed to permit of a milling machine attendant fixing work on one end of a jig, while the machine is milling similar pieces at the end opposite; an idea which is sometimes utilised on double-headed planers. The advantage lies chiefly in forgings and castings, which, being more or less rough and uneven, take more time in their adjustments than pieces of sheet metal, or pieces partly machined would do.

An example of extremely fine work in gang milling is seen in Fig. 227, done in the shops of A. Herbert Ltd.—It is the cutting of slots in burners for gas fires. Large numbers of slots were cut in one traverse, the widest burner having 120 slots, requiring the fitting of 120 saws on one arbor.—The difference in time between this and cutting single slots is enormous.

The photo in Fig. 228 illustrates profile milling on a Herbert machine, the work consisting of shaping the edges of the links for chain conveyors, two of which are seen lying in front of the fixture, which is a vice especially designed for holding them. The links are first drilled uniformly in a jig, and they are then located in line by bars passing through the holes. The cutter is made in three parts. As the work is broad, the necessity for a very rigid support to the cutter is obvious. How this is ensured is seen in the illustration, the bracing affording a support as rigid as a solid housing could be.

A very interesting photo is that shown by Fig. 229 from the practice of the same firm. It is a special fixture made for the horizontal milling of objects of irregular outline, the particular example on the machine being a mould such as is used for pressing tiles. It is concave in form, the radius being very large. The apparatus is mounted on links resembling those of an ordinary ruler, thus ensuring a parallel motion. On the under side of the table on which the work is mounted there is a former, the edge of which is seen, and its face is the exact complement of the object being milled. The former can thus be made in the first instance, if





Fig. 228.-Jig for Profile Milling.

indicated in their relation to the work. Bushes of various sizes can be substituted, all fitting alike in the bracket, but having holes of dialerent sizes, as many as may be required.

Fig. 226 illustrates a jig in the Ludwig Loewe shops for setting cutters-used for making the teeth in spiral mills. It comprises INNEE 3

has been discussed on page 164, and is a feature which is likely to grow in favour. Messrs Herbert say that in their experience very much coarser pitch cutters can be used with advantage than is common practice.

Fig. 230 illustrates a fixture for milling the feet of headstocks with a gang of cutters in the Ludwig Loewe Works. Fig. 231 shows the tooling of both faces of a quadrant piece with built-up cutters in the Cincinnati shops, the circular table being used to rotate the work.



precise and definite rotary motion may be imparted to the spindle relatively to the pitch of the lead serew, and therefore to the travel of the table, and the divisions effected by the index plate.

The Basis of Calculation.—The basis of calculation is the single-threaded worm, and the 40-te ithed worm wheel, which its general consent, and its great convenience in subdividing into thousands, is adopted in milling machines. As the worm thread and the worm-wheel teeth are as 40 to 1, forty torus of the crank produce one revolution of the spindle, and one turn of the crank a fortieth of a revolution of the spindle. To obtain torty divisions to the circle, therefore, the handle would be turned forty times. To obtain eighty divisions the crank would be turned half-way round for each division, but, to obtain twenty, two tirms would be required. The rule is therefore:

Divide 40 by the number of divisions required, and the quotient will be the number of turns or parts of a turn which will have to be imparted to the crank. Thus —

Wheel, 40 Number of divisions, 40 = 1 turn. Wheel, 40 Number of divisions, 80 = 0.5, or half a turn. Wheel 40 Number of divisions, 20 = 2 turns.

By means of the index plate a turn of the worral shaft can be air, ad into a very large number of equal parts, and the tortieth of a revolution of the spiral spindle correspondingly subdivided, hades plates furnish several circles of holes from one of which selection can be made for the majority of jobs required, that will perm to field similar equal divisions. Thus, for eighty divisions, the crank being turned half-way round, a circle will be selected that will divide into two equal parts. If three divisions, a circle most have a analogy of holes divisible by three, and so on.

To racilitate constring the divisions in the circles of holes is the object of the sector A. Fig. 232. Circles of holes on the index plate being selected which will divide equally as even numbers, or multiples of even numbers, the sector is used to avoid the counting of every hole at each partial rotation of the crank.

CHAPTER AX.

INDEXING, SPIRAL WORK, AND WAS AND REVEL GEARS AT

The Universal the Machine of April 1982.

The Basis of Calculations William in the Differential Indexing - Angles of Street Methods - Milling Street toward being Worm Greats: Elements of the Spread Graphic Methods - Example - The Methods of Catting

The Machine of Applied Geometry
has been termed the machine to the combinations which the product of the combinations which the product of the many fenctions combine many fenctions combine many fenctions combine that when the machine shep which is of the numerous advicets that as only they are not of the machine to the machine shep which is surfaces, and check a single early that the correct spacing of the correct space space

The advantages are most system is settings or spacings, as an extension of mothods. The latter are never six to so the control of the milling maximum as the six of the milling maximum as the six of the milling maximum as the six of the control of

The Spiral Dividing Head - The spiral spiral dividing head are the rotation of the control of the spiral spiral which it may be set, the strange of the spiral spir

The tables sapplied by makers of milling machines give but one circle of holes for any given division. But it is not necessary to change a plate simply to place on the one named in the tables. A simple calculation will show whether divisions can be effected with the plate that happens to be on the machine. Thus there are six circles on the B. & S. machine which are divisible by 3, namely, 39, 33, 27, 21, 18, and 15, though the index table gives the first only. Mr E. Gauthier prepared a table to save the slight trouble of calculating, which, with some improvements made by the American Machinist, is given below.

$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Division. Circle.	Turns.	Holes,	Division. Circle.	Turns.	Heler	Division. (Turns.	Holes.
$\begin{bmatrix} 21 & 3 & 7 \\ 18 & 3 & 6 \end{bmatrix}$ $\begin{bmatrix} 18 & 1 & 12 \\ 15 & 1 & 10 \end{bmatrix}$ Degrees.	$\begin{array}{c c} 39 \\ 33 \\ 27 \\ 21 \\ 48 \\ 15 \\ 40 \\ 39 \\ 39 \\ 48 \\ 6 \\ 27 \\ 21 \\ 8 \\ 6 \\ 27 \\ 21 \\ 8 \\ 9 \\ 48 \\ 49 \\ 48 \\ 9 \\ 48 \\ 10 \\ 33 \\ 49 \\ 48 \\ 10 \\ 33 \\ 22 \\ 21 \\ 22 \\ 21 \\ \end{array}$	13 13 13 13 14 16 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 7 7 8 8 8 8	13 11 9 7 6 5 :26 22 18 14 22 10 55 15 :28 :21 12 12 13	13 39 14 (49 21 33 25 23 (39 37 24 24 24 24 21 19 20 24 24 24 24 24 24 24 24 24 24 24 24 24	21 21 21 21 21 21 21 21 21 21 21 21 21 2	$\begin{array}{c} 428 \\ 228 \\ 141 \\ 100 \\ 98 \\ 66 \\ 42 \\ 1977 \\ 228 \\ 141 \\ 12 \\ \end{array}$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	21 13 21 9 11 13 11 9 5 4 7 2 3 2 4 7 2 3 1 4 7 7 7 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8

If 144 divisions are required, then $\frac{40}{144} = \frac{5}{18}$ and thus the index crank has to be moved $\frac{5}{18}$ of a turn to obtain each of the 144 divisions. A circle of holes is selected containing either 18 holes or a multiple of 18, and 5 spaces are measured off on an 18-hole circle, or 10 spaces on a circle of 36 holes.

Or, to cut 96 teeth—
$$\frac{40}{96} = \frac{10}{24}$$

The index pin must be moved $\frac{10}{24}$ of a turn, or, selecting a 24-hole circle, 10 holes

for each division.

Instead of counting every division of five or ten, as the case may be, the sector is set once, and pinched by its set screw, and then afterwards it is simply moved round into contact with the index pin, and then, after a cut has been taken, it is moved round and the pin inserted in the next division for the next cut. Only insetting the sector first, one more




Fig. 232.-- Index Plate with Graduat ous.

hole than the number required for the division must be taker, because that has to be occupied by the pin (see Fig. 232, a). The operation of turning and setting has to be repeated as many times as there are divisions required—144 times in the first example, 96 times in the second given, and in each case the spindle and the work will have made a complete revolution. This is the method of simple or plain indexing.


The index tables are furnished with index plates, and save calculation for a large number of divisions. But they do not cover exceptional cases, nor, in fact, all the divisions which are possible for any one circle of holes. This matter is discussed at length on page 248.

The denominators of the fractions indicate are used in the index plates. The follow Sharpe:—

"To illustrate the manner of using the indexing it may be supposed that we desire 69 parts. Reference to the table (supplied b the work is moved through 21 spaces or hole and then turned in the opposite direction 11 circle of one of the index plates. The first the ordinary manner. The stop or back 33-hole circle, the index crank pin is pulle circle and the index crank is turned thre desired direction, the holes being measured 1 second movement, the index crank pin is lef the back pin is pulled back from the plate, is given in the table, the crank is turned 11 opposite to that of the former movement. indexing the index plate and crank turn tog no sector on the back of the plate, the holes counted directly in the plate. Had the plus the indexing to obtain 77 divisions of the v of the crank would have been in the same the order of the covements is not material; for any reason, the back pin could usually be the meyement described as the second cor some instances, in lead, for example, in dividi 277 or 273 parts, the outer circle is naturall


Differential Indexing.—A new method becoming upplied to the Brown & Sharpe en allting machines. It is much simpler than her rotore coployed for obtaining divisions the Chell idexing is obtained in the same manner coupling that the spiral nead spindle is gentless that the spiral nead spindless that the spiral nead spindle is gentless that the spiral nead spindless that the spiral nead spir

Officential indexing differs from the com the maxement of the spiral head spindle in or ak is positively made by gearing. The in the bundle, thus giving a differential motion has to be made with one circle of holes and





DESCUATION	DE STORM	901	STORE STORE	EAR ON	10	4 5	NUMBER OF	MORE	IL OF TURNS	MORK	OLAR		100	30 E	SPINDLE	101	4 2	10 000	MDEX	OF THRMS	GRADUATION	DE WORK	10 05.48 00 04 07.00 co	WOLE OF	BANDA B	-	E 10.0	SWINDS OF	(INDEX CIRCLE	OF INDEX	GRADUATION	-	STUD I	De DEAD	SPINOLE SPINOLE	- 10
	0	100	28	**	*	2.5	20				1	5	0	18	0-	**	2 2	No.	-				58	25	32	44	aχ	3.0			65	24	18	48		24
6.65	H		-	-	H	+	45	18	100	5	+	+				H	\vdash	89	18	17	85 87 88	72	-	+	32	44		125	39	14	65	24				24
65							46	-		1	72	İ						1	27	拼	88								18	4	65	24			40	24
65					_	-	47		1	b	88	1				_		Ľ	18	ļā.	87 91 86	_			_				39	装	65	24			48	24
+	-	Н	-		H	H	48		12	1	61	+		-	H	H	-	91	39	120	86	24		-	48	24	44	126	18		65	24			48 45	24 24
132						t	50		1	1	58	1				1			27	심	88	24			32	24	44		39	蒜	65	24				24
130							51		1	3	30 2	1			48	24	44	33	18	13	87	24		1	32	24	44	127	33	H	65	24			56	44
132	-	Н	-	-	H	1	52	39		1			-	24	-	H	-	94 95		1	83	-	-	_	-	۱.,	-	_	18	ş	61	24	-	-+	50	24
142	-			-	H	1	53	21		1					72	H	-	1	49	뵱	83	28	-	-	32	14	44	120	39	뱒	65	24	- +	+	72	14
13.				-		İ	54	-		1		Ť			Ė			96	21	31	85	28			12	24	44	120	33	#	65	A.			72	24
88						1	55		1	1	44	1	=					97			78	40	-	1	48	44			19	å	65	74.			??	24
87	-	\vdash	-	-	-	+	56	45	13	1	40	Ť	-	-	-	-	+	98 99			79	56	20	43	12	-	-	130	20	39	58	1.				13
1,126	-				1	1	1	40		- 1	40 5		-		40	24	44	100	+		78	30	1					137	33		59	1	i		+	
65							57	23	4	1	42 5	b			40		44	10	20		178		24		48		24		49	14	55	31		1	10	11
3 65	L	-		_	_	1_	58			+1	36	+	4	_	-		-	102	20		78	40	-		32	24	##		-	å	56 55	4		- 1		11
65	-	-			-	+	59	39	1 8	Ť,	32 4		-	-	32	44	+		39	100	78	40			48	-4	**	134	21	140 -	56	18			1	41
169		34					1"	18	1	12	32 4				32			10		1	75							135	27	黃	18			1	1	Ü
18:470	L				-	L	1	35	ij	ŀ	12	1					L	io		13	75 75 73 78	86	24	24	48			36	7	**	57			1	1	
132	-		3	-	-	+	160	18	13	1	12	+	-	-	_	-	-	107		1 23	73	40	58	32	641	-	14	117	77	平.	55	JF .			11	200
132	-	- 14		-	1-	†-	1-	35	াৱ	I	32 4	a.	-	-	30	24	44	-		- 6	773	34			28	24	44	1	4.0	14 43	55	en.	. ;			44
0 an				-	1	1	161	13			32 4		- 1		32	24	44	110	33	13	71							138	10	義	Sb	an.	. 1	1	12	44
69					1-	1	Ŀ	18	15	1	32 4		-	_	34	24	14	1	19	13	65 63	24	-		72	12 12		114	1/,	10	55	9.	12	10 1		_ !
2143	-					Ť	100	31	12	17	37	4	1	-	48		1-	ľ	18	155	65	24			72 73	12		- 1	47	14	55 55 55 55	Y. 1	-	1	1	- 4
69 43 43				3	1	1	63	lai	i	5	32 2 32 2	1	i		48	24	144	1	139	19	65	2.4			64	44	-	140	21	ŭ.	55 56		12	1	1	1
· Y					١.	1	1.	18	1	Ţ	72	1	i		48	24	44	his	133	ţij	65	21		1	64	44		141	125	46	34	40		1		44
1 161		33		2	-	4	65	415	1	1	73	3				1	1 -	1.	114	1	65	21			50	44	-	142	40.0	42	55 56	56	- 1	12	32	24
1.147			. 11		ŀ	1 -	100	1,5	1	+	10	6					6	100	11		1.5	17		-	56	44	-		49	14	55	18	- 3	1	14	7
147					ı		07	49	District of the last of the la	Ţ	13 .		Ġ		12	11		1	1	A	164	11	+		56	44		43	21	1	55 56 54 54	28	7 - 1	113		24
1,132					1	1	100	123	1	į,	3 -				.1.	11	-	1			10	.,			48	44		744	18	ġ.	54	1		1	1	- !
132		. 1			-	1	69			di	al :	1	i		١,		4.	ľ	14	. 0	i.,	1		-	41	44	-	115	16 21 11 11 11 11	il.	춙	28	-1	1	,3	, i
A Local	١.	- 3			1-	4		AG			1	3	-			1			24	1	.,	1			â			146	21	0.1	56	23	1			,,
i.					ı		7"	21	1	Ŀ	13							1.	11	1	1.4	1					9	11-1	14	3	55	a.	1	,1		14
	1			1	ı	1	171	17	18	T.	1:				1	13	30	١			119	21			21	50			71	2) 10	50	18.			1	21
i.,	1			.11	1	i	t	177		ľ	tu					1		1				23				1		1		4	55		2		4	21
9 4					ı	ï	172	118	1	Ġ					•	1	1	1		1	1.4	10			14	41		147.	41	Š.	56	27				24
. 5		1		1	1	1	73	45	18		9				15.4	- 1	11	1		Q.	1.0	1			17	14			11	41	32		1			
6 40			1		1	1	24	12	48	1	2	100			1.	1	11	1	. ' '	17		1			1	11	1		101		48	1	- 1			" 1
			1		1		71					4				1		1	. '	1	1	1			14	1.	H	1		3	48	12	1	1	1	16
. P.					ı	į.	70	'n		1	a)						. 1	1	11	· P	1.5				71	11		1	11	A	48	1-	÷	. 1	1	11
1. 11	1				ı	L	77	i A	11	115					1.	"		1		11			1 10					110			90 90		- 5		1	
٧,.	1		9	:	i	1	79			Ţ					71	.,		ſ		5								100	. 1		48	10		2	,1	n
i	1				1		160	1 m	ab	ſ	a]				7	1		1	10	1	fee	17:				24	H	1 -			48	4	- 6	1		14
20	1						19	14		ľ		3	,		. 28	-3	, 11	1		11	13	1		. !	4	24	+1	1991		から かっかっかっかん	48	al.	32	36 2	9.	1
5, ,	1	0)			1	٠	12	10	.18	1			þ	-		14	14	1	139	42.78	65	1	1		11	74	44	161	20	T	48 48	64	32	10 2	i	-
7.	1		9		1	i	17.	20	1	Ľ			1			1	ī"	121	LL	153	65					74	44	160	10	ī	48	48	1	1		24
9	1				1		100	b	I	Ī	-1	1	1			L.	L	1	18	15	65	14		1	34	74	44		20	I	48	32	1	1	10	100
1.1.	1				1	1	86	4	13	E	11		- 1					1	.19	18	65	14	0.5		24	24	44	164	200/2	18	147	1	1	1	N	1



turned in one direction, the same as in plain indexing. This enables spacings to be made that cannot be obtained with an index plate locked with a stop pin in the usual way. When geared for differential indexing, the machine cannot be used to cut spirals, as the spiral head spindle is then geared to the lead screw.

In the differential method there is little opportunity for error. The index crank being moved the same as for plain indexing, it is necessary only to place the proper gears in position, as indicated by the table that accompanies the machine. The change gears and index plates furnished provide for all divisions from 1 to 382, including all the prime numbers, and enable the divisions to be made with no more care than is required in plain indexing. With additional change gears and index plates a large number of divisions beyond 382 can be obtained. In the compound method, however, it is necessary to exercise great care, as two circles are employed, and the direction in which the crank is to be moved, right or left, must be kept constantly in mind.

The Table adjacent is plainly and conveniently made up to include both plain and differential indexing, thus avoiding the necessity of two separate tables. It gives all divisions from 1 to 382.

The index spacing number is 40. In other words, forty revolutions of the index crank are required to make one complete revolution of the index spindle. Therefore, if the index plate is geared to the spindle, using one idler to rotate one turn in the same direction as the crank, and the crank pin enters the same index plate hole, the result will be the spacing number 39, for the reason that while the crank has made forty turns and the plate one, in the same direction, the crank has passed a given point only thirty-nine times. With this same gearing, and the addition of another idler, the motion of the index plate is in the opposite direction to that of the crank, and the plate gains one revolution while the crank has made forty, resulting in the spacing number 41.

With the spacing number 39, it is possible to obtain divisions equal to 3×39 with a circle of three holes, 4×39 with a circle of four holes, we. This will apply equally well to the spacing number 41. Any division not obtainable with the index plate can therefore be made up with proper gearing.

In general, if the plate rotates in the same direction as the crank, subtract the turns of the plate to one turn of the spindle

worm 44.

from the turns of the crank to one turn of the spindle, and the remainder is the specing number. If the plate rotates in the opposite direction to the crank, the spacing number will be the sum of the turns of the plate to one turn of the spindle, added to the turns of the crank to one turn of the spindle.

Fractional Spacing.—This class of spacing is often required, and, to illustrate the application of the differential method, assume that it is required to space a vernier to read $\frac{1}{12}$ of a degree, or 5 minutes.

Usually the method adopted is to have the vernier spaces occupy a distance corresponding to 11 degrees, and divide this into 12 parts or spaces, which may be expressed as follows: $\frac{11}{560} \div 12 = \frac{13}{120}$, which is equal to one space. Therefore, there would be $\frac{4729}{11}$ spaces in the whole circle, or $392\frac{5}{11}$ divisions. The indexing of $\frac{1}{9}$ or 360 gives the difference between $392\frac{5}{11}$ and 360, which equals $32\frac{5}{11}$ to be obtained with the gearing. $32\frac{5}{11} = \frac{360}{11}$, which when multiplied by $\frac{1}{9}$, the value of one indexing gives $\frac{360}{11} \times \frac{1}{9} = \frac{40}{11}$ and the proper gears will be $\frac{200}{53}$ or $\frac{64 \times 100}{40 \times 44}$, or gear on spindle 64 teeth; first gear on stud 100; second gear on stud 40; gear on

Angles of Spirals. We have now to consider the method of calculating the angles of spirals for milling cutters, betical teeth, twist drills, reamers, we, in which the change gears and table screw come in. This mechanism is distinct from that of the spiral head, which effects divisions, or spacing only.

The feed screw of the table has four threads per inch, and must therefore make four revolutions to move the table along one inch. As forty revolutions of the worm in the spiral head are required to give one tuen to the worm wheel, and the spiral head spindle, then, if change gears of equal size are used, the table must move lengthwise 10 inches for each turn of the worm wheel and spindle. This relation between a revolution of the spindle and the movement of the table is termed the lead of the screw, or a 10-inch lead; and being constant, is often conveniently adopted as a basis for calculations. In other words, instead of the pitch of the crew, the distance of the table travel for one revolution of the

spiral head is employed. Hence the common term, lead of a screw thread, or spiral, equivalent to its pitch, is referred to lead of the machine table.

The change gears are calculated similarly to those of a screwcutting lathe, the ratio of the driven to the driving gears equalling the ratio of the lead of the spiral required to the lead of the machine. Put in the form of an equation, it stands—

(a)
$$\frac{\text{Driven gears}}{\text{Driving gears}} = \frac{\text{lead of spiral required}}{\text{lead of machine}}$$

or,

(b)
$$\frac{\text{Product of driven gears}}{\text{Product of driving gears}} = \frac{\text{lead of required spiral}}{10}$$

That is, the compound ratio of the driven to the driving gears is represented by a fraction, the numerator of which is the lead to be cut, and the denominator of which is 10.

Or the ratio is as the required lead is to 10.

Or the ratio is as one-tenth of the required lead is to 1.

Or, lastly—

(c)
$$\frac{\text{Driven gears}}{\text{Driving gears}} = \frac{4 \text{ times the lead of spiral required}}{40}$$

As in screw-cutting gears, ratios can be broken up into fractions, and numerator and denominator multiplied by numbers to find suitable wheels.

Taking examples in each case and taking equation (a)—

Say the lead of the spiral required is 24 inches, then 10 to 24 is the ratio of the gears. Both terms of the factor are multiplied by a number that will give numbers corresponding with the teeth of the change wheels. Thus—

$$\frac{24}{10} = \frac{3}{2} \times \frac{8}{5}$$

Then-

$$\frac{3}{2} \times 24 = \frac{72}{48}$$
, and $\frac{8}{5} \times 8 = \frac{64}{40}$

And 72 and 64 are the driven, and 48 and 40 are the drivers; and either 72 or 64 can go on the worm, and either 48 or 40 on the screw, the others going on the stud in the same way that transpositions are effected on the swing plate of the lathe.

Taking (b), the rule becomes:—Divide ten times the product of the driven gears by the product of the drivers, and the quotient is the lead of the resulting spiral in inches to one turn. This rule is of value in ascertaining what spiral might be cut with gears at hand. Thus, what spiral would be cut by gears of 32 and 56 driven, and 24 and 40 drivers? Then—

$$\frac{10 \times 32 \times 56}{28 \times 40} = 16 \text{ inches to 1 turn.}$$

Taking (c), to cut a spiral with a lead of 21 inches, multiply 21 by 4=84. The lead screw must then make 84 turns to 40 turns of the worm. The ratio then stands—

$$\begin{array}{c} \text{Driven gears} = 84 \\ \text{Driving gears} = 40 \end{array}$$

The ratio $\frac{84}{40}$ is broken up:—

$$\frac{84}{40} = \frac{7}{4} \times \frac{12}{10}$$

Then-

$$\frac{7}{4} \times 8 = \frac{56}{32}$$
, and $\frac{12}{10} \times 4 = \frac{48}{40}$

Then $\frac{56}{32} \times \frac{48}{40}$ are the gears required, 56 and 48 being the driven, and 32 and 40 the drivers.

The foregoing can be put into words, thus:-

Multiply the lead of the spiral required by 4, because that is the pitch of the lead screw. The number thus obtained will be a numerator, and 40—the number of teeth in the wheel—a denominator of a fraction, which will give the ratio required, that is—

> Driven gears Driving gears

Break this up into two fractions. Multiply the numerator and denominator by a convenient number or numbers to obtain those corresponding with the number of teeth in the change wheels supplied with the machine. The numbers must be the same for each fraction, but not necessarily the same for both fractions. In fact, it is not often possible to find numbers that

will serve for both, and several trials may have to be made to get these. The numbers of teeth corresponding with the numerators will represent the teeth in the driven gears, and the numbers corresponding with the denominators will represent the teeth in the driving gears.

Simple trains of gears can often be used with an intermediate wheel. Thus, to cut a spiral with a lead of 12 inches, the ratio is $12 \times 4 = 48 = \frac{48}{40}$. Then the 48 gear can be put on the worm shaft, and the 40 on the screw, with any intermediate that will make the connection.

When the change gears are obtained, the bed or table has to be set to the angle of spiral required. This is done either by a diagram, or from a table of natural tangents.

If obtained graphically, a diagram of a right-angled triangle is drawn, having one side equal in length to the circumference of the screw to be cut, and the side adjacent equal in length to the lead or pitch, while the hypotenuse, or, strictly, the angle included between the lead and the hypotenuse, is the angle of the spiral. It is by this that the table has to be set.

The angle may be measured, and the spiral bed set to a corresponding angle by the graduations on the clamp bed, or the angle can be marked on the work by a protractor, and the machine set so that the spiral shall be in line with the cutter.

The second method depends on the fact that the natural tangent of the angle of the spiral is the quotient of the circumference of the piece divided by the lead of the spiral. In this method, therefore, the circumference of the piece is divided by the lead. Then note is taken of the number of degrees opposite the figures that correspond with the quotient in a table of natural tangents. Having obtained the angles thus, the spiral bed is set by the graduations on the clamp bed.

Milling Screw Gears.—In considering these gears we must bear in mind the fundamental relations between spiral, helical, and worm gears, which are all alike screw gears. In the first place the only difference between spiral and helical gears lies in the direction of the axes of the wheels engaged. If the axes are parallel the gears are termed helical; if they are at right or other

· man Bien in

angles, they are spiral. The difference is that in the resonastic the screw sections must be of opposite hands or right and let while in the second they are of the same hand. In the increase also the angles are similar, in the second they are rely small a when the ax s of the wheels cross at ragles of 90.

With regard to worm gearing, although as a general statement it is true that a worm is a spiral of very short lead, or exhibit year. vet becasional exceptions occur, as when times or four threats a co The requirements of electric-motor reductions have given a great impetus to the development and expansion or violar driving, so that some many-threaded worms differ in no respect from common spiral gears, excepting in their grater length-Worms of from six to twelve threads are cut successfully and accurately and worm wheels hobbed to gear with them. Such work lies outside that of the pattern maker, which is select practised when worms exceed from two to three threeds, and is as a rule confined to single-threaded worms. The growth of the practice of hobbing has enabled good worm gears to be produced. besides which the accurate work of gear-cutting machines paradis of the making of gears that have a curious appearance to old-time had is. Examples of this kind occur in the case of worms and their who is, having say equal numbers of teeth, done to avoid the case he sliding that would occur in spiral genrs. Other case some longth over list we can worm wheels that me come only resta-Fig. 1 and be with rampalser of well-than the regulation the reservoir of the contract of properly preportioned to degree a done of the constraint for to the length of tooth.

When considered to I sinn helic i goars, the nearlier is to be some and the consequence with velocity in this means of the consequence of the velocity in the means of the consequence of the interveloped of the considered and of the considered and of the considered and of the means of the sequence of the considered and of the means of the sequence of the consequence of the

The pair is near and along the axis, and the normal, are practically

the same in worms of one or two threads, but when these are exceeded a difference becomes apparent.

Cutters are used for the worms only in the best practice, the wheels being hobbed. Exceptions occur in the straight diagonal toothed type of worm wheel, the teeth of which are cut similarly to other spiral or helical gears, since they differ in no respect from these. The cutting of worm gears is treated on pages 274 and 275. We first consider at length the principles and practice involved in cutting spiral gears.

The cutting of spiral gears is one of the duties for which the milling machine is eminently adapted. Gears of large dimensions are not easily tackled, because of the small size of the dividing wheel, and the limitations of the power of the machines. But large gears are not often wanted, and then they can be cast from patterns; or if they have to be cut in quantity, a special type of machine can be built, or specially heavy dividing heads fitted to a stiff machine.

The term spiral gears is used in deference to common usage, though it does not correctly define the form of gear to which it is applied. The term screw gears is correct, but, as a worm gear is as truly a screw gear as the "spiral" form, it is convenient to make the usual distinction in terms. Worm gears and spiral gears differ only in proportions, and not in the principle of their design. A worm helix or thread has a short lead or total pitch, a spiral wheel has this dimension very long by comparison. A worm contains at least one complete revolution of its helix, the spiral wheel usually has but a portion of a revolution of a helix. Worm threads seldom exceed three or four in number, spiral gears may contain portions of ten, twenty, forty, or more threads. The relationship of both to the rack is seen in spiral rack drives, which may be worm, or spiral driven, for slow or rapid speeds. A rack tooth is the basis for both alike in interchangeable gears.

Elements of the Spiral Gear.—Fig. 234 shows the spiral gear in its essentials. P is the primary or axial pitch, p' the normal ditto, and d the circumferential, a the tooth angle of the teeth of a wheel of width of face A.

The case of these gears is not difficult to grasp, if we bear in mind the fact that the pitches of spirals are the bases of velocity

1

ratios. That is, a ratio of 2 to 1 would require a wheel having twice the pitch of spiral of its pinion; and equal ratios pitches of equal length. But only in the single case of equal ratios are the circular pitches equal, because making the ratios and diameters unequal alters the tooth angles, and consequently the circular pitches, though in all cases the normal pitches must be alike. This is where difficulty is often experienced. Moreover, the greater the difference in diameters, the greater will be the differences in the angles, and in the circular pitches, so that the latter will hardly look as though they could be capable of gearing correctly, since one may measure twice or more that of its mating pinion. It follows that the diameters of the pitch lines measured on the wheel faces must have the same ratio as the velocities in spur wheels, to the exclusion of the normal pitch.




Fig. 234.—Elements of Spiral Gear.

Velocity Ratio.—The first operation necessary in estimating gears is to determine the sizes corresponding with velocity ratio, whether equal or unequal. The rule for this is:—

Divide the centres of the gears by the sum of the terms of the ratio, find the product of twice the quotient by each term separately, and the two products will be the pitch diameters of the two wheels. This rule is not affected by the angles of spirals or worms, but applies to all gears alike.

Example.—Two gears are wanted with a ratio of 2 to 1, the distance between centres to be 6 inches.

Then 2+1=3

 $\frac{6}{3}$ = 2 × 2 = 4 in. × 2 = 8-inch diameter of pitch circle of large wheel.

2+1=3

 $\frac{6}{3}$ = 2 × 1 = 2 in, × 2 = 4-inch diameter of pitch circle of pinion.

Showing that wheels of 8-inch and 4-inch pitch diameter fulfil the conditions required.

And, having the number of teeth of two gears given, to find the centres:—

Divide half the sum of the teeth of both gears by the pitch.

Say 60 teeth, and 20 teeth of 8 diametral pitch:—60+20=80

$$\frac{80}{2}$$
 = 40 and $\frac{40}{8}$ = 5-inch centres.

Spiral gears are used to transmit equal or different velocity




Fig. 235.—Elements of Spiral Gear.

ratios with shafts set at right or other angles, and either between wheels, or between a wheel and rack. In this work puzzles arise in relation to pitch and angle.

In the first place it is well to mention, by way of caution, that the outside diameter or periphery of the blank is not the surface in reference to which calculations refer. These are always taken on the pitch diameter, and the blank (in the diametral pitch system) is always two standard pitches larger than the pitch diameter, just as in spur and bevel gears. The tooth angle at the surface is a steeper one than that at the pitch plane. The cutter, therefore, on its first setting in does not show the true angle of

the teeth. The correct angle is obtained by the setting of the table.

Fig. 235 illustrates the relations of the angles of spirals and tops of teeth for the pair of wheels shown.

Pitches.—The pitch of a spiral gear is measured in the plane of its rotation, or parallel with the gear faces. But as the cutter used operates along the plane of the spiral, the result is that cutters have to be selected which do not correspond with the circular pitch, but with the normal pitch, and which is measured at right angles with the plane of the spiral. Also the cutters to be selected must vary with changes in the angles of spirals. But the same cutter must always be used for gears which have to engage together.

The utility of the circumferential pitch is, therefore, as a basis for the measurement of the diameter of the wheel blank, the diameter of which must correspond with the number of teeth, or velocity ratios required, although the cutters must always be selected in reference to the normal pitch.

The angle to which the table carrying the blank has to be set must correspond with the angle of the total pitch or lead of the spiral, of which the wheel teeth are short portions only. The problem, therefore, is to impart one turn to the imaginary cylinder of which the blank forms a short length, while the table is fed along a distance equal to the total pitch or lead.

Angle of spiral is governed by diameter as well as by lead. The smaller the diameter the less the angle, and the larger the lead the less is the angle. It follows that in every pair of gears, excepting those which have their axis at an angle of 45° and their spirals equal, there is no relation common to both wheels except the normal pitch. In wheels of 45° with spiral angles equal, normal, circumferential, axial or primary pitches, and number of teeth coincide, but in all others the first-named only.

Velocity ratios in spiral gears differ from similar ratios in spur gears in an important way. In these last, ratio depends on diameter and number of teeth strictly. That is, a certain number of teeth of a given pitch are inseparable from a certain circumference. But with spiral gears the rule does not follow, except in the case of gears having spirals of 45° of angle. In all other cases the

velocity ratios depend on the number of teeth, and not on diameter. Taking an extreme case, that of worm gears, the diameter of a worm exercises no influence on the velocity of the wheel which it drives, but only its number of threads, as one, two, or three. A spiral gear is only a worm of coarse pitch, as also the worm may be considered as a spiral gear of fine pitch.

It follows that by varying the angles of the spirals, in other words, the primary pitches or leads of the helix, it is practicable to make spiral gears in which the ratios will be very different, and greater or less than those which the diameters have (page 271). It is also possible to have coarsely pitched strong teeth on gears of small diameter. In such cases the gear whose circular pitch or angle of spiral is the greater will be the driver, because of the greater obliquity of its teeth.

Graphic Methods.—The problems of spiral gears thus range themselves under two heads, namely, axes at right angles and axes not at right angles, numbers of teeth equal and numbers of teeth unequal.

i

There are two methods of working out spiral gears—the graphic and the method of calculation. Both are safe, but the last can be obtained more quickly by the assistance of tables. Many, however, feel safer with the graphic.

The following is a concise statement of the graphic method for obtaining angles and teeth of spirals:—

To find the angle of the spiral for a given pitch (axial or primary pitch) and diameter of work, or to find the pitch corresponding to a given angle and diameter, set out a triangle with the pitch as a horizontal line and the perpendicular equal to the circumference of the work, and draw the hypotenuse. The angle of the latter with the horizontal, or pitch length is the angle of the spiral. It is the angle to which the slide of the milling machine is set.

Again, if the angle of spiral is given, draw the perpendicular equal to the circumference of the work, and then draw the hypotenuse at the given angle, to an indefinite length. Complete the triangle by drawing the horizontal until it cuts the slant line. The length of the horizontal so obtained is the primary pitch.

Again, the circumference divided by the pitch gives the tangent to the angle.

To find the pitch, subtract the given angle from 90°. The tangent of the remaining angle multiplied by the circumference gives the pitch.

It must be remembered that in all that has been hitherto stated the pitch surface of the wheels is meant, and not the outside of the wheels. So that to attempt to check the work on the outside by these rules would result in apparent discrepancy. The angle which the cutter would skim over on a trial cut is not that of the pitch surface.

Two equal spiral wheels with right-hand spiral teeth are shown




Fig. 236.-Equal Spirals with 45° of Angle.

in Fig. 236, of the kind which most commonly occurs. The angles between their axes are 90°, and the teeth make angles of 45° with these axes and with the wheel faces. The tooth angle is also indicated by a deep line on the upper gear. In order that this angle of 45° shall exist, the pitch or lead of the spiral must obviously be equal in length to the circumference at the pitch line, because any differences in these lengths would not give an hypotenuse of 45°. Stated in another way, the circumference and the pitch of the spiral must be alike, because the tangent of 45° is 1. The development of the wheel is shown to the left, the perpendicular equalling in length the circumference of the wheel, and the length of the base the pitch of the spiral. We lay out the length of the

base equal to the circumference, without reference, in this case, to any direct attempt at measurement, because we know such must be correct if the angle of the spiral is to be 45°. Fig. 236 also shows the pitching-out for a 12-toothed wheel. We take no notice yet of the top and bottom of the teeth, because the diameter of the blank gives the first, and the cutter takes charge of the second. The relation between the circumferential pitch a-b and the normal u-c, in this case (see the diagram to the right, where a-b is the hypotenuse of a c b), is that of a 45° of angle, being that of the wheel teeth. The circumferential pitch a-b can be measured directly: but if calculated, it is obtained for an angle of 45° by multiplying the normal pitch a-c by 1:4142, because 1:4142 is the secant of the angle of 45° , or the normal pitch can be divided by the sine of 45°, 70710, to obtain the same result. Conversely, the circumferential pitch can be multiplied by the sine 70710 of 45° to obtain the normal.

This difference between the two pitches is very important in determining the selection of cutters for wheels. It is clear that although the circumferential pitch a-b, Fig. 236, must be taken for sizing the blanks, the cutters suitable for that pitch, having a thickness of half a-b at the pitch line, would cut spaces too wide and leave teeth too thin when cutting normally to a-c. Thinner cutters must therefore be selected than those used for spur wheels of the same nominal pitch. Hence the rule:—As the angle a-b-c equals the angle of the spiral, and the line b-c corresponds with its cosine, multiply the cosine of the angle of the spiral by the circumferential pitch. The product will be the normal pitch, one half of which will be the thickness of the cutter at the pitch line.

The reverse of this rule is to be borne in mind also: -

Divide the normal pitch by the cosine of the angle of the spiral. The product will be the circumferential pitch. (N.B.—"Circumferential" and "circular" pitch are terms used here loosely to denote the same pitch—that in the plane of the wheel faces as distinguished from the normal, and not necessarily in contrast to diametral pitch.) The diametral pitch of the gear can be obtained, after the selection of the cutter, by multiplying the diametral pitch of the latter by the secant of the angle of the tooth. A useful table is given overleaf for different pitches and angles.

TABLE OF SPIRAL GEAR-DIAMETRAL PITCHES.

		Angle—15°.	Angle—30°.	Angle—45°. Corresponding Diametral Pitch of Spiral Gear.		
Pitch of Cutter.	Depth to be cut in Gear.	Corresponding Diametral Pitch of Spiral Gear.	Corresponding Diametral Pitch of Spiral Gear.			
	Inch.	Inch.	Inch.	Inch.		
24	-090	0431	0481	0589		
22	-098	0470	·0525	0643		
20	·108	0517	0577	·0707		
18	·120	0575	0641	0785		
16	·135	0647	0721	.0883		
14	·154	.0739	.0824	·1010		
12	·180	.0862	-0962	·1178		
11	·196	0941	·1049	1285		
10	•216	·1035	1154	·1414		
9	•240	·1150	1283	·1571		
8	.270	·1294	.1443	1767		
7	-308	·1479	·1649	2020		
6	.359	1725	1924	2357		
5	431	2070	2309	2828		
4	539	2588	2886	3535		
3	·719	3451	·3849	4714		
•,	1:078	5176	5773	7071		

The diameter of the blank, equalling two pitches, added to the pitch diameter must be calculated on the basis of the normal pitch for which the cutter is selected, and not on the circumferential pitch, and the same remark applies to the depth of tooth. And hence, too, the circumference of a gear blank equals the number of teeth multiplied by the normal pitch, multiplied by the secant of the angle of spiral, plus two standard pitches.

Or,

Circ. = number of teeth × normal pitch × secant a + 2p.

Also, the pitch or lead of the spiral and the circumference of the wheel stand in the relation of secant and cosecant of the same angle of animal. Hence the lead of the spiral equals the number of teeth multiplied by the normal pitch, multiplied by the cosecant of the angle of the spiral.

Or,

Pitch, or lead of spiral = number of teeth \times normal pitch \times cosecant a.

If a piece of paper is cut, as in Fig. 237, and wrapped round a cylinder of the same diameter

as the pitch plane of the spiral gear in Fig. 236, but considerably longer than the thickness of the wheel, we

shall have the result shown in Fig. 237, in which the




Fig. 237.—Triangle wound round a Cylinder.

primary pitch or lead of the spiral is also the base of the triangle, the circumference is the same as the perpendicular, and the angle of spiral is the hypotenuse.

Also in Fig. 236 the spiral wheel is shown developed along the




Fig. 238.—Spiral Gears of Different Diameters, but Equal Angle.

edge of the circumference, from which the fact is clear that a spiral rack is only a developed spiral wheel, and hence such gears will engage correctly.

Wheels with their axes set at an angle must be bisected unequally for unequal ratios, Fig. 242, in which case the spirals are of different angles and the circular pitches different. The

PITCH OF A

Fig. 242.—Spirals with Unequal Ratios.

development is shown in Fig. 242 for wheels A and B.

Racks or spur gears can be mated with spiral wheels at an angle. In such cases the spirals must be the In Fig. 239 a drivers. spiral wheel with its teeth set at an angle of 45° was shown engaging a rack, or a spur wheel might be substituted for the rack. Fig. 243 a spiral with an angle of 45° engages a spur wheel. In both these cases the pitch of the rack or spur is the same as the normal pitch of the spiral gears.

This helps to illustrate the reason why cutters must be selected based on normal pitch for any spiral gears irrespective of the differences in circular pitch. In these examples, the shading only indicates the circular forms of the gears.

Trigonometrical Rules.—Many prefer to employ these graphic methods, which are safe. But they may be dispensed with by using a few of the simple rules of plane trigonometry. Since the functions of angles are constant, the relations of circumference, pitches, angles of spirals, and normal and circular pitches are obtainable. These will



Fig. 243.—Spiral Gearing with Spur.

be first briefly explained, and then formula for spiral gears based thereon tabulated.

Fig. 244 illustrates the functions of a right-angled triangle, which are applicable to spiral and bevel gears having axes at right angles.

ABC represents the triangle, in which AC is the base, BC the perpendicular, and AB the hypotenuse. In this we recognise also the base as equivalent to the pitch of a spiral, the perpendicular as equal to the circumference of the cylinder, and the angle of the hypotenuse as the same as the angle of the spiral. If a piece of paper is cut to the shape of the figure and wound round a cylinder of the same circumference as the length of the perpendicular, the spiral will be developed on the cylinder.

An arc is shown struck from C to D from A as centre. The perpendicular CB is the tangent to this arc, and it is perpendicular to the base, or radius AC which meets it at the point of tangency. The tangent CB is also the tangent to the angle CAB, and is used in calculation. If the length of the perpendicular or tangent CB is known, the number of degrees in the angle CAB can be found in a table of tangents, and this, as we see, is equivalent to the angle of spiral.

There are two angles in any right-angled triangle, either of which may be required to be known. Hence, when speaking of the angle CAB, the base CA is termed the side adjacent to that angle, and, when speaking of the angle CBA, the perpendicular CB is the side adjacent to that angle.




Fig. 244.—Trigonometrical Functions.

The following rules are based on the functions of right-angled triangles:—

To find the tangent of either acute angle in a right-angled triangle—

Divide the side opposite the angle by the side adjacent the angle, and the quotient will be the tangent of the angle. In Fig. 244 the rule might read correctly:—Divide the perpendicular by the base, and the quotient will be the tangent of the angle CAB.

Angles are measured by arcs in degrees and minutes. Thus a is the measure of the angle c a b, and b that of the angle c b a.

The complement of an arc is the difference between it and 90°. Thus *a* D in Fig. 244 is the complement of c D, and vice versa.

The supplement of an arc is the difference between it and 180°,

or of a semi-circle. The sine of an arc is the line drawn from one extremity of the arc perpendicular to the diameter passing through the other extremity. Thus b D is the sine of the arc a D, and it is equal to half the chord of the arc D c. The versed sine is the length a b between the chord and the arc. A d is the secant of the arc a D.

The complements of the functions of an arc are denoted by the prefix co—as cosine, cotangent, and cosecant. Thus the arcs C D, D a being the complement of each other, the sine, tangent, and secant of either is the cosine, cotangent, and cosecant of the other. Thus b D, the sine of a D, is the cosine of D C. D c, the sine of D C, is the cosine of a D; a d, the tangent of a D, is the cotangent of D C; c B, the tangent of C D, is the cotangent of a D; A d, the secant of a D, is the cosecant of D C; and A B, the secant of D C, is the cosecant of a D. In any arc a D, therefore, the versed sine a b and cosine D c make up the radius A a or A D. And the radius A a, the tangent a d, and the secant A d make the right-angled triangle A a d. Also the radius A c, the cotangent C B, and cosecant A B make the other right-angled triangle A C B.

The sine of an angle is the sine of the arc that measures the angle. It is always inside the arc, and can never be longer than the radius. As the arc approaches 90°, the sine comes nearer to the radius, or 1. Thus (a), the sine and cosine can never be greater than unity; and (b), the secant and cosecant can never be less than unity, while (c), the tangent and cotangent can have any value between zero and infinity.

Referring again to Fig. 244, the trigonometrical ratios of the angle at A may be summarised as follows:—

The sine of
$$A = \frac{\text{perpendicular}}{\text{hypotenuse}} = \frac{B}{A} \frac{C}{B}$$

The cosine of $A = \frac{\text{base}}{\text{hypotenuse}} = \frac{A}{A} \frac{C}{B}$

The tangent of $A = \frac{\text{perpendicular}}{\text{base}} = \frac{B}{A} \frac{C}{C}$

The cotangent of $A = \frac{\text{base}}{\text{perpendicular}} = \frac{A}{B} \frac{C}{C}$

The secant of $A = \frac{\text{hypotenuse}}{\text{base}} = \frac{A}{A} \frac{B}{C}$

The cosecant of $A = \frac{\text{hypotenuse}}{\text{perpendicular}} = \frac{A}{B} \frac{B}{C}$

We have now the following trigonometrical rules for spirals. In Fig. 244 the circumference of the cylinder around which the spiral is wound corresponds with the perpendicular of the triangle, or the side opposite the angle of the spiral.

In words the rules are:-

To obtain the angle of the spiral-

Divide the perpendicular (circumference of cylinder or spiral) by the base (number of inches of spiral to one turn), and the quotient will be the tangent of angle of spiral.

When the angle of spiral and circumference are given, to find the pitch—

Divide the perpendicular (circumference of cylinder or spiral) by the tangent of angle, and the quotient will be the base (pitch of the spiral).

When the angle of spiral and the pitch of the spiral are given, to find the circumference—



Multiply the tangent of angle by the pitch, and the product will be the circumference (perpendicular).

Fig. 245.—Circular and Normal Pitches.

The angles which the circular and normal pitches make with each other bear the same relation as the axes of the wheels and the tooth angles. Hence they can be deduced one from the other trigonometrically as well as by direct measurement. In Fig. 245 a c is the circular pitch, and a b the normal, and the angle b a c is the same as that of the spiral, a b is the cosine of the angle b a c.

Then--

Circular pitch \times cosine angle = normal pitch.

and--

normal pitch cosine angle eircular pitch.

We have seen (page 264) that the ratios of diameters are alike in some instances, and different in others. In the latter case the condition to be observed is that the pitch of the spiral of each gear shall be equal to the circumference of the other, or any fraction of the same, depending on the ratio desired. The velocity ratio is measured by the number of teeth, and not by the diameters. The object first is to select the angles, and from these the corresponding diametrical pitches.

ļ

Example.—Required two gears at right angles, measuring respectively 2-inch and 4-inch diameter, the 4-inch gear not to be used for speeding up the 2-inch, but for speeding it down, in the ratio of 2 to 1. The circumference of 4 inches is 12:5664, that of 2 inches is 6:28319. Half the circumference of the 2-inch gear is 3:14159, which is the lead of the spiral of the 4-inch gear. But the lead of the spiral of the 2-inch would be twice the circumference of the 4-inch gear (the axes being at 45-) or 25:1328 inches. Dividing the circumference by the pitch gives the tangent of the angle. Hence—

Circumference of 4-inch = 12.5664.

And $\frac{12\cdot5664}{3\cdot14159}$ =4, and 4=a tangent of angle of nearly 76°. 76° from 90° leaves 14°, which must be the angle of the 2-inch gear. These relations are shown in the diagram, Fig. 246.

To obtain the cutters by the rule (page 261):--

The secant of 76' is 4:1336. That of 14' is 1:0306. Selecting an 8-pitch cutter, and multiplying this by the secant of the angle, we have:—

 $4\cdot1336\times1250=5167$ = the corresponding diametrical pitch for 76 . And $1\cdot0306\times250=1288$, that for 14 .

The numbers of teeth that will work out nearest to the sizes of wheels required are:—

24 for the 4-inch wheel--

 $24 \times 5167 = 124008$ eirc.

And, 48 for the 2-inch wheel -

 $48 \times 1288 = 6.1824$ eire.

So that diameters would have to be slightly modified, and the leads of the spirals corrected to suit.

Another way of putting it is this:—

The tangent of the pitch diam, of wheel number of teeth in pinion spiral of wheel pitch diam, of pinion number of teeth in wheel and

The tangent of the pitch diam, of pinion s number of teeth in wheel spiral of pinion pitch diam, of wheel s number of teeth in pinion

The illustration given, Fig. 246, is an extreme case, and it is not a desirable gear, but it shows the flexibility of the spiral gears.

When axes are at any angle. When the numbers of teeth in the two wheels are given the angles are found by a graphic method. In Fig. 247, a b and c b are the axes of gears which include the angle o between them. On these axes distances are set off b a, b c representing the velocity ratios, and a parallelogram completed, so that the number of the teeth in the wheel: the number of teeth in the pinion: a d: c d. The tangent b d, if common to the teeth passing through the point of contact, ensures the least amount of sliding. But if the angle o is bisected at e b, the end thrust is equally distributed on both shafts. If an angle is taken, b f bisecting c b d, a slight advantage of each kind is gained.




Fig. 246.—Spirals with Velocity Ratios that do not correspond with Diameters.




Fig. 247.—Angles of Spiral obtained from Numbers of Teeth.

 $^{\prime\prime}$ Fig. 248 illustrates the milling of a spiral gear in the shops of Ludwig Loewe & Co.

Worm Gears.—There is more trouble experienced in getting good worm gears than spurs, or even bevels. I have seen some so badly cut that the wheel teeth have had to be trimmed and filed to make a decent fit, and have also known gears, machine-moulded from pattern blocks, substituted for those which have been cut, and better results obtained thereby. There are three reasons for this poor practice: one is that special types of machines are best adapted for cutting the concave forms of worm-wheel teeth; that a rather costly hob is generally necessary; and, in

the case of small wheels, the conditions required to ensure good gear are not always understood.

A worm wheel in which the teeth are straight, and inclined at an angle corresponding with the angle of the thread of the worm, is easily cut with a rotary cutter, and it is sufficiently good for a large quantity of work. Wheels used for dividing purposes, and for light running, are mostly made like this. But when heavy work has to be done, and good wearing capacity is desired, it is




Fig. 248.-Milling Spiral Gear.

the usual practice to make the teeth envelopes of the worm. Such gears, when run at moderate speeds, are very durable. Good results are obtained when both wheels are in cast iron, provided they are well lubricated with plumbago and grease. Sometimes steel worms run with cast-iron wheels, because iron worms always wear out before their wheels. The best results are found when the worm is of phosphor bronze running in an iron or steel wheel.

The breadth of the teeth of a worm wheel is about half the diameter of the worm, though it is often less. There is no advantage in excessive width. Three complete turns of a thread are sufficient for contact in any case. The diameter of a worm is

generally from four to five times the circular pitch. Worm-wheel teeth are reckoned by circular instead of diametral pitch. The pitch is measured along the axis of the worm and in the middle plane of the wheel, and is therefore axial. Normal pitch, though more correct, would not be so convenient a working basis. There is a way of reckoning pitch which differs from that of common gears, and which gives it as so many threads in the linear inch, as 1 pitch or 2 pitch.

Worm wheels frequently have their concave teeth cut with rotary

cutters, Fig. 249, on milling machines. The results are satisfactory as far as pitching and tooth angle are concerned, but the




Fig. 250.—Obtaining the Shape of Tool for Cutting Worms.

oth angle are concerned, but the curved teeth are not true envelopes of the worm, as they are when wheels are hobbed. There is doubtless more surface contact between the teeth than when straight teeth are employed, but the advantage is probably not very great.

Fig. 249.—Cutting Worm Wheel

Teeth with Common Cutter.

When teeth are cut thus, the wheel blank is carried between the index centres, and the centre of the wheel brought under the centre of the spindle which carries the cutter. The table is set with the saddle brought to the angle of the teeth, and the vertical feed of the table

takes the cutter into the proper depth.

Cutting wheel teeth to become true envelopes of the worm

can only be done properly by a hob in shape like the worm, or by a machine in which a single cutter is presented at various angles. This requires a stiff machine, support to the wheel rim against the cutting, and a motion of the wheel blank relatively to the hob at the same rate as the velocity ratios of the wheels when finished.

The involute tooth is accepted as the proper form of worm



Fig. 251.

Worm Gear Teeth.

gear, not because cycloidal forms cannot be cut, but because it simplifies matters to turn or mill the worm thread with a vee-shaped tool or cutter of definite angles, and to make that—the rack tooth—the basis for all wheels.

Though the threads of worms are very commonly turned in the lathe, yet they are also done more properly in the milling machine, using a swivel head set to the proper angle, and a rotary rack cutter.

Turning a worm thread is just like turning any screw thread in the lathe, whether it be single, double, or treble threaded. Fig. 250 shows how the shape of the tool for cutting the rack-

shaped teeth is obtained. Upon a line AB draw a circle AC, BD. From B lay off the distance BC and BD, each equal to one quarter the diameter of the circle. Draw CA. DA, which make an angle of 29°the angle of inclination of the sides of the rack tool. Make the breadth of the tool at the end x-yequal to 0.31 of the circular pitch.

The width of the top of the thread

of a worm is 0.335 of the circular pitch. The relations of the worm and wheel teeth are shown in Fig. 251.

Fig. 252.-Hob for Worm Wheel.

The hob, Fig. 252, by means of which the wheel teeth are cut, is turned in steel to the same shape as the actual worm, plus a little extra in diameter, sufficient to give the bottom clearance between worm and wheel. The proportions of the hob should be these:—The diameter exceeds that of the worm by twice the

í

amount of bottom clearance in the wheel teeth. The depth of the hob thread is equal to that of the working depth, plus the clearance; the diameter at the bottom of the hob thread is the same as that of the bottom of the worm threads. Grooves are then slotted out in order to form teeth, which are backed off and hardened, converting it into a cutting tool. The grooves are planed or milled out with a round-edged cutter, the straight portion terminating at the bottom of the thread, leaving the concavity below the bottom.

When a wheel has its teeth cut in this way, every portion of each tooth comes into successive contact with the thread of the worm during the revolution of the latter. At no instant is a tooth tace a perfect envelope of the worm thread, and therefore any attempt to cut such teeth perfectly with a single rotary cutter, as in Fig. 249, must needs result in a tooth space of uniform section, which would not give a correct gear. Neither teeth sections nor spaces are uniform and symmetrical, and the departure from symmetry is more pronounced with multiple-threaded than with single-threaded worms. The forms obtained result from the peculiar relations of the worm and the concave section of the wheel rim, and the effect is exactly as though the worm cut out its wheel teeth in a softer substance. The wheel blank is rotated through change wheels, regulated to move it at the proper velocity ratio in relation to the worm. This is essential to ensure perfect results, notwithstanding that a worm will cut its wheel teeth without change gears. To have the pitch right, however, by this method it is first necessary to block out the teeth; because if this precaution is not taken—that is, if the hob cuts its way into the blank from the beginning,—the first cutting will take place on a diameter larger than the pitch diameter, and by the time the wheel is finished the pitch on the pitch diameter will be less than that of the worm, and the teeth too many in number.

A relieved hob is formed on the same principle as the relieved milling cutters, so that its sectional form does not alter by regrinding on the front faces of the teeth.

J. E. Reinecker, one of the leading toolmakers in Germany, cuts worm wheels with a hob shaped as in Fig. 253, to which an endlong movement is imparted, as shown in its successive advances in Fig. 254, during its revolution. The advantage is that the hob has not to be fed deeper into the blank as it cuts,

but it is set to correct centres once for all. The blank is mount on an arbor in a machine illustrated on pages 147 and 148.




Fig. 253.—Triple-threaded Tapered Hob.




Fig. 254.—Reinecker Hob Cutting Worm Wheel.

Table of Worm Gear—Diametral Pitches. Brown & Sharpe Standard Depth.

Pitch of Worm.		Working Depth of Worm Thread.	of	Corresponding Diametral Pitch of Gear.	Working Depth of Worm Thes
1nches. 1- 8 1- 6 1- 5 1- 4 1- 3 3- 8 4-10 1- 2	Inch. •0398 •0531 •0637 •0796 •1061 •1193 •1273 •1592	Inch. :0796 :1062 :1274 :1592 :2122 :2388 :2546 :3184	Inches. 5 8 3 4 7 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Inch. ·1988 ·2388 ·2785 ·3183 ·3982 ·4774 ·5573 ·6366	Inches. :3978 :4774 :5570 :6366 :7960 :9550 :1141 :1:2732

The depths given do not include the clearance.

Rule.—Multiply the corresponding diametral pitch by the number of teeth to get the pitch diameter, and add the working depth of the tooth to this to get outside diameter.

Example.—40 teeth, 4-pitch worm. 0796 inch $\times 40 = 3.184$ inches pitch diameter. To the pitch diameter add the working depth of thread, 1592 inch, which gives 3.343 inches as outside diameter of flat top gear, or throat diameter of curved face gear.

There are indications that the practice of milling screws instead of cutting them in the lathe will assume great importance in the machine shop. The sizes produced are constantly increasing, and considerable economies effected over lathe work. The two best known machines, the Liebert, and the Pratt & Whitney, are constructed in a number of sizes, and produce both square and veethreaded screws, the cutters being of special type. In the Liebert, cutters of pressed sheet steel are employed. The machine has a long bed, carrying a head which supports the blank, the latter being fed by change gears situated at the end of the bed. The cutter head has adjustment for height, and a swivel motion, to bring the cutter into correct angling with the screw being operated upon.

In the Pratt & Whitney a somewhat different design is made, the screw being carried between a head and a tailstock, in lathe fashion, while the cutter slide travels along the bed, and has a swivelling head for the cutter arbor. The largest Pratt & Whitney machine takes up to 12 in diameter by 48 in in length, being therefore suited for the production of large worms, spiral gears, etc.

CHAPTER X.

SPUR AND BEVEL GEARS.

Sp. t. and Bevel Goars - Diametral Patch - Blanks - Currus - Projector - Bevel Wheels - Multiple Catters - Multiple Certus - Multiple Cert Tatered Work.

Spur and Bevel Gears.—The diameters of spur and bevel wheel Tanks in common with spirals and worm wheels are as termined by the amount of addendum added to plick apareter





Fig 255, -te ar Tooth Rule.

because there are four tooth in a of diameter in a 4-pitch wheel. This is a shade

easily began in mind the singular tracks is to be puried

roles. 01 001100 1. 20-1 (ed). officers in the conf-



This is generally equal to the diameter plach. Thus hi wheels of 4-pitch the addendum would measure 1 inch.

Fig. 256. - Diametral Why.

the wholer of teeth is read off on the line of asset the 20th divisions added thereto gives at one a proster of the blank.

The use of diametral pitch, illustrated by the diagram in Fig. 256 - an 8-pitch wheel—simplifies matters in calculation. It is very easy to lay down numbers of simple calculations (which need not be given here) all referable to this, and all facilitating the work of gear cutting, while, when necessary, diametral and their corresponding circular pitches can be ascertained by dividing 3:1416 by the diameter pitch for the circular pitch, and the latter can be converted to diametral by multiplying it by 0:3183, which is a short way of dividing by 3:1416.

Table of Diametral Pitch, with its Equivalent Circular Pitch in the Adjoining Column.

Diametral	Circular	Diametral	Circular	Circular	Diametral	Circular	Diametral
Pitch.	Pitch.	Pitch.	Pitch.	Pitch.	Pitch.	Pitch.	Pitch.
2 2 2 3 3 3 3 4 5 6 7 8 9	1:57 1:39 1:25 1:14 1:05 :898 :785 :628 :524 :448 :392 :350 :314	11 12 14 16 18 20 22 24 26 28 30 32	·280 ·262 ·224 ·196 ·174 ·157 ·143 ·130 ·120 ·112 ·104 ·098 	Inch. 13 15 15 15 16 15 16 15 16 16 16	1·79 2·09 2·18 2·28 2·39 2·51 2·65 2·79 2·96 3·14 3·35 3·59 3·86	Inch. 34 11 16 18 16 18 16 18 16 18 11 16 11 16 11	4·19 4·57 5·03 5·58 6·28 7·18 8·38 10·06 12·56 16·75 25·12 50·24

Blanks.—When sizing the blanks of bevel and mitre wheels the safest course is to draw them carefully in section, Fig. 257, adding, as in spurs, one diameter pitch beyond the pitch line on the large diameter. By drawing all lines in section the dimensions at the small end are obtained, and the working depth of tooth and the thickness of tooth or tooth space, which are equal, on the small end. The working depth is of course equal to the

addendum. The bottom clearance, added below this, is generally equal to one-tenth the thickness of the teeth on the pitch measured on the large side. The thickness of a tooth on pitches leaving no flank clearance, is half the pitch. It is obtained diameter pitches by dividing 1:57 by the diametrical pitch in 5-pitch it would be $\frac{1:570}{5} = 0:314$, and a tenth of this would




Fig. 257 - Development of Bevel Gears.

Fig. 258. Gauge Tooth Length.

0031 bottom clearance for a 5-pitch tooth. Tables are v in shops.

The blank, Fig. 258, is turned to the dimensions taken from the drawing, Fig. 257, and it is well to run round two lines taken from the drawing giving the depth of tooth to be cut, Fig.: using a gauge for the purpose, one of which is supplied for epitch by firms who manufacture cutters, &c. The depth of both

clearance c, Fig. 257, is generally made alike at large and small ends in wheels which are cut with rotary cutters.

There is no extra trouble involved in striking-out wheels which work at angles other than right angles, or wheels of different diameters. The methods illustrated in Fig. 257 show how the bounding faces of the teeth converge to the apex of the cones, and that the ends of the teeth stand at right angles with the pitch planes.

Cutters.—For gears most cutters now have a centre line round the edge which facilitates their setting. It is usual in spur wheels up to about 4 or 5 pitch to rough and finish at one traverse. In large teeth a stocking cutter, Fig. 259, generally removes the bulk of material, the finishing cut being taken by another, Fig. 260.—It




Fig. 259. Stocking Cutter.




Fig. 260, Gear Cutter.

is always judicious to test the first tooth and tooth space cut as to thickness before going round the wheel, and particularly so when the cutters or the machine have had much service.


The shapes of cutters are determined on a definite basis, which is that of a generating circle in the case of cycloidal teeth, that of the angle of the path contact or of pressure in involutes. In standard gears the latter is 75° with the line of centres, or 14½° with a line cutting the line of centres at right angles. This is the equivalent of the generating circles of the cycloidal-toothed wheels. The base of the system is a rack having teeth with straight sides, each inclined at an angle of 14½°, and therefore including an angle of 29° between them, Figs. 250 and 251. This is an extremely

simple and convenient system, both in design and in cutter formstion, but with wheels having less than thirty teeth it leads to some undercutting. If it is necessary to have small pinions without undercutting, then the angle of obliquity of the path of contact has to be increased to 20° or more, which means a special set of cutters designed on that basis, and a correspondingly high angle of pressure.

Manufacturers follow the Brown & Sharpe initiative in having eight cutters for a set of involute teeth of one pitch, which are well known by their numbers. As the numbers of teeth increase, the cutters include a wider range on which they will operate. A different set of cutters is properly used for spurs and bevels, the latter being thinner by 0.005 than the tooth space at the narrow end, taking the tooth length as not longer than one-third the distance from the larger-diameter of the teeth to the apex of the







cones. If wheels of longer face have to be manufactured, thinner cutters have to be specially made.

Cutting the teeth of spur wheels with rotary cutters is an accurate method. Not so that of bevel wheels. Difficulties occur in setting the wheel blanks to the proper angle laterally, but chiefly to the fact that a given cutter can only be of correct form for one section of the wheel tooth. If we look at the section of the bevel wheel in Fig. 257, we see that the longer the teeth of a wheel are, the more unfavourable are they for fairly correct cutting that in a length of d the difference in the section of the two ends is not so great as it would be in a length of e.

The forms of the cutters are variously taken as correct at the large end of the teeth, which is the most general practice, at a distance of one-third of the length of the teeth inwards, and, in the case of exceptionally wide teeth, at half-way along between the large and small ends. The intention, therefore, is to have the teeth true, or very approximately correct at the large end, and to allow such inaccuracies as are inseparable from the use of a single cutter to accumulate towards the smaller end. Here they will not be so very pronounced, by reason of the diminished length of teeth, and consequently of the diminished profile of the cutter in actual operation, and there will also be only the minimum of metal to be removed by the file for the purpose of correction. It is an excellent illustration of a method which is theoretically incorrect being made to produce in skilful hands fairly good results.

An important point in cutting is that the care of the profiles

at the smaller ends counts for much less than shaping the widths of the tooth spaces and tooth thicknesses correctly at the pitch lines. The first may be corrected, the second not at all, or not without a good deal of trouble.

On commencing to cut the teeth of bevel wheels, the first care is to set the blanks to the correct vertical angle, which corresponds with the angle at the bottom of the clearance




Fig. 263.—Gauging Gear Teeth.

space c in Fig. 257, keeping this parallel with the addendum length. Then the angle in the other plane is set with as close an approximation to accuracy as is practicable, Fig. 261, and a cut taken down one side. Here the need of having the cutter thinner than the tooth space at the small end of the wheel in a wide one is apparent, as a wide cutter would take out too much metal there. The gear blank is then set over at the opposite angle, and a cut taken down the opposite side of the space, Fig. 262. The widths of the space on major and minor pitch line are now checked before going further with a gauge, Fig. 263.

. Projection of Bevel Wheels.—The cutters selected for mitre and for bevel wheels are not those which correspond with the numbers of teeth in the wheels, as they are in the case of spurs, but those which correspond with the number of teeth of the diameters projected from the tooth ends to cut the axes of the wheels. In some wheels with a slight bevel the difference will not be great; in those of flat bevel it will be very different. Only in mitre wheels, and wheels which nearly approach them, will one cutter suffice for both wheels. In most pairs of bevels a distinct cutter will be used for each of the pair.

The method of ascertaining what cutter should be selected for bevel-wheel teeth is similar to that employed for striking out the teeth on the projected faces.

In Fig. 257 the pitch diameter A of the wheel, and B of the pinion, and the actual number of teeth, are not those upon which the size of cutters is based; but the diameters A' and B' projected in line with the ends of the teeth to cut the centre lines have to Thus in Fig. 257 the distances f-g, f-h correspond, so far as the selection of cutters is concerned, with the radii of spur wheels. So that these distances have simply to be multiplied by 2 to obtain diameter, and the product multiplied by the diametral pitch, which gives the number of teeth that would correspond with spur wheels of radii f-g, f-h. If the radius f-g is 14 inches, then twice 14 inches is 28 inches, and 28 inches multiplied by a diametrical pitch, say, of 5=140, the number of teeth which corresponds with the size of a wheel projected on the plane f-g, for which a No. 1 or "rack" cutter must be selected. For f-h the radius is 34 inches, and this multiplied by 2 gives 61 inches, and by the diametrical pitch 5=31.25 inches, which requires a No. 4 cutter.

This takes the cutters as being right for the large ends of the teeth, which is often done; but see page 283, except in the special cases of very long teeth. In mitre wheels, since the lengths of the projected radii would be equal, a single cutter serves for the teeth of both wheels.

The formation of the teeth by rotary cutters is done under the most favourable circumstances when the teeth are short. The proportion of one-third is given as an ordinary working limit; but this is too great in many instances. The most favourable condi-

tions are those in which the pitch is coarse and the teeth not longer than about two and a half times the pitch. In teeth of fine pitch and of greater width, accuracy depends very much upon the care with which the cutting is supplemented by filing. In some wheels used for gearing which is required to run with exceptional smoothness at high speeds, the cutting has been supplemented by grinding in a suitable framework with emery and oil.

It is clear now why the mere possession of accurate cutters does not ensure correct bevel-wheel teeth. The cutter which is right for one end is not right for the other or for any intermediate

position. Here the skill of the workman comes in. Different men adopt varied methods to get the best approximation to truth, of two evils choosing the lesser. The evil is that of having to file the faces of the teeth at the small end off to nothing at the large, as in Fig. 264, where the metal left for filing is indicated by dotted lines on the tooth on the left hand. The amount of filing can be lessened by using a cutter that gives more rounding of the faces, but then that imparts too much rounding to the faces at the large ends. Or an extra cut can be taken upon the small ends,




Fig. 264.—Effect of Cutting Bevel Gear Teeth with a Rotary Cutter.

which means another set of cuts all round on each face. Inaccuracies, too, arise due to the rolling of the gear sideways for obtaining the taper of the teeth, which tends in small pinions to cut too much off the faces, though scarcely apparent in flat bevels. The setting of the gear blank out of centre for cutting the faces to the correct bevel is not a simple matter for calculation, because the same part of the cutter which cuts the large end of the tooth at the pitch line does not cut the corresponding portion at the small end, but a narrower portion of the cutter. This is one reason why trial cuts between teeth are made at the commencement before going round, and the thicknesses of the teeth gauged at pitch lines. When the first tooth and two spaces are all right, the rest of the

cutting can be done all round one side first, followed by a cutting on the other side.

Cycloidal as well as involute-shaped cutters are suppli spur gears, but not for bevels, for which they would be unsu-If cycloidal bevels are wanted, they would have to be produ a planing process. Comparatively few cycloidal cutters are even for spurs, because a larger set is wanted—twenty-foeach pitch in place of eight for involutes—and because, gen




Fig. 265.—Cutting Twelve Wheels at once.

the system is not so elastic as that of the involute. In the it is well known that slight differences in centres do not affi working of the gears. A slight difference in the depth cutters, increasing or lessening the bottom clearance, mal difference in the action of the gears. But in cycloidal tee pitch lines must roll together, and, in fact, the depth of toot important that the cutters are made with shoulders which p cutting going below the exact depth suitable for the gear.

Avolves the necessity for very accurate sizing of the blanks. On he other hand, many, including the writer, think that, for smooth and easy running, double-curve cut teeth are preferable to involute, and that when the question is one of the best possible results they should be selected.

Both circular and diametrical pitches are employed in the sycloidal system of cutters, and the diameter of blanks is sized in the latter as in involutes by adding two diameter pitches to the pitch diameter.

The difference between the range of the involute and cycloidal autters is very wide. In the first-named, three cutters, 6, 7, and 8, cut numbers of teeth from 12 to 20. But in the second, nine autters are required, one to each separate wheel. In the higher numbers the difference is also nearly as great—three cutters from 21 to 26 teet!, in the double-

Curve system, against one Cutter from 21 to 25 in the involute, and so on.

The gear-cutting machines have appropriated a large volume of spur and bevel gear cutting formerly done on the milling machine. Still, the work is that of



Fig. 266. Multiple Cutter .

rotary cutters. But the regular machines have the advantage in point of economy, being stiffer, and often designed for operating, in the case of spurs, on several spurs at once. A fine example is given in Fig. 265, where twelve wheels are being cut at once in the shops of Ludwig Loewe & Co.

The Gould & Eberhardt system of multiple cutters is another device to increase the output of a machine. Fig. 266 shows three such cutters in operation. They are, of course, only suitable for wheels of one size. On the milling machine duplication is often effected by having two or more sets of centres in which pitching is done by division plates without indexing. These are used for small gears, taps, reamers, and articles having low numbers. Backs are cut with special attachments, one or several teeth being cut at once.

Fig. 267 illustrates multiple centres by the Garvin Company

the

100

ble, by sed for ly entting can be done all round one side first, followed by all the cutting on the other side.

Cycloidal as well as involute-shaped cutters are supplied to spur gears, but not for bevels, for which they would be unsuitable. If cycloidal bevels are wanted, they would have to be produced to a planing process. Comparatively few cycloidal cutters are use even for spurs, because a larger set is wanted—twenty-four to each pitch in place of eight for involutes—and because, generally




Fig. 265. -Cutting Twelve Wheels at once,

the system is not so elastic as that of the involute. In the latter it is well known that slight differences in centres do not affect the working of the gears. A slight difference in the depth of the cutters, increasing or lessening the bottom clearance, makes a difference in the action of the gears. But in cycloidal teeth the pitch lines must roll together, and, in fact, the depth of tooth is a important that the cutters are made with shoulders which preven cutting going below the exact depth suitable for the gear. The

involves the necessity for very accurate sizing of the blanks. On the other hand, many, including the writer, think that, for smooth and easy running, double-curve cut teeth are preferable to involute, and that when the question is one of the best possible results they should be selected.

Both circular and diametrical pitches are employed in the cycloidal system of cutters, and the diameter of blanks is sized in the latter as in involutes by adding two diameter pitches to the pitch diameter.

The difference between the range of the involute and cycloidal cutters is very wide. In the first-named, three cutters, 6, 7, and 8, cut numbers of teeth from 12 to 20. But in the second, nine cutters are required, one to each separate wheel. In the higher numbers the difference is also nearly as great—three cutters from

21 to 26 teeth in the doublecurve—system, against—one cutter from 21 to 25 in the involute, and so on.

The gear-cutting machines have appropriated a large volume of spur and bevel gear cutting formerly done on the milling machine. Still, the work is that of



Fig. 266.—Multiple Cutters.

rotary cutters. But the regular machines have the advantage in point of economy, being stiffer, and often designed for operating, in the case of spurs, on several spurs at once. A fine example is given in Fig. 265, where twelve wheels are being cut at once in the shops of Ludwig Loewe & Co.

The Gould & Eberhardt system of multiple cutters is another device to increase the output of a machine. Fig. 266 shows three such cutters in operation. They are, of course, only suitable for wheels of one size. On the milling machine duplication is often effected by having two or more sets of centres in which pitching is done by division plates without indexing. These are used for small gears, taps, reamers, and articles having low numbers. Racks are cut with special attachments, one or several teeth being cut at once.

Fig. 267 illustrates multiple centres by the Garvin Company

The lower figure is designed to obviate this. The tail A is cylindrical form, and is off-set so that its axis is in line with a end of the work B when the dog is set flush. An adjustable clar a is attached to the regular driver, which holds any size of d and permits the tail to swivel and slide.

TABLE TO FACILITATE CALCULATIONS INVOLVING FRACTIONS.

$\begin{array}{c} \frac{1}{64} = 01563 \\ \frac{1}{312} = 03125 \\ \frac{3}{314} = 04688 \\ 1 - 16 = 0625 \end{array}$	$\begin{vmatrix} \frac{1}{6}\frac{7}{4} = 26563 \\ \frac{9}{3}\frac{2}{5} = 28125 \\ \frac{1}{6}\frac{7}{4} = 29688 \\ 5 - 16 = 3125 \end{vmatrix}$	33 = ·51563 17 = ·53125 55 = ·54688 9-16 = ·5625	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
$^{6}_{0.4} = .07813$ $^{3}_{0.2} = .09375$ $^{3}_{0.4} = .10938$ $^{1}_{0.8} = .125$	$ \begin{array}{c} $	3.7 = .57813 1.9 = .59375 3.4 = .60938 5-8 = .625	$ \begin{array}{rcl} & 50 & = & .8281 \\ & 51 & = & .8437 \\ & 52 & = & .8593 \\ & 7-8 & = & .875 \end{array} $
 $^{8}_{64} = \cdot 14063$ $^{5}_{32} = \cdot 15625$ $^{11}_{64} = \cdot 17188$ $^{3-16} = \cdot 1875$	$\begin{array}{c} \frac{25}{64} = 39063 \\ \frac{13}{13} = 40625 \\ \frac{27}{64} = 42188 \\ 7-16 = 4375 \end{array}$	1 = ·64063 	$\begin{array}{rcl} \frac{57}{64} &=& *8906 \\ \frac{29}{32} &=& *9062 \\ \frac{59}{64} &=& *9318 \\ 15\cdot 16 &=& *9375 \end{array}$
$\begin{array}{c} \frac{15}{64} = \cdot 20313 \\ \frac{7}{34} = \cdot 21875 \\ \frac{15}{64} = \cdot 23438 \\ 1.4 < \cdot \cdot \cdot 25 \end{array}$	$\begin{array}{c} 29 = 45313 \\ 15 = 46875 \\ 31 = 48438 \\ 1 \cdot 2 = 5 \end{array}$	$\begin{array}{c} \frac{45}{64} = 70313 \\ \frac{25}{33} = 71875 \\ \frac{47}{47} = 73438 \\ 3-4 = 75 \end{array}$	64 = -9531 64 = -9687 659843 1 - (5000)

CHAPTER XI.

FEEDS AND SPEEDS.

Governing Conditions—Feeds of more Importance than Speeds—Hardness and Softness of Metal --Pickling—Its Limitations—Frequency of Grinding—Examples of Feeds and Speeds.

Governing Conditions.—Feeds and speeds are dependent on several circumstances, such as hardness or softness of metal, the character of the cutters, whether finely or coarsely pitched; on the stiffness of the machine and arbor, or whether castings and forgings have been pickled or not, besides other conditions of a minor character. The frequency of grinding is an important item also. If a cutter is reground frequently, it will stand much more than one which is worked for several days in a more or less dull condition. Then it becomes a question of the greater economy of slowing down to suit a dull cutter, or stopping for a while to change and grind the cutter.

In making comparisons of speeds and feeds account must be taken of all these. And a distinction fully as important as any is the difference between ordinary work, and record work made as tests. It is easy by using sharp cutters, running for short periods, to make a big show by comparison with work done under ordinary shop conditions. The question then is an economical one. Record work as a rule is not paying work, and therefore not much is done in that way in ordinary shop practice. These matters, which are discussed at greater length in different sections of this work, have to be all well weighed in making comparisons between milling speeds and feeds.

Speaking broadly, the same rule obtains as in the work of single-edged cutting tools. That under identical conditions a slow cutting speed and deep cutting may be combined, while a high speed is only possible with shallow cutting.

The state of the s

Then, further, the rate of feed must depend largely on the degree of accuracy or finish required. No accurate work can be done on light articles with heavy cutting. The lighter the articles and the greater the amount of accuracy needed, the lighter must be the depth of cut, and rate of feed. In all work, even where the roughing cuts are heavy, the finishing cuts must be light—that is, the depth of cut must be small, though the speed and feed may be increased beyond those used for the roughing.

The feeds of milling cutters are of more importance than the speeds. Feeds should be made as fast as the cutters will stand consistently with good work. Average surface speeds are usually given as 20 feet per minute for steel, 40 for cast iron, and 60 for brass. The speeds in gear cutting are higher, because the machine are designed specially and stiffly for that work alone: 40 feet per minute for steel, 60 for cast iron, and 80 for brass represent average speeds. The speeds of high-speed cutters can be increased by from 50 to 75 per cent, above those of ordinary steel.

Table of Average Cutting Speeds, Periphery Speed of Cutter (in Fret) per Minute.

· - ·	. ———			
. !	Brass.	Wrought Iron.	Cast Iron.	Cast Steel.
			-	
Rougtang	80	40	30	26
Fraishing	100	60	‡ ()	> 7,
Feed per minute	21 in.	} in. to 2 in.	į in. to 1½ in	$\tfrac{1}{4}\ln(t+\tfrac{1}{2}t),$

The rate of feed will very from \mathbb{Q}_0 inch to \mathbb{Q}_0 inch ber toot a cutter speed, according to the strength of the work or the efficiency and a because the finish required and the material special is. These taking a 4-inch diameter of cutter, and maintaining the average cutting speed of 41 feet per minute (say 40 revolution of cutter), the rate of feed may require to vary from $\frac{1}{2}$ inch the $2\frac{1}{2}$ inches per minute, according to the various conditions of the work, and also the breadth of cut; as a rule, the broader the cutter and the deeper the cut the slower should be the feed although this to a great extent depends upon the power or stability of the machine.

Table of Feeds in relation to Depth and Width of Ctt in Ordinary Cast Iron, giving Revolutions of Cutter for 1 Inch of Feed.

Diameter of cutters -	2	in.	3	in.	4 :	in.	6	in.
Width of cut -	l in.	2 in.	i in.	2 in.	½ in.	2 in.	₫ in.	2 in.
Revolutions, roughing in.								
to 🖟 in. deep	4.5	4()	30	25	25	22	15	12
Finishing, 1 in. deep	35	30	22	20	18	15	144	0

This will average for roughing $\frac{1}{2^{1}a}$ inch feed of work to each 12 inches of cutter this will average for finishing $\frac{1}{1^{1}a}$ inch diameter.

For broader cuts and harder material the number of revolutions per inch of feed should be increased.

Hardness or softpess of metal makes a great difference in the results obtained by the use of milling cutters. These differences will easily halve, or double the feeds and speeds, and weight of metal removed. In any comparisons, therefore, of this kind the quality of the metal or alloy must be known. Iron castings vary greatly in hardness, covering a wide range of differences. Certain grades of steel are very tough, and must be annealed before tooling, and then they and the cutters require a large volume of lubricant.

Cast metals may be soft, homogeneous, and cut sweetly: or they may be hard, honeycombed with blow-holes, interspersed with cold shuts or chilled parts, which strain or break the tools. Forged metal may be clean and homogeneous, or it may be spilly, seamy, open, trying to the tools.

Pickling has its limitations. It cannot be conveniently practised in the case of big work. Neither is it worth while in smaller pieces, portions only of which have to be tooled, as, say, valve faces, or cover plates, or bosses. Neither is it of much utility in work where the allowances for tooling are considerable, as in many hand-made forgings, or those such as cranks, in which webs are milled from the solid, or in castings where allowances of 1 inch or $\frac{\pi}{8}$ of an inch are made for facing-off feet or flanges. There are ready means of getting below the skin in such cases, either by single-edged planer tools, or by rotary cutters with inserted

teeth. But where pickling scores is in small forgings and eastings where allowances are cut uniformly fine, say from $\frac{1}{3^2}$ inch to $\frac{1}{16}$ inch, as in stamped work, and in machine-moulded work, and in which the shallowness of the allowance would not permit the cutters to get below the hard skin and scale.

The frequency of grinding cutters has a very close relation to the volume of work which can be got through in a given time. Frequent grinding means faster and deeper cutting, but it also involves frequent stoppage of the machine for taking out and replacing cutters. If cutters are kept in duplicate, the loss of time is not so great as when the machine has to stand while regrinding is being done. For doing record work it is understood that cutters must be kept very sharp. But it is none the less desirable, in doing the ordinary work of the shop only, that a reasonable mean must be struck. Too frequent stoppages mean loss, sharpening too long delayed involves losses of time also, but in other ways. These losses are due to the necessity for slowing down or feeding more finely, and to the inefficiency of the cutter to produce true results, due to spring caused by the friction of its dulled edges. Of the two it is better to err on the side of frequent grinding than in the other way.

A list of speeds and feeds is given below, taken from various sources. Its value lies in the guidance it affords in practice. General statements are nearly valueless, but these figures give rates under all conceivable conditions, for all classes of cutters, on all kinds of machines, and they should therefore be helpful for reference and check.

The thickness of a chip can be ascertained by dividing the table feed per revolution of cutter by the number of teeth. If the feed were 0300 meh per revolution, and the teeth 30 in number, the thickness of each chip would be

$$\frac{0.300}{30} = 0.010,$$

or a hundredth of an inch thick. This is extremely thin by comparison with the chip removed by a single-edged tool, yet it is fairly coarse for a milling chip.

The following is from the shops of A. Herbert Ltd., on fine classes of work, and in the ordinary course of practice without

any attempt to establish records, some of which are shown in previous photos.

A gang of cutters milling the faces of hexagon nuts of mild steel held in a turret head, six faces on three nuts being done simultaneously. Cutters of ordinary tool steel, 6 inches in diameter, 36 teeth, 46 revolutions per minute, equal to 72 feet per minute, feed \(\frac{1}{2}\) inch per minute. This gives a cut per tooth of 0 0003 inch. The heads of thirty-five \(\frac{1}{6}\)-inch bolts were milled per hour.

A form mill tooling the sides of links of mild steel for chain conveyors; diameter of largest part of cutter 4 inches. The total width of cut $9\frac{5}{9}$ inches, the number of teeth 14, 48 revolutions per minute, equal to 50 feet per minute, feed $\frac{1}{2}$ inch per minute, giving a feed per tooth of 0 0007 inch.

A gang of saws cutting slits $\frac{1}{32}$ inch wide in gas burners of cast iron, cutting 120 slits in one batch with 120 saws. Saws 3 inches in diameter, $\frac{1}{32}$ inch wide, number of teeth 30, 51 revolutions per minute, equal to 40 feet per minute, feed 2 inches per minute, or feed per tooth 0013.

A form mill profiling bars of mild steel. Cutter 5 inches diameter, by 3_4^3 inches wide, with 12 teeth. Speed 32 revolutions per minute, equal to 42 feet per minute, feed $\frac{1}{2}$ inch per minute, giving a feed per tooth of 0.0013 inch.

A gang of three saws cutting off blanks for screwing dies of ordinary tool steel. Cutters 4 inches diameter, by 4 inch wide, 36 teeth, 32 revolutions per minute, equal to 33:5 feet per minute, feed 4 inch per minute, giving a feed per tooth of 0:00043 inch.

A face mill with inserted cutters of Armstrong-Whitworth high-speed steel, and having front rake, surfacing capstan slides. The cutter was 12 inches in diameter, with 16 teeth, 11½ inches width of cut, z_2^2 inch depth of cut, 24 revolutions per minute, equal to 75 feet per minute, feed $7\frac{1}{2}$ inches per minute, or a feed per tooth of 0.015 inch.

The foregoing, the last excepted, were done on horizontal spindle machines of the pillar and knee type, the arbor being in each of the examples supported at the outer end.

The following examples are of work done with rotary face mills, with inserted cutters, on horizontal spindles.

Tooling castings very hard and with hard spots, and not pickled. Cutter 27 inches diameter, 36 teeth, width of cut

15 inches, depth 1 inch to 18 inch, speed 21 revolutions per minute, equal to 17 feet cutting speed, feed 31 inches per minute, giving a feed per tooth of 0.038 inch. The cutters were of Mushet steel, and tempered once only in 10 days.

Tooling castings of similar hard quality. Cutter 40 inches diameter, with 52 teeth, width of cut 32 inches, depth $\frac{1}{18}$ inch to $\frac{1}{18}$ inch in places, speed $\frac{1}{8}$ revolutions per minute, equal to 17 feet cutting speed, feed 3 inches per minute, giving a feed per tooth of 0 033 inch. The cutters were made of Mushet steel, sharpened once in from twelve to fifteen days.

Castings not so hard, but rough. Cutter 11 inches in diameter, with 8 teeth, width of cut 8 inches, depth $\frac{1}{8}$ inch, 7 revolutions per minute, equal to 20 feet cutting speed, feed 2 inches per minute, giving a feed per tooth of 0.033 inch. Cutters made of Armstrong-Whitworth steel, sharpened once in four days.

An inserted toothed slabbing cutter operating on a plane surface of cast iron, took a cut $8\frac{1}{4}$ inches wide, with a depth ranging from $\frac{3}{32}$ inch to $\frac{5}{32}$ inch from a scale surface, at a speed of cutter of 40 feet per minute, and a rate of feed of $8\frac{1}{2}$ inches per minute.

Examples of milling a tee groove in milling-machine platens. In one the body of the slot was first roughed out, and the bottom done on the milling machine, with a rate of feed of $6\frac{1}{2}$ inches per minute. In another the tee slot was roughed out with an end mill, at a feed of $6\frac{1}{2}$ inches per minute, after which the tee was done at a feed of $6\frac{1}{8}$ inches per minute. This was only possible by the application of a compressed air blast to clear out the chips.

The following are from the shops of the Cincinnati Milling Machine Company, using Novo steel.

In milling gibs of grey east iron, 2 inches wide, an edge cuttor 4 inches diameter, with 18 teeth, which it will be noted is a coarse pitch, is driven at a peripheral speed of 90 feet per minute, with a feed of 0500 inch per revolution of the cutters. The strip travels under the cutter at a rate of 27 inches per minute; and the cut is $\frac{\pi}{12}$ inch deep.

The finishing cut is taken by a face mill, removing 0 010 inch in depth, with a feed of 0 200 inch per revolution of cutter, or 10 inches per minute.

Another is milling cover plates of grey iron, measuring

6×4 inches. A slabbing spiral-toothed cutter, 3 inches diameter, with 16 feeth, makes 51 revolutions per minute, feeds at 0·210 inch per revolution, or 10·7 inches per minute, and removes 1 inch depth of metal.

Another job is milling tee slots in the tables of the firm's milling machines. These are first milled over the face, and the vertical cut for the slots taken. Then a stem cutter, measuring 1_{16} inch $\times \frac{1}{2}$ inch, with 8 teeth, tee-slots each groove at a travel of 12 inches per minute. The chips are removed by an air blast.

In these shops, extra duty is regularly got out of the milling cutters by utilising a blast of compressed air to drive the chips away from the cutters. Branch pipes are led to the machines, and a hose having a nozzle, with a spring-closed valve, is opened by a slight pressure of the thumb. Without the air blast, the chips would clog or break the cutters in heavy horizontal milling.

Another device employed is that of a strong jet of oil delivered against the cutters, with the same object—that of clearing away the chips.

The Holroyd patent pressed steel milling cutters have the tollowing records:—

Two ordinary steel patent cutters, $2\frac{\pi}{4}$ inches diameter, running 600 revolutions per minute, cutting drawn brass screws $\frac{1}{2}$ -inch diameter, $\frac{1}{2}$ -inch lead, $\frac{1}{4}$ -inch pitch, width and depth of cut $\frac{1}{16}$ inch, feed $6\frac{1}{2}$ inches per minute—these were ground once each week.

Two high-speed steel cutters, cut on three edges, 23 inches diameter, running 200 revolutions per minute, cutting bright drawn screw 1-inch diameter, ½-inch lead, ¼-inch pitch, width and depth of cut ½ inch, feed 4 inches per minute—these were ground every 11 hours.

One ordinary steel cutter, cut on three edges, $3\frac{1}{4}$ inches diameter, running 90 revolutions per minute, cutting mild steel screw $3\frac{1}{2}$ inches diameter, $3\frac{1}{2}$ inches lead, 3 starts, width of cut $\frac{1}{16}$ inch, depth of cut $\frac{1}{16}$ inch, feed $1\frac{1}{4}$ inch per minute—this was ground every 5 hours.

Two high-speed steel cutters, cut on three edges, $2\frac{3}{8}$ inches diameter, running 200 revolutions per minute, cutting bright drawn screw $\frac{3}{8}$ -inch diameter, $\frac{1}{2}$ -inch lead, $\frac{1}{4}$ -inch pitch, width and depth of cut $\frac{1}{16}$ inch, feed $\frac{4}{2}$ inches per minute—these were ground every 9 hours.

One high-speed steel cutter, cut on three edges, 2½ inches diameter, running 1,700 revolutions per minute, cutting cast brass screw 1-inch diameter, ½-inch pitch, ½-inch lead, width and depth of cut ½ inch, feed 60 inches per minute—there was no appreciable wear after the cutter had milled a gross of these screws, each 2 inches long.

Also two high-speed armour-plate bolt cutters made of Armstrong-Whitworth steel—one of the cutters, making 160 revolutions per minute, cutting 6 inches peripheral speed, was ground every 8 hours; the other, making 200 revolutions per minute, and cutting 12 inches per minute feed, lasted 2 hours.

A pair of high-speed steel cutters $2\frac{\pi}{4}$ inches diameter, worked eight weeks continuously, and cut 3,000 feet of double thread. When new they were $2\frac{\pi}{4}$ inches diameter, and lost $\frac{1}{8}$ inch diameter through grinding in eight weeks. The cutters were still in fair condition.

MILLING CUTTERS.

TABLE OF CUTTING SPEEDS. (See opposite page.)


(Morse Twist Drill & Machine Company.)

The table will be convenient for finding the number of revolutions per minute required to give a periphery speed from 5 feet to 50 feet per minute of diameters from 4 inch to 30 inches.

Examples.—A mill 2 inches in diameter, to have a periphery speed of 35 feet per minute, should make about 67 revolutions, while a 14-inch mill should make 120 revolutions to have the same periphery speed. If a 3-inch mill makes 250 revolutions per minute, the periphery speed is about 50 feet.

TABLE OF CUTTING SPEEDS.

Per	V	-	•		·· 					i	
Diam Revolutions Per Minute Inches 382 764 11446 15229 1914 2229 2675 3057 34440 3822 253 306 612 918 1225 1534 1837 2143 24449 2755 3064 7254 308 763 1017 1274 1525 1780 2034 2284 2242		5	10	15	-an	.)5	. 20	25	40	45	50
Tuches	Vioute		117	10		20	347	(16)	40	***	•,,,
Tuches	Diam			•	:					-	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Diam	Revolutions Per Minute									
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Inches.		l	:			<u> </u>		!	ı	l
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		38.2	76.4	114.6	152.9	191.1	229.3	267:5	305.7	344.0	382-2
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	ž	30 6	61.2	91.8	122.5	153.1	183.7		244.9	275.5	306:1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	ą	25.4	50.8	76:3	101.7	127.1	152.5	17840	2034	228.8	254.2
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	į	21.8	43.6	65.5	87:3	109.1	130.9		174.5	196.3	218.9
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1	19.1	38-2	57.3	76.4	95.5	114.6	133.8	152.9	172.0	191-1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			34.0	51 0	68 0	85.0	102.0	119.0	136.0	153.0	1700
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	11	15.3	30.6	45.8	61 2	76·3	91.8	106:9	122.5	137.4	153.1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			27.8	41.7	55.6	69.5	83.3	97.2	111.1	125.0	138-9
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	' 7	12.7	25.4	38.2	50.8	63.7	76.3	89-2	101.7	114.6	127.1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		• • •			47.0		70.5	85.5		105.7	117.4
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	17		21.8		43.6	54·5	65.2	76.4	87:3	98.2	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	14				40.7	50.9	61.1	71:3	81.5	91.9	101.9
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$.2										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	21				34.0	42.4	51.0	59.4	68.0	76.2	8540
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	21										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	23										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	3										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$!								
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		* * * * * * * * * * * * * * * * * * * *									
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	47										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	5			/							
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	51										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		3.2									
$\begin{array}{cccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$. ** **								
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				_							
$\begin{array}{cccccccccccccccccccccccccccccccccccc$											
$\begin{array}{cccccccccccccccccccccccccccccccccccc$											
$\begin{array}{cccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$								7.0			
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			_								
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	٠,১)	-0	1.2					1		-	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$											
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		• • • • • • • • • • • • • • • • • • • •									
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						-		1		1 1	
29 7 13 20 26 33 40 46 53 59 66	28										
								i			
3 1 1 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3											
	,	Ū		''	- ''	-, -	•, .,	10	".	"'	, ,
		-		-							



INDEX.

A CCURATE work, conditions of, 7
Angles of spirals, 250-253
Angular movements to spindles, 75-82
Arbors for cutters, 170, 171
— support of, 85
Arm, overhanging, 22, 84, 85.
Attachments for spiral work, 78
— for slotting, 82-84.
— to horizontal machines, 75-84

BACK gears, 22, 25, 26, 35, 39, 110
Belt feeds, 32, 33
Bevel and spur gears, 278-290
Bevel gears, cutters for, 281-283
— gears, development of, 279-281, 283, 284
Bracings for overhanging arm, 86-91

CAM cutting, 155, 156
Casting cutters in heads, 177, 178
Centres, multiple spindle, 287-289
Classification of machines, 11
Clearance of milling cutters, 165, 166, 167, 189-191
Compound indexing, 247, 248
Conditions of accurate work, 7
Cone mandrels, 226, 227
Circular tables, 102, 103
Cutter arbors, 170, 171
Cutters, 162-197
— built up in gangs, 219
— for bevel gears, 281-283
Cycloidal and involute teeth, 286, 287

DEVELOPMENT of bevel gears, 279-281, 283, 284

— of milling cutters, 1
Diameter of milling cutters, 163
Diametral pitch, 278, 279
Differential indexing, 248-250
Dividing heads, 63-72
Drills, fluting, 149-152

ELEVATING screws, 53
Elliptical hole milling, 159-161
Emery grinder, influence of, 11

FEIDS, 29, 30, 31, 36, 37, 39, 46, 50, 105, 107, 112, 124, 140

— and speeds, 291-299

— belt, 32, 33

— positive, 32, 36, 37, 39, 40-50

— spindles, micrometer fittings to, 56
Finishing, 201
First milling machine, 8, 9
Fluting twist drills, 149-152
Footstocks, 72-74
Form-cutter grinding, 196
Former, 227, 230

GANG cutting George 1 Georg, ve 205 !

Gears, worm, 145-149 General shop, milling in, 4 Graphic methods for spiral gears, 259-271 Gri ding milling cutters, 185-197

HANDLES, 61 Hardening cutters, 179-182 Headstocks of milling machines, 24-29 Heads, swivelling, 78-82 — universal, 63-72 Hobbing worm gears, 145-149 Hobs for worm gears, 274-276 Holding work for milling, 208 227 Horizontal machines, attachments to.

75 84 - spindle machines, 10, 16 - v. vertical spindle machines, 95

NDEX centres, 62-72 - plate, 244 247 Indexing and spiral work, 243-271 -- competitial, 247, 248 differential, 248-250 Inserved tooth cutters, 171-178

Involute and cycloidal teeth, 286, 287

I lGS, 228 242

EVWAYS in cutters, 171 -Krees, 51/53--- and tables, 29-31 --- elevating screws of, 53

AMITATIONS of milling machines, 7 Lincoln machines, 10 15 Locking handles, 117

Lubrication, 118, 121, 152, 199

- special, 139-161 Machining improved by milling, 7 Magnetic chuck, 220-222

ACHINES classified, 11

Micrometer fittings to feed spindles, 56 Milling, and the reciprocating tools, 5

- and tool making, 6 compared with planing, etc., 200-202,

206, 207, 208-217 cutters, 162-197 - cutters, arbors for, 170, 171 cutters, cast in head, 177, 178

- cutters, cutting teeth of, 183-185 - cutters, development of, 1 cutters, diameter of, 163

- cutters for die work, 227, 229 - cutters, grinding and sharpening, 185 197 --- cutters, hardening of, 179-182

- cutters, inserted tooth, 171-178 - cutters, keyways of, 171 - cutters, oil stoning, 197 cutters, rake and clearance of, 165, 166, 167

cutters, spacing of teeth, 163-165 - cutters, spiral form, 167-169, 173 cutters, steel for, 178, 179 - cutters, the first, 1 cutters, tooth rest for grinding, 189-

192 cutters r, single-edged tools, 162 cutters, wear of, 169

-- effects of, on machining. 7 elliptical holes, 159-161 holding work, 208-227 - in the general shop, 4

-- machine, early improvements in, 9, 10 - machine feeds, 29, 30, 31 - machine for drill fluting, 149-152

- machine headstocks, 24-29 - machine knees, 51-53 - machine, limitations of, 7

- machine requires skilled attendance, 5. 6 -- machines for elliptical holes, 159-161

-- machines for gear cutting, 139-149 -- machines for worm hobbing, 142-149

- - machines, horizontal spindle, 10, 16

Milling machines, indexing and spiral | work, 243-271 - - machines, pillar, 16-24 machines, pillar and knee, 16-74 - · machines, plano-millers, 130-138 - machines, profiling, 96, 97, 102 - machines, special, 139-161 - machines, tables and knees, 29-31 - machines, the first, 8, 9 - machines, the Lincoln, 10-15 - machines, three-spindle, 153-155 - machines, utilities of, 2-5 -- machines, vertical spindle, 94-129 -- on planer, 158, 159 -- operations, 198-242 - operations summarised, 203-205 screw gears, 253-255 --- spiral gears, 272 - spur and bevel gears, 278-290 - work in specialities, 3, 4 -- worm gears, 271-277

OHL stoning cutters, 197
Operating handles, 61
Operations on milling machines, 198-242
Oval hole milling, 159-161
Overhanging arm, 22, 84, 85
— arm, bracings for, 86-91

— worm threads, 142-149

Multiple cutting, 287, 288

spindle centres, 287-289

PILLAR and knee machine, general description, 21-24

— and knee machine, work of, 92

— and knee machines, 16-74

— machines, 16-24

— machines, dimensions of, 18

— machines, points in, 19

Pitch, diametral, 278, 279

— of spiral gears, 258

Plain machines and universals, differences in, 59-61

— machines, work of, 19

Planer, milling attachment to, 158, 159

Plano-millers, 130-138

Positive feeds, 32, 36, 37, 39, 40-50

Profile milling, 227, 230
Profiling attachments, 100, 101, 157, 158
— machines, 96, 97, 100-103, 128, 129

RAKE of milling cutters, 165, 166, 167.
Reciprocating tools, and milling, 5
Revolution mark, 163
Rotary planers, 136-138
Roughing, 199, 200

SCREW gears, milling, 253-255 Serew milling, 277 Sector, 244, 245 Sharpening milling cutters, 185-197 Single-edged tools r. milling cutters, 162 Skilled attendance in milling, 5, 6 Slabbing machines, 130-138 Slotting attachments, 82-84 Special machines, 139-161 Specialities and milling, 3, 4 Speeds, 124 – and feeds, 291-299 — of spindles, 25, 26, 31, 32, 34 Spindle bearings, 27, 28, 34, 36, 39 speeds, 25, 26, 31, 32, 34 Spindles, 27, 34, 36, 39, 105, 106, 112, 122, 126, 127, 128, 133-136 angular movements of, 75-82 Spiral gears, graphic methods, 259-271 - gears, pitch of, 258 - gears, trigonometry of, 266-271 — heads, 62-72 -- mills, 167-169, 173 work and indexing, 243-271 Spirals, angles of, 250-253 Spur and bevel gears, 278-290 Standard movements, 62 Steel for cutters, 178, 179 Stops, 117 Straddle mills, 219

TABLES, 54-57, 102, 103, 104, 126 — and knees, 29-31 — vernier applied to, 57, 58

_ 0.4

Swivelling heads, 78-82

Tapered work, 289
Teeth of cutters, spacing, 163-165
Three-spindle machines, 153, 155
Tool maker and milling, 6
Tooth rest for cutter grinding, 189-192
Trigonometrical functions of spiral gears, 266-271
Trips, 117

U NIVERSAL heads, 63-72
— machine, first, 16, 17
Universals and plan machines, differences in, 59-61

VELOCITY ratios of gears, 256, 257, 264, 265.
Vernier applied to tables, 57, 58.
Vertical spindle attachment, 76.
Spindle machines, 94-129.
c. horizontal spindle machines, 95.

EAR of cutters, 169
Work of pillar and knee machine,
92

Worm gear hobbing, 145-149

- gears, 271 277
- --- gears, hobs for, 274-276
- -- thread milling machine, 142-149

CROSBY LOCKWOOD & SON'S Catalogue of

SCIENTIFIC, TECHNICAL AND INDUSTRIAL BOOKS.

		PAGE				AUE	
Mechanical Engineering		1	Carpentry and Timber	-			
Civil Engineering							
Marine Engineering		17	Natural Science		-	33	
Mining, Metallurgy and Colliery Chemical Manufactures							
Working					-	36	
Electricity		23	Commerce, Tables, &c	-		41	
Architecture and Building .	i 14	26	Agriculture and Gardening .		6	43	
Sanitation and Water Supply		28	Auctioneering, Valuing, &c			46	
Law and	Misc	ellane	ous 47				

MECHANICAL ENGINEERING, ETC.

THE MECHANICAL ENGINEER'S POCKET-BOOK.

Comprising Tables, Formulæ, Rules, and Data: A Handy Dook of Reference for Daily Use in Engineering Practice. By D. Kinnear Clark, M. Inst. C.E. Fifth Edition, thoroughly Revised and Enlarged. By H. H. P. Powies, A.M.I.C.E., M.I.M.E. Small 8vo, 700 pages, bound in flexible leather cover, rounded corners

Summary of Contents.

Mathematical Tables — Measurement of Suntages and Solids — English Weights and Measures — Farnos Metric Weights and Measures — Foreign Weights and Measures — Foreign Weights and Measures — Monry — Specific Genville, Weight and Volume — Maduractured Metals — Syfel Perk—Bolts and Nots, — Sunday Articles in Weight and Cart Inon, Copyre, Bross, Lead, Tis, Zing — Syreights of Matemals — Syreights of Timber — Syreights of Cart Inon, — Strength of Weights Inon, — Syreights of Strength of Cart Inon, — Strength of Weights Inon, — Syreights of Strength of Cart Inon, — Strength of Weights Inon, — Strength of Matemals — Butter of Johns in Bolles Flats — Bolles Shrifts, — Weights Royes and Herf Royes — Chains and Carin Carlos — Benjiel — Herrich of Matemals — Matematical Principles — Genvilly and Pall of Bolles — Accelerating and Repres — Composition: Foreign — Matematical Composition of Motive Power — Heart — Composition: Foreign — Matematical Composition of Motive Power — Heart — Composition: Foreign — Warning Office — Weights — Purpose Syrem — Stream — Stream English and Butters — Kardways — Transways — Stream Shrifts — Purpose Syrem — Brosses — Royer — Royer — Composition — Royer — Weights — Court — Purpose Syrem — Register — Royer — Court — Royer — All Purpose Syrem — Stream — Stream — Court — Royer — Royer — Royer — Court — Royer — Royer — Royer — Court — Royer — Royer — Royer — Royer — Court — Royer — Royer — Royer — Royer — Court — Royer — Royer — Royer — Royer — Royer — Court — Royer — Roy

"Mr. Clark manifests what is an innate perception of what is likely to be useful to a pocket-book and he is really untivalled in the art of condensation. It is very difficult to hit upon any unschanical engineering subject concerning which thes work supplies no information, and the excellent index at discard adds to its utility. In one word, it is an axceedingly handy and efficient tool, possessed of which the engineer will be saved many a weartsome calculation, or yet more weartsome hant through various introduction and transition, and, as such, we can heartily recommend it to our readers."—The Engineer.

"It would be found difficult to compress more matter within a similar company or produce a book at your pages which should be more company or convenient for pocket reference. . Will be attracted by mechanical engineers of all places." Practical Engineer.

MR. HUTTON'S PRACTICAL HANDBOOKS

THE WORKS' MANAGER'S HANDBOOK.

Comprising Modern Rules, Tables, and Data. For Engineers, Millwrigh solition Boiler Makers: Tool Makers, Machinists, and Metal Workers: Iron an improvement, &c. By W. S. Hutton, Civil and Mechanical Engineer, Author The Practical Engineer's Handbook." Sixth Edition, carefully Revised: Revised Enlarged. In One handsome Volume, medium 8vo, strongly bound ...

The Author having compiled Rules and Data for his own use in a great of modern engineering work, and having found his notes extremely useful, Jecided to ful them oriented to date - believing that a practical work, suited to the DAILY PROUIREMENT. MODERN ENGINEERS, would be favourably received.

MODERN ENGINEERS, would be favourably received.

"The author treats every subject from the point of view of one who has collected work diops for application in workshop practice, rather than from the theoretical or literary aspect. The very contains a great deal of that kind of information which is gained only by practical experience, as seldom written in books."—The Engineer.

"Of this edition we may repeat the appreciative remarks we made upon the first and faired is the operature of the latter very considerable modifications have been made, aithough the total nation page is maintained the same. It is a very useful collection of rules, tables, and workshop drawing office, data."—The Engineer. (Second Notice.)

"The volume is an exceedingly useful one, britaful with engineer's notes, increaranda, and rand well worthy of being on every mechanical engineer's book, helf."—Mechanical World.

"The information is precisely that likely to be required in practice. The work form desirable addition to the library not only of the works manager, but of any one connected with centengency."—Mining Journal.

"Britandi of useful information, stated in a concise form. Mr. Hutton's books have met a piese want among engineers. The book must prove extremely useful to every practical man puscessificopy."—Practical Engineer.

THE PRACTICAL ENGINEER'S HANDBOOK.

Comprising a Treatise on Modern Engines and Boilers, Marine, Locomotive, Comprising a Treatise on Modern Engines and Boners, Marine, Bocomorve, a Stationary And containing a large collection of Rules and Practical Direlating to recent Practice in Designing and Constructing all kinds of Engineering, and other Engineering work. The whole constituting to capture in the state of the Engineering work. Resylve the Found of Trade and other Examinations for Certificates of Competer in Modern Mechanical Engineering By Walter S. Hurrey, civil a Mechanical Engineering By Walter S. Hurrey, civil a Mechanical Engineer, Author of a The Worls Microger's Hample is leagueered, we. With upwards of 4.5 illustrations. Sixth column 12 of and hidden seed. We live syo, meanly 50 pp. savingly bound.

Community of the data sweet early good processed by blanch the second of

the contribution of the experimental property of the property of the contribution of

(ii) A service of the offset the coloring explanation of the artistic following the order of

So of the various of the control of

English Me. Halls

MR. HUTTON'S PRACTICAL HANDBOOKS-continued.

STEAM BOILER CONSTRUCTION.

A Practical Handbook for Engineers, Boiler-Makers, and Steam Users. A Practical Handbook for Engineers, Boiler-Makers, and Steam Users. Containing a large Collection of Rules and Data relating to Recent Practice in the Design, Construction, and Working of all kinds of Stationary, Locomotive, and Marine Steam-Boilers. By Walter S. Hutton, Civil and Mechanical Engineer, Author of "The Works' Manager's Handbook," "The Practical Engineer's Handbook," &c. With upwards of 500 Illustrations. Fourth Edition, carefully Revised, and Enlarged. Medium 8vo, over 680 pages, cloth, strongly bound.

[Just Published. 18]—

This Work is issued in continuation of the Series of Handbooks written by the Author, viz:—"The Works' Manager's Handbook" and "The Practical Engineers Handbook," which are so highly appreciated by Engineers for the practical nature of their information; and is consequently written in the same style as those works.

The Author believes that the concentration, in a convenient form for easy reference, of such a large amount of thoroughly practical information on Steam-Bollers, will be of considerable service to those for whom it is intended, and he trusts the book may be deemed worthy of as favourable a reception as has been accorded to its predecessors.

"One of the best, if not the best, books on bollers that has ever been published. The information

favourable a reception as has been accorded to its predecessors.

"One of the best, if not the best, books on bollers that has ever been published. The information is of the right kind, in a simple and accessible form. So far as generation is concerned, this is, undoubtedly, the standard book on steam practice."—Electrical Review.

"Every detail, both in boller design and management, is clearly laid before the reader. The volume shows that boller construction has been reduced to the condition of one of the most exact sciences; and such a book is of the unnest value to the fin de siècle Engineer and Works Manager.—

"There has long been room for a modern handbook on steam bollers; there is not that room now, because Mr. Hutton has filled it. It is a thoroughly practical book for those who are occupied in the construction, design, selection, or use of bollers."—Engineer.

"The book is of so important and comprehensive a character that it must find its way into the libraries of every one interested in boller using or boller manufacture if they wish to be thoroughly informed. We strongly recommend the book for the intrinsic value of its contents."—Machinery Market.

PRACTICAL MECHANICS' WORKSHOP COMPANION.

Comprising a great variety of the most useful Rules and Formulæ in Mechanical Science, with numerous Tables of Practical Data and Calculated Results for Facilitating Mechanical Operations. By William Templeton, Author of "The Engineer's Practical Assistant," &c., &c. Eighteenth Edition, Revised, Modernised, and considerably Enlarged by Walter S. Hutton, C.E., Author of "The Works" Manager's Handbook, "The Practical Engineer's Handbook, "&c. Fcap. 8vo, nearly 500 pp., with 8 Plates and upwards of 250 Illustrative Diagrams, strongly bound for workshop or pocket wear and tear

bound for workshop or pocket wear and tear

"In us modernised form Hutton's 'Templeton' should have a wide sale, for it contains much valuable information which the mechanic will often find of use, and not a few tables and notes which he might look for in vain in other works. This modernised edition will be appreciated by all who have learned to value the original editions of 'Templeton.'"—English Mechanic.

"It has met with great success in the engineering workshop, as we can testify; and there are a great many men who, in a great measure, owe their rise in life to this little book."—Building Nams.

"This familiar test-book—well known to all mechanics and engineer—is of essential service to the every-day requirements of engineers, millwrights, and the various trades connected with engineering and building. The new modernised edition is worth its weight in gold."—Huilding Nams. (Second Notice.)

"This well-known and largely-used book contains information, brought up to date, of the sort so useful to the foreman and draughtsman. So much fresh information has been introduced as to constitute it practically a new book. It will be largely used in the onice and workshop."—Meckanicall Werld.

"The publishers wisely entrusied the task of revision of this popular, valuable, and useful book to Mr. Hutton, than whom a more competent man they could not have found."—Iron.

ENGINEER'S AND MILLWRIGHT'S ASSISTANT.

A collection of Useful Tables, Rules, and Data. By William Templeton.

Eighth Edition, with Additions. 18mo, cloth . 2/6

"Occupies a foremost place among books of this kind. A more suitable present to an appropriate any of the mechanical trades could not possibly be made. — Building News.

"A deservedly popular work. It should be in the "drawer" of every mechanic. — English Machinic

THE MECHANICAL ENGINEER'S REFERENCE BOOK.

THE MECHANICAL ENGINEER'S REFERENCE BOOK.

For Modifine and Budler Construction in Two buts. Last I Grungal by discourse but a Part II Buller Cost of the Wish so Plates and manifestal but and much inflammed. If he half-hour?

Not 23 38.

1 Met I do a loss of a non-last soles and soles are to the Forth Powersed throughout and much inflammed. If he half-hour?

Not 23 38.

1 Met I do a loss of a non-last soles and soles are to the Forth Powersed throughout the hourse of the soles and the Forth Powerses Signatures to know the hourse of the I have a forth Power before the soles are hoursed in Wishing Plant I have a forth Power before the Known of the Englastic Manifestal and the Englastic Manifestal and the Power before the Soles and the soles are the soles and the soles and the soles and the soles are the soles and the soles and the soles are the soles and the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles are the soles and the soles and the soles are the soles and the soles are the soles and the soles are the soles are the soles and the soles are the soles and the soles are the soles are the soles and the soles are the soles are the soles are the soles and the soles are the soles are the soles and the soles are the soles are the soles are the soles are the soles are the soles and the soles are the s

TEXT-BOOK ON THE STEAM ENGINE.

With a Supplement on Gas Engines and Paul II or Heat Engines.

With a Supplement on Gas Engines and Paul II or Heat Engines. By T. M. C. on vo. M. A. Parristersac Law, Profess at of Mechanics, at the Royal College of Science, London: Author of "The Principles of Mechanics," "The Elements of Mechanics," "The Elements of Mechanics," "The Elements of Mechanics," "The Elements of Mechanics, at the common with Education of Mechanics, "The Professor and the common with anything critical by Hixley of Mexical and we can would it to have plant "Theories." "Microsoft book is a work of which every very engagement head passes himself."—Microsoft passes himself."—Microsoft passes himself.

ON GAS ENGINES.

With Eq.() as describing a factor for a win false a four By $^{\circ}$ M Good two, M.A. Crown two Call. 26 The left from the control of the pro-cent country to the control of the conor Englanding of Aug. Exc. of the Control

GAS AND OIL ENGINE MANAGEMENT.

A relation Gire for Constant Agendarys (pich), Noticion Selection, Construction and Companies (Fig. M. Power strik, M.A. II., A.M. 1.0 m., Author of the Wessell Williams, Machinery, Tol. Construction of the A.M. 1.0 m., A strike of the Wessell Williams (M. 1. 3.6).

THE GAS ENGINE HANDBOOK.

A Min, in of Cheful information to the Deslines and the Engineer F. W. Komure, M.E. With a coefficient trajectory as Suptherace N(t)Ţ,

A TREATISE ON STEAM BOILERS.

Their Service Construction, which comments Western . Their Witson, C(P) lifts Economic transportation (P, P)Fig. 36 Artists Crimital Consistent published in the artists of

THE MECHANICAL ENGINEER'S COMPANION.

of Atom. Commutationers, Deep ad Editivelents, in Each Society and millionetres, spaces, edges, roots, edges. Strongth of Fells, Weight of Iron, &c., Weight, and advantage of the Strongth of Fells, Weight of Iron, &c., Weight, and advantage of the Strongth of the Strong A server of buth volume. It contains many tables, classified data order morandal generally of divident sers." Figure 1.

What is probless to be, 'a handy office companion, oving, in a securet form, a variety of formation likely is be required by mechanical engagers in their veryday office work."—Nature out of the enga-What is

A HANDBOOK ON THE STEAM ENGINE.

With especial Reference to Small and Medium-sized Engines. For the Use of Engine Makers, Mechanical Draughtsmen, Engineering Students, and Users of Steam Power. By HERMAN HARDER, C.E. Translated from the German with Additions and Alterations, by H. H. P. Powles, A.M.I.C.E., M.I.M.E. Third Edition, Revised. With nearly 1,100 Illustrations. Crown 8vo, cloth Not 76

"A perfect encyclopædia of the steam engine and its details, and one which must take a permanent place in English drawing-offices and workshops."—A Foreman Pattern-maker.

"This is an excellent book, and should be in the hands of all who are interested in the construction and design of medium-stated stationary engines. A careful study of its contents and the arrangement of the sections leads to the conclusion that there is probably no other book like it in this country. The volume aims at showing the results of practical experience, and it certainly may claim a complete achievement of this idea."—Nature.

"There can be no question as to its value. We contially commend it to all concurred in the design and construction of the steam engine."—Mechanical World.

BOILER AND FACTORY CHIMNEYS.

Their Draught-Power and Stability. With a Chapter on Lightning Conductors, By Romert Wilson, A.I.C.E., Author of "A Treatise on Steam Boilers," &c. Crown Svo, cloth

"A valuable contribution to the literature of scientific building."-The Builder.

BOILER-MAKER'S READY RECKONER & ASSISTANT.

With Examples of Practical Geometry and Templating, for the Use of Platers, Smiths, and Riveters. By JOHN COURTNEY, Edited by D. K. CLARK, M. I.C.E. Fourth Edition, 480 pp., with 140 Illustrations. Fcap. 8vo, half-bound. 7/"No workman or apprentice should be without this book."—Iron Trade Circular.

REFRIGERATION, COLD STORAGE, & ICE-MAKING.

A Practical Treatise on the Art and Science of Refrigeration. By A. J. Walt TAYLER, A. M. Inst. C. E., Author of "Refrigerating and Ice-making Machiner 600 pp. With 360 Illustrations. Medium 8vo, cloth. Net 1

"The author has to be congratulated on the completion and production of such an important work, and it cannot fall to have a large body of readers, for it leaves out nothing that would in any way be of value to those interested in the subject."—Steamskip.

"No one whose duty it is to handle the mammoth preserving installations of these latter days can afford to be without this valuable book."—Glasgow Herald.

THE POCKET BOOK OF REFRIGERATION AND ICE-MAKING.

By A. J. Wallis-Tayler, A.M. Inst.C.E. Author of "Refrigerating and Ico-making Machinery," &c. Third Edition, enlarged. Small crown 8vo, cloth. [Just Published. Net 3]6

REFRIGERATING & ICE-MAKING MACHINERY.

A Descriptive Treatise for the Use of Persons Employing Refrigerating and Ice-Making Installations, and others. By A. J. Wallis-Tayles, A.M. Inst.C.E. Third Edition, Enlarged. Crown 8vo, cloth 7/6

"Practical, explicit and profusely illustrated"—Giasgow Heraid.

"We recommend the book, which gives the cost of various systems and illustrations showing details of parts of machinery and general arrangements of complete installations.—Heilder,

"May be recommended as a useful description of the machinery, the processes, and of the facts, figures, and tabulated physics of refrigerating. It is one of the best compilations on the

ENGINEERING ESTIMATES, COSTS, & ACCOUNTS,

A Guide to Commercial Engineering. With numerous Examples of Estimates and Costs of Millwright Work, Miscellaneous Productions, Steam Engines and Steam Boilers; and a Section on the Preparation of Costs Accounts. By A GENERAL MANAGER. Second Edition Svo, cloth 12/-

"This is an excellent and very useful book, covering subject-matter in constant requisition in every factory and workshop.

The book is invaluable, not only to the young engineer, but also to the estimate department of every works."—Builder.

"We accord the work unqualified praise. The information is given in a plain, straightforward snanner, and bears throughout evidence of the infilmate practical acquaintance of the author with every phase of commercial engineering."—Mechanical World.

١

HOISTING MACHINERY.

An Elementar, Treatise on Including the Elements of Crane Construction and descriptions of the various Types of Cranes in use. By Joseph Horner, A.M.I.M.I., Author of "Plattern Making" and other works, Crown Soo, with are Illustrations, a chading Folding Prates, cleta . Just Published. Net

AËRIAL OR WIRE-ROPE TRAMWAYS.

Their Construction and Management. By A. J. Wallas-Torlyn, A M.Inst.C.E.

With St Illustrations Cookin State (oth) and the natural of the subject, it yes have before their every good expected in the various systems of the transmission in too, and goes as well not a bub various definition. We can gately recommend the a useful confidence of the state of the various of the transmission in too, and goes as well not a bub various definition of the transmission in too, and goes as well not a bub various definition of the state of their working, it pair and management. We can gately recommend that a nest of contrast read on the sale of a -The Engineer.

MOTOR CARS OR POWER CARRIAGES FOR COMMON ROADS.

Br. A. J. Waltis-Tayler, A.M.Inst C.E. Author of "Modern Cycles," &c. 212 pp., with 50 Hibstrations. Crown 850, Goth.

"The book it clearly expressed throughout, and is just the soft of work that an engineer, thinking i turning he ato in on to restor-carriage work, mend do well to read as a preliminary to starting speciations." Engineering.

PLATING AND BOILER MAKING.

A Practical Handbook for Workshop Operations. By JOSEPH G. HORNER, A.M.I.M.E. 380 pp., with 338 Illustrations. Crown 800, cloth 77.6 "This work is characterised by that eldence of close acquaint acce with workshop methods which will render the book exceedingly acceptable to the practical band. We have to hesitation in comending the work as a server-cable and if a recombination on a subject which has not hithertor acceived much attention from those qualified to deal with it in a satisfactory manner."—Mechanical World.

PATTERN MAKING.

A Practical Treatise, embracing the Main Types of Engineering Construction and including Gearing, Engine Work, Sheaves and Pulleys, Lipes and Columns, Screws, Machine Parts, Uneps and Cocks, the Moulding of Patterns in Loam and Greenend, Estimating the Weight of Castings, AC. By JOSEPH G. HORNER, A.M.I.M.E. Third Edition, Enlarged. With 480 Blustrations. Crown Syd. 748.

Cloth. Net 7/8

"A well-written technical gade, evidently written by a man who unders and has practise what he has written about. We couldn't recommend it to employing students, young journeymen and choice destroyes of being furnated not the masteries of a strength sking "--fundles."

An excellent the recomber the apprentic, who desires to be a neutral entert the trade. "English Mechanic."

MECHANICAL ENGINEERING TERMS

TOOTHED GEARING.

A Practical Handbook for Offices and Workshops. By J. HORNER, A M.I M.E.

With 184 Hustrations. Crown 8vo, cloth
"We give the book our inqualified praise for its thoroughness of treatment and recommend it is all interested as the most practical book on the subject yet written." "Mechanical World.

FIRES, FIRE-ENGINES, AND FIRE-BRIGADES.

With a History of Fire-Engines, their Construction, Use, and Management.

Foreign Fire Systems: Hints on Fire-Brigades, &c. By C. F. T. Young, C.E. 8vo, cloth . £1 4s.

"To such of our readers as are interested in the subject of fires and fire apparatus, we can most heartily commend this book."—Engineering.

AERIAL NAVIGATION.

A Practical Handbook on the Construction of Dirigible Balloons, Aërostats, Aëroplanes, and Aëromotors. By Frederick Walker, C.E., Associate Member of the Aëronautic Institute. With 104 Illustrations. Large Crown 8vo, cloth.

STONE-WORKING MACHINERY.

A Manual dealing with the Rapid and Economical Conversion of Stone. With Hints on the Arrangement and Management of Stone Works. By M. Powis Bale, M.I.M.E. Second Edition, Enlarged. Crown 8vo, cloth. 3/"The book should be in the hands of every mason or student of stonework."—Colliery Guardian.
"A capital handbook for all who manipulate stone for building or ornamental purposes."—Machinery Market.

PUMPS AND PUMPING.

A Handbook for Pump Users. Being Notes on Selection, Construction, and Management. By M. Powis Bale, M.I.M.E. Fourth Edition. Crown

8vo, cloth.

The matter is set forth as concisely as possible. In fact, condensation rather than diffuseness has been the author's aim throughout; yet he does not seem to have omitted anything likely to be of use.—Journal of Gas Lighting. "Thoroughly practical and clearly written.—Glasgow Hereid.

MILLING MACHINES AND PROCESSES.

A Fractical Treatise on Shaping Metals by Rotary Cutters. Including Information on Making and Grinding the Cutters. By Paul N. Hasluck, Author of "Lathe Work." With upwards of 300 Engravings. Large Crown 8vo, cloth 12/8 "A new departure in engineering literature. . . . We can recommend this work to all interested in milling machines; it is what it professes to be—a practical treatise. —Engineer.

"A capital and reliable book which will no doubt be of considerable service both to those who are already acquainted with the process as well as to those who contemplate its adoption."—Industries.

LATHE-WORK.

A Practical Treatise on the Tools, Appliances, and Processes employed in the Art of Turning. By PAUL N. HASLUCK. Eighth Edition. Crown 8vo, cloth 5/"Written by a man who knows not only how work ought to les done, but who also knows how to do it, and how to convey his knowledge to others. To all turners this book would be valuable."

"We can safely a second to be a safely a second and the safely and the safely and the safely and the safely and the safely are safely as a safely a safely and the safely and the safely and the safely are safely as a safely as a safely a safely as a safely a

Engineering.

"We can safely recommend the work to young engineers. To the amateur it will simply be invaluable. To the student it will convey a great deal of useful information."—Engineer.

SCREW THREADS.

And Methods of Producing Them. With numerous Tables and complete Directions for using Screw-Cutting Lathes. By Paul N. Hasluck, Author of "Lathe-Work," &c. Sixth Edition. Waistcoat-pocket size. 1/6 "Full of useful information, hints, and practical criticism. Taps, dies, and screwing tools generally are illustrated and their action described." Methanical World. "It is a complete compendium of all the details of the screw-cutting lathe; in fact a multum-in-parso on all the subjects it treats upon."—Carpenter and Builder.

TABLES AND MEMORANDA FOR ENGINEERS, MECHANICS, ARCHITECTS, BUILDERS, &c.

Selected and Arranged by FRANCIS SMITH. Seventh Edition, Revised, including Waistcoat-pocket size, [Just Published. 1/8 ELECTRICAL TABLES, FORMULE, AND MEMORANDA limp leather.

"It would, perhaps, be as difficult to make a small pocket-book selection of notes and formulæ to suit aft, engineers as it would be to make a universal medicine; but Mr. Smith's waistcoat-pocket collection may be looked upon as a successful attempt."—Engineer.

"The best example we have ever seen of zop pages of useful matter packed into the dimensions of a card case."—Building News.

"A vertiable pocket treasury of knowledge."—Iron.

POCKET GLOSSARY OF TECHNICAL TERMS.

English-French, French-English; with Tables suitable for the Architectural, Engineering, Manufacturing, and Nantical Professions. By John James Fletchen. Third Edition. 200 pp. Waistcoat-pocket size, limp leather 1/6 "It is a very great advantage for teaders and correspondents in France and England to have so large a number of the words relating to engineering and manufactures collected in a liliputtan volume. The little book will be useful both to students and travellers. "Architect."

"The glossary of terms is very complete, and many of the Tables are new and well-arranged. We confinilly commend the book."—Mechanical World.

CIVIL ENGINEERING, SURVEYING, ETC.

PIONEER IRRIGATION.

A Manuel of Information for harmers in the Colonles. By E. C. Mauss & M. Inst. C. E., icolonle Elegener, I mile Works Department, Bombay. We defined and Chapters on Liquir Extravels by E. R. Caltusop, M.Inst. C. P. M. E. Blastrated by Numerous Plates and Diagrams. Department of the Colonless of Just Fueltshed. Net 10 6

SURPLEY OF CONTROL ASSESSED IN THE PROPERTY OF WATER SURPLEY OF AND WILLIAM OF CONTROL AND WATER SURPLEY OF AND WATER SURPLEY OF AND WATER SURPLEY OF AND ASSESSED OF THE SURPLEY OF AND ASSESSED OF THE SURPLEY OF THE PROPERTY OF THE PROPER

TUNNELLING.

A Practical Treatise - Py Charties Premist, C.E., with Additions by Charles 5 Hill - C.E. With 15 Diagrams and Illustrations. Royal 8vo, cloth - Net 16,-

PRACTICAL TUNNELLING.

Explaining in letail Setting-out the Works, Shaft-sinking, and Heading-driving, Ranging the Lines and Leveling underground, Sub-Executating, Timbering and the Construction of the Brickwork of Tonnels. By F. W. Shans, M. Inst. C. F. Lourth Edition, Kevised and Further Extended, including the most Recc.; (1865) Examples of Sub-appeaus and other Tuonels by D. Kinnear Claix, M.Inst C.E. With 44 Lolding Plates. Imperial 8vo. cloth . \$2.25.

The present from each on has been brought right up to date, and is a work to which civil commer should have ready across, and enumers why have construction work can harryly site? To be written hat which it he young remarklers of the profession is invaluable, as from the pages they can bear the since to which the same confirmation has attained. Rather, New 8.

THE WATER SUPPLY OF TOWNS, AND THE CON-STRUCTION OF WATER-WORKS.

STRUCTION OF WATER-WORKS.

A Practical Tract of the Use of Engineers and Students of Engineering. To W. K. Harles, S., A M. Inc. C. C., Consoling that we to the Tokyo Water Works. Second February 16 St., Isotropic of the Tokyo Water Works. Second February 16 St., Isotropic of the Tokyo Water Proposed Second February 19 actus of Water 11 to the Stational of the Management of the Managemen

RURAL WATER SUPPLY.

A Practical Handbook on the Supply of Water and Construction of Waterwork, for small Country Districts. By Allan Greenwall, A.M.I.C.E., and W. T. Cuero, A.M.I.C.E., F.G.S. With Illustrations. Second Edition, Revised Crown Second Edition, Revised Crown Svo, cloth

"We conscientiously recommend it as a very useful book for those concerned in obtaining wells for small district; giving a great deal of practical information in a small compass," Builder, "The volume contains valuable information upon all matters connected with water supply. It is full of details on points which are continually before waterworks engineers."—Nature

MODERN MACHINE SHOP TOOLS.

Practical Treatise describing in every detail the Construction, Operation and A Practical Treatise describing in every detail the Construction, Operation and Manipulation of both Hand and Machine Tools; being a work of Practical Instruction in all Classes of Machine Shop Practice, including Chapters on Filing, Fitting and Scraping Surfaces; on Drills, Reamers, Tapa and Dies; the Lathe and its Tools; Planers, Shapers and their Tools; Milling Machines and Cutters; Gear Cutters and Gear Cutting; Drilling Machines and Drill Work; Grinding Machines and their Work; Hardening and Tempering, Gearing, Belting, and Transmission Machinery; Useful Data and Tables. By William H. Van Dervoort, M.E. Fourth Edition, Illustrated by 673 Engravings of Latest Tools and Methods, all of which are fully described. Medium Svo, cloth [Just Published. Net 21]—

LOCOMOTIVE ENGINE DRIVING.

A Practical Manual for Engineers in Charge of Locomotive Engines. By MICHAEL REYNOLDS, formerly Locomotive Inspector, L. B. and S. C. R. Eleventh Edition. Including a Key to the Locomotive Engine. Cr. 8vo, cloth. 4/6

"Mr. Reynolds has supplied a want, and has supplied it well. We can confidently recommend the book not only to the practical driver, but to everyone who takes an interest in the performance of locomotive engines."—The Engineer.

"Mr. Reynolds has opened a new chapter in the literature of the day. This admirable practical treatise, of the practical utility of which we have to speak in terms of warm commendation."—Athersaum.

THE MODEL LOCOMOTIVE ENGINEER,

Fireman, and Engine-Boy. Comprising a Historical Notice of the Pioneer Locomotive Engines and their Inventors. By Michael Reynolds. Second Edition, with Revised Appendix. Crown 8vo, cloth 4/6

"We should be glad to see this book in the possession of everyone in the kingdom who has ever laid, or is to lay, hands on a locomotive engine."—Iron.

CONTINUOUS RAILWAY BRAKES.

A Practical Treatise on the several Systems in Use in the United Kingdom: their Construction and Performance. By MICHAEL REVNOLDS. 8vo, cloth 9-

"A popular explanation of the different brakes. It will be of great assistance in forming public opinion, and will be studied with benefit by those who take an interest in the brake."—English Mechanic-

STATIONARY ENGINE DRIVING.

A Practical Manual for Engineers in Charge of Stationary Engines.
MICHAEL REYNOLDS. Sixth Edition. With Plates and Woodcuts. 8vo, cloth

"The author's advice on the various points treated is clear and practical."—Engineering.

"Our author leaves no stone unturned. He is determined that his readers shall not only know something about the stationary engine, but all about it."—Engineer.

ENGINE-DRIVING LIFE.

Stirring Adventures and Incidents in the Lives of Locomotive Engine-Drivers.

By Michael Reynolds. Third Edition. Crown Svo, cloth.

"From first to last perfectly faccinating. Wilkie Collins's most thrilling conceptions are thrown into the shade by true incidents, endless in their variety, related in every page."—North British Masi.

THE ENGINEMAN'S POCKET COMPANION,

And Practical Educator for Enginemen, Boiler Attendants, and Mechanics.

By Michael Reynolds. With Forty-five Illustrations and numerous Diagrams.

Fourth Edition, Revised. Royal 18mo, strongly bound for pocket wear. 3/6

"A most methodos work, giving in a succinct and practical form all the information as engineminder designed of mastering the scientific principles of his daily calling would require."—The Miller.

THE RECLAMATION OF LAND FROM TIDAL WATERS.

A Handbook for Engineers, Landed Proprietors, and other interested in Works of Reclamation. By Alex. Beazeley, M.Inst.C.E. 800, cloth. Nes 10/8

"The book shows in a concise way what has to be done in reclaiming land from the sea, and the best way of doing it. The work contains a great deal of practical and useful information which cannot fail to be of service to engineers entrusted with the enclosure of salt marshes, and to land owners intending to reclaim land from the sea."—The Engineer.

"The author has carried out his task efficiently and well, and his book contains a large amount of information of great service to engineers and others interested in works of reclamation."—Nature.

MASONRY DAMS FROM INCEPTION TO COMPLETION.

Including numerous Formulæ, Forms of Specification and Tender, Diagram of Forces, &c. For the use of Civil and Mining Engineers. ECOURTNEY, M.Inst.C.E. 8vo, cloth COURTNEY, M.Inst.C.E. 8vo, cloth

"The volume contains a good deal of valuable data. Many useful suggestions will be found the remarks on site and position, location of dam, foundations and construction."—Building News

RIVER BARS.

The Causes of their Formation, and their Treatment by "Induced Tidal Scour;" with a Description of the Successful Reduction by this Method of the Ber at Dublin. By I. J. Mann, Assist. Eng. to the Dublin Port and Docks Board. Royal 8vo, cloth

"We recommend all interested in harbour works—and, indeed, those concerned in the improvements of rivers generally—to read Mr. Mann's interesting work."—Engineer.

TRAMWAYS: THEIR CONSTRUCTION & WORKING.

Embracing a Comprehensive History of the System: with an exhaustive Analysis of the Various Modes of Traction, including Horse Power, Steam, Cable Traction, Electric Traction, &c.; a Description of the Varieties of Rolling Stock; and ample Details of Cost and Working Expenses. New Edition, Thoroughly Revised, and Including the Progress recently made in Tramway Construction, &c. &c. By D. Kinnear Clark, M.Inst.C.E. With 400 Illustrations. 8vo, 780 pages, buckram

"The new volume is one which will rank, among trainway engineers and those interested in trainway working, with the author's world-famed book on railway machinery."—The Engineer.

AS PRACTISED BY CIVIL ENGINEERS SURVEYING AND SURVEYORS.

Including the Setting Out of Works for Construction and Surveys Abroad, with many Examples taken from Actual Practice. A Handbook for use in the Field and the Office, intended also as a Text-book for Students. By John White Law, Jun., A.M.Inst.C.E., Author of "Points and Crossings." With about 260 Illustrations. Demy 8vo, cloth . Net 10,6

"This work is written with admirable lucidity, and will certainly be found of distinct value both to students and to those engaged in actual practice."—The Builder.

PRACTICAL SURVEYING.

A Text-Book for Students preparing for Examinations or for Survey-work in the Colonies. By George W. Usill, A.M.I.C.E. Eighth Edition, thoroughly Revised and Enlarged by Alexander Beazeley, M.Inst.C.E., Author of "The Reclamation of Land from Tidal Waters," &c. With 4 Lithographic Plates and 360 Illustrations. Large Crown 8vo, 7 6 cloth; or, on Thin Paper, leather, gilt edges, rounded corners, for pocket use ... [Just Published. 12.6]

"The first book which should be put in the hands of a pupil of Civil Engineering."—Architect.

AID TO SURVEY PRACTICE.

For Reference in Surveying, Levelling, and Setting-out; and in Route Surveys of Travellers by Land and Sea. With Tables, Illustrations, and Records. By Lowis D'A. Jackson, A.M.I.C.E. Second Edition, Enlarged. 8vo, cloth 126

"Mr. Jackson has produced a valuable vade-mecum for the surveyor. We can recommend this book as containing an admirable supplement to the teaching of the accomplished surveyor."—Athenaum.

"The author brings to his work a fortunate union of theory and practical experience which, aided by a clear and lucid style of writing, renders the book a very useful one."—Builder.

THE WATER SUPPLY OF CITIES AND TOWNS.

By WILLIAM HUMBER, A.M.Inst.C.E., and M.Inst.M.E., Author of "Cast and Wrought Iron Bridge Construction," &c., &c. Illustrated with 50 Double Plates, 1 Single Plate, Coloured Frontispiece, and upwards of 250 Woodcuts, and containing 400 pages of Text. Imp. 4to, elegantly and substantially half-bound

LIST OF CONTENTS.

I. HISTORICAL SERTCH OF SOME OF THE MEANS I. HISTORICAL SERTCH OF SOME OF THE MEANS THAT HAVE BEEN ADDITED FOR THE SUPPLY OF WATER AND TOWNS.—II. WATER NOT THE FOREIGN MATTER USUALLY ASSOCIATED WITH 17—III. RAINALL AND EVAPOKATION.—IV. SPRINGS AND TOWN EXAMINATION OF PLATES.—AFFENDERS, GIVING TABLES OF RATES OF SUPPLY. VELOCITIES, &C., &C., TOOKTHER WITH SPECIFICATIONS OF VARIOUS DISTRICTS.—V. MEASUREMENT AND ESTIMATION OF THE FLOW OF WATER.—XI. TREES OF RATES OF SUPPLY, VELOCITIES, &C., &C., TOOKTHER WITH SPECIFICATIONS OF SIVERAL WORKS ILLUSTRATED, AMONG WHICH WILL BE FOUND; AMERICAN LANGETH, IX. THE PURIFICATION OF WATER.—X. PUMPS.

—XI. PUMPING MACHINERY.—XII. CONDUITS.—

"The most systematic and valuable work upon water supply hitherto produced in English, or in any other language. Mr. Humber's work is characterised almost throughout by an exhaustiveness much more distinctive of French and German than of English technical treaties."—Engineer.

ONTENTS.

XIII. DISTRIBUTION OF WATER.—XIV. METERS, SERVICE PIPER, AND HOUSE FITTINGS.—XV. THE LAW AND ECONOMY OF WATER WORKS.—XVII. CONSTANT AND INTERMITTENT SUPPLY—XVII. DESCRIPTION OF PLATES.—APPERBUCES, CHVING TABLES OF RATES OF SUPPLY, VELOCITIES, &C., &C., TOORTHER WITH SPECIFICATIONS OF SEVERAL WORKS ILLUSTRATED, AMONG WHICH WILL BE FOUND: ABENDEEN, BIDEFORD, CANTERBURY, DUNDEE, HALIFAX, LAMBETH, ROTHEFHAM, DUBLIN, AND OTHERS.

THE PROGRESS OF ENGINEERING (1863-6).

By WM. HUMBER, A.M.Inst.C.E. Complete in Four Vols. Containing 148
Double Plates, with Portraits and Copious Descriptive Letterpress. Impl. 4to, half-morocco. Price, complete, £12 12s.; or each Volume sold separately at £3 3s. per Volume. Descriptive List of Contents on application.

HYDRAULIC POWER ENGINEERING.

A Practical Manual on the Concentration and Transmission of Power by Hydraulic Machinery. By G. CROYDON MARKS, A.M.Inst.C.E. With nearly 200 Illustrations. 8vo, cloth .

Summary of Contents

Principles of Hydraulics.—The Flow of Water, —Hydraulic Pressures. — Material.

—Test Load.—Packings for Sliding Survaces.—Plee Johns.—Controlling Valves.
—Platform Lipts.—Workshop and Foundry Crames.—Warehouse and Dock Crames.—Hydraulig Accumulators—Presses for Baling and other Purposes.—Sheet Metal.

"Ware have nouther but rese for this thoroughly subable of the control of the proposition of the proposition of the control of the

CONTENTS.

WORKING AND FORGING MACHINERY.—HYDRAULIC RIVETERS.—HAND AND POWER PUMPS.—STEAM PUMPS.—TURBINES.—REACTION TORRINES.—IMPULSE TURBINES.—REACTION TORRINES.—DESIGN OF TORRINES IN DETAIL.—WATER WHEELS.—HYDRAULIC ENGINES.—RECENT ACRIEVEMENTS.—PRESSURE OF WATER.—ACTION OF PUMPS, &c.

"We have nothing but praise for this thoroughly valuable work. The author has succeeded in rendering his subject interesting as well as instructive."—Practical Engineer.

"Can be unbesitatingly recommended as a useful and up-to-date manual on hydraulic transmission and utilisation of power."—Mechanical World.

HYDRAULIC TABLES, CO-EFFICIENTS, & FORMULÆ.

For Finding the Discharge of Water from Orifices, Notches, Weirs, Pipes, and Rivers. With New Formulæ, Tables, and General Information on Rain-fall, Catchment-Basins, Drainage, Sewerage, Water Supply for Towns and Mill Power. By John Neville, C.E., M.R.I.A. Third Edition, Revised, with Additions. Numerous Illustrations. Crown 8vo, cloth

"It is, of all English books on the subject, the one nearest to completeness,"-Architect,

HYDRAULIC MANUAL.

Consisting of Working Tables and Explanatory Text. Intended as a Guide in Hydraulic Calculations and Field Operations. By Lowis D'A. Jackson, Author of "Aid to Survey Practice," "Modern Metrology," &c. Fourth Edition, Enlarged. Large crown 8vo, cloth

"The author has constructed a manual which may be accepted as a trustworthy guide to this branch of the sugineer's profession."—Engineering.

WATER ENGINEERING.

A Practical Treatise on the Measurement, Storage, Conveyance, and Utilisation of Water for the Supply of Towns, for Mill Power, and for other Purposes. By CHARLES SLAGG, A.M.Inst.C.E. Second Edition. Crown 8vo, cloth . 7/6

"As a small practical treatise on the water supply of towns, and on some applications of water-power, the work is in many respects excellent." - Engineering.

11

i I

:

EARTHWORK TABLES.

Showing the Contents in Cubic Yards of Embankments, Cuttings, &c., of Height or Depths up to an average of 80 feet. By JOSEPH BROADSENT, C.E., and FRANCIS CAMPIN, C.E. Crown 8vo, cloth

"The way in which accuracy is attained, by a simple division of each cross section into three elements, two in which are constant and one variable, is ingenious."—Atheneum.

A MANUAL ON EARTHWORK.

By ALEX. J. GRAHAM, C.E. With numerous Diagrams. Second Edition. 18mo. 2/6

THE CONSTRUCTION OF LARGE TUNNEL SHAFTS. A Practical and Theoretical Essay. By J. H. WATSON BUCK, M.Inst.C.E.,

A Practical and Theoretical Essay. By J. H. WATSON BUCK, M.In Resident Engineer, L. and N. W. R. With Folding Plates, 8vo, cloth.

"Many of the methods given are of extreme practical value to the mason, and the observations on the form of arch, the rules for ordering the stone, and the construction of the templates, will be found of considerable use. We commend the book to the engineering profession."—Building News.
"Will be regarded by civil engineers as of the utmost value, and calculated to save much time and obviate many mistakes."—Colliery Guardies.

CAST & WROUGHT IRON BRIDGE CONSTRUCTION

(A Complete and Practical Treatise on), including Iron Foundations. In Three Parts—Theoretical, Practical, and Descriptive. By WILLIAM HUMBER, A.M.Inst.C.E., and M.Inst.M.E. Third Edition, Revised and much improved, with 115 Double Plates (20 of which now first appear in this edition), and numerous Additions to the Text. In 2 vols., imp. 4to, half-bound in morocco.

"A very valuable contribution to the standard literature of civil engineering. In addition to elevations, plans, and sections, large scale details are given, which very much enhance the instructive worth of those illustrations."—Civil Engineer and Architect's Journal.

"Mr. Humber's stately volumes, lately issued—in which the most important bridges erected during the last five years, under the direction of the late Mr. Brunel, Sir W. Cubitt, Mr. Hawkshaw, Mr. Page, Mr. Fowler, Mr. Hemans, and others among our most eminent engineers, are drawn and specified in great detail."—Engineer.

ESSAY ON OBLIQUE BRIDGES

(Practical and Theoretical). With 13 large Plates. By the late GEORGE WATSON BUCK, M.I.C.E. Fourth Edition, revised by his Son, J. H. WATSON Buck, M.I.C.E.; and with the addition of Description to Diagrams for Facilitating the Construction of Oblique Bridges, by W. H. L. Low, M.I.C.E. Royal 8vo, 12/-

"The standard text-book for all engineers regarding skew arches is Mr. Buck's treatise, and twould be impossible to consult a better."—Engineer,
"Mr. Buck's treatise is recognised as a standard text-book, and his treatment has divested the subject of many of the intricacles supposed to belong to it. As a guide to the engineer and architect, on a confessedly difficult subject, Mr. Buck's work is unsurpassed."—Huilding News.

THE CONSTRUCTION OF OBLIQUE ARCHES

(A practical Treatise on). By JOHN HART. Third Edition, with Plates. Imperial 8vo, cloth .

GRAPHIC AND ANALYTIC STATICS.

In their Practical Application to the Treatment of Stresses in Roofs, Solid Girders, Lattice. Bowstring, and Suspension Bridges, Braced Iron Arches and Piers, and other Frameworks. By R. Hudson Graham, C.E. Containing Diagrams and Plates to Scale. With numerous Examples, many taken from existing Structures. Specially arranged for Class-work in Colleges and Universities. Second Edition, Revised and Enlarged. 8vo, cloth 16/-Mr. Graham's book will find a place wherever graphic and analytic statics are used or studied."-

Engineer.

"The work is excellent from a practical point of view, and has evidently been prepared with much care. The directions for working are ample, and are illustrated by an abundance of well-selected examples. It is an excellent text-book for the practical draughtsman."—Athenaum.

WEIGHTS OF WROUGHT IRON AND STEEL GIRDERS.

A Graphic Table for Facilitating the Computation of the Weights of Wrought Iron and Steel Girders, &c., for Parliamentary and other Estimates. By J. H. Watson Buck, M.Inst.C.E. On a Sheet 26

GEOMETRY FOR TECHNICAL STUDENTS.

An Introduction to Pure and Applied Geometry and the Mensuration of Surfaces and Solids, including Problems in Plane Geometry useful in Drawing. By E. H. Sprague, A.M.I.C.E. Crown 8vo, cloth . [just Published. Net 1].

PRACTICAL GEOMETRY.

For the Architect, Engineer, and Mechanic. Giving Rules for the Delineation and Application of various Geometrical Lines, Figures, and Curves. By E. W. Tarn, M.A., Architect. 8vo, cloth

"No book with the same objects in view has ever been published in which the clearness of the rules laid down and the illustrative diagrams have been so satisfactory."—Scottman.

THE GEOMETRY OF COMPASSES.

Or, Problems Resolved by the mere Description of Circles, and the use of Coloured Diagrams and Symbols. By OLIVER BYRNE. Coloured Plates. Crown 8vo, cloth

EXPERIMENTS ON THE FLEXURE OF BEAMS.

Resulting in the Discovery of New Laws of Failure by Buckling. By Albert E. Guy. Medium Svo, cloth Net 9/-

HANDY BOOK FOR THE CALCULATION OF STRAINS

In Girders and Similar Structures and their Strength. Consisting of Formulæ and Corresponding Diagrams, with numerous details for Practical Application, &c. By William Humber, A.M.Inst.C.E., &c. Fifth Edition. Crown 8vo, with nearly 100 Woodcuts and 3 Plates, cloth . 7/6

"The formula are neatly expressed, and the diagrams good."—Athenaum.
"We heartily commend this really handy book to our engineer and architect readers."—English schools.

TRUSSES OF WOOD AND IRON.

Practical Applications of Science in Determining the Stresses, Breaking Weights, Safe Loads, Scantlings, and Details of Construction. With Complete Working Drawings. By William Griffiths, Surveyor. Oblong 8vo, cloth 4/6

"This handy little book enters so minutely into every detail connected with the construction of roof trusses that no student need be ignorant of these matters."—Practical Engineer.

THE STRAINS ON STRUCTURES OF IRONWORK.

A TREATISE ON THE STRENGTH OF MATERIALS.

With Rules for application in Architecture, the Construction of Suspension Bridges, Railways, &c. By Peter Barlow, F.R.S. A New Edition, revised by his Sons, P. W. Barlow, F.R.S., and W. H. Barlow, F.R.S.; to which are added, Experiments by Hodgkinson, Fairbairn, and Kirkaldy; and Formulæ for Calculating Girders, &c. Edited by WM. Hunber, A.M.I.C.E. 8vo, 400 pp., with 19 Plates and numerous Woodcuts, cloth

"Valuable alike to the student, tyro, and the experienced practitioner, it will always rank in future, as it has hitherto done, as the standard treatise on that particular subject."—Engineer.

SAFE RAILWAY WORKING.

A Treatise on Railway Accidents, their Cause and Prevention; with a Description of Modern Appliances and Systems. By CLEMENT E. STRETTON, C.E., With Illustrations and Coloured Plates. Third Edition, Enlarged. Crown 8vo, cloth. 3/6

"A book for the engineer, the directors, the managers; and, in short, all who wish for information on rallway matters will find a perfect encyclopædia in Safe Railway Working."—Railway Series.

EXPANSION OF STRUCTURES BY HEAT.

By John Kenny, C.E., late of the Indian Public Works Department. Crown Swo, cloth 3/6

"The aim the author has set before blue, viz., to show the effects of heat upon metallic and other structures, is a landable one, for this is a branch of physics upon which the engineer or architect can find but little reliable and comprehensive data in books."—Builder.

PUBLICATIONS OF THE ENGINEERING STANDARDS COMMITTEE.

THE Engineering Standards Committee is the outcome of a Committee appointed by the Institution of Civil Engineers at the instance of Sir John Wolfe Barry, K.C.B., to inquire into the advisability of Standardising Rolled Iron and Steel Sections.

The Committee is supported by the Institution of Civil Engineers, the Institution of Mechanical Engineers, the Institution of Naval Architects, the Iron and Steel Institute, and the Institution of Electrical Engineers; and the value and importance of its labours has been emphatically recognised by His Majesty's Government, who have made

a liberal grant from the Public Funds by way of contribution to the financial resources of the Committee. The subjects already dealt with, or under consideration by the Committee, include not only Rolled Iron and Steel Sections, but Tests for Iron and Steel Material used in the Construction of Ships and their

Machinery, Bridges and General Building Construction, Railway Rolling Stock Underframes, Component Parts of Locomotives, Railway and Tramway Rails, Electrical Plant, Insulating Materials, Screw Threads and Limit Gauges, Pipe Flanges, Cement, &c.

Reports already Published:-

BRITISH STANDARD SECTIONS.

List 1. Equal Angles.—List 2. Unequal Angles.—List 3. Bulb Angles.

List 4. Bulb Tees.—List 5. Bulb Plates.—List 7. Channels.—List 8.

Beams. Fcap folio, sewed. Just Published. Net 1/-

BRITISH STANDARD TRAMWAY RAILS AND FISH PLATES: STANDARD SECTIONS AND SPECIFICA-

TION. Fcap. folio, sewed . Just Published. Net 21/-

3. REPORT ON THE INFLUENCE OF GAUGE LENGTH AND SECTION OF TEST BAR ON THE PERCENTAGE OF ELONGATION.

By Professor W. C. Unwin, F.R.S. Fcap. folio, sewed,

[Just Published. Net 26

PROPERTIES OF STANDARD BEAMS.

Just Published. Demy 8vo, sewed PROPERTIES OF BRITISH STANDARD SECTIONS.

Embracing Diagrams, Definitions, Tables, and Formula: Demy 8vo, cloth. Just Published. Net 5/-

BRITISH STANDARD TABLES FOR COPPER CONDUCTORS AND THICKNESSES OF DIELECTRIC. Fcap. folio, sewed Just Published. Net 2 6

BRITISH STANDARD SPECIFICATION FOR TUBULAR TRAMWAY POLES.

. Just Published. Net 51-Fcap. folio, sewed

BRITISH ENGINEERING STANDARDS CODED LIST.
Rolled Sections for Constructional Iron and Steel Tram Rails. Compiled by
Net 21/-ROBERT ATKINSON. 476 pages. 4to, cloth .

MARINE ENGINEERING, SHIPBUILDING, NAVIGATION, ETC.

MARINE ENGINES AND BOILERS.

Their Design and Construction. A Handbook for the Use of Students, Engineers, and Naval Constructors. Based on the Work "Berechnung und Konstruktion der Schiffsmaschinen und Kessel," by Dr. G. Bauer, Engineerin-Chief of the Vulcan Shipbuilding Yard, Stettin. Translated from the Second German Edition by E. M. Donkin and S. Bryan Donkin, A.M.I.C.E. Edited by Leslie S. Robertson, Secretary to the Engineering Standards Committee, M.I.C.E., M.I.M.E., M.I.N.A., &c. With numerous illustrations and Tables. Medium 8vo, cloth [Nearly Ready. Price about Net 25]

Summary of Contewes. Part I.—Main Engines.—Determination of Cylinder Dimensions.—The Utilisation of Steam in the Engine.—Stroke of Piston.—Number of Revolutions.—Tuening Moment—Balancing of the Movino Parts.—Areamorement of Main Engines.—Tobetaile of Main Engines.—The Cylinder.—Valves.—Various Kidds of Valve Grar.—Piston Rode.—Pistons.—Connecting Rod and Crosshead.—Valve Grar Rods.—Bed Plates.—Engine Collumb.—Reversing and Turning Grar. Part II.—Plmps.—Air. Circulating, Fred, and Auxiliary Pumps. Part III.—Shafting, Resistance of Shids, Propellers.—Theory Shaft and Theust Block.—Tundel Shafting, Resistance of Shids, Propellers.—Theory Tobe.—The Screw Propeller.—Construction of the Screw.—Part IV.—Pipes and Connections.—Main Steam, Auxiliary Steam, and Ernaust Piping.—Fred Water, Biog, Balladt and Circulating Pipes.
Part V.—Steam Boilers.—Valves, &c.—Under Water Fittings.—Main Steam, Auxiliary Steam, and Engines.—Fibing and the Generation of Steam.—Cylindrical Boilers.—Part VI.—Engines.—Water Tube Boiler.—Shall Tube Water-Tube Boilers.—Swore Box.—Punnel and Boiler Lagging.—Forceh Draught.—Boiler Fittings and Mountings.—Part VI.—Warious Details.—Bolts, Nots, Screw Therade, &c.—Platfouns, Gratings.—Ladders.—Foundation.—Seatings.—Luberia-Tion.—Vextilation of Engine Rooms.—Rules for Spare Gear. Part VIII.—Additional Tables.

THE NAVAL ARCHITECT'S AND SHIPBUILDER'S POCKET-BOOK

fully Revised and Enlarged. Fcrp., leather

Summary of Contents. Signs and Symbols, Decimal Fractions.—Trigonometry.—Practical Grometry.—Mensuration.—Certres and Moments of Figores.—Moments of Intertal and Radii Gyration.—Aloarraical Expressions for Stimpson's Rules.—Mechanical Principles.—Certre of Geavity —Laws of Motion.—Displacement, Centre of Buovancy.—Certre of Geavity —Laws of Motion.—Displacement, Centre of Buovancy.—Certre of Geavity of Ship's Hull.—Stability Curves and Metacentres.—Sea and Shallow-water Waves.—Rolling of Ship's.—Propulsion and Resistance of Vessels.—Speed Trials.—Salling, Centre of Effort.—Distances down Rivers, Coast Lines.—Steering and Rudders of Vessels.—Laurging Calculations and Revoluties.—Weight of Material and Grap.—Gun Particulars and Weight.—Standard Gauges.—Rivered Joints and Rivering.—Streegth and Treats of Materials.—Binding and Shearing Stresses.—Streegth of Shapting, Philars, Wheels, Rtc.—Hydraciac Data, Rtc.—Comic Sections, Cathragian Corpes.—Mechanical Powers, Work.—Board of Trade Regulations for Ships.—Lovy's Weight of Chains.—Liopy's Scantings for Ships.—Data of Engines and Vessels.—Ships Fittings and Tests.—Seasoning Preserving Timeer.—Measurement of Timeer.—Allovy's Weight of Chains.—Liopy's Scantings for Ships.—Lavy for Preserving Timeer.—Measurement of Timeer.—Allovy. Paints, Varnishes.—Data for Stowage.—Admiralty Transfort Regulations.—Rules for Horse-fower, Screw Propellars, etc.—Precentages for But Steaps.—Particulars of Yachts.—Masting and Rigging.—Distances of Foreign Ports.—Tomage Tables of Weights and Measures.—Decimal Equivalents.—English Weights and Measures.—Foreign Weights and Centres Records of Circles.—Tables of Squabes and Cubes and Roots of Numbers.—Tables of Squabes and Cubes and Roots of Numbers.—Tables of Squabes and Cubes and Roots of Numbers.—Tables of Scapentimes of Circles.—Tables of Squabes and Cubes and Roots of Numbers.—Tables of Logarithms of Circles.—Tables of Squabes and Cubes and Roots of Numbers.—Tables of Numbers.—Tables of Numbers.

"In these days of advanced knowledge a work like this is of the greatest value. It contains a vast amount of information. We unhesitatingly say that it is the most valuable compilation for its specific purpose that has ever been printed. No navel architect, engineer, surveyor, seaman, wood or iron shipbuilder, can afford to be without this work."—Nunical Magazine.

"Should be used by all who are engaged in the construction or design of vessels. Will be found to contain the most useful tables and formulæ required by shipbuilders, collected from the best authorities, and put together in a popular and simple form. It is of exceptional ment."—Engineer.

"A pocket-book of this description must be a necessity in the shipbuilding trade. It contains a mass of useful information clearly expressed and presented in a handy form,"—Marine Engineer,

WANNAN'S MARINE ENGINEER'S GUIDE

To Board of Trade Examinations for Certificates of Competency.

To Board of Trade Examinations for Certificates of Competency.

Solutions:

302 Elementary Questions with Illustrated Answers, and Verbal Questions and Answers: complete Set of Drawings with Statements completed.

By A. C. Wannan, C. E., Consulting Engineer, and E. W. I. Wannan, M.I.M.E. Certificated First Class Marine Engineer. With numerous Engravings.

Third Edition, Enlarged. 500 pages. Large crown 8vo, cloth.

Not 10/8 Na 10/6 "The book is clearly and plainly written and avoids unnecessary explanations and formulas, a we consider it a valuable book for students of marine engineering."—Nastical Magazine.

WANNAN'S MARINE ENGINEER'S POCKET-BOOK.

Containing latest Board of Trade Rules and Data for Marine Engineers. By A. C. WANNAN Third Edition, Revised, Enlarged, and Brought up to Date. Square 18mo, with Thumb Index, leather.

"There is a great deal of useful information in this little pocket-book. It is of the rule-of-th order, and is, on that account, well adapted to the uses of the sea-going engineer."—Engineer.

THE SHIPBUILDING INDUSTRY OF GERMANY.

Compiled and Edited by G. LEHMANN-FELSKOWSKI. With Coloured Prints, Art Supplements, and numerous Illustrations throughout the Text. Superroyal 4to, cloth [Just Published. Net 10:6]

SEA TERMS, PHRASES, AND WORDS

(Technical Dictionary of) used in the English and French Languages. (English-French, French-English) For the Use of Seamen, Engineers, Pilots, Shipbuilders, Shipowners, and Ship-brokers. Compiled by W. Pirrie, late of the African Steamship Company. Fcap. 8vo, cloth limp

"This volume will be highly appreciated by seamen, engineers, pilots, shipbuilders and shipners. It will be found wonderfully accurate and complete."—Scotumes.

MARINE ENGINEER'S POCKET-BOOK,

Consisting of useful Tables and Formulæ. By FRANK PROCTOR, A.I.N.A. Third Edition. Royal 32mo, leather

"We recommend it to our readers as going far to supply a long-felt want."—
"A most useful companion to all marme engineers."—United Service Gazette -Naval Science.

ELEMENTARY MARINE ENGINEERING.

A Manual for Young Marine Engineers and Apprentices. By J. S. BREWER.

PRACTICAL NAVIGATION.

Consisting of The Sallor's Sea-Book, by J. Greenwood and W. H. Rosser; with Mathematical and Nautical Tables for Working the Problems, by H. Law, C.E., and Professor J. R. Young. 12mo, half-bound

THE ART AND SCIENCE OF SAILMAKING.

By SAMCEL B. SADLER, Practical Sailmaker, late in the employment of Messrs. Ratsey and Lapthorne, of Cowes and Gosport. Plates 4to, cloth 12/8
"This extremely practical work gives a complete education in all the branches of the manufacture, cutting out, roping, seaming and goring. It is copiously illustrated, and will form a first-rate text-book and guide,"—Portsmouth Times.

CHAIN CABLES AND CHAINS.

Comprising Sizes and Curves of Links, Studs, &c., Iron for Cables and Chains, Chain Cable and Chain Making, Forming and Welding Links, Strength of Cables and Chains, Certificates for Cables, Marking Cables, Prices of Chain Cables and Chains, Historical Notes, Acts of Parliament, Statutory Tests, Charges for Testing, List of Manufacturers of Cables, &c., &c. By Thomas W. Traill, F.E.R.N., M.Inst.C.E., Engineer-Surveyor-in-Chief, Board of Trade, Inspector of Chain Cable and Anchor Proving Establishments, and General Superintendent, Lloyd's Committee on Proving Establishments. With numerous Tables, Illustrations, and Lithographic Drawings. Folio cloth. Superintendent, Lloyd's Committee on Proving Establishments. With numerous Tables, Illustrations, and Lithographic Drawings. Folio, cloth. \$22. 28.

"It contains a vast amount of valuable information. Nothing seems to be wanting to make it a complete and standard work of reference on the subject."—Nantical Magazine.

MINING, METALLURGY, AND COLLIERY WORKING.

FIELDS OF RUSSIA AND THE RUSSIAN

PETROLEUM INDUSTRY.

A Practical Handbook on the Exploration, Exploitation, and Management of Russian Oil Properties, including Notes on the Origin of Petroleum in Russia, a Description of the Theory and Practice of Liquid Fuel, and a Translation of the Rules and Regulations concerning Russian Oil Properties. By A. Berry Trompson, A.M.I.M.E., late Chief Engineer and Manager of the European Petroleum Company's Russian Oil Properties. About 500 pp. With numerous Illustrations and Photographic Plates, and a Map of the Balakhary-Saboontchy-Romany Oil Field. Super-royal 8vo, cloth . [Just Published. Nat £3 38.

MACHINERY FOR METALLIFEROUS MINES.

A Practical Treatise for Mining Engineers, Metallurgists and Managers of Mines. By E. Henry Davies, M.E., F.G.S. 600 pp. With Folding Plates and other Illustrations. Medium 8vo, cloth

"Deals exhaustively with the many and complex details which go to make up the sum total of machinery and other requirements for the successful working of metalliferous mines, and as a book of ready reference is of the highest value to mine managers and directors."—Mining Journal.

THE DEEP LEVEL MINES OF THE RAND,

And their Future Development, considered from the Commercial Point of View.

By G. A. Denny (of Johannesburg), M.N.E.I.M.E., Consulting Engineer to the
General Mining and Finance Corporation, Limited, of London, Berlin, Paris,
and Johannesburg. Fully Illustrated with Diagrams and Folding Plates. Royal

8vo, buckram.

Net 25

"Mr. Denny by confining himself to the consideration of the future of the deep-level mines of the Rand breaks new ground, and by dealing with the subject rather from a commercial standpoint than from a scientific one, appeals to a wide circle of readers. The book cannot fall to prove of very great value to investors in South African mines."—Mining Journal.

PROSPECTING FOR GOLD.

A Handbook of Practical Information and Hints for Prospectors based on Personal Experience. By Daniel J. Rankin, F.R.S.G.S., M.R.A.S., formerly Manager of the Central African Company, and Leader of African Gold Prospecting Expeditions. With Illustrations specially Drawn and Engraved for the Work. Fcap. 8vo, leather

"This well-compiled book contains a collection of the richest gems of useful knowledge for the prospector's benefit. A special table is given to accelerate the spotting at a glance of minerals associated with gold."—Mining Journal.

THE METALLURGY OF GOLD.

A Practical Treatise on the Metallurgical Treatment of Gold-bearing Ores.
Including the Assaying, Melting, and Refining of Gold. By M. EISSLER,
M.Inst.M.M. Fifth Edition, Enlarged. With over 300 Illustrations and

Numerous Folding Plates. Medium 8vo, cloth

"This book thoroughly deserves in title of a "Practical Treatise." The whole process of gold mining, from the breaking of the quartz to the assay of the bullion, is described in clear and orderly narrative and with much, but not too much, fulness of detail."—Salueday Review.

THE CYANIDE PROCESS OF GOLD EXTRACTION.

And its Practical Application on the Witwatersrand Gold Fields and elsewhere. By M. Etsslar, M. Inst. M. M. With Diagrams and Working Drawings. Third Edition, Revised and Enlarged. 8vo, cloth . Net 7/8 "This book is just what was needed to acquain mining men with the actual working of a process which is not only the most popular, but is, as a general rule, the most successful for the extraction of gold from tailings."—Mining Journal.

DIAMOND DRILLING FOR GOLD & OTHER MINERALS.

A Practical Handbook on the Use of Modern Diamond Core-Drills in Prospecting and Exploiting Mineral-bearing Properties, including Particulars of the Cost of Apparatus and Working. By G. A. Denny, M.N.E. Inst. M.E., M.Inst. M.M. Medium 8vo, 168 pp., with Illustrative Diagrams 12/6
"There is certainly scope for a work on diamond drilling, and Mr. Denny deserves grateful recognition for supplying a decided want."—Mining Journal.

GOLD ASSAYING.

A Practical Handbook, giving the Modus Operandi for the Accurate Assay of Auriferous Ores and Bullion, and the Chemical Tests required in the Processes of Extraction by Amalgamation, Cyanidation, and Chlorination. With an Appendix of Tables and Statistics. By H. Joshua Phillips, F.I.C., F.C.S., Assoc Inst.C.E., Author of "Engineering Chemistry," &c. With Numerous Illustrations. Large Crown 8vo, cloth . [Just Published. Nat 7/6]

FIELD TESTING FOR GOLD AND SILVER.

A l'ractical Manual for Prospectors and Miners. By W. H. MERRITT,
M.N. E.Inst.M.E., A.R.S.M., &c. With Photographic Plates and other Illustrations. Fcap. 8vo, leather

"As an instructor of prospectors' classes Mr. Merritt has the advantage of knowing exactly the
information likely to be most valuable to the miner in the field. The contents cover all the details of
sampling and testing gold and silver ores. A useful addition to a prospector's kit."—Missing Journal.

THE PROSPECTOR'S HANDBOOK.

A Guide for the Prospector and Traveller in Search of Metal-Bearing or other Valuable Minerals. By J. W. Anderson, M.A. (Camb.), F.R.G.S. Ninth Edition. Small crown 8vo, 3/6 cloth; or, leather

"Will supply a much felt want, especially among Colonists, in whose way are so often thrown meany mineralogical specimens the value of which it is difficult to determine."—Engineer.

"How to find commercial minerals, and how to identify them when they are found, are the leading points to which attention is directed. The author has managed to pack as much practical detail into his pages as would supply material for a book three times its size."—Mining Journal.

THE METALLURGY OF SILVER.

A Practical Treatise on the Amalgamation, Roasting, and Lixiviation of Silver Ores. Including the Assaying, Melting, and Refining of Silver Bullion. By M. EISSLER, M.Inst. M.M. Third Edition. Crown 8vo, cloth

"The work will supply a long felt want amongst practical men, and at the same time be of value to students and others indirectly connected with the industries."—Mining Journal.

THE HYDRO-METALLURGY OF COPPER.

Being an Account of Processes Adopted in the Hydro-Metallurgical Treatment of Cupriferous Ores, including the Manufacture of Copper Vitriol. With Chapters on the Sources of Supply of Copper and the Roasting of Copper Ores. By M. FISSLER, M. Inst M.M. 8vo, cloth.

"In this volume the various processes for the extraction of copper by wet methods are fully detailed. Costs are given when available, and a great deal of useful information about the copper industry of the world is presented in an interesting and attractive manner."—Mining Journal.

THE METALLURGY OF ARGENTIFEROUS LEAD.

A Practical Treatise on the Smelting of Silver-Lead Ores and the Refining of Lead Bullion. Including Reports on various Smelting Establishments and Descriptions of Modern Smelting Furnaces and Plants in Europe and America By M. EISSLER, M.Inst.M.M., Author of "The Metallurgy of Gold," &c.

Crown 8vo, 400 pp., with 183 Illustrations, cloth

"The numerous metallurgical processes, which are fully and extensively treated of, embrace all the stages experienced in the passage of the lead from the various natural states to its issue from the refinery as an article of commerce."—Practical Engineer.

METALLIFEROUS MINERALS AND MINING.

By D. C. Davies, F.G.S. Sixth Edition, thoroughly Revised and much Enlarged by his Son, E. Henry Davies, M.E., F.G.S. 600 pp., with 173 Illustrations.

EARTHY AND OTHER MINERALS AND MINING.

By D C. Davies, F.G.S., Author of "Metalliferous Minerals," &c. Third

Edition, Revised and Enlarged by his Son, E. Henry Davies, M.E., F.G.S.

With about 100 Illustrations. Crown 8vo, cloth

"We do not remember to have met with any English work on mining matters that contains the same amount of information packed in equally convenient form."—Academy.

POCKET-BOOK FOR MINERS & METALLURGISTS.

Comprising Rules, Formulæ, Tables, and Notes, for Use in Field and Off Work. By F. Danvers Power, F.G.S., M.E. Second Edition, Corrects Fcap. Svo, leather

"This excellent book is an admirable example of its kind, and ought to find a large sale among English-speaking prospectors and mining engineers."—Engineering.

THE MINER'S HANDBOOK,

A Handy Book of Reference on the subjects of Mineral Deposits, Mining Operations, Ore Dressing, &c. For the Use of Students and others interested in Mining matters. Compiled by JOHN MILNE, F.R.S., Professor of Mining in the Imperial University of Japan. Third Edition. Fcap. 8vo, leather . 7/6

"Professor Milne's handbook is sure to be received with favour by all connected with mining, and will be extremely popular among students."—Athenous.

IRON ORES OF GREAT BRITAIN AND IRELAND.

Their Mode of Occurrence, Age and Origin, and the Methods of Searching for and Working them. With a Notice of some of the Iron Ores of Spain. By

MINE DRAINAGE.

A Complete Practical Treatise on Direct-acting Underground Steam Pumping Machinery. By STEPHEN MICHELL. Second Edition, Re-written and Enlarged. With 250 Illustrations. Royal 8vo, cloth. Nat 25/-

HORIZONTAL PUMPING ENGINES—ROTARY AND NON-ROTARY HORIZONTAL ENGINES—
STRITER AND COMPOUND STRAM PUMPS—VERTICAL PUMPING ENGINES—ROTARY AND NORBOTARY VERTICAL ENGINES—SIMPLE AND COMPOUND STRAM PUMPS—TRIPLE EXPANSION STRAM
PUMPS—PULSATING STRAM PUMPS—PUMP VALVES—SINKING PUMPS, &c., &c.

"This volume contains an immertar amount of important and interesting new matter. The book should undoubtedly prove of great use to all who wish for information on the subject."—The Engineer.

ELECTRICITY AS APPLIED TO MINING.

By Arnold Lupton, M Inst. C.E., M.I.M.E., M.I.E.E., late Professor of Coal Mining at the Yorkshire College, Victoria University, Mining Engineer and Colliery Manager; G. D. Asymall Parr, M.I.E.E., A.M.I.M.E., Associate of the Central Technical College, City and Guilds of London, Head of the Electrical Engineering Department, Yorkshire College, Victoria University; and Herment Perrin, M.I.M.E., Certificated Colliery Manager, Assistant Lecturer in the Mining Department of the Yorkshire College, Victoria University. With about 170 Illustrations. Medium 800 cloth. With about 170 Illustrations. Medium Svo, cloth (For SUMMARY OF CONTENTS, see page 23.)

THE COLLIERY MANAGER'S HANDBOOK.

A Comprehensive Treatise on the Laying-out and Working of Collieries, Designed as a Book of Reference for Colliery Managers, and for the Use of Coal-Mining Students preparing for First-class Certificates. By Caler Pamelly, Mining Engineer and Surveyor; Member of the North of England Institute of Mining and Mechanical Engineers; and Member of the South Wales Institute of Mining Engineers. With over 1,000 Diagrams, Plans, and other Illustrations. Fifth Edition, Carefully Revised and Greatly Enlarged. 1,200 pp. Medium 8vo, cloth.

[Just Published. Net £158.]

GEOLOGY.—SEARCH FOR COAL.—MINERAL LEARER AND OTHER HOLDING.—SHAPE SINKING.—FITTING UP THE SHAPE AND SURFACE ABRANGSMENTS.—STEAM BOILERS AND THEIR FITTINGS.—THERREIFG AND WALLING.—NARROW WORE AND METHODS OF WORKING.—UNDERGROUND CONVEY.
AREA.—DRAIRAGE.—THE GASES WET WITH IN MINES!—VENTUATION.—ON THE PRICTION OF ARE IN
MINES.—THE PRICTIANS OF ENGINEE PETROLEUM AND NATURAL GAS.—SCRUNKING AND PLANHING.—SAFETY LAMPS AND FIRE-DAMP DETROCTORS.—SUNDRY AND INCIDENTAL OPERATIONS AND
APPLANCES.—COLLERY EXPLOSIONS.—MISCRILARIOUS QUESTIONS AND ANAWERS.—Approxiz
SUMMARY OF REPORT OF H.M. COMMISSIONERS ON ACCIDENTS IN MINES.

"Mr. Pamely's work is emimently suited to the purpose for which it is intended—being clear, interesting, exhapsive, rich in detail, and up to date, giving descriptions of the latest machines in every department. A mining engineer could scarcely go wrong who followed this work.—Colliery Grandian.

"Ms. Pamely has not only given us a comprehensive reference book of a very high order, suitable to the requirements of mining engineers and colliery managers, but has also provided mining students while a class-book that is as interesting as it is instructive."—Colliery Manager.

"This is the most complete 'all-round' work on coal-mining published in the Ringlish language.

"This is the most complete 'all-round' work on coal-mining published in the Ringlish language.

"I has is the most complete 'all-round' work on coal-mining pul . . . No library of coal-mining books is complete without it "—Colliery

PRACTICAL COAL MINING.

An Elementary Class Book for the use of Students preparing for the Examinations of the Board of Education and for Colliery Manager's Certificates, by T. H. COCKIN, Mining Engineer, Lecturer on Coal Mining at University College, Sheffield. Crown 8vo, 450 pages, with 200 Illustrations.

[Nearly Ready. Price about 4:8 Nd.

COLLIERY WORKING AND MANAGEMENT.

Comprising the Duties of a Colliery Manager, the Oversight and Arrangement of Labour and Wages, and the different Systems of Working Coal Seams. E. H. F. BULMAN and R. A. S. REDMAYNE. 350 pages, with 28 Plates and other Illustrations, including Underground Photographs. Medium 8vo, cloth. 18,

"This is, indeed, an admirable Handbook for Colliery Managers, in fact, it is an indispensable adjunct to a Colliery Manager's education, as well as being a most useful and interesting work on the subject for all who in any way have to do with ooal mining. The underground photographs are an attractive feature of the work, being very life-like and necessarily true representations of the scenes they depict."—Colliery Guardian.

"Mr. Bulman and Mr. Redmayne are to be congratulated on having supplied an authorizative work dealing with a side of the subject of coal mining which has hitherto received but scant treasmont. The illustrations are excellent."—Nature.

COAL AND COAL MINING.

By the late Sir Warington W. Smyth, M.A., F.R.S. Eighth Edition, Revised and Extended by T. Forster Brown, Chief Inspector of the Mines of the Crown and of the Duchy of Cornwall. Crown 8vo, cloth 3/6

"As an outline is given of every known coal-field in this and other countries, as well as of the principal methods of working, the book will doubtless interest a very large number of readers."—Mining Journal.

NOTES AND FORMULÆ FOR MINING STUDENTS.

By John Herman Merivale, M.A., Late Professor of Mining in the Durham College of Science, Newcastle-upon-Tyne. Fourth Edition, Revised and Enlarged, by H. F. Bulman, A.M.Inst.C.E. Small crown 8vo, cloth . 2/6

"The author has done his work in a creditable manner, and has produced a book that will be of service to students, and those who are practically engaged in mining operations."—Engineer.

INFLAMMABLE GAS AND VAPOUR IN THE AIR

(The Detection and Measurement of). By Frank Clowes, D.Sc., Lond., F.I.C.

With a Chapter on The Detection and Measurement of Petroleum Vapour, by Daning of Patroleum Vapour, by by Boverton Redwood, F.R.S.E. Crown 8vo, cloth Net 5 -

"Professor Clowes has given us a volume on a subject of much industrial importance.

Those interested in these matters may be recommended to study this book, which is easy of comprehension and contains many good things."—The Engineer.

COAL & IRON INDUSTRIES OF THE UNITED KINGDOM.

Comprising a Description of the Coal Fields, and of the Principal Seams of Coal with Returns of their Produce and its Distribution, and Analyses of Special Varieties. Also, an Account of the Occurrence of Iron Ores in Veins or Seams; Analyses of each Variety; and a History of the Rise and Progress of Pig Iron Manufacture. By RICHARD MEADE. 8vo, cloth

"A book of reference which no one engaged in the iron or coal trades should omit from his library."—Iron and Coal Trades Review.

ASBESTOS AND ASBESTIC.

Their Properties, Occurrence, and Use. By ROBERT H. JONES, F.S.A., Mineralogist, Hon. Mem. Asbestos Club, Black Lake, Canada. With Ten Collotype Plates and other Illustrations. Demy 8vo, cloth An interesting and invaluable work."-Colliery Guardian.

GRANITES AND OUR GRANITE INDUSTRIES. By George F. Harris, F.G.S. With Illustrations. Crown 8vo, cloth.

TRAVERSE TABLES.

For use in Mine Surveying. By WILLIAM LINTERN, C.E. With two Plates. Small crown 8vo, cloth Net 3/-

ELECTRICITY, ELECTRICAL ENGINEERING, ETC.

THE ELEMENTS OF ELECTRICAL ENGINEERING.

A First Year's Course for Students. By Tyson Sewell, A.I.E.E., Assistant Lecturer and Demonstrator in Electrical Engineering at the Polytechnic, Regent Street, London. Second Edition, Revised, with Additional Chapters on Alternating Current Working, and Appendix of Questions and Answers. 450 pages, with 274 Illustrations. Demy 8vo, cloth [Just Published. Nat 7/6]

450 pages, with 274 linistrations. Demy 8vo, Goth | Isst Published. 1465

Ohm's Law.—Units Employed in Electrical Engineering.—Series and Paraliel Circuits; Current Density and Potential Drop in the Circuit.—The Heating Effect of the Electric Current.—The Magnetics. Figure 16 for the Electric Current.—The Magnetics of Iron.—Electro-Chemistry: Frimary Batteries.—Accumulators.—Indicating Instruments; Ammeters, Voltneters, Ohmmeters.—Electricity Supply Meters.—Measuring Instruments, and the Magneters of Electrical Resis ance.—Measuring Instruments, and the Magneters of Electrical Resis ance.—Measuring Instruments, Ammeters.—Measuring Instruments, and the Magneters of Electrical Resis ance.—Measuring Lamps; Manufacture and Installation; Photometry.—The Continuous Current Dynamo.—Direct Current Motors.—Alternating Currents.—Transformers, Alternators, Synchronous Motors.—Polyphase Working.—Affender of Questions and Answers.

"An excellent treatise for syncholis of the elemplary facts connected with electrical

TE

"An excellent treatise for students of the elementary facts connected with electrical engineering."—The Electrician.

"One of the best books for those commencing the study of electrical engineering. Everything is explained in simple language which even a beginner cannot fail to understand."—Engineer.

"One welcomes this book, which is sound in its treatment, and admirably calculated to give students the knowledge and information they most require."—Nature.

CONDUCTORS FOR ELECTRICAL DISTRIBUTION.

CONDUCTOR MATERIALS—ALLOYED CONDUCTORS—MANUFACTURE OF WIRE—WIRE-FINISHING—WIRE INSULATION—CARLES—CALCULATION OF CIRCUITS—KELVIN'S LAW OF ECONOMY IN CONDUCTORS—MULTIFLE ARC DISTRIBUTION—ALTERNATING CURRENT CALCULATION—OVERSEAD LINES—POLE LINE—LINE INSULATORS—UNDERGROUND CONDUCTORS.

WIRELESS TELEGRAPHY.

Its Origins, Development, Inventions, and Apparatus. SEWALL. With 85 Diagrams and Illustrations. Demy By CHARLES HENRY Demy 8vo, cloth.

[Just Published.

ARMATURE WINDINGS OF DIRECT CURRENT DY-NAMOS.

Extension and Application of a General Winding Rule. By E. Arnold, Engineer. Assistant Professor in Electrotechnics and Machine Design at the Riga Polytechnic School. Translated from the Original German by Francis B. De Gress, M.E., Chief of Testing Department, Crocker-Wheeler Company. With 146 Illustrations. Medium Svo, cloth

ELECTRICITY AS APPLIED TO MINING.

By Arnold Lupton, Minst.C.E., Mim.E., Mie.E., late Professor of Coal Mining at the Yorkshire College, Victoria University, Mining Engineer and Colliery Manager: G. D. Aspinall Parr. Mie.E., A.M.I.M.E., Associate of the Central Technical College, City and Guilds of London, Head of the Electrical Engineering Department, Yorkshire College, Victoria University: and Herbert Perkin, M.I.M.E., Certificated Colliery Manager, Assistant Lecturer in the Mining Department of the Yorkshire College, Victoria University. With about 170 Illustrations. Medium 8vo, cloth. Net 9/Introductory.—Dynamic Electricity.—Driving of the Dynamo.—The Steam Turbulan Distribution of Rescribeal Engroy.—Starting and Stopping Electrical Generators and Motores.—Electric Carles.—Central Electrical Plants.—Electrical Generators and Motores.—Electric Carles.—Central Electrical Plants.—The Alectric Carles and Harling.—Electric Lighting by Arc and Glow Lamps.—Miscellaneous Applications of Rescribing and Barles of Bectricity as Compared with Other Modes of Transmitting Power.—Dangers of Blectricity.

DYNAMO, MOTOR AND SW FOR ELECTRICAL ENGINEERS. AND SWITCHBOARD CIRCUITS

A Practical Book dealing with the subject of Direct, Alternating and Polyphase Currents. By William R. Bowker, C.E., M.E., E.E., Consulting Tramwav Engineer. 8vo, cloth [Just Published. Net 6]

DYNAMO ELECTRIC MACHINERY: ITS CONSTRUCTION DESIGN, AND OPERATION.

By Samuel Shelixon, A.M., Ph.D., Professor of Physics and Electrical Engineering at the Polytechnic Institute of Brooklyn, assisted by Hobart MASON, B.S.

In two volumes, sold separately, as follows :-

Vol. I.—DIRECT CURRENT MACHINES. Third Edition, Revised. ed. Large Not 12/-

Designed as Text-books for use in Technical Educational Institutions, and by Engineers whose work includes the handling of Direct and Alternating Current Machines respectively, and for Students proficient in mathematics.

ELECTRICAL AND MAGNETIC CALCULATIONS.

For the Use of Electrical Engineers and Artisans, Teachers, Students, and all others interested in the Theory and Application of Electricity and Magnetism. By A. A. Atkinson, Professor of Electricity in Ohio University. Crown 8vo. Net 9/-

"To teachers and those who already possess a fair knowledge of their subject we can recommend this book as being useful to consult when requiring data or formulæ which it is neither convenien: nor necessary to retain by memory."—The Electrician.

SUBMARINE TELEGRAPHS.

Their History, Construction and Working. Founded in part on WÜNSCHENDORFF'S "Traité de Télégraphie Sous Marine," and Compiled from Authoritative
and Exclusive Sources. By CHARLES BRIGHT, F.R.S.E., A M.Inst.C.E., M.I.E.E.
780 pp., fully illustrated, including Maps and Folding Plates. Royal 8vo, cloth.
Not. 880. Net £3 3s.

"There are few, if any, persons more fitted to write a treatise on submarine telegraphy than Mr. Charles Bright. He has done his work admirably, and has written in a way which will appeal as much to the las man as to the engineer. This admirable volume must for many years to come hold the position of the English classic on submarine telegraphy."—Engineer.

"This book is full of information. It makes a book of reference which should be in every engineer's library."—Nature.

"Mr. Bright's interestingly written and admirably illustrated book will meet with a welcome reception from cable men."—Electrician.

"The Author deals with his subject from all points of view—political and strategical as well as scientific—the work will be of interest not only to men of science, but to the general public. We can strongly recommend it."—Athen.cum.

THE ELECTRICAL ENGINEER'S POCKET-BOOK.

Consisting of Rules, Formula, Tables, and Data. By H. R. KEMPE, M.I.E.E., A.M.Inst.C.E., Technical Officer, Postal Telegraphs, Author of "A Handbook of Electrical Testing," &c. Second Edition, Thoroughly Revised, By H. R. KEMPE. with Additions. With numerous Illustrations. Royal 32mo, oblong, leather 5-"It is the best book of its kind."—Electrical Engineer.
"The Electrical Engineer's Pocket-Book is a good one."—Electrician.
"Strongly recommended to those engaged in the electrical industries."—Electrical Review.

POWER TRANSMITTED BY ELECTRICITY.

DYNAMIC ELECTRICITY AND MAGNETISM.

By Philip Atkinson, A.M., Ph.D., Author of "Elements of Static Electricity,"

10/6 &c. Crown 8vo, 417 pp., with 120 Illustrations, cloth .

THE MANAGEMENT OF DYNAMOS.

A Handybook of Theory and Practice for the Use of Mechanics, Engineers, Students and others in Charge of Dynamos. By G. W. LUMMIS-PATERSON Third Edition, Revised. Crown 8vo, cloth

"An example which deserves to be taken as a model by other authors. The subject is treated in a manner which any intelligent man who is fit to be entrusted with charge of an engine should be able to understand. It is a useful book to all who make, tend or employ electric machinery."—Architect.

THE STANDARD ELECTRICAL DICTIONARY.

A Popular Encyclopædia of Words and Terms Used in the Practice of Electrical Engineering. Containing upwards of 3,000 Definitions. By T. O'Conor Sloans, A.M., Ph.D. Third Edition, with Appendix. Crown 8vo, 690 pp., 390 Net 7/8

"The work has many attractive features in it, and is, beyond doubt, a well put together and useful sublication. The amount of ground covered may be gathered from the fact that in the index about coo references will be found."—Electrical Review.

ELECTRIC LIGHT FITTING.

A Handbook for Working Electrical Engineers, embodying Practical Notes on Installation Management. By J. W. URQUHART, Electrician, Author of "Electric Light," &c. With numerous Illustrations. Third Edition, Revised, with Additions, Crown Svo, cloth

"This volume deals with the mechanics of electric lighting, and is addressed to men who are already engaged in the work, or are training for it. The work traverses a great deal of ground, and may be read as a sequel to the author's useful work on 'Electric Light.'"—Electrician.

"The book is well worth the perusal of the workman, for whom it is written."—Electricial Review.

ELECTRIC LIGHT.

Its Production and Use, Embodying Plain Directions for the Treatment of Dynamo-Electric Machines, Batteries, Accumulators, and Electric Lamps. By J. W. URQUHART, C.E. Sixth Edition, Enlarged. Crown 8vo, cloth . 7/6 The whole ground of electric lighting is more or less covered and explained in a very clear and se manner."—Electrical Review.

A vade-mesum of the salient facts connected with the science of electric lighting."—Electrician. concise manner

DYNAMO CONSTRUCTION.

A Practical Handbook for the Use of Engineer Constructors and Electricians-in-Charge. Embracing Framework Building, Field Magnet and Armature Winding and Grouping, Compounding, &c. By J. W. URQUHART. Second Edition, Enlarged. With 114 Illustrations. Crown 8vo, cloth 7/6

"Mr. Urquhart's book is the first one which deals with these matters in such a way that the engineering student can understand them. The book is very readable, and the author leads his readers up to difficult subjects by reasonably simple tests."—Engineering Review,

ELECTRIC SHIP-LIGHTING.

A Handbook on the Practical Fitting and Running of Ship's Electrical Plant. For the Use of Shipowners and Builders, Marine Electricians, and Sea-going Engineers-in-Charge. By J. W. URQUHART, C.E. Second Edition. Revised and Extended. With 88 Illustrations, crown 8vo, cloth 7/6

"The subject of ship electric lighting is one of vast importance, and Mr. Urquhart is to compilmented for placing such a valuable work at the service of marine electricians."—The compilmented for placing such a valuable work at the service of marine electricians."—The

By ALAN A. CAMPBELL SWINTON, M.Inst.C.E., M.I.E.E. Fifth Edition, With 16 Illustrations. Crown 8vo, cloth

ELECTRIC LIGHT FOR COUNTRY HOUSES.

A Practical Handbook on the Erection and Running of Small Installations, with Particulars of the Cost of Plant and Working. By J. H. KNIGHT. Third Edition, Revised. Crown 8vo, wrapper 1/-

HOW TO MAKE A DYNAMO.

A Practical Treatise for Amateurs. Containing Illustrations and Detailed Instructions for Constructing a Small Dynamo to Produce the Electric Light. By ALFRED CROFTS. Sixth Edition, Revised. Crown Svo, cloth

THE STUDENT'S TEXT-BOOK OF ELECTRICITY.
By H. M. Noad, P.R.S. 650 pp., with 470 Illustrations. Grown 8vo, cloth. 9/-

. 1

ARCHITECTURE, BUILDING, ETC.

SPECIFICATIONS IN DETAIL.

By Frank W. Macey, Architect, Author of "Conditions of Contract." Secondition, Revised and Enlarged, containing 644 Pages and 2,000 Illustration Royal 8vo, cloth . [Just Published. Na. 21] SUMMARY OF CONTENTS.

Summary of Contents.

General Notes (including Points in Specification Writing, The Order of a Specification, and Notes on Items often Omitted from a Specification.—Form of Outsil Cover to a Specification.—Specification of Works and List of General Comditions.

Preliminary Items (including Shoring and House Breaker).—Draimage (including Rat Water Welli4 and Reports).—Excavator (including Concrete Floors, Roofs, Stairs as Walls).—Pavior.—Bright aver (including Fintwork, River and other Walling, Sprim Water Wells, Storage Tanks, Fountains, Filters, Terra Cotta and Fairnce).—Mason.—Campenter, Joiner and Bronmonger (including Fricing and Piling).—Smith and Founds (including Heating, Fire Hydramts, Staile and Cow House Fittings).—Slater (including Hot Water Mason).—Tiler.—Sione Tiler.—Shingler.—Thatcher.—Plumber (including Hot Water Wore).—Zincworker.—Coppersmith.—Plasterre.—Gartiter.—Bellibanger.—Gealier.—Painter.—Paperranger.—General Repairs and Alterations.—Ventilatios.—Road-Making.—Electric Lighting.—Index.

PRACTICAL BUILDING CONSTRUCTION.

A Handbook for Students Preparing for Examinations, and a Book of Reference for Persons Engaged in Building. By John Parnell Allen, Surveyor Lecturer on Building Construction at the Durham College of Science, Newcastle on-Tyne. Fourth Edition, Revised and Enlarged. Medium 8vo, 570 pages, with over 1,000 Illustrations, cloth [Just Published. Net 7]

"The most complete exposition of building construction we have seen. It contains all that is necessary to prepare students for the various examinations in building construction."—Building Nows.

"The author depends nearly as much on his diagrams as on his type. The pages suggest the hand of a man of experience in building operations—and the volume must be a blessing to many teachers as well as to students."—The Architect.

PRACTICAL MASONRY.

A Guide to the Art of Stone Cutting. Comprising the Construction, Setting-out, and Working of Stairs, Circular Work, Arches, Niches, Domes, Pendentives, Vaults, Tracery Windows, &c.; to which are added Supplements relating to Masonry Estimating and Quantity Surveying, and to Building Stones and Marbles, and a Glossary of Terms. For the Use of Students, Masons, and Craftsmen. By William R. Purchase, Building Inspector to the Borough of Hove. Fifth Edition, Enlarged. Royal 8vo, 226 pages, with 52 Lithographic Plates, comprising over 400 Diagrams, cloth [Just Published. Net 716]

"The book is a practical treatise on the subject, the author himself having commenced as an operative mason, and afterwards acted as foreman mason on many large and important buildings prior to the attainment of his present position. Most of the examples given are from actual work carried out. It should be found of general utility to archite ctural students and others, as well as to those to whom it is specially addressed."—Journal of the Royal Institute of British Architects.

MODERN PLUMBING,

STEAM AND HOT WATER HEATING.

A New Practical Work for the Plumber, the Heating Engineer, the Architect, and the Builder. By J. J. LAWLER, Author of "American Sanitary Plumbing," With 284 Illustrations and Folding Plates. 4to, cloth

HEATING BY HOT WATER,

VENTILATION AND HOT WATER SUPPLY.

By WALTER JONES, M.I.M.E. 360 pages, with 140 Illustrations. Medium 8vo, [Just Published. cloth

CONCRETE: ITS NATURE AND USES. A Book for Architects, Builders, Contractors, and Clerks of Works. By George

A BOOK FOR ARCHITECTS, DURIGETS, CONTRACTORS, AND CIERRS OF WORKS. By GRORGE L. SUTCLIFFE, A.R.I.B.A. 350 pages, with Illustrations. Crown 8vo, cloth 7:6 "The author treats a difficult subject in a lucid manner. The manual fills a long felt gap. It is full and exhaustive; equally useful as a student's guide and an architect's book of reference."—neal of the Royal Institute of British Architects.

LOCKWOOD'S BUILDER'S PRICE BOOK FOR 1904.

A Comprehensive Handbook of the Latest Prices and Data for Builders, Architects, Engineers, and Contractors. Re-constructed, Re-written, and Greatly Enlarged. By Francis T, W. Miller. 800 closely-printed pages, crown 8vo, cloth

"This book is a very useful one, and should find a place in every English office connected with the building and engineering professions." Industries. "An excellent book of reference." Architect.

"Comprehensive, reliable, well arranged, legible, and well bound." -British Architect.

MEASURING AND VALUING ARTIFICERS' WORK

(The Student's Guide to the Practice of). Containing Directions for taking Dimensions, Abstracting the same, and bringing the Quantities into Bill, with Tables of Constants for Valuation of Labour, and for the Calculation of Areas and Solidities. Originally edited by E. Dorson, Architect. With Additions by E. W. TARN, M.A. Seventh Edition, Revised. Crown 8vo, cloth. 7/6

"The most complete treatise on the principles of measuring and valuing artificers' work."—Building

TECHNICAL GUIDE, MEASURER, AND ESTIMATOR.

For Builders and Surveyors. Containing Technical Directions for Measuring Work in all the Building Trades, Complete Specifications for Houses, Roads, and Drains, and an Easy Method of Estimating the parts of a Building collectively. By A. C. Beaton. Ninth Edition. Waistcoat-pocket size, gilt edges 1/6 "No builder, architect, surveyor, or valuer should be without his 'Beaton."—Building News.

THE HOUSE-OWNER'S ESTIMATOR.

Or, What will it Cost to Build, Alter, or Repair? A Price Book for Unprofessional People, as well as the Architectural Surveyor and Builder. By J. D. Simon. Edited by F. T. W. Miller, A.R.I.B.A. Fifth Edition, carefully Revised. Crown 8vo, cloth "In two years it will repay its cost a hundred times over."-Field,

SPECIFICATIONS

FOR PRACTICAL ARCHITECTURE.

A Guide to the Architect, Engineer, Surveyor, and Builder. Upon the Basis of the Work by A. Bartholomew, Revised, Corrected, and greatly added to by F. Rogers, Architect. Third Edition. Svo, cloth.

"One of the books with which every young architect must be equipped."—Architect.

ARCHITECTURAL PERSPECTIVE.

The whole Course and Operations of the Draughtsman in Drawing a Large House in Linear Perspective. Illustrated by 43 Folding Plates. By F. O. Ferguson. Third Edition. 8vo, boards

"It is the most intelligible of the treatises on this ill-treated subject that I have met with."—

E. INGREES BELL, Esq., in the K.I.B.A. Journal.

PRACTICAL RULES ON DRAWING.
For the Builder and Young Student in Architecture. By G. PYNE. 4to . 7/6

THE MECHANICS OF ARCHITECTURE.

A Treatise on Applied Mechanics, especially Adapted to the Use of Architects.

By E. W. Tarn, M.A., Author of "The Science of Building," &c. Second Edition, Enlarged. Illustrated with 125 Diagrams. Crown 8vo, cloth.

"The book is a very useful and helpful manual of architectural mechanics."—Builder. &c. Second

A HANDY BOOK OF VILLA ARCHITECTURE

Being a Series of Designs for Villa Residences in various Styles. With Outline Specifications and Estimates. By C. Wickes, Architect, Author of "The Spires and Towers of England," &c. 61 Plates, 4to, half-morocco, gilt edges £1 11s.6d.

DECORATIVE PART OF CIVIL ARCHITECTURE.

By Sir William Chambers, F.R.S. With Portrait, Illustrations, Notes, and an Examination of Grecian Architecture, by Joseph Gwilt, F.S.A. Revised and Edited by W. H. Lerds. 66 Plates, 410, cloth . 21-

THE ARCHITECT'S GUIDE.

Being a Text-book of Useful Information for Architects, Engineers, Surveyor Contractors, Clerks of Works, &c., &c. By F. Rogers. Crown 8vo, cloth 3:

SANITATION AND WATER SUPPLY.

THE PURIFICATION OF SEWAGE.

Peing a level Account of the Scientific Principles of Sewage Purification, and their Proctic d'Application. By Singley Barwise M.D. (Lond., B.Sc., M.R.C.S. D.) If at any a letter of the Sanitary Institute, Medical Officer of Health to the Derryshine County Council. Second I dition, Revised and Enlarged, with an Appendix on the Analysis of Sewage and Sewage Effluents. With numerous Illustration and Phagrams. Demy 200, cloth. Just Published. Not. 106

Services of Contents of Services of Contents of Services of Contents of Services of Contents of Services of Contents of Services of Contents of Services of Contents of Contents of Services of Contents of Conten

THE HEALTH OFFICER'S POCKET-BOOK.

A Guide to Sandaty Practice and Law For Melical Officers of Health Sanitary Inspectors, Members of Sanitary Authorities, &c. By Edward F Williams and M.D. (Lond.), &c. Second Edition, Revised and Enlarged Fcap See, bather.

PCAP SVO, Batther.

"A time of conserved information of a partinent and useful kind. The various subjects of which it treats being suchiefly but fully and substitutifically dealt with "—The Lancet.

"We recommend ad those engaged in practical saturary work to furnish themselves with a constormation of substitution of the sub

WATER AND ITS PURIFICATION.

A Har listel, for the Use of Local Authorities, Sanitary Officers, and others interested a Water Supply—By S. Rideau. D Sc., Lond., F.I.C. Second Edition. Revised, with Adadious, including numerous Illustrations and Tables—Large crown and order.

Nat. 9-

RURAL WATER SUPPLY.

Control there is a CW nor and Constrained Water cere of Lorentz Control to the Street AM I CEL, and W. T 1.00 from is a con-Cres (A. C. College L. C. College Coll Congression Clark

THE WATER SUPPLY OF CITIES AND TOWNS.

Dy West, vi. Husting, A.M.Inst C.E., and M.Inst M.U., Imp. 4to, half-bourge Net £6 6s.

THE WATER SUPPLY OF TOWNS

AND THE CONSTRUCTION OF WATER WORKS.

Politically W. K. Lutter, V.M. Installer, Second Library Revised a
Extension of second operations. £1 5s.

WATER ENGINEERING.

PLUMBING.

A Text-Book to the Practice of the Art or Craft of the Piember By W. P. North Edition, Enlarged, with 500 Illustrations - Crown Svo

VENTILATION.

36

CARPENTRY, TIMBER, ETC.

THE ELEMENTARY PRINCIPLES OF CARPENTRY.

A Treatise on the Pressure and Equilibrium of Timber Framing, the Resistance of Timber, and the Construction of Floors, Arches, Bridges, Roofs, Uniting Iron of Timber, and the Construction of Floors, Arches, Bridges, Roots, Uniting Iron and Stone with Timber, &c. To which is added an Essay on the Nature and Properties of Timber, &c., with Descriptions of the kinds of Wood used in Building; also numerous Tables of the Scantlings of Timber for different purposes, the Specific Gravities of Materials, &c. By Thomas Tredgold, C.E. With an Appendix of Specimens of Various Roofs of Iron and Stone, Illustrated. Seventh Edition, thoroughly Revised and considerably Enlarged by E. WYNDHAM TARN, M.A., Author of "The Science of Building," &c. With 61 Plates, Portrait of the Author, and several Woodcuts. In One large Vol., 4to, cloth.

"Ought to be in every architect's and every builder's library."—Builder.

"A work whose monumental excellence must commend it wherever skilful carpentry is concerned.

The author's principles are rather confirmed than impaired by time. The additional plates are of great initiastic value."—Building News.

WOODWORKING MACHINERY.

Its Rise, Progress, and Construction. With Hints on the Management of Saw Mills and the Economical Conversion of Timber. Illustrated with Examples of Recent Designs by leading English, French, and American Engineers. By M. Powis Bale, A.M.Inst.C.E., M.I.M.E. Second Edition, Revised, with large Additions, large crown 8vo, 440 pp., cloth

"Mr. Bale is evidently an expert on the subject, and he has collected so much information that his book is all-sufficient for builders and others engaged in the conversion of timber."—Architect,

"The most comprehensive compendium of wood-working machinery we have seen. The author is a thorough master of his subject."—Building News.

SAW MILLS.

Their Arrangement and Management, and the Economical Conversion of Timber. By M. Powis Bale, A.M.Inst.C.E. Second Edition, Revised. Crown 8vo, cloth

"The administration of a large sawing establishment is discussed, and the subject examined from a financial standpoint. Hence the size, shape, order, and disposition of saw-mills and the like are gone into in detail, and the course of the limber is traced from its reception to its delivery in its converted state. We could not desire a more complete or practical treatise."—Builder.

THE CARPENTER'S GUIDE.

Or, Book of Lines for Carpenters; comprising all the Elementary Principles essential for acquiring a knowledge of Carpentry. Founded on the late Peter Nicholson's standard work. A New Edition, Revised by ARTHUR ASHETTEL, F.S.A. Together with Practical Rules on Drawing, by George Pyke. With 74 Plates, 4to, cloth

A PRACTICAL TREATISE ON HANDRAILING.

Showing New and Simple Methods for Finding the Pitch of the Plank, Drawing the Moulds, Bevelling, Jointing-up, and Squaring the Wreath. By Georgi Collings. Revised and Enlarged, to which is added A TREATISE ON STAIR BUILDING. Third Edition. With Plates and Diagrams. 12mo, cloth . 26 Collings. Revised and Colling. Third Edition.

"Will be found of practical utility in the execution of this difficult branch of joinery."—Builder,
"Almost every difficult phase of this somewhat intricate branch of joinery is elucidated by the aid of plates and explanatory letterpress."—Furniture Gazette.

CIRCULAR WORK IN CARPENTRY AND JOINERY.

A Practical Treatise on Circular Work of Single and Double Curvature. By
GRONGE COLLINGS. With Diagrams. Fourth Edition, 12mo, cloth

26 "An excellent example of what a book of this kind should be. Cheap in price, clear in definition, and granteal in the examples selected,"—Builder,

THE CABINET-MAKER'S GUIDE

TO THE ENTIRE CONSTRUCTION OF CABINET WORK.

By RICHARD BITMEAD. Illustrated with Plans, Sections, and Working Drawing Crown 8vo, cloth

HANDRAILING COMPLETE IN EIGHT LESSONS.

On the Square-Cut System. By J. S. GOLDTHORF, Teacher of Geometry and Building Construction at the Halifax Mechanics' Institute. With Eight Plates and over 150 Practical Exercises. 4to, cloth

"Likely to be of considerable value to joiners and others who take a pride in good we agement of the book is excellent. We heartily commend it to teachers and students."

TIMBER MERCHANT'S & BUILDER'S COMPANION.

Containing New and Copious Tables of the Reduced Weight and Measurement of Deals and Battens, of all sizes, and other useful Tables for the use of Timber Merchants and Builders. By William Dowsing. Fourth Edition. Revised and Corrected. Crown 8vo, cloth

"We are glad to see a fourth edition of these admirable tables, which for correctness and simplicity of arrangement leave nothing to be desired."—Timber Trades Journal.

THE PRACTICAL TIMBER MERCHANT.

Being a Guide for the use of Building Contractors, Surveyors, Builders, &c., comprising useful Tables for all purposes connected with the Timber Trade, Marks of Wood, Essay on the Strength of Timber, Remarks on the Growth of Timber, &c. By W. RICHARDSON. Second Edition. Fcap. 8vo, cloth. 3/6 "This handy manual contains much valuable information for the use of timber merchants, builders, foresters, and all others connected with the growth, sale, and manufacture of timber."—Journal of Forestry.

PACKING-CASE TABLES.

Showing the number of Superficial Feet in Boxes or Packing-Cases, from six inches square and upwards. By W. Richardson, Timber Broker. Third Edition. Oblong 4to, cloth Oblong 4to, cloth

"Invaluable labour-saving tables."—Ironmon, "Will save much labour and calculation."—G

GUIDE TO SUPERFICIAL MEASUREMENT.

Tables calculated from 1 to 200 inches in length, by 1 to 108 inches in breadth
For the use of Architects, Surveyors, Engineers, Timber Merchants, Builders.
&c. By James Hawkings. Fifth Edition. Fcap., cloth

"These tables will be found of great assistance to all who require to make calculations in superficie. measurement."—English Machanic.

PRACTICAL FORESTRY.

And its Bearing on the Improvement of Estates. By Charles E. Curtis, F.S.I., Professor of Forestry, Field Engineering, and General Estate Management, at the College of Agriculture, Downton. Second Edition, Revised.

CTOWN 8VO, Cloth

PREFATORY REMARKS.—OBJECTS OF PLANTING.—CHOICE OF A FORESTER.—CHOICE OF SOIL AND SITE.—LAYING OUT OF LAND FOR PLANTATIONS.—PREFARATION OF THE GROUND FOR PLANTING.—DISTANCES AND DISTRIBUTION OF TREES IN PLANTATIONS.—TREES AND GROUND GAME.—ATTENTION AFTER PLANTING.—THINNING OF PLANTATIONS.—PRUNING OF FOREST TREES.—REALIZATION.—MYTHOUS OF SALE.—MEASUREMENT OF TIMBER.—MEASUREMENT AND VALUATION OF LARCH PLANTATION.—FIRE LINES.—COST OF PLANTING.

"Mr. Curtis has in the course of a series of short pithy chapters afforded much information of a useful and practical character on the planting and subsequent treatment of trees."—Illustrated Carpenter and Builder.

THE ELEMENTS OF FORESTRY.

TIMBER IMPORTER'S, TIMBER MERCHANT'S, AND BUILDER'S STANDARD GUIDE.

By Richard E. Grandy. Comprising:—An Analysis of Deal Standards, Home and Foreign, with Comparative Values and Tabular Arrangements for fixing Net Landed Cost on Baltic and North American Deals, including all intermediate Expenses, Freight, Insurance, &c. &c.; together with copious Information for the Retailer and Builder. Third Edition, Revised. 12mo, cloth . 2/"Bverything it pretends to be: built up gradually, it leads one from a forest to a treenall, and throws in, as a makeweight, a host of material concerning bricks, columns, cisterns, &c."—English Mechanic.

DECORATIVE ARTS, ETC.

SCHOOL OF PAINTING FOR THE IMITATION OF WOODS AND MARBLES.

As Taught and Practised by A. R. VAN DER BURG and P. VAN DER BURG. Directors of the Rotterdam Painting Institution. Royal folio, 18½ by 12½ in., Illustrated with 24 full-size Coloured Plates; also 12 plain Plates, comprising 154 Figures. Fourth Edition, cloth

LIST OF PLATES.

LIST OF PLATES.

L. VARIOUS TOOLS REQUIRED FOR WOOD PAINTING.—2, 3. WALNUT; PRELIMINARY STAGES OF GRAINING AND FINISHED SPECIMEN.—4. TOOLS USED FOR MARKILE PAINTING AND METHOD OF MANIPULATION.—5, 6. S.T. REMI MARRILE; BABLIER OPERATIONS AND FINISHED SPECIMEN.—7, METHODS OF SKETCHING DUPERRAT GRAINS, KNOTS, &C.—8, 9, 48H: PERLIMINARY STAGES AND FINISHED SPECIMEN.—10. METHODS OF SKETCHING MARRILE GRAINS.—11, 12. BERCHE MARRILE; PRELIMINARY STAGES OF WORKING AND FINISHED SPECIMEN.—13. MAPLE; METHODS OF PRODUCING THE DIPERRENT GRAINS.—14, 13. BIRDS-EVE MAPLE; PRELIMINARY STAGES AND FINISHED SPECIMEN.—16. METHODS OF SKETCHING THE DIPERRENT SPECIES OF WHITE MARRILE—17, 18. WHITE MARBLE; PRELIMINARY STAGES OF PROCESS AND FINISHED SPECIMEN.—19. MANOGANY; SPECIMENS OF VARIOUS GRAINS AND METHODS OF MANIPULATION.—20. 11. MANOGANY; RABLIER STAGES AND FINISHED SPECIMEN.—25, 26, 27. JUNIVER WOOD; METHODS OF FRODUCING GRAIN, &C.: PRELIMINARY STAGES AND FINISHED SPECIMEN.—25, 26, 27. JUNIVER WOOD; METHODS OF PRODUCING GRAIN, &C.: PRELIMINARY STAGES AND FINISHED SPECIMEN.—31, 32, 33. OAK; LARRIERS OF GRAIN, TOOLS EMPLOYED AND METHODS OF MANIPULATION, PRELIMINARY STAGES AND FINISHED SPECIMEN.—34, 36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—34, 36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—34, 36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—34, 36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, UNFINISHED AND FINISHED SPECIMEN.—36, 36. WADLSORT MARBLE; VARIETIES OF GRAIN, U

"These who desire to attain skill in the art of pointing woods and marbles will find advantage in consulting this book. . . . Some of the Working Men's Clubs should give their young men the opportunity to study it."—Builder.

"A comprehensive guide to the art. The explanations of the processes, the manipulation and management of the colours, and the beautifully executed plates will not be the least valuable to the student who alms at making his work a faithful transcript of nature."—Building News.

"Students and novices are fortunate who are able to become the possessors of so noble a work."—The Architect,

ELEMENTARY DECORATION.

A Guide to the Simpler Forms of Everyday Art. Together with PRACTICAL HOUSE DECORATION. By James W. Facey. With numerous Illustrations. In One Vol., strongly half-bound

HOUSE PAINTING, GRAINING, MARBLING, AND SIGN WRITING.

A Practical Manual of. By ELLIS A. DAVIDSON. Eig Coloured Plates and Wood Engravings. Crown 8vo, cloth Eighth Edition. With

" A mass of information, of use to the amateur and of value to the practical man."-English Mechanic.

THE DECORATOR'S ASSISTANT.

A Modern Guide for Decorative Artists and Amateurs, Painters, Writers, Gilders,

"Full of receipts of value to decorators, painters, gilders, &c. The book contains the gist of larger treatiess on colour and technical processes. It would be difficult to meet with a work so full of varied information on the painter's art."—Building News.

MARBLE DECORATION

And the Terminology of British and Foreign Marbles. A Handbook for Students. By George H. Blagkove, Author of "Shoring and its Application," &c. With 28 Illustrations, Crown 8vo, cloth 3/6

"This most useful and much wanted handbook should be in the hands of every architect and builder."—Building World.
"A carefully and usefully written treatise; the work is essentially practical."—Scotman.

DELAMOTTE'S WORKS ON ILLUMINATION AND ALPHABETS.

ORNAMENTAL ALPHABETS, ANCIENT & MEDIÆVA

Financial La Alphabetts, Ancient & Mediav Jevich Land to it. 2. th Century with Normals and ding Gothic, Crurch Jevich and model Corner, 1986, Anchor open Immost for Standingson, Monogra Corner, as the second achievation and Invalenting Demonstration. Monographics in Contract Means the auto-Philippes, Latinggraphers. Engravers, Care Acts. Control of England Breaked by F. Dingworth, and Princel in Consequent Control of Control

MODERN ALPHABETS, PLAIN AND ORNAMENTA

In home a constant Col. Parlish, Sanor, India, Longestive, Coronic Bielo, and Control College, and an analysis of the Longest and Col. Eng. Alphales, our proof should not longest to the association of Engineering the graphers, Engravers, Carvers, College of an Language by Language I, the graphers, Engravers, Carvers, College of an Language by Language I, and promotion Colours News, Chargest belief to the Association of the Association of the Colours of the analysis of the above which is the consequence of the Language Colours of the above which has been expended in the consequence of the Association.

MEDIÆVAL ALPHABETS AND INITIALS.

By U.G. Dar viscous. Continuing 2: Cities and Hemmutel Title principle. Gode and Coloris. With a single limit in by J. Winter. Phooris. Prof. L. Linn. Small stop granulated sources. No. 5. (Axolen and All L. Linner, State of the distribution of the form of the form of the distribution of the control of th

A PRIMER OF THE ART OF ILLUMINATION.

The description of the control of the contr The state of the s

THE EMBROIDERER'S BOOK OF DESIGN.

of more and the More expect topic bental Backet who and the Wester, With the proof National Expension of the expension of the Control of the control of the second of the second of the control of the second of the 16000 Ν. or selected a speed at the first selection of the selecti the second and the second of a second wed wright a Appearance and the second

WOOD CARVING FOR AMATEURS.

PAINTING POPULARLY EXPLAINED.

of the Color of th on Ivery, Veham, Pottery Enronel, Glass, we Usfish Edition of Grown Svo, cloth 5, 20 Machinary to be ared, even by the Advisor of the Same Reading in the careft of Machinary to be ared, even by the experience of the other name to be tability from the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusul of the name to intend the careft perusulation of

NATURAL SCIENCE, ETC.

THE VISIBLE UNIVERSE.

Chapters on the Origin and Construction of the Heavens. By J. E. Gorz, F.R.A.S., Author of "Star Groups," &c. Illustrated by 6 Stellar Photographs and 12 Plates. Demy 8vo, cloth 16/-
STAR GROUPS.
A Student's Guide to the Constellations. By J. ELLARD GORE, F.R.A.S., M.R.I.A., &c., Author of "The Visible Universe," "The Scenery of the Heavens," &c. With 30 Maps. Small 4to, cloth
AN ASTRONOMICAL GLOSSARY.
Or, Dictionary of Terms used in Astronomy. With Tables of Data and Lists of Remarkable and Interesting Celestial Objects. By J. ELLARD GORE, F.R.A.S., Author of "The Visible Universe," &c. Small crown 8vo, cloth 2/6
THE MICROSCOPE.
Its Construction and Management. Including Technique, Photo-micrography, and the Past and Future of the Microscope. By Dr. Henri van Heures. Re-edited and Augmented from the Fourth French Edition, and Translated by Wynne E. Baxter, F.G.S. Imp. 8vo, cloth
A MANUAL OF THE MOLLUSCA.
A Treatise on Recent and Fossil Shells. By S. P. Woodward, A.L.S., F.G.S. With an Appendix on Recent and Fossil Conchological Discoveries, by RALPH TATE, A.L.S., F.G.S. With 23 Plates and upwards of 300 Woodcuts. Reprint of Fourth Edition (1880). Crown 8vo, cloth 7/6
THE TWIN RECORDS OF CREATION.
Or, Geology and Genesis, their Perfect Harmony and Wonderful Concord. By G. W. V. LE VAUX. 8vo, cloth 5/-
LARDNER'S HANDBOOKS OF SCIENCE.
HANDBOOK OF MECHANICS. Enlarged and re-written by B. LOEWY, F.R.A.S. Post 8vo, cloth . 6-
HANDBOOK OF HYDROSTATICS AND PNEUMATICS. Revised and Enlarged by B. Logwy, F.R.A.S. Post 8vo, cloth . 5,-
HANDBOOK OF HEAT. Edited and re-written by B. Lonwy, F.R.A.S. Post Svo, cloth . 6-
HANDBOOK OF OPTICS. New Edition. Edited by T. OLVER HARDING, B.A. Small 8vo, cloth
ELECTRICITY, MAGNETISM AND ACOUSTICS. Edited by Gro. C. FOSTER, B.A. Small 8vo, cloth
HANDBOOK OF ASTRONOMY. Revised and Edited by EDWIN DUNKIN, F.R.A.S. 8vo, cloth
MUSEUM OF SCIENCE AND ART. With upwards of 1,200 Engravings. In Six Double Volumes, cloth, 1/1/-, or half-morocco. £1 11s. 6d.
NATURAL PHILOSOPHY FOR SCHOOLS 3/6
ANIMAL PHYSIOLOGY FOR SCHOOLS 3/6
THE ELECTRIC TELEGRAPH. Revised by E. B. BRIGHT, F.R.A.S.
Fcap. 8vo, cloth

CHEMICAL MANUFACTURES. CHEMISTRY, ETC.

PETROLEUM INDUSTRY.

A Practical Handbook on the Exploration, Exploitation, and Management Russian Oil Properties, including Notes on the Origin of Petroleum in Russia a Description of the Theory and Practice of Liquid Fuel, and a Translation the Rules and Regulations concerning Russian Oil Properties. By A. Bern Thomeson, A.M.I.M.E., late Chief Engineer and Manager of the Europe: Petroleum Company's Russian Oil Properties. About 500 pp., with numeroullustrations and Photographic Plates, and a Map of the Balakhany-Saboontch Romany Oil Field. Super-royal 8vo. cloth.

[Just Published. Net 23 34]

THE ANALYSIS OF OILS AND ALLIED SUBSTANCES
By A. C. WRIGHT, M.A.Oxon., B.Sc. Lond., formerly Assistant Lecturer is
Chemistry at the Yorkshire College, Leeds, and Lecturer in Chemistry at the
Hull Tacknical School Demy 8vo. cloth

Not 9 Hull Technical School. Demy 8vo, cloth

THE GAS ENGINEER'S POCKET BOOK.

Comprising Tables, Notes and Memoranda relating to the Manufacture Distribution and Use of Coal Gas and the Construction of Gas Works. B. H. O'CONNOR, A.M. Inst.C.E. Second Edition, Revised. 470 pp., crown 8vg fully Illustrated, leather.

The buok contains a vant amount of information. The author more consecutionals about the contact of the conta

runty illustrated, leather

"The book contains a vast amount of information. The author goes consecutively through the engineering details and practical methods involved in each of the different processes or parts of a gas works. He has certainly succeeded in making a compilation of hard matters of fact absolutely interesting to read."—Gas World.

"The volume contains a great quantity of specialised information, compiled, we believe, from trustworthy sources, which should make it of considerable value to those for whom it is specifically produced."—Engineer.

LIGHTING BY ACETYLENE
Generators, Burners and Electric Furnaces. By William E. Gibbs, M.E. With 66 Illustrations. Crown Syo, cloth

ENGINEERING CHEMISTRY.

A Fractical Treatise for the Use of Analytical Chemists, Engineers, Iron Masters, Iron Founders, Students and others. Comprising Methods of Analysis and Valuation of the Principal Materials used in Engineering Work, with numerous Analyses, Examples and Suggestions. By H. JOSHUA PHILLIPS, F.I.C., F.C.S. Third Edition, Revised and Enlarged. Crown 8vo, 420 pp., with Plates and other Illustrations, cloth

NITRO-EXPLOSIVES.

A Practical Treatise concerning the Properties. Manufacture, and Analysis of Nitrated Substances, including the Fulminates, Smokeless Powders and Celluloid. By P. Gerald Sanford, F.I.C., Consulting Chemist to the Cotton Powder Company, Limited, &c. With Illustrations. Crown 8vo, cloth. 9/"One of the very few text-beeds in which can be found just what is wanted. Mr. Sanford goes steadily through the whole list of explosives commonly used, he names any given explosive and tells us of what it is composed and how it is manufactured. The book is excellent."—Engineer.

A MANUAL OF THE ALKALI TRADE.

Including the Manufacture of Sulphuric Acid, Sulphate of Soda, and Bleaching Powder. By John Lomas, Alkali Manufacturer. With 232 Illustrations and Working Drawings. Second Edition, with Additions. Super-royal 8vo, cloth.

"We find not merely a sound and luminous explanation of the chemical principles of the trade, but a notice of numerous matters which have a most important bearing on the successful conduct of talkall works, but which are generally overlooked by even experienced technological authors."—Chemical Review.

DANGEROUS GOODS.

Their Sources and Properties, Modes of Storage and Transport. With Notes and Comments on Accidents arising therefrom. A Guide for the Use of Government and Railway Officials, Steamship Owners, &c. By H. JOSHUA PHILLIPS. With Notes F.I.C., F.C.S. Crown 8vo, 374 pp., cloth
"Merits a wide circulation and an intelligent, appreciative study."—Ghemical News.

THE BLOWPIPE IN CHEMISTRY, MINERALOGY, Etc.

"The student who goes conscientiously through the course of experimentation here laid down will gain a better insight into inorganic chemistry and mineralogy than if he tend 'got up' any of the best text-books of the day, and passed any number of examinations in their contents."—Chemical News,

THE MANUAL OF COLOURS AND DYE WARES.

Their Properties, Applications, Valuations, Impurities, and Sophistications. For the Use of Dyers, Printers, Drysalters, Brokers, &c. By J. W. Slater. Second Edition, Revised and greatly Enlarged. Crown 8vo, cloth 7/6

"There is no other work which covers precisely the same ground. To students preparing for examinations in dyeing and printing it will prove exceedingly useful."—Chemical News.

A HANDYBOOK FOR BREWERS.

Being a Practical Guide to the Art of Brewing and Malting. Embracing the Conclusions of Modern Research which bear upon the Practice of Brewing. By HERBERT EDWARDS WRIGHT, M.A. Second Edition, Enlarged. Crown 8vo. 530 pp., cloth 12/6

"May be consulted with advantage by the student who is preparing himself for examinational tests, while the scientific brewer will find in it a return of all the most important discoveries of modern times. The work is written throughout in a clear and countse manner, and the author takes great care to discriminate between vague theories and well-established facts."—Brewers Journal.

"We have great pleasure in recommending this handy book, and have no hesitation in saying that it is one of the best—find the best—which has yet been written on the subject of beet-brewing in this country, it should have a place on the shelves of every brewer's library."—Brewers' Guardian.

FUELS: SOLID, LIQUID, AND GASEOUS.

Their Analysis and Valuation. For the Use of Chemists and Engineers. By
H. J. PHILLIPS, F.C.S., Formerly Analytical and Consulting Chemist to the
Great Eastern Rallway. Fourth Edition. Crown 8vo, cloth . 2/-

"Unglit to have its place in the laboratory of every metallurgical establishment, and wherever fuel is used on a large scale, "Chemical News.

THE ARTISTS' MANUAL OF PIGMENTS.

Showing their Composition, Conditions of Permanency, Non-Permanency, and Adulterations, &c., with Tests of Purity. By H. C. STANDAGE. Third Edition. Crown 8vo, cloth

"This work is indeed undimm-in-parso, and we can, with good conscience, recommend it to all who come in contact with pigments, whether as makers, dealers, or users."—Classical Reside.

A POCKET-BOOK OF MENSURATION & GAUGING.

Containing Tables, Rules, and Memoranda for Revenue Officers, Brewers, Spirit Merchants, &c. By J. B. Manr, Inland Revenue. Second Edition, Revised. 18mo, leather

"Should be in the hands of every practical brower,"-Braners' Journal

INDUSTRIAL ARTS. TRADES AND MANUFACTURES.

TEA MACHINERY AND TEA FACTORIES.

A MACHINER I AIND THA TRANSPORTED IN the Cultivation of the Serique of the Teach souther the Mechanical Appliances required in the Cultivation of the Teach State of the Paris Souther Taylor VM test Const. Mechanisms of the Taylor VM test Const. Mechanisms of the M

amitalida e E. Contents

MARY OF RELIGIOUS CONTINUES. TO SERVICE STREETS OF THE SERVICE STREE

The state of the s

FLOUR MANUFACTURE.

A front even Milan Societ and Practice By Litteriori Kick, In per all Region at an Articles of a Meanwhile To incology in the Imperial German Logische at statue from the Second Enlarged and Region 1 forces with copperation by H. H. P. Powers, Assoc Memor Lastination of Call Discusses. Nearly to pp. Blustrated with as Februar Batter, and top Wood outs. Level over left.

A service of the serv The state of the s

COTTON MANUFACTURE.

I North the extra control of the control of t

in the second section of the second section of the second

MODERN CYCLES.

A Decided for the control of the control and force the Warris Force National Control of the control of the Control of the con A stream of the

MOTOR CARS OR POWER CARRIAGES FOR COMMON

4 6

PRACTICAL TANNING.

THE ART OF LEATHER MANUFACTURE.

Being a Practical Handbook, in which the Operations of Tanning, Currying, and Leather Dressing are fully Described, and the Principles of Tanning Explained, and many Recent Processes Introduced; as also Methods for the Estimation of Tannin, and a Description of the Arts of Glue Boiling, Gut Dressing, &c By Alexander Warr. Fourth Edition. Crown 8vo, cloth.

"A sound, comprehensive treatise on tanning and its accessories. The book is an eminently valuable production, which redounds to the credit of both author and publishers."—Chemical Review.

THE ART OF SOAP-MAKING.

PRACTICAL PAPER-MAKING.

A Manual for Paper-Makers and Owners and Managers of Paper-Mills. With Tables, Calculations, &c. By G. CLAPPERTON, Paper-Maker. With Illustrations

of Fibres from Micro-Photographs. Crown 8vo, cloth

"The author caters for the requirements of responsible mill hands, apprentices, &c., whilst
manual will be found of great service to students of rechnology, as well as to veteran paper-mak
and mill-owners. The illustrations form an excellent feature."—The World's Paper Trade Review.

THE ART OF PAPER-MAKING.

A Practical Handbook of the Manufacture of Paper from Rags, Esparto, Straw, A Practical Handbook of the Manufacture of Paper from Rays, Esparto, Straw, and other Fibrous Materials. Including the Manufacture of Pulp from Wood Fibre, with a Description of the Machinery and Appliances used. To which are added Details of Processes for Recovering Soda from Waste Liquors. By Alexander Watt. With Illustrations. Crown 8vo, cloth. 7/6
"It may be regarded as the standard work on the subject. The book is full of vainable information. The 'Art of Paper-Making' is in every respect a model of a text-book, either for a technical class, or for the private student,"—Paper and Printing Trades Journal.

A TREATISE ON PAPER

For Printers and Stationers. With an Outline of Paper Manufacture; Complete Tables of Sizes, and Specimens of Different Kinds of Paper. By RICHARD PARKINSON, late of the Manchester Technical School. Demy 8vo, cloth 3/6

CEMENTS, PASTES, GLUES AND GUMS.

A Practical Guide to the Manufacture and Application of the various Agglutinants required in the Building, Metal-Working, Wood-Working, and Leather-Working Trades, and for Workshop and Office Use. With upwards of 900 Recipes. By H. C. STANDAGE. Third Edition. Crown 8vo, cloth . 2/-We have pleasure in speaking favourably of this volume. So far as we have had experience, Recipes. By H. C. STANDAGE. Third Edition. Co.

We have pleasure in speaking favourably of this volume. So which is not inconsiderable, this manual is trustworthy."—Athenaum.

THE CABINET-MAKER'S GUIDE

TO THE ENTIRE CONSTRUCTION OF CABINET WORK.

Including Veneering, Marquetrie, Buhlwork, Mosaic, Inlaying, &c. B RICHARD BITMEAD. Hinstrated with Plans, Sections, and Working Drawing By Small crown Syo, cloth .

FRENCH POLISHING AND ENAMELLING.

A Practical Work of Instruction. Including Numerous Recipes for making Polishes, Varnishes, Glaze-Lacquers, Revivers, &c. By Richard Bitman, Author of "The Cabinet-Maker's Guide." Small crown 8vo, cloth

WATCH REPAIRING, CLEANING, AND ADJUSTING.

A Practical Handbook dealing with the Materials and Tools Used, and the Methods of Repairing, Cleaning, Altering, and Adjusting all kinds of English and Foreign Watches, Repeaters, Chronographs, and Marine Chronometers. By F. J. GARRARD, Springer and Adjuster of Marine Chronometers and Deck Watches for the Admiralty. With over 200 Illustrations. Crown 8vo, cloth.

[Just Published. Net 4/6]

MODERN HOROLOGY IN THEORY AND PRACTICE.

Translated from the French of CLAUDIUS SAUNIER, ex-Director of the School of Horology at Macon, by JULIEN TRIPPLIN, F.R.A.S., Besançon Watch Manufacturer, and Edward Rigg, M.A., Assayer in the Royal Mint. With Seventy-eight Woodcuts Aventy-two Coloured Copper Plates. Second Edition. Super-royal 8vo, £2 28., cloth; half-calf

"There is no horological work in the English language at all to be compared to this production of M. Saunier's for clearness and completeness. It is alike good as a guide for the student and as a reference for the experienced horologist and skilled workman."—Horological Journal.

"The latesat, the most complete, and the most reliable of those literator productions to which continental watchmakers are indebted for the mechanical superiority over their English breakren—in fact, the Book of Books is M. Saunier's 'Treatise,'"—Watchmaker, Jeweller, and Silversmith.

THE WATCH ADJUSTER'S MANUAL.

A Practical Guide for the Watch and Chronometer Adjuster in Making, Springing,
Timing and Adjusting for Isochronism, Positions and Temperatures. By C. E.
FRITTS. 370 pp., with Illustrations, 8vo, cloth

THE WATCHMAKER'S HANDBOOK.

Intended as a Workshop Companion for those engaged in Watchmaking and the Allied Mechanical Arts. Translated from the French of Claudius Saunier, and enlarged by Julien Tripplin, F.R.A.S., and Edward Rigg, M.A., Assayer in the Royal Mint. Third Edition. Crown 8vo, cloth

"Each part is truly a treatise in itself. The arrangement is good and the language is clear and concise. It is an admirable guide for the young watchmaker."—Engineering.

HISTORY OF WATCHES & OTHER TIMEKEEPERS.
By James F. Kendal, M.B.H.Inst. 1/6 boards; or cloth, gilt . 2

"The best which has yet appeared on this subject in the English language."—Industries.

"Open the book where you may, there is interesting matter in it concerning the ingentions devices of the ancient or modern horologer."—Saturday Review.

ELECTRO-PLATING & ELECTRO-REFINING OF METALS.
Being a new edition of ALEXANDER WAIT'S "ELECTRO-DEPOSITION." Revised and Largely Rewritten by ARNOLD PHILIP, B.Sc., A.I.E.E., Principal Assistant to the Admiralty Chemist, Large Crown 8vo, cloth Nat 12/6

"Altogether the work can be highly recommended to every electro-plater, and is of undoubted interest to every electro-metallurgist."—Electrical Review.
"Eminently a book for the practical worker in electro-deposition. It contains practical descriptions of methods, processes and materials, as actually pursued and used in the workshop."—Engineer.

ELECTRO-METALLURGY.

"From this book both smateur and artisan may learn everything necessary for the successful prosecution of electroplating."—fron.

JEWELLER'S ASSISTANT IN WORKING IN GOLD.

A Practical Treatise for Masters and Workmen, Compiled from the Experience of Thirty Years' Workshop Practice. By George E. Gee. Crown 8vo. 76 "This manual of technical education is apparently destined to be a valuable auxiliary to a handi-craft which is certainly capable of great improvement."—The Times.

ELECTROPLATING.

A Practical Handbook on the Deposition of Copper, Silver, Nickel, Gold, Aluminium, Brass, Platinum, &c., &c. By J. W. Urguhart, C.E. Fourth Edition, Revised. Crown 8vo. cloth

"An excellent practical manual."—Engineering.

"An excellent work, giving the newest information."—Horological fournal.

ELECTROTYPING.

The Reproduction and Multiplication of Printing Surfaces and Works of Art by the Electro-deposition of Metals. By J. W. URQUHART, C.E. Crown 8vo.

"The book is thoroughly practical; the resider is, therefore, conducted through the leading lasss of electricity, then thipugh the metals used by electrotypers, the apparatus, and the depositing processes, up to the final preparation of the work."—Art Journal.

GOLDSMITH'S HANDBOOK.

By George E. Gre, Jeweiler, &c. Fifth Edition. 12mo, cloth . . . 3/"A good, sound educator."—Horological Journal.

SILVERSMITH'S HANDBOOK.

By GEORGE E. GEE, Jeweller, &c. Third Edition, with numerous Illustrations. 12mo, cloth
"The chief merit of the work is its practical character. . . . The workers in the trade will speedily discover its merits when they alt down to study it."—English Mechanic.

* .* The above two works together, strongly half-bound, price 7s.

SHEET METAL WORKER'S INSTRUCTOR.

SAVOURIES AND SWEETS

Suitable for Luncheons and Dinners. By Miss M. L. Allen (Mrs. A. Macaire), Author of "Breakfast Dishes," &c. Twenty-ninth Edition. Fcap. Syo. sewed

BREAKFAST DISHES

For Every Morning of Three Months, By Miss Allen (Mrs. A. Magaire), Author of "Savouries and Sweets," &c. Twenty-second Edition, Fcap. 8vo.

BREAD & BISCUIT BAKER'S & SUGAR-BOILER'S ASSISTANT.

Including a large variety of Modern Recipes. With Remarks on the Art of Bread-making. By ROBERT WELLS. Third Edition. Crown 8vo, cloth . 1/= "A large number of wrinkles for the ordinary cook, as well as the baker."—Saturday Review.

PASTRYCOOK & CONFECTIONER'S GUIDE.

For Hotels, Restaurants, and the Trade in general, adapted also for Family Use.

By R. Wells, Author of "The Bread and Biscuit Baker". 1/"We cannot speak too highly of this really excellent work. In these days of keen competition our readers cannot do better than purchase this book."—Baker's Times.

ORNAMENTAL CONFECTIONERY.

MODERN FLOUR CONFECTIONER.

Containing a large Collection of Recipes for Cheap Cakes, Biscuits, &c. With Remarks on the Ingredients Used in their Manufacture. By R. Wells. 1/"The work is of a decidedly practical character, and in every recipe regard is had to economical working."—North British Daily Mail.

RUBBER HAND STAMPS

HANDYBOOKS FOR HANDICRAFTS.

BY PAUL N. HASLUCK,

1. The P. William New Series, Author of "Lathe Work", Malling Machines, Ac Crown Svo, 144 pp., price 12 each

Exp. 161. A Hard viscous sources in a critical to supply information of a Widdings of the first viscous and the second thanderally, on the action. Presenting of the Widges of an experience of the Widges of a contrast intended to a new to plant language Technical. Known to post of the Widges of the contrast intended to a contrast of the contrast of

METAL TURNER'S HANDYBOOK.

The first Marchal for Workers at the Foot-Lathe. With too Illustrations of the control of the transfer of the amateur and the artisan turner. It shows ye removed the control of the contr

WOOD TURNER'S HANDYBOOK.

A Proctice Minoral for Workers at the Lathe With over too Illustrations 1.-2 Workers and the a New york enteriors and amateurs. A multiplic of workmers have be received a to a receive of the special and cores. Machanical World.

WATCH JOBBER'S HANDYBOOK.

A first deal Manual on Cleaning Resumer and Adjusting. With upwards of sex la la trafficia. which is all only only the salt young persons connected with the watch trade to acquire and study inexpersive work to the same at Case and

PATTERN MAKER'S HANDYBOOK.

A Uncerteal Manual on the Construction of Patterns for Founders. With appeared. of the flie strations. and value of a strong independence, same a for the patiern maker."-Knowledge.

MECHANIC'S WORKSHOP HANDYBOOK.

A second of the North Annual Control of the Contr

MODEL ENGINEER'S HANDYBOOK.

A triver will the offer the objective terror of Model Steam Engines, Wiles and Control of the Co

CLOCK JOBBER'S HANDYBOOK.

Various level of a real on Chesteric Averages and Adjusting. With appear is ex-fect the state of the state of the state of the state of the state of $T_{\rm state}$

CABINET WORKER'S HANDYBOOK.

A first of Model at on the Tools Antervals, Mystamers, and Processes employed and Johnst Asiana. With an exerts of a self-instruction.

The control of the Asian control to the took as a consist the most process dealers we have seen to be an a secretary control of the Asian

WOODWORKER'S HANDYBOOK.

WOODWORKER, STATIND BOOK.

It is a want Internation of the Wood Materials, Apparents, and Processes Engineers on West directions. Vertically all its experience in a continuous terms of the repeated of the features to direct and how to Continuous terms of the process of the features to direct and how to Materials with the features the resolution of the practical terms with the manipulation skill and solution as the process of a practical terms with the manipulation skill and solution as a population of the features of the process of the manifest of manifest terms of the reference and population of the second of the process of experience and the manifest terms of the process of the process of the manifest terms of the process of the

COMMERCE, COUNTING-HOUSE WORK, TABLES, ETC.

LESSONS IN COMMERCE.

By Professor R. Gambaro, of the Royal High Commercial School at Genoa.
Edited and Revised by James Gaully, Professor of Commerce and Commercial
Law in King's College, London. Fifth Edition. Crown 8vo, cloth . 3/6

"The publishers of this work have rendered considerable service to the cause of commercial education by the opportune production of this volume.

The work is peculiarly acceptable to English readers and an admirable addition to existing class books. In a phrase, we think the work attains its object in furnishing a brief account of those laws and customs of British trade with which the commercial man interested therein should be familiar."—Chamber of Commerce Journal.

"An invaluable guide in the hands of those who are preparing for a commercial career, and, in fact, the information it contains on matters of business should be impressed on every one."—Counting House.

THE FOREIGN COMMERCIAL CORRESPONDENT.

Being Aids to Commercial Correspondence in Five Languages—English, French, German, Italian, and Spanish. By Conrad E. Baker. Third Edition. Carefully revised throughout. Crown 8vo, cloth

"Whoever wishes to correspond in all the languages mentioned by Mr. Baker cannot do better than study this work, the materials of which are excellent and conveniently arranged. They consist not of entire specimen letters, but—what are far more useful—short passages, sentences, or phrases expressing the same general idea in various forme,"—Athenaum.

"A careful examination has convinced us that it is unusually complete, well arranged and reliable. The book is a theroughly good one."—Schoolmaster.

FACTORY ACCOUNTS: THEIR PRINCIPLES AND PRACTICE.

A Handbook for Accountants and Manufacturers, with Appendices on the Nomenclature of Machine Details; the Income Tax Acts; the Rating of Factories; Fire and Boiler Insurance; the Factory and Workshop Acts, &c., including also a Glossary of Terms and a large number of Specimen Rulings, By EMILE GARCKE and J. M. FELLS. Fifth Edition, Revised and Enlarged. Demy 890, cloth Demy 8vo, cloth

"A very interesting description of the requirements of Factory Accounts. . . . The principle of assimilating the Factory Accounts to the general commercial books is one which we thoroughly agree with "—Accountants Tournal.

"Characterised by extreme thoroughness. There are few owners of factories who would not derive great benefit from the perusal of this most admirable work."—Local Government Chronicle.

MODERN METROLOGY.

A Manual of the Metrical Units and Systems of the Present Century. With an Appendix containing a proposed English System. By Lowis D'A. Jackson, A.M. Inst. C.E., Author of "Aid to Survey Practice," &c. Large crown 8vo,

"We recommend the work to all interested in the practical reform of our weights and measures."-

SERIES OF METRIC TABLES.

In which the British Standard Measures and Weights are compared with those of the Metric System at present in Use on the Continent. By C. H. Dowling. 8vo, cloth C.E.

"Mr. Dowling's Tables are well put together as a ready reckoner for the conversion of one system into the other," — Thousand.

IRON AND METAL TRADES' COMPANION.

For expeditionally ascertaining the Value of any Goods bought or sold by Weight, from 15. per cwt. to 1125. per cwt., and from one farthing per pound to one shilling per pound. By Thomas Downie. Strongly bound in leather, 396 pp. 9/-

"A most useful set of tables, nothing like them before existed."—Fluiding News.

"Although specially adapted to the iron and metal trades, the tables will be found useful in every other business in which merchandise is bought and sold by weight."—Railway News.

NUMBER, WEIGHT, AND FRACTIONAL CALCULATOR.

Containing upwards of 250,000 Separate Calculations, showing at a glance the value at 422 different rates, ranging from 114th of a Penny to 20s. each, or per cwt., and 520 per ton, of any number of articles consecutively, from 1 to 470 Any number of cwts., qrs., and lbs., from 1 cwt. to 470 cwts. Any number of tons, cwts., qrs., and lbs., from 1 to 1,000 tons. By William Chadwick, Public Accountant. Fourth Edition, Revised and Improved. 8vo, strongly bound 18-

"It is an easy of reference for any answer or any number of answers as a dictionary. For making up accounts or estimates the book must prove invaluable to all who have any considerable quantity of calculations involving price and measure in any combination to do."—Engineer.

"The most perfect work of the kind yet prepared."—Glangow Harable.

THE WEIGHT CALCULATOR.

Being a Series of Tables upon a New and Comprehensive Plan, exhibiting at one Being a Series of Tables upon a New and Comprehensive Plan, exhibiting at one Reference the exact Value of any Weight from 1 lb. to 15 tons, at 300 Progressive Rates, from 1d. to 1685, per cwt., and containing 186,000 Direct Answers, which, with their Combinations, consisting of a single addition (mostly to be performed at sight), will afford an aggregate of 10,266,000 Answers; the whole being calculated and designed to ensure correctness and promote despatch. By Henry Harben, Accountant. Sixth Edition, carefully corrected. Royal 8vo. strongly half harben. half-bound

"A practical and useful work of reference for men of business generally."—Ironmonger
"Of priceless value to business men. It is a necessary book in all mercantile officer
Independent.

THE DISCOUNT GUIDE.

Comprising several Series of Tables for the Use of Merchants, Manufacturers Ironmongers, and others, by which may be ascertained the exact Profit arising from any mode of using Discounts, either in the Purchase or Sale of Goods, and the method of either Altering a Rate of Discount, or Advancing a Price, so as to produce, by one operation, a sum that will realise any required profit after allowing one or more Discounts; to which are added Tables of Profit or Advance from 1½ to 90 per cent. Tables of Discount from 1½ to 98½ per cent. and Tables of Commission, &c., from ½ to 10 per cent. By Henry Harben, Accountant. New Edition, Corrected Demy 8vo, half-bound

"A book such as this can only be appreciated by business men, to whom the saving of time means awing of money. The work must prove of great value to merchants, manufacturers, and general traders."—British Trade Journal.

TABLES OF WAGES.

At 54, 52, 50, and 48 Hours per Week. Showing the Amounts of Wages from One-quarter-of-an-hour to Sixty-four hours in each case at Rates of Wages advancing by One Shilling from 4s. to 55s. per week. By Thos. Garbutt. Accountant. Square crown 8vo, half-bound

IRON-PLATE WEIGHT TABLES.

For Iron Shipbuilders, Engineers and Iron Merchants. Containing the Calculated Weights of Upwards of 150,000 different sizes of Iron Plates from 1 foot by 6 in. by \(\frac{1}{2}\) in. to 10 feet by 5 feet by 1 in. Worked out on the basis of 40 lbs. to the square foot of Iron of 1 inch in thickness. By H. Burlinson and W. H. Simpson. 4to, half-bound

ORIENTAL MANUALS AND TEXT-BOOKS.

Notice, Messrs. Crosby Lockwood & Son will forward on application a New and Revised List of Text-books and Manuals for Students in Oriental Languages, many of which are used as Text-books for the Examinations for the Indian Civil Service and the Indian Staff Corps; also as Class Books in Colleges and Schools in Indian

AGRICULTURE, FARMING, GARDENING, ETC.

THE COMPLETE GRAZIER AND FARMER'S AND

CATTLE BREEDER'S ASSISTANT.

A Compendium of Husbandry. Originally Written by WILLIAM YOUATT.
Fourteenth Edition, entirely Re-written, considerably Enlarged, and brought up to Present Requirements, by WILLIAM FREAM, LL.D., Assistant Commissioner, Royal Commission on Agriculture, Author of "The Elements of Agriculture," &c.
Royal Svo. 1,100 pp., 450 Illustrations. Handsomely bound £1 11s. 6d.

Royal Svo, 1,100 pp., 450 Illustrations. Handsomely bound £1 11s. 6d.

Summary of Contents.

Book I. On the Varieties, Bereding, Rearing, Rearing, Fattering and Management of Cattle.

Book II. On the Bosomev and Management of Cattle.

Book III. On the Breeding, Rearing, and Management of Hieses.

Book III. On the Breeding, Rearing, and Management of Hieses.

Book IV. On the Breeding, Rearing, and Fattering of Sumer.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Fattering of Swine.

Book IV. On the Breeding, Rearing, and Management of Politics and Difficulties of Management of Politics.

Book IV. On the Breeding, Rearing, and Management of Politics and Management of Politics and Management of Politics.

Book IV. On the Cultivation and Application of the Cultivation and Application to the Swines.

Book IV. On the Breeding, Rearing, and Management of Politics and Management of Politics and Management of Politics.

Book IV. On the Breeding, Rearing, and Management of Politics and Management of Politics.

Book IV. On the Breeding, Rearing, and Management of Politics.

Book IV. On the Cultivate and Management of Politics.

Book IV. On the Cultivate and Management of Politics.

Book IV. On the Cultivate and Management of Politics.

Book IV. On the Cultivate and Management of Politics.

Book IV. On the Culture and Management of Politics.

Book IV. On the Cultivate and Management of Politics.

Book IV. On the Cultivate and Defect and Management of Politics.

Book IV. On the Cultivate and Manageme

FARM LIVE STOCK OF GREAT BRITAIN.

By Robert Wallace, F.L.S., F.R.S.E., &c., Professor of Agricultural and Rural Economy in the University of Edinburgh. Third Edition, thoroughly Revised and considerably Enlarged. With over 120 Phototypes of Prize Stock. Demy 8vo, 384 pp., with 70 Plates and Maps. Cloth

"A really complete work on the history, breeds, and management of the farm stock of Great Britain, and one which is likely to find its way to the shelves of every country gentleman's library,"—
Tas Times.

"The Farm Live Stock of Great Britain' is a production to be proud of, and its issue not the

"The Farm Live Stock of Great Britain' is a production to be proud of, and its issue not the least of the services which its author has rendered to agricultural science."—Scottish Farmer,

NOTE-BOOK OF AGRICULTURAL FACTS AND FIGURES FOR FARMERS AND FARM STUDENTS.

By PRIMROSE McConnell, B.Sc., Fellow of the Highland and Agricultural Society, Author of "Elements of Farming." Sixth Edition, Rewritten, Revised, and greatly Enlarged. F'cap. 8vo, 480 pp., leather, gilt edges

CONTENTS — SURVEYING AND LEVELLING. — WEIGHTS AND MEASURES. — MACHINERY AND BUILDINGS.—LABOUR.—OPERATIONS — DESLING.—EMBANKING.—GEOLOGICAL MEMORANDA.—SOILS.—MANURES.—CROPPING.—CKOPS.—ROTATIONS.—WEEDS.—PERDING.—DAIRYING.—LIVE STOCK.—HORBICULTURE.—MISCELLANEOUS.

"No farmer, and certainly no agricultural student, ought to be without this multum in parso manual of all subjects connected with the farm,"—North British Agriculturist,

"This little pocker-book contains a large amount of useful information upon all kinds of agricultural subjects. Something of the kind has long been wanted."—Mark Lane Express.

"The amount of information it contains is most surprising; the arrangement of the matter is so methodical—although to compressed—as to be intelligible to every one who takes a glance through its pages. They teem with information."—Farm and Homs.

THE ELEMENTS OF AGRICULTURAL GEOLOGY.

A Scientific Aid to Practical Farming. By PRIMROSE McConnell, Author of "Notebook of Agricultural Facts and Figures," &c. Royal 8vo, cloth.

Net

"On every page the work bears the impress of a masserly knowledge of the subject deals with, and we have nothing but unstituted praise to offer." - Field.

BRITISH DAIRYING.

The Property of the War of the Forey Carm. Provide the residence of the War of the Forey Carm. Provide the Strike War of the Provide the Strike War of the Colleges and the War War of the Strike War. Provide the Strike War. The same and the transfer of the second of the form $(e_1, e_2, \dots, e_{n-1}, e_n)$, which is a set of e_n , in Thomas

MILK, CHEESE, AND BUTTER.

LK, CHEESE, AND BUTTER.

A cross of Hamilton, the rat period and the Processes, total two to a chapter on cream and the Mentions of the Separation of the second and the Separation of the second and the Separation of the second control of the

SYSTEMATIC SMALL FARMING.

The first of the Farm the gar stred structs Male of large enders as the structure of the first o £2 is the sale of the second constant of the se

OUTLINES OF MODERN FARMING.

There is the second flator of the role barries and Farndag to the area should not flator barries Michaelment of Pairy, Pies and Francis in the second for the end of the second flator of the second f

FARM ENGINEFRING, THE COMPLETE TEXT BOOK OF

When the property of the control of

THE FIELDS OF GREAT PRITAIN.

The Committee of the co

TABLES AND MEMORANDA FOR FARMERS, GRAZIER? MIRICULTURAL STUDENTS, SUPPEYORS, LAND AGENTS NOTHONIERS, WA

A Country of the Res Country of the Country of the Server France of the Server France of the Server

THE ROTHAMSTED EXPERIMENTS AND THEIR

FRACTICAL LESSONS FOR FARMERS.

I had been Paul II Crops By to be been Crown Syn, cloth , 3 cown in the been been while we now produce to official translations and others improve a particularly send of the contract and others improve a particularly send of the contract and others improve a particular to the contract and others improve a particular to the contract and others improve a particular to the contract and others improve a particular to the contract and others improve a particular to the contract and others in the contract and other in the contract and other in the contract and others in the contract and other interests. The contra

FERTILISERS AND FEEDING STUFFS.

Their Properties and Uses. A Handbook for the Practical Farmer. By Bernard Dver, D.Sc. (Lond.). With the Text of the Pertilisers and Feeding Stuffs Act of 1893. The Regulations and Forms of the Board of Agriculture, and Notes on the Act by A. J. Davio, B.A., LL.M. Fourth Edition, Revised. Crown 8vo, cloth

"This little book is precisely what it professes to be—'A Handbook for the Practical Farmer.'

Dr. Dyer has done farmers good service in placing at their disposal so much useful information in so intelligible a form,"—The Times.

BEES FOR PLEASURE AND PROFIT:

Guide to the Manipulation of Bees, the Production of Honey, and the General Management of the Apiary. By G. Gordon Sanson, With numerous Illustrations. Crown 8vo, wrapper

BOOK-KEEPING FOR FARMERS AND ESTATE OWNERS.

A Practical Treatise, presenting, in Three Plans, a System adapted for all Classes of Farms. By Johnson M. Woodman, Chartered Accountant. Fourth Edition. Crown 8vo, cloth . 2/6

"The volume is a capital study of a most important subject."-Agricultural Gamilie.

WOODMAN'S YEARLY FARM ACCOUNT BOOK.

Giving Weekly Labour Account and Diary, and showing the Income and Expenditure under each Department of Crops, Live Stock, Dairy, &c., &c. With Valuation, Profit and Loss Account, and Balance Sheet at the end of the Year. By Johnson M. Woodman, Chartered Accountant. Second Edition. Folio, half-bound

"Contains every requisite for keeping farm accounts readily and accurately,"-Agriculture.

THE FORCING-GARDEN.

Or, How to Grow Early Fruits. Flowers, and Vegetables. With Plans and Estimates for Building Glasshouses, Pits and Frames. With Hinstrations By Samuel Wood. Crown Svo. cloth 3/6 With Plans and

"A good book, containing a great deal of valuable teaching,"-Gardener's Magazine.

A PLAIN GUIDE TO GOOD GARDENING.

Or, How to Grow Vegetables, Fruits, and Flowers. By S. Wood. Fourth Edition, with considerable Additions, and numerous Illustrations. Crown Svo, cloth 3/6

"A very good book, and one to be highly recommended as a practical guide. The practical directions are excellent."—Athensom.

MULTUM-IN-PARVO GARDENING.

Or, How to make One Acre of Land produce £620 a year, by the Cultivation of Fruits and Vegetables; also, How to Grow Plowers in Three Glass Houses, so as to realise £176 per annum clear Profit. By Samuel Wood, Author of "Good Gardening," &c. Sixth Edition. Crown Svo, sewed . . . 1/-

THE LADIES' MULTUM-IN-PARVO FLOWER GARDEN.

And Amateur's Complete Guide. By S. Wood. Crown 8vo, cloth

POTATOES: HOW TO GROW AND SHOW THEM.

Practical Guide to the Cultivation and General Treatment of the Potato By J. PINK. Crown Svo

MARKET AND KITCHEN GARDENING.

By C. W. Shaw, late Editor of "Gardening Illustrated," Crown Svo, cloth.

36

AUCTIONEERING, VALUING, LAND SURVEYING, ESTATE AGENCY, ETC.

INWOOD'S TABLES FOR PURCHASING ESTATES AND FOR THE VALUATION OF PROPERTIES

Including Advowsons, Assurance Policies, Copyholds, Deferred Annuaire, Freeholds, Ground Rents, Immediate Annuaires, Leaseholds, Life Interests, Mortgages, Perpetuities, Renewals of Leases, Reversions, Sinking Funds, &c., &c. 27th Edition, Revised and Extended by William Schooling, F.R.A.S., with Logarithms of Natural Numbers and Thomas's Logarithmic Interest and Annuity Tables. 360 pp., damy 8vo, cloth [Just Published. Net 8]

"Those interested in the purchase and sale of entates, and in the adjustment of compensation easiervice."—Engineering.

"This valuable book has been considerably enlarged and improved by the labours of Mr. Schooling, and is now very complete indeed,"—Economist.

"Altogether this edition will prove of extreme value to many classes of professional men in saving them many long and tedious valculations,"—Investors Exview.

THE APPRAISER, AUCTIONEER, BROKER, HOUSE AND ESTATE AGENT AND VALUER'S POCKET ASSISTANT,

For the Valuation for Purchase, Sale, or Renewal of Lesses, Annuities and Reversions, and of property generally; with Prices for Inventories, &c. By John Wheeler, Valuer, &c. Sixth Edition, Re-written and greatly Extended by C. Norris. Royal 32mo, cloth.

"A neat and concise book of reference, containing an admirable and clearly arranged has of practa for inventories, and a very practical guide to determine the value of furniture, occ."—Standard.

"Contains a large quantity of varied and useful information as to the valuation for purchase, sie, or renewal of leases, annuties and reversions, and of property generally, with prices for inventories, and a guide to determine the value of interior fittings and other effects."—Dutility.

AUCTIONEERS: THEIR DUTIES AND LIABILITIES.

A Manual of Instruction and Counsel for the Young Auctioneer, By Roman Squines, Auctioneer, Second Edition, Revised. Demy 8vo, cloth 12/6

"The work is one of general excellent character, and gives much information in a compensation and satisfactory form."—Builder.

"May be recommended as giving a great deal of information on the law relating to acctionners, in a very readable form."—Law Journal.

THE AGRICULTURAL VALUER'S ASSISTANT.

A Practical Handbook on the Valuation of Landed Estates, including Example of a Detailed Report on Management and Realisation; Forms of Valuations of Tenant Right; Lists of Local Agricultural Customs; Scales of Compensation under the Agricultural Holdings Act, and a Brief Treatise on Compensation under the Lands Clauses Acts, &c. By Tom Bright, Agricultural Valuer, Author of "The Agricultural Surveyor and Estate Agent's Handbook." Fourth Edition, Revised, with Appendix containing a Digest of the Agricultural Holdings Acts, 1883-1900. Crown 8vo, cloth Net 6

"Full of tables and examples in connection with the valuation of tenant-right, states labrier, contents and weights of timber, and farm produce of all kinds "— agricultural Gaszite.

"An entimently practical handbook, fail of practical tables and data of indoubted interest and value to surveyors and auctionests in preparing valuations of all kinds."—Farmer.

POLE PLANTATIONS AND UNDERWOODS.

A Practical Handbook on Estimating the Cost of Forming, Renovating, Improving, and Grubbing Plantations and Underwoods, their Valuation for Purposes of Transfer, Rental, Sale or Assessment. By Ton Bright, Crown Svo, cloth 3/6

To valuers, foresters and agents it will be a welcome aid."—North Beitink Agraculturist,
"Well calculated to assist the valuer in the discharge of his duties, and of undoubted interest and
use both to surveyors and auctioners in preparing valuations of all kinds."—Kent Herald.

AGRICULTURAL SURVEYOR AND ESTATE AGENT'S HANDBOOK.

Of Practical Rules, Formulæ, Tables, and Data: A Comprehensive Manual for the Use of Surveyors, Agents, Landowners, and others interested in the Equipment, the Management, or the Valuation of Landed Estates. By Tow Bright, Agricultural Surveyor and Valuer, Author of "The Agricultural Valuer's Assistant," &c. With Illustrations. Fcap. 8vo, Leather. Na 7/6

"An exceedingly useful book, the contents of which are admirably chosen. The classes for whom the work is triended will find it convenient to have this comprehensive handbook accessible for reference."—Live Stock Journal.

'It is a singularly compact and well informed compendium of the facis and figures likely to be required in estate work, and is certain to prove of much service to those to whom it is addressed."—Scottman.

THE LAND VALUER'S BEST ASSISTANT.

Being Tables on a very much improved Plan, for Calculating the Value of Estates. With Tables for reducing Scotch, Irish, and Provincial Customary Acres to Statute Measure, &c. By R. Hudson, C.E. New Edition. Royal 32mo, leather, elastic band

"Of incalculable value to the country gentleman and professional man."-Farmers' Journal,

THE LAND IMPROVER'S POCKET-BOOK.

Comprising Formulæ, Tables, and Memoranda required in any Computation relating to the Permanent Improvement of Landed Property. By John Ewart, Surveyor, Second Edition, Revised, Royal 32mo, oblong, leather 4,-"A compendious and handy little volume,"-Speciator,

THE LAND VALUER'S COMPLETE POCKET-BOOK.

HANDBOOK OF HOUSE PROPERTY,

Popular and Practical Guide to the Purchase, renancy, and Company, Houses and Land, including Dilapidations and Fixtures: with Examples of kinds of Valuations, Information on Building and on the right use of Ru E I. Tarreck, Architect and Surveyor. Seventh Edition. A Popular and Practical Guide to the Purchase, Tenancy, and Compulsory Sale all kinds of Valuations, Information on Bunding and Surveyor. Seventh Edition.

Decorative Art. By E. L. Tarbuck, Architect and Surveyor. Seventh Edition.

[Just Published. 5]

"The advice is thoroughly practical."—Law Journal.

"For all who have dealings with house property this is an indispensable guide."—Decoration.

"Carefully brought up to date, and much improved by the addition of a division on Fine Arr. A well-written and thoughtful work."—Law Agents Record.

LAW AND MISCELLANEOUS.

MODERN JOURNALISM.

A Handbook of Instruction and Counsel for the Young Journalist. By John B.

Mackie, Fellow of the Institute of Journalists. Crown Svo, cloth

This invaluable guide to journalism is a work which all arphrants to a journalistic current will read with advantage."—Journalist.

HANDBOOK FOR SOLICITORS AND ENGINEERS

Engaged in Promoting Private Acts of Parliament and Provisional Orders, for
the authorisation of Railways, Tramways, Gas and Water Works, &c. By
L. L. Macassev, of the Middle Temple, Barrister-at-Law, M.I.C.E. 870, cloth. £1 5s.

PATENTS FOR INVENTIONS, HOW TO PROCURE THEM.

CONCILIATION AND ARBITRATION

IN LABOUR DISPUTES.

A Historical Sketch and Brief Statement of the Present Position of the Question at Home and Abroad. By J. S. Jaans. Crown 8vo, 200 pp., cloth . 2/6

EVERY MAN'S OWN LAWYER.

A Handy-Book of the Principles of Law and Equity. With a Concise Dictionary of Legal Terms. By A Barrister. Forty-first Edition, carefully Revised, and comprising New Acts of Parliament, including the Mainter Act, 1903; Employment of Children Act, 1903; Pistols Act, 1903; Pour Prisoners' Defence Act, 1903; Education Acts of 1902 and 1903; Housing of the Working Classes Act, 1903, 6-c. Judicial Decisions pronounced during the year have also been duly noted. Crown 8vo, 800 pp., strongly bound in cloth. [Just Published. 8/8

. This Standard Work of Reference forms a Complete Epitome of the Laws of England, comprising (amongst other matter):

THE RIGHTS AND WRONGS OF INDIVIDUALS

LANDLORD AND TENANT VENDORS AND PURCHASERS LEASES AND MORTGAGES JOINT-STOCK COMPANIES MASTERS, SERVANTS AND WORKMEN CONTRACTS AND AGREEMENTS MONEY-LENDERS, SURETISHIP PARTNERSHIP, SHIPPING LAW SALE AND PURCHASE OF GOODS CHEQUES, BILLS AND NOTES BILLS OF SALE, BANKRUPTCY LIFE, FIRE, AND MARINE INSURANCE LIBEL AND SLANDER

CRIMINAL LAW PARLIAMENTARY ELECTIONS COUNTY COUNCILS DISTRICT AND PARISH COUNCILS BOROUGH CORPORATIONS TRUSTEES AND EXECUTORS CLERGY AND CHURCHWARDENS COPYRIGHT, PATENTS, TRADE MARKS HUSBAND AND WIPE, DIVORCE INFANCY, CUSTODY OF CHILDREN PUBLIC HEALTH AND NOISANCES INNKERPERS AND SPORTING TAXES AND DEATH DUTIES

FORMS OF WILLS, AGREEMENTS, NOTICES, ETC.

The object of this work is to enable those who consult it to help themselves to the law; and thereby to dispense, as far as possible, with professional assistance and advice. There are many wrongs and grievances which persons submit to from time to time through not knowing how or where to apply for redress; and many persons have as great a dread of a lawyer's office as of a lion's den. With this book at hand it is believed that many a SIX-AND-EIGHTPENCE may be saved; many a wrong redressed; many a right reclaimed; many a law suit avoided; and many an evil abuted. The work has established itself as the standard legal adviser of all classes, and has also made a reputation for itself as a useful book of reference for lawyers residing at a distance from law libraries, who are glad to have at the law as the pare at the standard meantments. to have at hand a work embodying recent decisions and enactments.

* .* Opinions of the Press.

- "The amount of information given in the volume is snoply wonderful. The continued popularity of the work shows that it fulfils a useful purpose," +Law Journal.

 "As a book of reference this volume is without a rival," -Pall Mall Gazette.

 "No Englishman ought to be without this book," --Engineer.

 - "Ought to be in every business establishment and in all libraries." -- Sheffield Port,

 - "The 'Concise Dictionary' adds considerably to its value." -- Westminster Gazette,
- "It is a consider code of English Law written in plain language, which all can understand.

 Should be in the hords of every business man, and all who wish to abolish lawyers' bills."—Weekly Times.

 "A assolid and concise epitome of the law, compiled with considerable care."—Law Magazzne,

 "A complete digest of the most useful facts which constitute English law."—Globe.
- "Admitably done, admirably arranged, and admirably the ip."—Leeds Mercury.

 "A concise, cheap, and complete epitome of the English law. So plainly written that he who runs may read, and he who reads may understand."—Figure
 - "A dictionary of legal facts well put together. The book is a very useful one."-Spectator.

LABOUR CONTRACTS.

A Popular Handbook on the Law of Contracts for Works and Services. By DAVID GIBBONS—Fourth Edition, with Appendix of Statutes by T. F. UTTLEY Solicitor.—Fcap. 8vo. cloth 36

WEALE'S SERIES SCIENTIFIC & TECHNICAL WORKS.

"It is not too much to say that no books have ever proved more popular with or more useful to young engineers and others than the excellent treatises comprised in Weale's Series."—Engineer.

A New Classified List.

Civil Engineering and Surveying 50	PAGE Industrial and Useful Arts 57
Mining and Metallurgy 51	Agriculture, Gardening, Etc 58
Mechanical Engineering 52	Mathematics, Arithmetic, Etc 60
Navigation, Shipbuilding, Etc 53	Books of Reference and Mis-
Architecture and Building 54	cellaneous Volumes 62



CROSBY LOCKWOOD AND SON,
7, STATIONERS' HALL COURT, LONDON, E.C.
1905.

Iron and Steel Bridges and Viaducts
A Profit Construction. For the use of Figure 8.8 (a) 18. The Profit of the Use of Figure 18. The Profit of The Use of The Profit of The Use of The Profit of The Use of The Profit of The Use of The Profit of The Use of The Profit of The Use of The Profit of The Use of The Profit of The Use of T

Iron Bridges of Moderate Span:

Then Constituting and Invention By H. W. PENDERD, AND State of the engineering practical

Constructional Iron and Steel Work

A application of the around Demonstrating By Francisco and the product of the around the environment of the around the

Tubular and other Iron Girder Brid Describing to Dominic and Commy political Bridges W Bridge LWC B. G. David Ale. On Mestry, C.E. Fourt. Edit

Materials and Construction.

With determination By First is Campia C.E. The "Necks of Construction By First is Campia C.E. The "Necks of Construction by First is Campia C.E. The "Neckstone professional transfer of the principal and decision of the principles of confident to the our language of the decision of the principles of confident to the our language of the decision of the principles."

Sanitary Work in Small Towns and

by Chatter Shaon, Associate, the Chi. Diriched on, En17th is a very section in There is a great real of work regimed to be
and where shad the real end and will divide section on a dirich color in the Fig.

Construction of Roads and Streets.

PARLAW, C.F., and D. K. CLARK, C.E., Sorth Edition, re-Chapter (V.A. I. WALLIS-LAVILE, A.M., Inst. C.F., "A beal wideless of trong's streyo and enther must be sess, and which exists a manufects, widen, and property owners generally," - mallding News.

Gas Works:

Their Construction and Arrangement, and the Manufacture and Gas. Oraqually written by S. Heronis, C.F. Ninth Edition, R. Rogent Improvements, by HERRY O'CONNOR, A.M. Inst. C.E., by Will be excellent convict able to practifacturers, distributors, and consumer

Water Works, for the Supply of Cities
With a Description of the Principal Geological Formations of F
Supplies of Water. By SAMLET HUGHES.
"Exercise where, delating how his village, town, or city shall be plenti

Bla	sting and Quarrying of Stone, For Building and other Purposes. With Remarks on the Blowing up of Bridges. By Gen. Sir J. Burgovne, K. C. B.
For	undations and Concrete Works. With Fractical Remarks on Footings, Planking, Sand, Concrete, Béton, Pile-driving, Calssons, and Cofferdams. By E. Donson, M.R.I.B.A. Ninth Edition 1/6
	Eumatics, Including Acoustics and the Phenomena of Wind Currents, for the use of Beginners. By CHARLES TOMLINSON, F.R.S. Fourth Edition, enlarged, Hinstrated 1/6
Lai	nd and Engineering Surveying. For Students and Practical Use. By T. BAKER, C.E. Twentieth Edition, revised and extended by F. E. Dixon, A.M. Inst. C.E. With Plates and Diagrams . 2/0
Me	With the Mensuration and Levelling of Land for the purposes of Modern Engineering. By T. Barker, C.E. New Edition by E. NUGENT, C.E. 1/6
7071	MINING AND METALLURGY.
MAI	For the use of Students Preparing for the Examinations for Colliery Managers' Certificates, comprising numerous Rules and Examples in Arithmetic, Algebra, and Mensuration. By T. A. O'DONAHUE, M.E., First-class Certificated Colliery Manager.
Min	neralogy, Rudiments of. By A. RAMSAY, F.G.S. Fourth Edition. Woodcuts and Plates 3/6 The author throughout has displayed an intimate knowledge of his subject, and great facility in
Impart	ting that knowledge to others. The book is of great utility."-Mining Journal.
	Al and Coal Mining, By the late Sir Warington W. Smyth, M.A., F.R.S. Eighth Edition, Revised and Extended by T. Forster Brown, Chief Inspector of the Mines of the Crown and of the Duchy of Cornwall
given.	Every portion of the volume appears to have been prepared with much care, and as an outline is of every known coal-field in this and other countries as well as of the two principal methods of og, the book will doubtless interest a very large number of readers."—Mining Journal.
	Containing History of Iron Manufacture, Methods of Assay, and Analyses of Iron Ores, Processes of Manufacture of Iron and Steel, &c. By H. BAUKRMAN, F.G.S., A.R.S.M. With numerons Illustrations. Sixth Edition, revised and enlarged
	neval Surveyor & Valuer's Complete Guide. Comprising a Treatise on Improved Mining Surveying and the Valuation of Mining Properties, with New Traverse Tables. By W. Lintern, C. E., Fourth Edition, with an Appendix on Magnetic and Angular Surveying, with Records of the Peculiarities of Needle Disturbances. With Four Plates of Diagrams, Plans, &c. 3/6 Contains much valuable information, and is thoroughly trustworthy."—Tres & Coal Trades Review.
Sla	scientific, Practical, and Commercial. By D. C. DAVIES, F.G.S., Mining Engineer, &c. With numerous Illustrations and Folding Plates. Fourth Edition 3/0 One of the heat and best-balanced treatises on a special subject that we have met with."—Engineer.
A :	First Book of Mining and Quarrying. By J. H. COLLINS, F.G.S. 1/6 For those concerned in schools in the mining districts, this work is the very thing that should be in add of their schoolmasters. —/res.
	bterpaneous Surveying. By Thomas Ferwick. Also the Method of Conducting Subtermneous Surveys without the use of the Magnetic Newfle, &c. By T. Barre, C.E

Mining Tools,
Manual of, By W. Morgans, Lecturer on Mining at the Bristol School of Mines 2/6
Mining Tools, Atlas
Of Engravings to the above, containing 235 Illustrations drawn to Scale. 4to. 4/6
"Stellents, Overmen, Capains. Managers, and Viewers may gain practical knowledge and useful hims by the study of Mr. Mergans' Manual."—Collect Guardien.

Physical Geology,

Historical Geology,
Partly based on Major-Recent Porttocks "Radiments." Dr Raspu Tare

PRIVACAL and HISTORICAL Consisting of "Thysical Goology ships Leading Principles of the Science; and "Historical Goology, which we Mineral and Organic Conditions of the Earth at each successive epoch.

TATE, V.G.S. With 250 Illustrations
"The follows of the matter has stevand the look into a manual. Its information is a stronged, so that any subject may be uponed upon at occa." "School Record Classical.

multi-arranged.

MECHANICAL ENGINEERING

Workman's Manual of Engineering Drawing. Royal Naval College By JOHN MAKTON, Instructor in Enginer with. Eighth Edition. 300 Pintes and I. "A copy of it should be kept for reference in every

Fuels: Solid, Liquid, and Gaseous.

Their Analysis and Valuation. For the use of Chemists and Engineers.

Pattatrs, F.C.S., formerly Analytical and Consulting Chemist to the GraRailway. Fourth Edition Ought to have its place to the laboratory of every untallergual establishess ton a large scale. "Chemical News. used on a

Fuel, Its Combustion and Economy.

Consisting of an Abridgment of "A Treatise on the Combustion of CoPrevention of Smoke." By C. W. Williams, A.I.C.E. With extensive
hy D. Kinnkah Clark, M. Irst. C.E. Fourth Edition.

"Students should buy the book and read it, as one of the most amplete and substact on
the combustion and economy of fuel to be had." Engineer.

Boilermaker's Assistant

In Drawing, Templating, and Calculating Boiler Work, &c. By J. Practical Boilermaker. Edited by D. K. CLARK, C.E. Seventh Edition "With very great care we have gone through the Bollermaker. Assistant," and have been omitted."—Foreman Magintary.

Boilermaker's Ready Reckoner,

With Examples of Practical Geometry and Tempiating for the Use of Planers and Riveters. By John Courtney. Edited by D. K. CLARK, M. I.C.E.

"I The last two Works in One Vol., half-bound, sufficient "The Boilermakers"

RECKONER AND ASSISTANT." By J. Courtney and D. K. CLARK. Pr.

"A most useful work. No workman or appendice should be subboil it. "I test Track Cir.

Steam Boilers.

Their Construction and Management. By R. ARMSTRONG, C.E. Hustrated "A mass of information suitable for beginners," — Bergen and Work,

Steam and Machinery Management.

A Guide to the Arrangement and Economical Management of Machinery, with Himse Construction and Selection, By M. Power Barr. M. Inst. M.E. "Gives the results of wide experience."—Lieut's Newsylaper.

The Steam Engine,

A Treatise on the Mathematical Theory of, with Rules and Examples for Men. By T. BAKER, C.E.

Teems with scientific information with reference to the steam-engine. — Design and Men.

The Steam Engine.
For the use of Beginners. By Dr. LARDNER. Illustrated

For the use of Beginners.

Locomotive Engines.

A Rudimentary Treatise on. By G. D. DEMPSEY, C.E. With large Addition of the Modern Locomotive, by D. K. CLARK, M. Inst. C.E. With Illustration of the Modern Locomotive, by D. K. CLARK, M. Inst. C.E. With Illustration of the Modern Locomotive of the Conference of the Co

Locomotive Engine-Driving.

A Practical Manual for Engineers in Charge of Locomotive Engines. By Michael.
REYNOLDS, M.S.E. Twelfth Edition. 3/6; cloth boards 4/6
We can confidently recommend the look, not only to the practical driver, but to everyone who takes an interest in the performance of locomotive engines. — The Engineer.

Stationary Engine Driving.

A Practical Manual for Engineers in Charge of Stationary Engines. By Michael Revnolds, M.S.E. Seventh Edition. 3/6 | cloth boards 4/6

"The author is thoroughly acquainted with his subjects, and has produced a manual which is an exceedingly useful one for the class for whom it is specially intended, —Engineering.

Smithy and Forge
Including the Farrier's Art and Coach Smithing. By W. J. E. CRANE. 2/6
The first modern English book on the subject. Great pains have been bestowed by the author upon the book; shoeing-smiths will find it book useful and interesting. — Builder.

Modern Workshop Practice,

As applied to Marine, Land, and Locomotive Engines, Floating Docks, Dredging Machines, Bridges, Ship-Building, &c. By J. G. Winton. 4th Edn., Illustrated 3/6

"Whether for the apprentice determined to master his profession, or for the artisan bent upon raising himself to a higher position, this clearly-written and practical treatise will be a great help."—Scottman.

Mechanical Engineering.

Comprising Metallurgy, Moulding, Casting, Forging, Tools, Workshop Machinery, Mechanical Manipulation, Manufacture of the Steam Engine, &c. By Francis Campin, C.E. Third Edition 2/6

"A sound and serviceable text-book, quite up to date."—Building News.

Details of Machinery.

Comprising Instructions for the Execution of various Works in Iron in the Fittingshop, Foundry, and Boiler-Yard. By Francis Campin, C.E. 3/0

"A sound and practical handbook for all engaged in the engineering trades."—Building World.

Elementary Engineering:

A Manual for Young Marine Engineers and Apprentices. In the Form of Questions and Answers on Metals, Alloys, Strength of Materials, &c. By J. S. BREWER. Fifth Edition 1/6 "A useful introduction to the more elaborate text-books," - Scotpmen.

Practical Mechanism,
And Machine Tools. By T. BAKER, C.E. With Remarks on Tools and Machinery
by J. NASMYTH, C.E. 2/6

Mechanics.

Being a concise Exposition of the General Principles of Mechanical Science, and their Applications. By CHARLES TOMLINSON, F.R.S.

The Construction of, and other Machinery for Raising Heavy Bodies for the Erection of Buildings, &c. By JOSEPH GLYNN, F.R.S.

NAVIGATION SHIPBUILDING, ETC.

Sailor's Sea Book:

A Rudimentary Trentise on Navigation. By James Greenwood, B.A. With numerous Woodcuts and Coloured Plates. New and Enlarged Edition. By W. H. Rossur 2/6 "Is perhaps the Lest and simplest epitonse of navigation ever compiled."—Field.

Navigation and Nautical Astronomy,
In Theory and Practice. By Prof. J. R. Young. New Edition. Illustrated . 2/6
"A very complete, thorough, and useful minual for the young navigator."—Contractory.

	[athematical Tables, For Tagonometrical, Astronomical, and Nautical Calculations; to which is pure Treatise on Logarithms, by H. Law, C.E. Together with a Series of Tanavigation and Nautical Astronomy. By Professor J. R. Young. New Edition.		ŝ
M	lasting, Mast-Making, and Rigging of Shir Also Tables of Spars, Rigging, Blocks: Chain, Ware, and Herup Ropes, &c., to every class of vessels. By ROBERT KIPPING, N.A.	•	
Sŧ	Rils and Sail-Making. With Draughting, and the Centre of Effort of the Sails. Weights and Sizes of Masting, Rigging, and Sails of Steam Vessels, &c. By R. Kipping, N.A.	R	
	Arine Engines and Steam Vessels. By R. MURRAY, C.E. Eighth Edition, thoroughly Revised, with Additions Author and by GEORGE CARLISLE, C.E. "An indispensable manual for the student of marine engineering."—Liveryed Marray.	•	•
N	aval Architecture. An Exposition of the Elementary Principles. By JAMES PEAKE hips for Ocean and River Service.		
Aı	Principles of the Construction of. By H. A. SOMMERFELDT n Atlas of Engravings To Illustrate the above. Twelve large folding Plates. Royal 4to, cloth		
St	hips and Boats. By W. Brand. With numerous Illustrations and Models. Tenth Edition	•	
•.	ARCHITECTURE AND BUILDING	-	
	Onstructional Iron and Steel Work, As applied to Public, Private, and Domestic Buildings. By Francis Campin, C.E. "Anyone who wants a book on ironwork as employed for stanchious, columns, and beams, present volume to be suitable."—British Architect.	, wi	i

A Ir at second the Development, Sale, Purch se, and Management of Building Laniby E. MATTEAND. Fearth Edition. 20 This book health and uncombodity for added to the library of every professional man dealing with building book a Land agents Knord.

Science of Building:

An Florameter Trains on the Principles of Construction. By E. Wyndman Fasts, M.A. Front. Fearth Politica. 3:8

Art of Building,
Rudments of, General Principles of Construction, Strength, and Use of Materials.
Working Prawings, Specifications &c. By Edward Dorson, M.R. I.B.A. &c. 2/0
A good book for practical ke whenge, and a sout the best to be obtained."—Building Acros. Book on Building,
Coal and F closest oil. By Sir Edwind Beckert, Bert., LL.D., Q.C., F.R.A.S.,
Author of the looks, Wateres and Bei's," &c. Second Edition
TAlesk which is always award goard rearly always instructive,"—Times.

4:8

Dwelling-Houses,

Building Estates:

2/0

1/6

Errection of, Elastrated by a Perspective View, Plans, Elevations, and Sections of a Par-of Vilas, with the Specification, Quantities, and Estimates. By S. H. BROOKS 2/6

Cottage Building.

By C. BRICE ALLEN. Twelfth Edition, with Chapter on Economic Cottages for Allotments, by E. E. ALLEN, C.E. 2/0

Acoustics of Public Buildings: The Laws of Sound as applied to the Arrangement of Buildings. By Professor T. ROGER SMITH, F.R. I.B.A. New Felition, revised. With numerous illustrations 1/8

Practical Bricklaying.

General Punciples of Bricklaying; Arch Drawing, Cutting and Setting;
Paving, Tiling, &c. By ADAM HAMMOND. With 68 Woodcuts
"The young bricklayer will find it infinitely valuable to him."—Glasgow Herald.

Art of Practical Brick-Cutting and Setting. By ADAM HAMMOND, With 90 Engravings

to a large to the same of the
Brickwork:
Embodying the General and Higher Principles of Brinklaying, Cutting and Setting; with the Application of Geometry to Roof Tiling, &c. By F. WALKER
"Contains all that a young tradesman or student needs to learn from books."—Building News.
Bricks and Tiles,
Rudimentary Treatise on the Manufacture of. Containing an Outline of the Principles of Brickmaking. By E. Doason, M.R.I.B.A. Additions by C. TOMLINSON, F.R.S.
Illustrated 3/0 The best handhook on the subject. We can safely recommend it as a good investment,"—Builder.
Practical Brick and Tile Book.
Comprising: BRICK AND TILE MAKING, by E. DOBSON, M.Insl.C.E.; Practical BRICK- LATING, by A. HAMMOND; BRICK-CUTTING and SETTING, by A. HAMMOND. 350 pp.
with 270 Illustrations, strongly half-bound
Carpentry and Joinery-
THE ELEMENTARY PRINCIPLES OF CARPENTRY. Chiefly composed from the Standard Work of Thomas Tredgold, C.E. With Additions, and a Treatise on Joinery by E. W. Tarn, M.A. Eighth Edition
Carpentry and Joinery.
Atlas of 35 Plates to accompany and illustrate the foregoing book. With Descriptive Letterpress, 410.
"These two volumes form a complete treasury of carpentry and joinery, and should be in the hands of every carpenter and joiner in the Empire."—Irw.
Practical Treatise on Handrailing:
Showing New and Simple Methods. By GEO. COLLINGS. Third Edition, including a TREATISE ON STAIRBUILDING. With Plates
"Will be found of practical utility in the execution of this difficult branch of joinery."—Builder.
Circular Work in Carpentry and Joinery.
A Practical Treatise on Circular Work of Single and Double Curvature. By George Collings. Fourth Edition. 2/6
"Cheap in price, clear in definition, and practical in the examples selected."—Hadder.
Roof Cappentry: Practical Lessons in the Framing of Wood Roofs. For the use of Working Carpenters.
By GEO. COLLINGS, Author of "Handratling and Stairbuilding," &c 2/0
Construction of Roofs, of Wood and Iron:
Deduced chiefly from the Works of Robison, Tredgold, and Humber. By E. WYNDHAM TARN, M.A., Architect. Fourth Edition
"Mr. Tarn is so thoroughly master of his subject, that although the treatise was founded on the works of others he has given it a distinct value of his own. It will be found valuable by all students."—Builder.
The Joints Made and Used by Builders.
By WYVILL J. CHRISTY, Architect. With 160 Woodcuts 3/0
"The work is deserving of high commendation,"—Builder. Shoring,
And its Application: A Handbook for the use of Students. By G. H. BLASSKOVE 1/6
"We recommend this valuable treatise to all students."—Building News. Timber Importer's, Timber Merchant's, and
Builder's Standard Guide.
By R. E. GRANDY
"Everything it pretends to be: built up gradually, it leads one from a forest to a tree all, and throws in, as a makeweight, a best of quaterial concerning bricks, columns, classes, &c."—Kaylish Machanic.
Plumbing:
A Text-Book to the Practice of the Art or Craft of the Plumber. With Chapters opon House Drainage and Ventilation. By WM. PATON BUCHAN, R.P., Sanitary Engineer.
Ninth Edition, with \$12 Illustrations 3/6 "A text-book which may be safely put into the hands of every young plainber, and which will also
he found useful by architects and medical professors."—Builder.
Ventilation:
A Text-Book to the Practice of the Art of Ventilating Buildings. By W. P. BUCHAN. R. P., Author of "Plambing," &c. With 170 Blustrations 3/6
The Practical Plasterer:
A Compendium of Plain and Ornamental Plaster Work. By WILFRED KEMP 2/0

House Painting, Graining, Marbling, and Sign Writing:

With a Course of Elementary Drawing, and a Collection of Useful Receipts. By ELLIS A. DAVIDSON. Ninth Edition. Coloncet Plates. 5/0

"The above, in cloth boards, strongly bound, 6/0.

"A man of information of use to the smatter and of value to the gractical man."—English Mechanic.

Grammar of Colouring.

Applied to Decorative Painting and the Arts. By Growge Fig. D. New Editive versed and enlarged by ELLIS A. DAVIDSON. With Coloured Plants.

"The book is a most coeful released of the properties of pigments."—Builder.

Elementary Decoration:

As Applied to Dwelling-Houses, &c. By James W. Facry. Illustrated 2:0

"The principles which ought to guide the decoration of dwelling-houses are clearly as firsts, and elucidated by examples; while full instructions are given to the learner. —Source.

Practical House Decoration.

A Guide to the Art of Ornamental Painting, the Arrangement of Colours in Apartmental and the Principles of Decorative Design. By James W. Facry 25

The last two Works in One hundrons Vol., half-bound, entitled "House Decorations Elementary and Practical," pric 50.

Portland Cement for Users.

By the late HENRY FAHA. M. Inst. C.E. Fifth Edition, Revised and Enlarged by D. B. BUTLER, A.M. Inst. C.E. [Just political, 3,0]

"Supplies in a small compass all that is necessary to be known by users of cement."—Buttling News.

Limes, Cements, Mortars, Concretes, Mastics, Plastering, &c.
By G. R. BURNELL, C.E. Fifteenth Edition

Masonry and Stonecutting,
The Principles of Masonic Projection, and their Application to Construction.
E. Donson, M.R.I.B.A.

Arches, Piers, Buttresses, &c.
Experimental Essays on the Principles of Construction in: By WILLIAM BLAND 1/6

Quantities and Measurements,

In Bricklayers', Masons', Plasterers', Plumbers', Painters', Paperbungers', Gilders',
Smiths', Carpenters' and Joiners' Work. By A. C. Braton, Surveyor

"This book is indispensable to builders and their quantity clerks."—English Mechanic.

Complete Measurer;

Setting forth the Measurement of Boards, Glass, Timber, and Stone. By R. HORTON Sixth Edition

Guide to Superficial Measurement.

Tables calculated from 1 to 200 inches in length, by 1 to 108 inches in brendth. For the use of Architects, Surveyors, Engineers, Timber Merchants, Builders, &c. Branes Hawkings. Fifth Edition 3/6

Light:

An Introduction to the Science of Optics. Designed for the Use of Students of Architecture, Engineering, and other Applied Sciences. By E. W. TARN, M.A. . 1/8

Hints to Young Architects.

By GEORGE WIGHTWICK, Architect, Author of "The Palace of Architecture," &c., &c., Sixth Edition, revised and enlarged by G. HUSKISSON GUILLAUME, Architect 378
"A copy ought to be considered as necessary a purchase as a box of instruments,"—Architect.

Architecture-Orders.

The Orders and their Æsthetic Principles. By W. H. LEEDS, Illustrated

Architecture-Styles.

The History and Description of the Styles of Architecture of Various Countries, from the Earliest to the Present Period. By T. Talbot Bury, F.R.L.B.A., &c. Illustrated 2/0. "Orders and Styles of Architecture," in One Vol., 3/6.

Architecture-Design.

The Principles of Design in Architecture, as deducible from Nature and exemplified in the Works of the Greek and Gothic Architects. By Edw. L. Garantit, Architect 2/6 "We know no work that we would some recommend to an attentive reader desirous to obtain Heaviews of the nature of architectural art. The book is a valuable one."—Builder.

The three preceding Works in One hardsome Vol., helf-board, entitled. "Modern Auchitectural, price 6/0.

Architectural Modelling in Paper,
The Art of. By T. A. RICHARDSON. With Illustrations, engraved by O. Jawitt
"A valuable sid to the practice of architectural modelling." - Swilder's Weekly Reporter.

Perspective for Beginners.

For Students and Amateurs in Architecture, Painting, &c. By G. Pysn . . . 2/0

The state of the s
Glass Staining, and the Art of Painting on Glass.
From the German of Dr. GESSERT and EMANUEL OTTO FROMBERG. With an
Appendix on The ART OF ENAMELLING
Vitruvius-The Architecture of Marcus Vitruvius
Pollio.
In Ten Books. Translated from the Latin by J. Gwilly. With 23 Plates . 5/0
N.B.—This is the only Edition of Verreuvius procurable at a moderate price.
Grecian Architecture,
An Inquiry into the Principles of Beauty in; with an Historical View of the Rise and
Progress of the Art in Greece. By the EARL OF AREKDERN 1/0
** The two preceding Works in One handsome Vol., half-bound, entitled "ANCIENT ARCHITECTURE," price 6/0.
memicane pear div.
INDUSTRIAL AND USEFUL ARTS.
Cements, Pastes, Glues, and Gums.
A Guide to the Manufacture and Application of Agglutinants for Workshop, Laboratory,
or Office Use. With 900 Recipes and Formulæ. By H. C. STANDAGE
among the large number of industries it touches."-Daily Chronicle.
Clocks, Watches, and Bells for Public Purposes.
A Rudimentary Treatise. By EDMUND BECKETT, LORD GRIMTHORPE, LL.D., K.C.,
F.R.A.S. Eighth Edition, with new List of Great Bells and an Appendix on
Weathercocks
"The above, handsomely bound, Cloth Boards, 5/6. "The best work on the subject probably extant. The treatise on hells is undoubtedly the best in the
language."-Engineering. "The only modern treatise on clock-making."-Herelogical fournal.
Electro-Metallurgy,
Practically Treated. By ALEXANDER WATT. Tenth Edition, enlarged and revised.
With Additional Illustrations, and including the most Recent Processes 3/6
"From this book both amateur and artisan may learn everything necessary."-Iron.
Goldsmith's Handbook,
Containing full Instructions in the Art of Alloying, Melting, Reducing, Colouring,
Collecting, and Refining. The processes of Manipulation, Recovery of Waste, Chemical and Physical Properties of Gold; Solders, Enamels, and other useful Rules
and Recipes, &c. By GEORGE E. GEE. Sixth Edition
"A good, sound, technical educator." - Horological Journal.
Silversmith's Handbook,
On the same plan as the above. By GEORGE E. GEE. Third Edition 3/0
"A valuable sequel to the author's "Practical Goldworker," "Silversmith's Trade Journal, "The two preceding Works, in One kandsome Vol., half-bound, entitled "TRE
GOLDSMITH'S AND SILVERSMITH'S COMPLETE HANDBOOK," 7/0.
Hall-Marking of Jewellery.
Comprising an account of all the different Assay Towns of the United Kingdom; with
the Stamps at present employed; also the Laws relating to the Standards and Hall-
Marks at the various Assay Offices. By GEORGE E. GEE 3/0
French Polishing and Enamelling.
A Practical Book of Instruction, including numerous Recipes for making Polishes,
Varnishes, Glaze-Lacquera, Revivers, etc. By RICHARD BITMEAD 1/6
Practical Organ Building.
By W. E. DICKSON, M.A., Processor of Ely Cathedral. Second Edition, Revised 2/6 "The smatter builder will find in this book all that is necessary to enable him personally to construct
"The smateur builder will find in this book all that is necessary to enable him personally to construct a perfect organ with his own hands."—Academy.
Coach-Building:
A Develop Provide All and a Developing De Later M. Developing 0.0

A Practical Treatise, Historical and Descriptive. By JAMES W. BURGESS . 2/6

"This handbook will apply a long-felt want, not only to manifecturers themselves, but more particularly apprentices, and others connected with the trade of coach-building. — Encodern Mark.

The Cabinet-Maker's Guide

The Cabinet-Maker's Guide

To the Entire Construction of Cabinet-Work, including Veneering, Marqueterie, BahiWork, Mosaic, Inlaying, Working and Polishing Ivory, Trade Recipes, &c. By
RICHARD BITMEAD. With Plans, Sections, and Working Drawings 2/6

Brass Founder's Manual:
Instructions for Modelling, Pattern Making, Moulding, Turning, &c. By W. GRAHAM 2/0

Sheet Metal-Worker's Guide.

A Practical Handhook for Timemiths, Copperamiths, Zineworkers, &c., with 46
Diagrams and Working Patterns. By W. J. E. Chane. Fourth Edition 16

"The author has acquired himself with considerable tact in choosing his examples, and with no
less shifty in treating them,"—Flueber.

Sewing Machinery.

Construction, History, Adjusting, &c. By J. W. URQUHART, C.E
Gas Fitting:
A Practical Handbook. By JOHN BLACK. Revised Edition. With 130 Hinstrations 2/6 "It is written in a simple practical style, and we heartily recommend in "-Plember and December.
Construction of Door Locks.
From the Papers of A. C. Honns. Edited by CHARLES TOMLINSON, F.R.S. With a Note upon 180% SAFES by ROBERT MALLEY. Historied
The Model Locomotive Engineer, Fireman, and
Engine-Boy. By Michael Reynolds
Art of Letter Painting made Easy.
By JAMES GREIO BADENOCH. With 12 full-page Engravings of Examples 1/8 "Any intelligent lad who fulls to turn out decest work after studying this system, has enlitted in woration."—English Mechanic.
Art of Boot and Shoemaking,
Including Measurement, Last-fitting, Curting-out, Closing and Making; with a Description of the most Approved Machinery employed. By J. B. LENO 2/0 by far the best work ever written on the subject."—Scottlik Leather Teader.
Mechanical Dentistry:
A Practical Treatise on the Construction of the Various Kinds of Artificial Dennares, comprising also Useful Formulæ, Tables and Receipts. By C. HUNTER . 3/0
A Practical and Easy Introduction to the Study of the Art. By W. N. Brown 1/6
Laundry Management.
A Handbook for Use in Private and Public Laundries. Fourth Edition 270 "This look should certainly occupy an honoured place on the shelves of all housekeepers who wish to keep themselves an courant of the newest appliance and methods." — The Queen.
The state of the s
AGRICULTURE, GARDENING, ETC.
Draining and Embanking. A Practical Treatise. By JOHN SCOTT, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnocster, With 68 lilustrations
Draining and Embanking. A Practical Treatise. By JOHN SCOTT, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnocator, With 68 Illustrations. 1/6 "A valuable handbook to the engineer as well as to the surveyor."—Land.
Draining and Embanking. A Practical Treatise. By JOHN SCOTT, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnessier, With 68 Illustrations. 1/8 "A valuable handbook to the engineer as well as to the surveyor."—Lawd. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. 1/6
Draining and Embanking. A Practical Treatise. By JOHN SCOTT, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesster, With 68 Illustrations. 1/8 "A valuable handbook to the engineer as well as to the surveyor."—Land. Irrigation and Water Supply: A Practical Treatise on Water Meadows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. 1/6 "A valuable and indispensable book for the estate manager and owner."—Forestry.
Draining and Embanking. A Practical Treatise. By Join Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesser, With 68 Illustrations. "A valuable handbook to the engineer as well as to the surveyor."—Law. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. "A valuable and indispensable book for the estate manager and owner."—Forcity. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6
Draining and Embanking. A Practical Treatise. By Join Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesser, With 68 Illustrations. 1/6 "A valuable handbook to the engineer as well as to the surveyor."—Law. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. 1/6 "A valuable and indispensable book for the eatate manager and owner."—Forestry. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6 "A useful practical work, which should be in the hands of every farmer."—Farewer.
Draining and Embanking. A Practical Treatise. By Join Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesser, With 68 Illustrations. "A valuable handbook to the engineer as well as to the surveyor."—Law. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. "A valuable and indispensable book for the estate manager and owner."—Forcity. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6 "A useful practical work, which should be in the hands of every farmer."—Farmer. Farm Buildings: A Practical Treatise on the Buildings necessary for various kinds of Farms, their Arrangement and Construction, with Plans and Estimates. By Professor J. Scott. 2/0
Draining and Embanking. A Practical Treatise. By Join Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesser, With 68 Illustrations. "A valuable handbook to the engineer as well as to the surveyor."—Law. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. "A valuable and indispensable book for the estate manager and owner."—Forestry. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6 "A useful practical work, which should be in the hands of every farmer."—Farmer. Farm Buildings: A Practical Treatise on the Buildings necessary for various kinds of Farms, their Arrangement and Construction, with Plans and Estimates. By Professor J. Scott. 2/0 "No one who is called upon to design farm buildings can afford us be without this work."—Builder.
Draining and Embanking. A Practical Treatise. By Join Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnesser, With 68 Illustrations. "A valuable handbook to the engineer as well as to the surveyor."—Law. Irrigation and Water Supply: A Practical Treatise on Water Mendows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. "A valuable and indispensable book for the estate manager and owner."—Forcity. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6 "A useful practical work, which should be in the hands of every farmer."—Farmer. Farm Buildings: A Practical Treatise on the Buildings necessary for various kinds of Farms, their Arrangement and Construction, with Plans and Estimates. By Professor J. Scott. 2/0
Draining and Embanking. A Practical Treatise. By John Scott, late Professor of Agriculture and Rural Economy at the Royal Agricultural College, Circnester, With 68 Illustrations. 1/6 "A valuable handbook to the engineer as well as to the surveyor,"—Land. Irrigation and Water Supply: A Practical Treatise on Water Meanlows, Sewage Irrigation, Warping, &c. on the Construction of Wells, Ponds, and Reservoirs, &c. By Professor J. Scott. 1/6 "A valuable and indispensable book for the catale manager and owner."—Forestry. Farm Roads, Fences, and Gates: A Practical Treatise on the Roads, Tramways, and Waterways of the Farm; the Principles of Enclosures; and on Fences, Gates, and Stiles. By Prof. John Scott. 1/6 "A useful practical work, which should be in the hands of every farmer."—Farmer. Farm Buildings: A Practical Treatise on the Buildings necessary for various kinds of Parms, their Arrangement and Construction, with Plans and Estimates. By Professor J. Scott. 2/0 "No one who is called upon to design farm buildings can afford us be without this work."—Building. Barn Implements and Machines: Treating of the Application of Power to the Operations of Agriculture; and of the various Machines used in the Threshing-barn, in the Stockyard, Dairy, &c. By

With Principles and Details of Construction and Points of Excellence, their Management, &c. By Professor John Scott. With 138 Illustrations 270

Agricultural Surveying:

A Treatise on Land Surveying, Levelling, and Setting-out; with Directions for Valuing and Reporting on Farms and Estates. By Professor J. Scorr . 1/8

Farm Engineering.

By Professor John Scott. Comprising the above Seven Valumes in One, 1,130 pages, and over 600 Blustrations. Half-bound 12/0

"A copy of this work should be treasured up in every library where the owner thereof is in any war connected with land."—Farm and Henry.

Outlines of Landed Estates Management.

Treating of the Varieties of Lands, Methods of Farming, the Setting-out of Farms, &c.;

Roads, Fences, Gates, Irrigation, Drainage, &c. By R. S. Burn. 2/6

"A complete and comprehensive outline of the duties appertaining to the management of landed estates."—formul of Forestry.

Soils, Manures, and Crops.
(Vol. 1. Outlines of Modern Farming.) By R. Scott Burn. Woodcuts. 2/0
Farming and Farming Economy.

Farming and Farming Economy,

Historical and Practical. (Vol. II. OUTLINES OF MODERN FARMING.) By R. SCOTT

BURN.

"Emineutly calculated to enlighten the agricultural community on the varied subjects of which it

treats; hence it should find a place in every farmer's library,"—City Press.

Stock: Cattle, Sheep, and Horses.

(Vol. III. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts 2/6

"The author's grasp of his subject is thorough, and his grasping of facia affective. We commend this excellent treatise."—"Probly Diplates."

Dairy, Pig's, and Poultry.

(Vol. IV. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts 2/0

"We can testify to the clearness and intelligibility of the matter, which has been compiled from the best numberines."—Lenders Resign.

Utilization of Sewage, Irrigation, &c.
(Vol. V. Outlines of Modern Farming.) By R. Scott Burn. Woodcuts 2/6
"A work containing valuable information, which will recommend itself to all interested in modern farming."—Field.

Book-keeping for Farmers and Estate Owners.

A Practical Treatise, presenting, in Three Plans, a System adapted for all classes of Farms. By J. M. WOODMAN, Chartered Accountant, Fourth Edition . 2/6

"Well be found of great assistance by those who intend to commence a system of book-keeping, the author's examples being clear and explicit, and his explanations full and accurate."—Live Stock Journal.

Ready Reckoner for Admeasurement of Land.

By A. Arman. Revised and extended by C. Norrets, Surveyor, Fifth Edition 2/0

"A very swellal book to all who have land to measure."—Mark Lans Express.
"Should be in the hands of all persons having any connection with land."—Irish Farm.

Ready Reckoner for Millers, Corn Merchants,
And Farmers. Second Edition, revised, with a Price List of Modern Flour Mill
Machinery. By W. S. HUTTON, C.E. 2/0
"Will prove an indispensible said maxwe. Nothing has been spared to make the book complete and
perfectly adapted to its special purpose." Miller.

The Hay and Straw Measurer:

New Tables for the use of Auctioneers, Valuers, Farmers, Hay and Straw Dealers, &c., forming a complete Calculator and Ready Reckoner. By JOHN STRELE 2/0

"A most useful handbook. It should be in every professional office where agricultural valuations are conducted."—Land Agent's Record.

Meat Production:

A Manual for Producers, Distributors, and Consumers of Butchers' Meat. By Jours

EWART

2/6

"A compact and handy volume on the meat question."

-Meat and Previous Produce Review.

with Engravings, including Specimens of New and Improved Breeds. "The book is decidedly the best of the kind in our language."—Sections.	5/ 5
"The most valuable compendium of kitchen and market-garden work published."Farmer.	3 <i>i</i> 6
Kitchen Gardening made Easy. Showing the best means of Cultivating every known Vegetable and Herb, &c., v directions for management all the year round. By GEO. M. F. GLEMMY. Illustrated "This book will be found trustworthy and useful."—North British Agriculturist.	rith 1/6
Cottage Gardening;	1/6
Garden Receipts Edited by CHARLES W. QUIN. Fourth Edition. "A singularly complete collection of the principal receipts needed by gardeners."—####################################	1/6
	ifth 3/6
Tree Planter and Plant Propagator: With numerous Illustrations of Grafting, Layering, Budding, Implements, Houring, Rc. By S. Wood, Author of "Good Gardening," &c. "Sound in its teaching and very comprehensive in its aim. It is a good book."—Gardeners' Magazine.	
Tree Pruner: Being a Practical Manual on the Pruning of Fruit Trees, including also their Training a Renovation, also treating of the Pruning of Shrubs, Climbers, and Plowering Plants. We numerous Illustrations. By Samuel Wood, Author of "Good Cardening," &c. 1 "A useful book, written by one who has had great experience."—Mark Lane Experse. ""The above Tree Vols. in One, handsomely half-bound, entitled "The Tree Plants Propagator and Pruner." By Samuel Wood. Price 3/6.	and With L/6
Art of Grafting and Budding. By CHARLES BALLEL, With Bustrations. "The one claudard work on this subject." Neetsman.	
	, U
MATHEMATICS, ARITHMETIC, ETC.	, u
MATHEMATICS, ARITHMETIC, ETC. Descriptive Geometry, An Elementary Treatise on; with a Theory of Shadows and of Perspective, extracte from the French of G. Monge. To which is added a Description of the Principles an Practice of Isometrical Projection. By J. F. HEATHER, M.A. With 14 Plates. 2/6	র d
Descriptive Geometry, An Elementary Treatise on; with a Theory of Shadows and of Perspective, extracte from the French of G. Mosge. To which is added a Description of the Principles an	ਜ਼ d 0 d
Descriptive Geometry, An Elementary Treatise on; with a Theory of Shadows and of Perspective, extracte from the French of G. Monge. To which is added a Description of the Principles an Practice of Isometrical Projection. By J. F. HEATHER, M.A. With 14 Plates. 2/6 Practical Plane Geometry: Giving the Samplest Modes of Constructing Figures contained in one Plane and Geometrical Construction of the Ground. By J. F. HEATHER, M.A. "The author is well-known as an experienced professor, and the volume contains as complete a collection of problems as is likely to be required in ordinary practice."—Architect. Analytical Geometry and Conic Sections. By Jamis Hann. New Edition, Enlarged by Professor J. R. YOUNG. "The author's style is exceedingly clear and simple, and the book is well adapted for the beginner and those who may be obliged to have recourse to self-truition."—Engineer.	4d d0 d0 d0 d
Descriptive Geometry, An Elementary Treatise on; with a Theory of Shadows and of Perspective, extracter from the French of G. Mosde. To which is added a Description of the Principles and Practice of Isometrical Projection. By J. F. HEATHER, M.A. With 14 Plates. 2/6 Practical Plane Geometry: Giving the Simplest Modes of Constructing Figures contained in one Plane and Geometrical Construction of the Ground. By J. F. HEATHER, M.A. 2/6 "The author is well-known as an experiencel professor, and the volume contains as complete a collection of problems as is likely to be required in ordinary practice."—Architect. Analytical Geometry and Conic Sections. By JAMIS HANN. New Edition, Enlarged by Professor J. R. YOUNG. "The author's style is exceedingly clear and simple, and the book is well adapted for the beginner and those who may be obliged to have recourse to self-tuition."—Engineer. Euclid, The Elements of; with many Additional Propositions and Explanatory Notes; to which is prefixed an Introductory Essay on Logic. By Henry Law, C.E. 2/6	d d O
Descriptive Geometry, An Elementary Troctise on; with a Theory of Shadows and of Perspective, extracte from the French of G. Monge. To which is added a Description of the Principles an Practice of Isometrical Projection. By J. F. HEATHER, M.A. With 14 Plates. 2/6 Practical Plane Geometry: Giving the Samplest Modes of Constructing Figures contained in one Plane and Geometrical Construction of the Ground. By J. F. HEATHER, M.A. 2/6 "The author is well-known as an experiencel professor, and the volume contains as complete a collection of problems as is likely to be required in ordinary practice."—Architect. Analytical Geometry and Conic Sections. By James Hann. New Edition, Enlarged by Professor J. R. Young . 2/0 "The author's style is exceedingly clear and simple, and the book is well adapted for the beginner and those who may be obliged to have recourse to self-tuition."—Engineer. Euclid, The Elements of; with many Additional Propositions and Explanatory Notes; to	d d O

Spherical Trigonometry,
The Elements of By James Hann. Revised by Charles II. Downby, C.E. 1/0
Differential Calculus,
Elements of the. By W. S. B. WOOLHOUSE, F.R.A.S., &c. 1/8
Integral Calculus. By Homersham Cox, B.A
Algebra,
The Elements of, By JAMES HADDON, M.A., formerly Mathematical Master of King's College School. With Appendix, containing Miscellaneous Investigations, and a collection of Problems 2/0
Key and Companion to the Above. An extensive repository of Solved Examples and Problems in Illustration of the various Expedients necessary in Algebraical Operations. By J. R. You'sa . 1/6
Commercial Book-keeping. With Commercial Phrases and Forms in English, French, Italian, and German, By JAMES HADDON, M.A., formerly Mathematical Master, King's College School. 1/6
Arithmetic,
A Rudimentary Treatise on : with full Explanations of its Theoretical Principles, and numerous Examples for Practice. For the use of Schools and for Self-Jastruction. By J. R. Young, late Professor of Mathematics in Belfast College. Fourteenth Edition 1/8
Key to the Above.
By J. R. Young
Applied to Questions of Interest, Annulties, Life Assurance, and General Commerce: with various Tables by which all calculations may be greatly facilitated. By W. HIPSLEY 1/8
Apithmetic, Rudimentary, for the Use of Schools and Self-Instruction. By JAMES HADDON, M.A. Revised by ABRAHAM ARMAN 1/6
Key to the Above.
By A. Arman
Mathematical Instruments, A Treatise on; Their Construction, Adjustment, Testing, and Use conceely explained. By J. F. HEATHER, M.A., of the Royal Military Academy, Wisolwich. Fitteenth Edition, Revised with Additions, by A. T. Walmisley, M.J.C.E., Fellow of the Surveyors' Institution. Original Edition in One Vol., Illustrated. 2/0 *** In ordering be careful to say "Original Edition," in distinguish it from the Enlarged Edition in Three Vols. (see below).
Drawing and Measuring Instruments.
Including—I. Instruments employed in Geometrical and Mechanical Drawing, and in the Construction, Copying, and Measurement of Maps and Plans. II. Instruments used for the purposes of Accurate Measurement, and for Arithmetical Computations. By J. F. HEATHER, M.A. 1/6
Optical Instruments. Including (more especially) Telescopes, Microscopes, and Apparatus for producing enpies of Maps and Plans by Photography. By J. F. HEATHER, M.A. Illustrated 1/6
Surveying and Astronomical Instruments.
Including—I. Instruments used for Determining the Geometrical Features of a portion of Ground. II. Instruments employed in Astronomical Observations. By J. F. HEATHER, M.A. Illustrated
"." The above Three Volumes form an enlargement of the Author's original work, "Mathematical Instruments," price 2/0.
Mathematical Instruments:
Their Construction, Adjustment, Testing and Use. Comprising Drawing, Measuring, Optical, Surveying, and Astronomical Instruments. By J. F. HEATHER, M.A. Enlarged Edition, for the most part re-written. Three Parts as above 4/6 "An exhaustice treaties, belonging to the well-known Weals's Series. Mr. Heather's experience well qualifies him for the task be has so ably fulfilled."—Engineering and Building Times.
Slide Rule, and How to Use It.
Containing full, easy, and simple Testractions to perform all Business Calculations with unexampled rapidity and accuracy. By CHARLES HOARE, C.E. With a Slide Rule, in tuck of cover. Eighth Edition 2/6

Mathematical Tables,

For Trigonometrical, Astronomical, and Namical Calculations: in which is profited a Treatise on Logorithms. By H. LAW, C.E. Together with a Series of Tunto as Navigation and Nautical Astronomy. By Professor J. R. Visusu. Naw Edmin. 40

Logarithms.

With Mathematical Tables for Trigonometrical, Astronomical, and Nautical Calestions. By Hanny Law, C.E. Revised Edition. (Forming part of the above week) 20

Theory of Compound Interest and Annuities:

With Tables of Logarithms for the more Defined Computation of Interest, DisAnnualties, &c., in all their Applications and Uses for Mercantile and State Purpo
By Pariou Tuoman, of the Societé Crédit, Mobilier, Paris. Focrila Belvion
"A very powerful work, and the author has a very remarkable command of his subject."—Prob
A, on Moscans, "We recommend it to the mulice of accounts and accountants,"—Addomnum.

Treatise on Mathematics,
As applied to the Constructive Arts. By Francis Campin, C.E., &c. and Eds. 3/0
"Should be in the hands of every one connected with building communities." - Switters Report

Astronomy.

By the late Rev. Robert Main, M.A., F.R.S. Third Edition, revised and corner By William Thynne Lynn, B.A., F.R.A.S. "A sound and simple treatise, very carefully edited, and a capital book for legioners."

Statics and Dynamics,
The Principles and Practice of; embracing also a clear development of Hydroscarch,
Hydrodynamics, and Central Forces. By T. BAKER, C.E. Fourth Edulon 10

BOOKS OF REFERENCE AND MISCELLANEOUS VOLUMES.

Manual of the Mollusca:

A Treatise on Recent and Fossil Shells, By Dr. S. P. Woodward, A.L.S.

Appendix by RALPH TATE, A.L.S., F.G.S. With numerous Plates and
Woodcuts

"A storehouse of conchological and geological information."-Hardwicke's Science Grant,

Dictionary of Painters,

And Handhook for Picture Anuareurs; being a Guide for Visitors to Public and Private Picture Galleries, and for Art Students, including Glossary of Terms, &c. By Phylleric 2:6

"Considering its small compass, really admirable. We cordially recommend the back," - For there

Painting Popularly Explained.

By Thomas John Gullick, Painter, and John Times, F.S.A. Including Presonal, Mosaic, Water Colour, Water-Glass, Tempera, Encaustic, Miniature, Painting on Ivory, Vellum, Pottery, Enamel, Glass, &c. Sixth Edition

Adopted at a Prize Book at South Kensington.

"Much may be learned, even by those who fancy they do not require to be taught, from the perusal of this suppretending but comprehensive treatise."—Art fournat.

Dictionary of Terms used in Architecture,
Building, Engineering, Mining, Metallurgy, Archieology, the l'ine Arts, &c.
By John Wrale. Sixth Edition. Edited by Rourt. Hunt, I'.R.S., Keeper of
Mining Records, Editor of "Ure's Dictionary." Numerous Illustrations 5/0 "The best small technological dictionary in the language." - Architect.

Music,

A Rudimentary and Practical Treatise on. By CHARLES CHILD SPENCES:

"Mr. Spencer has marshalled his information with much skill, and yet with a simplicity trait recommend his works to all who wish to thoroughly understand music."—Heavily Times.

Pianoforte,
The Art of Playing the. With Exercises and Lessons. By C. C. Spencine
"A sound and excellent work, written with spirit, and calculated to inspire the pupil with a daim at high accomplishment in the art."—School Board Chronicle.

Wanta Wantana
House Manager: Being a Guide to Housekeeping, Practical Cookery, Pickling and Preserving, House-
bold Work, Dairy Management, the Table and Dessert, Callarage of Wines, Home- brewing and Wine-making, the Bondoir and Dressing-room, Travelling, Stable Economy, Gardening Operations, &c. By An Old Housekeeper 3/6
"We find here directions to be discovered in no other book, fending to save expense to the pocker, as well as labour to the head,"—John Bull,
Manual of Domestic Medicine. By R. GOODING, R.A., M.D. Intended as a Family Guide in all Cases of Accident and Emergency. Third Edition. "The author has performed a useful service by placing at the disposal of those situated at a distance from medical aid, a reliable and sensible work in which professional knowledge and accuracy have been well seconded by the ability to express himself in ordinary untechnical language."—Public Health.
Management of Health. A Manual of Home and Personal Hygiene. By the Rev. James Barne. R.A 1/0 "It is wonderfully reliable, it is written with excellent taste, and there is instruction crowded into every page."—English Mechanic.
House Book, Comprising—I. The House Manager. By An Old Housekeeper. II. Domestic Medicine. By Ralph Gooding, M.D. III. Management of Health. By James Baird. In One Vol., strongly half-bound. 6/0
Natural Philosophy, For the Use of Beginners. By CHARLES TOMLINSON, F.R.S
Electric Lighting:
The Elementary Principles of. By Alan A. Campbell Swinton, M.Inst.C.E., M.J.E.E. With 16 Blustrations. Fifth Edition . 1/6
Handbook of Field Fortification. By Major W. W. KNOLLYS, F.R.G.S. With 163 Woodcuts. "A well-timed and able contribution to our military literature
Logic, Pure and Applied. By S. H. EMMENS "This admirable work should be a sext-book not only for schools, stratents, and philosophers, for all little actives and men of science, but for those concerned in the practical affairs of life, &c."—The News.
Locke's Essays on the Human Understanding. Selections, with Notes by S. H. EMMENS
Compendious Calculator (Intuitive Calculations); or Easy and Concise Methods of performing the various Arithmetical Operations required in Commercial and Business Transactions; together with Useful Tables, &c. By DANIEL O'GORMAN. Twenty-eighth Edition, carefully revised by C. NORRIS.
"It would be difficult to exaggerate the usefulness of this book to every one engaged in commerce or manufacturing industry. It is crammed full with rules and formula for shortaning and employing calculations in money, weights and measures, &c., of every sort and description."—Knowledge.
Measures, Weights, and Moneys of all Nations, And an Analysis of the Christian, Hebrew, and Mahometan Calendars. By W. S. B. WOOLHOUSE, F. R.A.S., F.S.S. Seventh Edition "A work necessary for every mercaptile office."—Building Trades forward. 2/6
Grammar of the English Tongue, Spoken and Written. With an Introduction to the Study of Comparative Philology. By Hyde Clarke, D.C.L. Sixth Edition
Dictionary of the English Language, An Spoken and Written. Containing about 100,000 Words. By Hydr Clarke, D.C.L 3/8
Composition and Punctuation, Familiarly Explained for those who have neglected the Study of Grammer. By JUSTIN BRENAN. Twentieth Edition 1/6

French Grammar. With Complete and Concise Rules on the Genders of French Normalis, G. L. Strauss, Ph.D.
English-French Dictionary.
French Dictionary. Two Parts: L. French-English. H. English-French. Complete in One Vol. 18.0
French and English Phrase Book. Containing Introductory Lessons, with Translations, Vocabularies of Wanta, Collector of Phrases, and Easy Familiar Dialogues 100
German Grammar. Adapted for English Students, from Heyer's Theoretical and Practical Grammar, by Dr. G. 1. STRAUSS
German Triglot Dictionary. By N. E. S. A. HAMILTON, Part I. German-French-English, Part II. English, German-French, Part III. French-German-English
German Triglot Dictionary (As above). Together with German Grammar in One Vol
Italian Grammar, Arranged in Twenty Lessons, with Exercises. By ALEREN ELWES . 138
Italian Triglot Dictionary, Wherein the Genders of all the Italian and French Nouss are sarefully noted as By ALPRED ELWES. Vol. I. Italian-English-French
Italian Triglot Dictionary. By ALERED ELWES. Vol. II. English-French-Italian
Italian Triglot Dictionary. By ALFRED ELWES, Vol. III. French-Italian-English
Italian Triglot Dictionary (As above), In One Vol
Spanish Grammar. In a Simple and Practical Form. With Exercises. By ALFRED ELWES 1/6
Spanish-English and English-Spanish Dictionary. Including a large number of Technical Terms used in Mining, Englacering, &c., with the proper Accents and the Gender of every Noun, By ALFRED ELWES 4/0 *** 1 Or with the GRAMMAR, 6/0.
Portuguese Grammar, In a Simple and Practical Form. With Exercises. By ALFRED ELWES 1/6
Portuguese-English and English-Portuguese Dic- tionary. Including a large number of Technical Terms used in Mining, Engineering, &c., with the proper Accents and the Gender of every Noun. By ALPRED ELWES. Fourth Edition, revised.
Animal Physics, Handbook of. By Dionysius Landner, D.C.L. With 520 Illustrations. In One Via (732 pages), cloth boards. **Sold also in Two Parts, as follows:—
ANIMAL PHYSICS. By Dr. LARDNER. Part L. Chapters L.—VII. ANIMAL PHYSICS. By Dr. LARDNER. Part II. Chapters VIII.—XVIII.

